INJ. CASE OWNER: Boon Sen | CC 3, CTI 180 14511, 19fa34 | LKK: IDAC:

ASSIGNMENT

Surveyor: Awk | DOI: 8/8/18 | Date / Time: 8/8/18 Pohkin

Registered in Merimen:

Pre-assign / CCU / FTE

Insured Vehicle No.:	SLM 4484 A	Claim No.:	SNM18003850C02
Name of Insured:	TAN JIA WEN GERRY	Policy No.:	DMFCSN30201918000
Insured Tel No.:	HP: 94246577	Make / Model:	Honda City
Excess Sec II :S$	D.O.A.: 6/8/18	Place of Accident:	PIE
Is driver the owner? (YES / NO)	Nature of Accident:		

If NO, Driver Name / Age:

Driver Tel No.: (V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % **Final ? Yes / No**

SHC 8489K → → →

INSRS: WSP: China Taiping Tel: Liability: RMKS:	INSRS: WSP: Tel: Liability: RMKS:	INSRS: WSP: Tel: Liability: RMKS:	INSRS: WSP: Tel: Liability: RMKS:

Date/ Time	
1/8/18	SHC8489K - CC(FCI180000)? ...
CPIC	SLM4484A - x
	received video footage from OI
	potential reject case, KIV LOD to reject TP claim;
17/8/2018	Spoke to OI, confirmed TP BOLA 15, OI got in car camera, received OI video footage.
	KIV TP LOD to write to CTI reject TP claim
	LOD ✓
18/10/2018	Seek mandate to reject TP claim
24/10/2018	mandate approved ✓
24/10/2018	E-mail to reject TP claim
	After repair photo ✓

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	17/8/2018
After call ltr to OI:	

Documentation Check List:	Handler	Typist
Notification ltr (if non-pickup)		
After call ltr to OI:		
Authorisation To Act:	✓	
Release Voucher:		
Final Repair Bill:	✓	
Car Rental Invoice:	✓	
Towing Invoice:		
LTA / GIA:	✓	
Medical Bill:		
PIR:		
Mandate/Reject Instruction:	✓	
LOD	✓	
Payment Breakdown Form:		
Post-Repair Photos:		
Others:		

26-10-18 Pohkin

PRELIMINARY ADVICE	Date/Time: 15/8/2018	Sent By: HMK	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	S$ (days)	Reduction: %	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with	Email ☐ Call ☐
Final Liability:	% 0 (Agreed / Assessed)	BOLA S/N No.: 15	If NO or B 28, Ass. Lia.: TP change lane
Repair Cost:	S$		
Loss of Rental (LOR):	S$ (days)		
Loss of Use (LOU):	S$ ($ x days)		
Loss of Income (LOI):	S$ ($ x days)		CPL 26/10/18
LOR only ☐	LOU only ☐ LOR + LOU ☐	LOR + LOI ☐ [Tick only one]	
GIA/LTA Search	S$		
Medical:	S$		1) Claim status: Normal/Reject/Private Settle
Disbursement:	S$	(e.g. Tow/ Independent)	2) Report Format: WP
Legal Cost	S$		3) Survey fee: $400.00
Total:	S$	**Global Sum S$:**	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	S$	Name 1:	
Payee 2: (Strike if N.A.)	S$	Name 2:	Typist: Please create
Payee 3: (Strike if N.A.)	S$	Name 3:	LOD.

(08/21n3)
Surveyor: Kelvin

REF:

ASSIGNMENT

From: ______ Date: ______

Estimated Cost: ______

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: ______

at Workshop m/s ______

of ______

Insured: ______

Policy No. ______

Claims No. ______

Sum Insured: . ______ Excess: ______

(Client's Record)

Make of Veh: ______

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: ______

IDAC Accident Rport: ______ Consistent? : Yes or No

GIA / PR Seen: ______ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: IBIZ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: ______ Person Contacted: ______

Veh No: SHC 8489K Yr Regn: 7 Dec, 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Hyundai I40 c.c 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp.Reading: 349173 T/Radio: Insured / Std / NI / NA

Eng/No: ______

C/No: KMHLB41UMGU080696

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or ______

Brake: Inorder / Jammed / Leaked / Burnt or ______

Modi: Nil / S/Rim / STD Rim or ______

Tyre Size: F: 205/60 R16

R: ______

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Hankook.

Front			Rear		
R/Bal.	7	mm	R/Bal.	7	mm
L/Bal.	7	mm	L/Bal.	7	mm
D.O.A.	6/8/18		D.O.I.	8/8/18	

Survey held at: CDHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or N/S Front.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	CTZ
	PIR
	• IBIZ : $700.00 (Rch 2,278.32 / 76.50%)

Date/Time, File Pass to? ☐ : Prell. Report

1) ______ ☐ : Final Report

Date/Time, File Return to?

2) ______

Report Format: ______

Lump Sum / I.B.I: ($ ______)

Days Of Repair: ______

Resurvey No. of Trip: ______

Add Fee: ☐ : Site Insp ($ ______)
☐ : Interview ($ ______)
☐ : Tech. Invs ($ ______)
☐ : Weekend ($ ______)

Survey Fee:	
Transportation:	
___S + RS___SI	
Photos	
Others	
TOTAL	

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

Date/Time: 07.08.2018 16:55 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305197315

TOMER

MS COMFORT TRANSPORTATION PTE LTD

TOMER NO. 7010045

RESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65508755 (O)

(P)

CHINA

COUNT CARD NO.

REGN NO.: SHC8489K	MILEAGE
MAKE: HYUNDAI	FUEL E 1/2 F
MODEL: I-40	DATE/TIME IN: 07.08.2018 13:00
YR OF MANU: 03.12.2015	TARGET DATE
CHASSIS CODE: KMHLB41UMGU080694	COMPLETION DATE/TIME

JOB DESCRIPTION

Accident Date: 06.08.2018
NATURE: 3P 06.08.2018 / c

S/NO	LABOR CODE	DESCRIPTION



ECKED & PASSED OUT BY

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wledgement Slip

Exit Pass

e No.: SHC8489K LKE

Vehicle No.: SHC8489K

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No 305197315

Date : 18/08/18

FINALIZATION FORM

To : LKK Fax :

Attn : Mr KALVIN ANG

Vehicle Reg No. SHC8489K CTPL 06.08.18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **CHINA — SLM4484A**

2. The finalized amount shall be:

(a)	Spare Parts after List discount	$0.00
(b)	Labour Charges	$700.00
	Total for Part-By-Part Repair Cost	**$700.00**
(c.)	Lumpsum Repair (if applicable)	
	Total for Lumpsum repair cost after Less: 20%	
	Final Lumpsum Repair cost	

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

Signature :

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

We confirm the estimates and finalized amount

Signature :

Name : Kalvin

Date : 20/8/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

LKK/Kalvin PbyP CHINA

VEHICLE NO : SHC 8489K **DATE 7/8/2018 16:35**

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ×			$ 1,052.20
	Front Bumper Bracket Top (LH) ×			$ 22.40
	Front Bumper Bracket (LH) ×			$ 24.60
	Front Fender (LH) ×			$ 619.00
	Front Fender Shield (LH) ×			$ 169.80
	Front Fender Retainer ×			$ 9.20
	Frt Wheel Hub Cap, LH ×			$ 150.70
	SUB TOTAL			**$ 2,047.90**
	LESS 20%			$ 409.58
	DISCOUNTED TOTAL			**$ 1,638.32**
	Front Fender Advertisemnt Logo (LH) ✓			$ 100.00 **Nett**
				$ 100.00
	Labour Charge			
	Panel Beating			$ ~~560.00~~ 200
	Spray Painting Charge			$ ~~500.00~~ 800
	Wiring Charge			$ 50.00 ×
	Tuff Kote			$ 50.00 ×
	Frt Wheel Alignment			$ 80.00 ×
	TOTAL LABOUR			**$ 1,240.00**
	ESTIMATE TOTAL			**$ 2,978.32**

Kalvin LKK
8/8/18 1035h
2 hr
P/P
After Repair ...

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary ... and is subject to ... Insurance Company

Acknowledged by Repairer
Sign:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 18.08.2018
Time: 10:32:56
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO	:	305197315
REGN NO	:	SHC8489K
MILEAGE	:	0000000000
MAKE	:	HYUNDAI
MODEL	:	I-40
DATE OF REGN	:	03.12.2015
DATE/TIME IN	:	07.08.2018 13:00
ACCIDENT DATE	:	06.08.2018

JOB / PARTS DESCRIPTION		QTY IND UNIT-PRICE DISC% AMOUNT
PART REQUISITION		
	SUB-TOTAL :	0.00
JOB NATURE		
0000 20-05	RENEW ADVERTISMENT STICKER-	100.00
0001 L	PANEL BEATING	200.00
0002 23-502	SPRAYPAINT ON AFFECTED AREA	400.00
	SUB-TOTAL :	700.00
	TOTAL :	700.00

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

LKK/Kalvin

PbyP

CHINA

VEHICLE NO : **SHC 8489K**

DATE **7/8/2018 16:35**

MAKE :

Like

MODEL : **HYUNDAI i40**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover × repair			$ 1,052.20
	Front Bumper Bracket Top (LH) ?			$ 22.40
	Front Bumper Bracket (LH) ?			$ 24.60
	Front Fender (LH) × repair			$ 619.00
	Front Fender Shield (LH) ×			$ 169.80
	Front Fender Retainer ×			$ 9.20
	Frt Wheel Hub Cap, LH ×			$ 150.70
	SUB TOTAL			**$ 2,047.90**
	LESS 20%			$ 409.58
	DISCOUNTED TOTAL			**$ 1,638.32**
	Front Fender Advertisemnt Logo (LH) —			$ 100.00 **Nett**
				$ 100.00
	Labour Charge			200
	Panel Beating			$ ~~560.00~~
	Spray Painting Charge			$ ~~500.00~~ 800
	Wiring Charge			$ ~~50.00~~ ×
	Tuff Kote			$ ~~50.00~~ ×
	Frt Wheel Alignment			$ ~~80.00~~ ×
	TOTAL LABOUR			**$ 1,240.00**
	ESTIMATE TOTAL			**$ 2,978.32**

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kalvin LKK

8/8/18 1035h

2 hrs

P/P

After Repair pls

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Mei Kwan (LKKAuto)

From:	Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent:	Wednesday, 15 August, 2018 9:34 AM
To:	Mei Kwan (LKKAuto)
Subject:	RE: Direct Settlement - Accident Involving SLM4484A (OI : CTI - SNM18D03850C02) and SHC8489K (TP : LKK REF - CC3/CTI18014511/K1fa3) on 06/08/2018
Attachments:	leeSZ_SNM18D03850C01-SLM4484A-LKKDirectSettlementAccidentLtr_CLCR95.251.pdf; MCHM18101836-SLM4484A.pdf
Follow Up Flag:	Follow up
Flag Status:	Flagged
Categories:	HMK

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Chong Boon Sen

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :
This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, 15 August, 2018 7:50 AM
To: Claims Dept of CTI
Cc: Chong Boon Sen; Lucas Lee; Poh Kin (LKKAuto); Hsiao Tong (LKKAuto); Admin A
Subject: Direct Settlement - Accident Involving SLM4484A (OI : CTI - TBA) and SHC8489K (TP : LKK REF - CC3/CTI18014511/K1fa3) on 06/08/2018

中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.chinataiping.com
Co. Reg. No. 200208384E

Our Reference: ***SNM18D03850/C01/4***

Date : ***15 AUGUST 2018***

via Ordinary & Registered Mail

TAN JIA WEI GERRY
BLK 317 ANG MO KIO STREET 31
#02-203
SINGAPORE 560317

Dear Sir / Madam

ACCIDENT INVOLVING SLM4484A AND SHC8489K ON 06 AUGUST 2018 ALONG PIE

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHC8489K** , is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd,** to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd
Attn : POH KIN
Ref : CC3/CTI18014511/K1FA3
Contact No : 68412132
via Email : POHKIN@LKKAUTO.COM

CC : Agent - (AN0444A) - META AGENCY PTE LTD

F01/LKKDS-2013

Poh Kin (LKKAuto)

From:	Poh Kin (LKKAuto)
Sent:	Monday, 24 December 2018 1:42 PM
To:	'William Tan Thoo Seng'; 'Catherine Koh Mui Gek'
Cc:	Admin A
Subject:	Our Ref: CC3/CTI18014511/K1fa3; Your Ref: T0818/ SHA8489K/WT(st)
Attachments:	OI video footage.mp4
Importance:	High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC3/CTI18014511/K1fa3
Your Ref: T0818/ SHA8489K/WT(st)

Dear Sir/Madam,

ROAD TRAFFIC INVOLVING VEHICLE NOS. SLM 4484A AND SHC 8489K ON 06/08/2018

We refer to the above matter.

We have reviewed the circumstances of the incident and we are of the opinion that your driver is more liable by changing lane. This is evidenced of video footage from our Insured.

In view of this, we regret to inform you that we are unable to look into your claim.

Should you have further evidence to prove otherwise, please send us a copy for our review.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Poh Kin, Chong (Mr) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd *Save the Earth· Print only when necessary·*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Poh Kin (LKKAuto)

From:	Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent:	Monday, 24 December 2018 12:09 PM
To:	Poh Kin (LKKAuto); Admin A
Cc:	Chong Boon Sen; Alfred Toh; Chee So Chow; Hsiao Tong (LKKAuto); KKLau
Subject:	Direct Settlement - Accident Involving SLM4484A (OI: SNM18D03850C01/4) and SHC8489K (TP : LKK REF - CC3/CTI18014511/K1fa3) on 06/08/2018
Attachments:	OI video footage.mp4; MCHM18101836-SLM4484A.pdf
Importance:	High

LKK REF - CC3/CTI18014511/K1fa3
CTI REF – SNM18D03850C02/4 (SLM4484A)

Dear Poh Kin

We refer to your email of 18 December 2018 pertaining to the above matter.

Please proceed to reject the third party property damage claim based on the video footage.

Meanwhile, **please assist to check with mutual client (Tan Jia Wei Gerry)'s on the status of his claim against SHC8489K.**

Aside to Boon Sen, please assist to keep track on the matter.

Best Regards

Alfred Toh
Senior Executive
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: +65 6389 6183
FAX: +65 6224 7478/6224 7175
Email: claimsdept@sg.cntaiping.com
alfred.toh@sg.cntaiping.com
www.sg.cntaiping.com

80 ANNIVERSARY
In Singapore since 1938

Disclaimer :
This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Poh Kin (LKKAuto)

From:	Poh Kin (LKKAuto)
Sent:	Tuesday, 18 December 2018 10:26 AM
To:	claimsdept@sg.cntaiping.com
Cc:	Chong Boon Sen; alfred.toh@sg.cntaiping.com; Admin A
Subject:	RE: Direct Settlement - Accident Involving SLM4484A (OI : CTI - SNM18D03850C01) and SHC8489K (TP : LKK REF - CC3/CTI18014511/K1fa3) on 06/08/2018
Attachments:	OI video footage.mp4
Importance:	High

WITHOUT PREJUDICE

Our Ref: CC3/CTI18014511/K1fa3
Your Ref: SNM18D03850C01

Dear Sir/Madam,

ROAD TRAFFIC ACCIDENT INVOLVING SLM 4484A (OI) & SHC 8489K (TP) ALONG SLM 4484A ON 06/08/2018

We refer to the above matter.

Third party reported that he was ahead into the lane when both vehicle filtered into the same lane and causing collision.

OI reported that he driven along 2nd lane from left of PIE. When TP vehicle encroached into OI lane from right and collided to his vehicle right rear portion.

Based on OI's video footage, OI driven along 2nd lane from left of PIE when TP Changing lane and collided into OI vehicle right rear portion. **BOLA 15** should applied against TP vehicle. Vehicles should keep in the proper lane and change lane only when it is safe.

In view of this, we are intending to reject third party claim.

For your approval/comments/instruction.

Best Regards,
Poh Kin, Chong (Mr) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK *Save the Earth· Print only when necessary·*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Poh Kin (LKKAuto)

From:	Gerry Tan <gerrytanjw@gmail.com>
Sent:	Friday, 17 August 2018 1:44 PM
To:	Poh Kin (LKKAuto)
Cc:	e-claims@sg.cntaiping.com; michelle.chin@bemeta.com.sg
Subject:	Third Party Claim - CC3/CTI18014511/K1FA3
Attachments:	SNM18D03850-C01-4.pdf; 06-Aug-18-SLM4484 Accident Report.pdf
Categories:	clear

China Taiping Reference: SNM18D03850/C01/4

LKK Auto Reference: CC3/CTI18014511/K1FA3

To: LKK Auto Consultants Pte Ltd

Dear Person-In-Charge,

With reference to the attached letter with reference number stated above this email, I am both the owner and insurance policy holder of the Vehicle SLM4484A stated in the letter.

As advised in the letter, I am writing in to provide detailed information of this accident which the third party vehicle SHC8489K is claiming against.

I wish to inform both China Taiping and LKK Auto to disregard this third party claim as the fault 100% lies with SHC8489K. As the policy holder, **I refuse to accept SHC8489K third party claim against my policy. And I am claiming my own damage to SHC8489K as well. - had submitted to my workshop and lawyer.**

The summary of the accident are as follows:

- I, SLM4484A was travelling straight on my own lane
- SHC8489K suddenly cut into my lane without checking blind spot.
- SHC8489K cuts in when my vehicle SLM4484A is already infront of him.
- SHC8489K hit the right side rear of my SLM4484A vehicle.
- Upon exiting vehicle to check on damages, SHC8489K say he assume I, SLM4484A will give way for him.
- But I, SLM4484A cannot do that because at the rear of my vehicle, there is another vehicle traveling at my back. I cannot do sudden brake and jeopardize the back vehicle.

Refer to attached report submitted.

Also please **download the video** for the back and front video camera **from my vehicle (SLM4484A) from this link:** (https://www.dropbox.com/s/0yfbsfubiqi6iuk/SLM4484A%20-%2006-08-19%20Accident%20Video.zip?dl=0)

The camera clearly **show SHC8489K suddenly cuts in and there is vehicle behind me,SLM4484A.**

Please assist to look into this matter and reject their claim.

Kindly feel free to contact me at 94246577 for more details.

Poh Kin (LKKAuto)

From:	Gerry Tan <gerrytanjw@gmail.com>
Sent:	Friday, 17 August 2018 2:42 PM
To:	Poh Kin (LKKAuto)
Cc:	e-claims@sg.cntaiping.com; michelle.chin@bemeta.com.sg
Subject:	Re: Third Party Claim - CC3/CTI18014511/K1FA3
Categories:	clear

Dear Poh Kin,

Thanks for the call 30mins + ago.

Noted on you confirmation that SHC8489K third party claim against my policy will be rejected.

Thanks.

Regards,
Gerry Tan

On Fri, Aug 17, 2018 at 1:44 PM, Gerry Tan <gerrytanjw@gmail.com> wrote:

China Taiping Reference: SNM18D03850/C01/4

LKK Auto Reference: CC3/CTI18014511/K1FA3

To: LKK Auto Consultants Pte Ltd

Dear Person-In-Charge,

With reference to the attached letter with reference number stated above this email, I am both the owner and insurance policy holder of the Vehicle SLM4484A stated in the letter.

As advised in the letter, I am writing in to provide detailed information of this accident which the third party vehicle SHC8489K is claiming against.

I wish to inform both China Taiping and LKK Auto to disregard this third party claim as the fault 100% lies with SHC8489K. As the policy holder, I **refuse to accept SHC8489K third party claim against my policy. And I am claiming my own damage to SHC8489K as well. - had submitted to my workshop and lawyer.**

The summary of the accident are as follows:

- I, SLM4484A was travelling straight on my own lane
- SHC8489K suddenly cut into my lane without checking blind spot.
- SHC8489K cuts in when my vehicle SLM4484A is already infront of him.
- SHC8489K hit the right side rear of my SLM4484A vehicle.
- Upon exiting vehicle to check on damages, SHC8489K say he assume I, SLM4484A will give way for him.

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainline +65 6383 6280
Facsimile +65 6280 9755
www.cdge.com.sg

Workshops
Braddell
205 Braddell Road
Singapore 579701
Loyang
59 Loyang Drive
Singapore 508969
Sin Ming
383 Sin Ming Drive
Singapore 575717
Pandan
45 Pandan Road
Singapore 609286
Ubi
320 Ubi Road 3
Singapore 408649
Senoko
24 Senoko Loop
Singapore 758156
Sungei Kadut
7 Sungei Kadut Way
Singapore 728791
Yishun
Yishun Industrial Park A
Singapore 768732

Our Ref : T 0818 / SHC8489K /WT(st)
Your Ref :
Date : 24-Aug-18

CDGE Taxi Claims Dept
59 Loyang Drive 4th Flr
Singapore 508969

CHINA INSURANCE CO LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Attn : Motor Claims Department **WITHOUT PREJUDICE**

Dear Sir

ACCIDENT INVOLVING OUR TAXI SHC8489K YOUR INSURED SLM4484A AND OTHER ON 06.08.18

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : **SHC8489K** which was involved in the captioned accident with your insured vehicle.The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving **SLM4484A** we are submitting these claims for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	$	749.00
2	4 days Loss of Rental @ $ 115.00 per day	$	460.00
3	Survey Report Fees **(Surveyed by M/s LKK)**	$	-
4	LTA Search Fees	$	7.49
5	GIA / Police Report Fees	$	-
6	Towing / Medical / Transporation Fees	$	-
	Sub Total :	$	1,216.49

HIRER'S CLAIM

7	4 days Loss of Income @ $ 80.00 per days	$	320.00
	Total Claims :	$	1,536.49

We enclose herewith the following documents to support the claims: -

a) Original repair bill and photocopies of photographs : 9 pcs.
b) LTA search slip/s of : SLM4484A
c) GIA / Police report/s of : SHC8489K
d) Letter of authority from owner / hirer / operator
( ) Traffic Compound ( ) Towing/Medical bill/receipts ( ) Certificate of Insurance
(X) Photograph/s of Accident Scen (x) Downtime/Mileage record (x) Rental Rate letter

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully
William Tan
Deputy Manager
CDGE Claims Department
Tel: 6214 8737 Fax: 6214 1843 Email : williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

A member of
COMFORTDELGRO

LETTER OF AUTHORISATION
(NAF / PAF)

ACCIDENT INVOLVING	**i 40 SHC8489K , SLM4484A**		**ON 06-Aug-18 22:15**
ALONG	**PIE(TUAS) BF CTE(CITY) EXIT**		
I / We	**ROSMAN BIN MUDA**	(Hirer) NRIC No.:	**S1423503E**
and/or	**LIM BEE WAH**	(Relief) NRIC No.:	**S2080253G**
Taxi Number	**SHC8489K**		

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.

2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).

3. To sign Discharge Voucher on my/our behalf.

4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd".**

Date	**07-Aug-2018**		
Name of Hirer	**ROSMAN BIN MUDA**		
Hirer NRIC	**S1423503E**	Signature :	
Address	**143 BEDOK RESERVOIR ROAD #01-...** **470143**		
Contact No.	**97941554**		
Name of Relief	**LIM BEE WAH**		
Relief NRIC	**S2080253G**	Signature :	
Address	**613B BEDOK RESERVOIR ROAD 13-1382** **472613**		
Contact No.	**97512765**		

Our Ref: CT18080191

Date: 23 August 2018

TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON	06/08/2018 @ 22:15 hrs
ALONG	PIE(TUAS) BF CTE(CITY) EXIT
INVOLVING	SLM4484A

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHC8489K** (the "Taxi"). The Taxi was hired to **ROSMAN BIN MUDA IC NO S1423503E** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **$115.00** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

383 Sin Ming Drive Singapore 575717 Mainline +65 6555 1188 Facsimile +65 6453 3183

SHC8489K

DATE	NAME OF DRIVER	MILEAGE READING	MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME) FROM	TO
3.8.18	RS	347355	179	0618	1700
03.08.18	Abu Hassan	347646	291	1745	0520
04.08.18	RS	347760	113	0700	1701
04.08.18	Abu Hassan	348055	295	1757	0515
05.08.18	RS	348207	145	0655	1620
05.08.18	Abu Hassan	348427	220	2151	0500
06.08.18	RS	348637	209	0615	1665
06-08-18	Lim	348941	304	17.0	0230
07/8/18	Accident ?	[illegible]	Loyang	1300	—
10/8/18	Repair	[illegible]		—	1600

DATE	NAME OF DR

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainline + 65 6383 8280 Facsimile + 65 6280 9755
Workshops
59 Loyang Drive Singapore 508965
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Ubi Road 3 Singapore 408649
24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728781
501 Yishun Industrial Park A Singapore 76873

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD
SPRINGLEAF TOWER

3 ANSON ROAD #16-00
SINGAPORE SG 079909

CONTACT NO: 62222366

VEHICLE NO SHC8489K	INV. NO/DATE 91391442 23.08.2018
MAKE HYUNDAI	JOB NO. 305197315
MODEL I-40	ODOMETER READING
DATE OF REG 03.12.2015	DATE/TIME IN 07.08.2018 13:00
CHASSIS CODE KMHL841DMGU080694	

Description : 3P 06.08.2018

S/No	Part No.		Qty	Unit Price	%Disc	Net
PART REQUISITION						
		SUB-TOTAL :				0.00
JOB NATURE						
0001	20-05	RENEW ADVERTISMENT STICKER-		100.00		100.00
0002	L	PANEL BEATING		200.00		200.00
0003	23-502	SPRAYPAINT ON AFFECTED AREA		400.00		400.00
		SUB-TOTAL :				700.00

1 WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED AT OWNERS' RISK.
2 CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
3 INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.
4 PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010012	91391442	749.00	

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainline + 65 6303 6280 Facsimile + 65 6280 9755
Workshops
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609288
320 Ubi Road 3 Singapore 408849
24 Benoni Loop Singapore 758136
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 768775

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD
SPRINGLEAF TOWER

3 ANSON ROAD #16-00
SINGAPORE SG 079909

CONTACT NO: 62222366

VEHCLE NO SHC8489K	INV. NO/DATE 91391442 23.08.2018
MAKE HYUNDAI	JOB NO. 305197315
MODEL I-40	ODOMETER READING
DATE OF REG 03.12.2015	DATE/TIME IN 07.08.2018 13:00
CHASSIS CODE KMHL841UMGU080694	

Items total		700.00
Add GST @	7.000 %	49.00
Invoice amount		749.00

Issued by : KATHERINETAN 23.08.2018 16:56:55
Repair type : CLSO/57/57
Payment Type/Term: /Credit 30 days

1 WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARE OF OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND RISKED A OWNERS' RISK.
2 CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
3 INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OR PAYMENT I.E. AFTER 30 DAYS FROM THE INVOICE DATE IN PERIOD OF DEFAULT.
4 PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL PRESUME THE INVOICE A CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010012	91391442	749.00	

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SLM4484A	06 Aug 2018 / 22:15:00	Successful	C01	CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Previous OK

SH C8489K

Poh Kin (LKKAuto)

From:	Poh Kin (LKKAuto)
Sent:	Monday, 24 December 2018 1:42 PM
To:	'William Tan Thoo Seng'; 'Catherine Koh Mui Gek'
Cc:	Admin A
Subject:	Our Ref: CC3/CTI18014511/K1fa3; Your Ref: T0818/ SHA8489K/WT(st)
Attachments:	OI video footage.mp4
Importance:	High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC3/CTI18014511/K1fa3
Your Ref: T0818/ SHA8489K/WT(st)

Dear Sir/Madam,

ROAD TRAFFIC INVOLVING VEHICLE NOS. SLM 4484A AND SHC 8489K ON 06/08/2018

We refer to the above matter.

We have reviewed the circumstances of the incident and we are of the opinion that your driver is more liable by changing lane. This is evidenced of video footage from our Insured.

In view of this, we regret to inform you that we are unable to look into your claim.

Should you have further evidence to prove otherwise, please send us a copy for our review.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK *Save the Earth· Print only when necessary·*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Poh Kin (LKKAuto)

From:	Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent:	Monday, 24 December 2018 12:09 PM
To:	Poh Kin (LKKAuto); Admin A
Cc:	Chong Boon Sen; Alfred Toh; Chee So Chow; Hsiao Tong (LKKAuto); KKLau
Subject:	Direct Settlement - Accident Involving SLM4484A (OI: SNM18D03850C01/4) and SHC8489K (TP : LKK REF - CC3/CTI18014511/K1fa3) on 06/08/2018
Attachments:	OI video footage.mp4; MCHM18101836-SLM4484A.pdf
Importance:	High

LKK REF - CC3/CTI18014511/K1fa3
CTI REF – SNM18D03850C02/4 (SLM4484A)

Dear Poh Kin

We refer to your email of 18 December 2018 pertaining to the above matter.

Please proceed to reject the third party property damage claim based on the video footage.

Meanwhile, **please assist to check with mutual client (Tan Jia Wei Gerry)'s on the status of his claim against SHC8489K.**

Aside to Boon Sen, please assist to keep track on the matter.

Best Regards

Alfred Toh
Senior Executive
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: +65 6389 6183
FAX: +65 6224 7478/6224 7175
Email: claimsdept@sg.cntaiping.com
alfred.toh@sg.cntaiping.com
www.sg.cntaiping.com

80 ANNIVERSARY
In Singapore since 1938

Disclaimer :
This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Poh Kin (LKKAuto)

From:	Poh Kin (LKKAuto)
Sent:	Tuesday, 18 December 2018 10:26 AM
To:	claimsdept@sg.cntaiping.com
Cc:	Chong Boon Sen; alfred.toh@sg.cntaiping.com; Admin A
Subject:	RE: Direct Settlement - Accident Involving SLM4484A (OI : CTI - SNM18D03850C01) and SHC8489K (TP : LKK REF - CC3/CTI18014511/K1fa3) on 06/08/2018
Attachments:	OI video footage.mp4
Importance:	High

WITHOUT PREJUDICE

Our Ref: CC3/CTI18014511/K1fa3
Your Ref: SNM18D03850C01

Dear Sir/Madam,

ROAD TRAFFIC ACCIDENT INVOLVING SLM 4484A (OI) & SHC 8489K (TP) ALONG SLM 4484A ON 06/08/2018

We refer to the above matter.

Third party reported that he was ahead into the lane when both vehicle filtered into the same lane and causing collision.

OI reported that he driven along 2nd lane from left of PIE. When TP vehicle encroached into OI lane from right and collided to his vehicle right rear portion.

Based on OI's video footage, OI driven along 2nd lane from left of PIE when TP Changing lane and collided into OI vehicle right rear portion. **BOLA 15** should applied against TP vehicle. Vehicles should keep in the proper lane and change lane only when it is safe.

In view of this, we are intending to reject third party claim.

For your approval/comments/instruction.

Best Regards,
Poh Kin, Chong (Mr) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth· Print only when necessary·

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Ref : CC3/CTI18014511/K1fa3q2

Date : 27-12-2018

Code : CTI

1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SLM 4484A	**Veh. Inspected**	SHC 8489K
	Policy No.	DMPCSN3020191800	**Coverage ($)**	0.00
	Claim No.	SNM18D03850/C01/4	**Excess ($)**	0.00
	Assign From		**Assign Date**	08/08/2018

2.	Vehicle Particulars & Condition			
	Make & Model	HYUNDAI I40	**c.c**	1685
	Engine No.	HIDDEN	**Year of Reg.**	2015
	Chassis No.	KMHLB41UMGU080694	**Colour**	BLUE
	Odometer	349133	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	STANDARD ALLOY RIM
	General	FAIR		

3.	Conditions of Tyres			
		Size	**Make**	**Balance**
	R/H Front Tyre	205/60 R16	HANKOOK	7 mm
	L/H Front Tyre	205/60 R16	HANKOOK	7 mm
	R/H Rear Tyre	205/60 R16	HANKOOK	7 mm
	L/H Rear Tyre	205/60 R16	HANKOOK	7 mm

4.	Description of Damages
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5.	General Information			
	Accident Date	06/08/2018	**Inspection Date**	08/08/2018
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a.	Remarks
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b.	Estimate Days of Repair	
	ESTIMATED NORMAL PERIOD FOR REPAIR:	**2 Working Days**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8489K

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER COVER	TO REPAIR SEE LABOUR	1,052.20	-
1	FRONT BUMPER BRACKET TOP (LH)	SERVICEABLE	22.40	-
1	FRONT BUMPER BRACKET (LH)	SERVICEABLE	24.60	-
1	FRONT FENDER (LH)	TO REPAIR SEE LABOUR	619.00	-
1	FRONT FENDER SHIELD (LH)	SERVICEABLE	169.80	-
1	FRONT FENDER RETAINER	SERVICEABLE	9.20	-
1	FRT WHEEL HUB CAP ,LH	SERVICEABLE	150.70	-
	LESS 20% DISCOUNT		-409.58	-
			1,638.32	-
	SPECIAL NETT ITEMS			
1	FRONT FENDER ADVERTISEMENT LOGO (LH) (SN)	NECESSARY	100.00	100.00
			100.00	100.00
	LABOUR			
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF FRONT BUMPER COVER AND FRONT FENDER (LH).		560.00	200.00
	SPRAY PAINTING CHARGE.		500.00	400.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.	NOT NECESSARY	50.00	-
	FRT WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
			1,240.00	600.00
	GRAND TOTAL		**2,978.32**	**700.00**

RECOMMENDED COST OF REPAIRS			**700.00**

Report Ref No. CC3/CTI18014511/K1fa3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.