23/08/2018

ASS. REC. BY: | REF: CS/MSI/18015253/Urbez | Special Instruction:

Surveyor: Marius.

**ASSIGNMENT (Office)**

From (Person): Pang Xiu Shi of MSIG Date/Time: 23082018 10526am

Estimated Cost: Bill to:

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**

To Inspect Vehicle No: SJN 9071C Insured: SLR 9066P

at Workshop m/s Jm Auto Tel: 6289 8126

of Blk 114 Defu Lane 10 #01-412

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 16082018
(Client's Record)

**CA / REV / REP. / REV 24 HRS 'wp'** H.O.D. Endorsement:

Date/Time: 23082018 11am Person Contacted: Jouis Vehicle IN / OUT

| Date/Time | Action/Instruction ( ✓ ) Estimate |
|---|---|
| | SJN 9071C - CS3/AXA12012245/Krzy DOA: 12062017 |
| | SLR 9066P - x |
| | |
| 29/8/18 | Revert thru merimen. |
| | |
| | Submit total loss report |

(08/11/13) wef

ASS. REC. BY: Marcus

REF: MSIM

# ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJN 9077C

at Workshop m/s Y.n Aut.

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| N/S | O/S |
|---|---|
| | |

Bal. or Market Value: 18500

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / BR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJN 9077C Yr Regn: 4/3/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or Car

Make: Honda civic c.c 1799

Colour Blue A/C: Insured / Std / NI / NA

Sp.Reading 179462 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMFD16309S201754

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/55-R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Habilead

| Front | | Rear | |
|---|---|---|---|
| R/Bal. | 8 mm | R/Bal. | 8 mm |
| L/Bal. | 8 mm | L/Bal. | 8 mm |
| D.O.A. | 16/8/18 | D.O.I. | 23/8/18 |

Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|---|---|
| | TOTAL LOSS 6mth plus. |
| | LTA 14274 NVF 4226 |
| | please send email to Y.n Aut. MV $18500 LTA as of 24-8-18 $14274 NVF 4226 and summary TOTAL LOSS. |
| | MV: $18,500.00, LTA: $14,274.00, NV: $4226.00 |

RECEIVED 03 SEP 2018

Date/Time, File Pass to?

1) typed

Date/Time, File Return to?

2)

☐ : Preli. Report

☑ : Final Report

Days Of Repair: -

Resurvey No. of Trip: -

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Report Format : -

Lump Sum / I.B.I: ($ - )

| | |
|---|---|
| Survey Fee: | 150 |
| Transportation: | |
| S + RS S | |
| Photos | 10 |
| Others | |
| TOTAL | 160 |

# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

MSIG INSURANCE (SINGAPORE) PTE LTD

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Ref : CS/MSG18015293/Urb

Date : 23-08-2018

Code : MSG

| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | |
|---|---|---|---|---|
| | Insured Veh. | SLR 9066P | Veh. Inspected | SJN 9077C |
| | Policy No. | | Coverage ($) | 0.00 |
| | Claim No. | | Excess ($) | 0.00 |
| | Assign From | PANG XIU SHI | Assign Date | 23/08/2018 |

| 2. | Vehicle Particulars & Condition | | | |
|---|---|---|---|---|
| | Make & Model | | c.c | 0 |
| | Engine No. | HIDDEN | Year of Reg. | |
| | Chassis No. | | Colour | |
| | Odometer | - | Steering | |
| | Brakes | | Modification | |
| | General | | | |

| 3. | Conditions of Tyres | | | |
|---|---|---|---|---|
| | | Size | Make | Balance |
| | R/H Front Tyre | | | mm |
| | L/H Front Tyre | | | mm |
| | R/H Rear Tyre | | | mm |
| | L/H Rear Tyre | | | mm |

| 4. | Description of Damages |
|---|---|
| | |

| 5. | General Information | | | |
|---|---|---|---|---|
| | Accident Date | 16/08/2018 | Inspection Date | 23/08/2018 |
| | Survey held at | JIN AUTO SERVICES PTE LTD<br>BLK 14 DEFU LANE 10<br>#01-412<br>SINGAPORE 539195 | | |

| 5a. | Remarks |
|---|---|
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |

## Catherine Chong (LKK Auto)

**From:** Pang Xiu Shi <xiushi_pang@sg.msig-asia.com>
**Sent:** Thursday, 23 August, 2018 10:52 AM
**To:** jouis
**Cc:** 'Catherine Chong (LKK Auto)'; Elaine Ngu
**Subject:** RE: Third Party claim survey ( Accident Involving VehicleSJN9077C and SLR9066P MSIG insured on 16/8/2018

Dear Sirs,

Thank you for your email.

We have both agreed on a common surveyor **LKK Auto Consultants Pte Ltd** to be the SJE (Single Joint Expert).

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Thank you.

*Have a great week ahead!*

**Pang Xiu Shi**
Admin Officer, Claims Services (Motor)
Direct line +65 6594 2586 | Direct fax +65 6225 7402 | xiushi_pang@sg.msig-asia.com

Insurer Claims Team of the Year 2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

A Member of MS&AD INSURANCE GROUP

---

**From:** jouis [mailto:jouis@jinauto.com.sg]
**Sent:** Thursday, 23 August, 2018 10:26 AM
**To:** Pang Xiu Shi <xiushi_pang@sg.msig-asia.com>
**Cc:** 'Catherine Chong (LKK Auto)' <admin-d@lkkauto.com>
**Subject:** RE: Third Party claim survey ( Accident Involving VehicleSJN9077C and SLR9066P MSIG insured on 16/8/2018

Without Prejudice

Dear Xiu Shi

Please appoint LKK Auto Consultants Pte Ltd

Thank you & Best Regards,

Jouis Seow
Jin Auto Services Pte Ltd
Blk 14 #01-412 Defu Lane 10
Singapore 539195.

Tel : (65) 62898126
Fax : (65) 62870590
Email : jouis@jinauto.com.sg

---

**From:** Pang Xiu Shi [mailto:xiushi_pang@sg.msig-asia.com]
**Sent:** Thursday, 23 August 2018 10:07 AM
**To:** jouis@jinauto.com.sg
**Cc:** Elaine Ngu <elaine_ngu@sg.msig-asia.com>
**Subject:** RE: Third Party claim survey ( Accident Involving VehicleSJN9077C and SLR9066P MSIG insured on 16/8/2018

Dear Sirs

We refer to your email dated 21/8/2018

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

1) LKK Auto Consultants Pte Ltd

2) Formteam Consultancy Pte Ltd

3) Automobile Inspection Services Pte Ltd

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

| | | |
|---|---|---|
| 1. | Kalvin Ang | 6. Frankie Pang |
| 2. | Kenneth Kong | 7. Ng You Han |
| 3. | Marcus Chua | 8. Gary Soon |
| 4. | Henry Ng | 9. Chow Bo Xiong |
| 5. | Lau Kwok Kwong | 10. Axel Lee |

NB; If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

Thank you.

*Have a great week ahead!*

**Pang Xiu Shi**
Admin Officer, Claims Services (Motor)
Direct line +65 6594 2586 | Direct fax +65 6225 7402 | xiushi_pang@sg.msig-asia.com

Insurer Claims
Team of the Year
2016

**MSIG Insurance (Singapore) Pte Ltd** 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

A Member of MS&AD INSURANCE GROUP

**From:** jouis [mailto: jouis@jinauto.com.sg ]
**Sent:** 21 August 2018 12:13
**To:** Claims <claims@sg.msig-asia.com>
**Cc:** cassandra@jinauto.com.sg
**Subject:** Third Party claim survey ( Accident Involving VehicleSJN9077C and SLR9066P MSIG insured on 16/8/2018

Without Prejudice

Dear Sir/Madam

Accident Involving VehicleSJN9077C and SLR9066P on 16/8/2018

We are assisting owner of SJN9077C handling her third party claim

recovery against SLR9066P. Please arrange third party survey at our workshop.

Kindly establish liability for this case.

Thank you & Best Regards,

Jouis Seow
Jin Auto Services Pte Ltd
Blk 14 #01-412 Defu Lane 10
Singapore 539195.

Tel : (65) 62898126
Fax : (65) 62870590
Email : jouis@jinauto.com.sg

---

CONFIDENTIALITY NOTICE
This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 29 Aug 2018

# Preliminary Advice

| | | | |
|---|---|---|---|
| Insured Vehicle No | : SLR9066P | | |
| TP Vehicle No | : SJN9077C | Accident Date | : 16/08/2018 |
| Make | : HONDA CIVIC | Assignment Date | : 27/08/2018 |
| Date of Inspection | : 23/08/2018 | Est. Duration of Repair | : 0.00 |
| Inspection At | : JIN AUTO SERVICES PTE LTD (DEFU)<br>BLK 14 DEFU LANE 10, #01-410/412<br>SINGAPORE 539195 | | |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident. The undercarriage and chassis frame affected due to collision.

| | | |
|---|---|---|
| Repairer's Estimate (Gross) | :S$ | Total loss |
| Revised Amount | :S$ | |
| Check Items (Estimated) | :S$ | |
| Total | :S$ | |
| Lump Sum Repair | :S$ | |

**Total Loss Consideration**

| | | |
|---|---|---|
| New for Old Value | :S$ | |
| Pre-Accident Value | :S$ | 18,500.00 |
| COE / PARF Rebate | :S$ | 14,274.00 |
| Salvage Value | :S$ | |
| Margin for Repair | :S$ | 4,226.00 |

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

# SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| ACCIDENT STATEMENT | |
|---|---|
| Date Of Report | 18/08/2018 10:37 |
| Date Of Accident | 16/08/2018 08:55 |
| Exact Location Of Accident | BKE TOWARDS PIE |
| Country/State of Loss | SINGAPORE |
| **DETAILS OF OWN VEHICLE** | |
| Vehicle Registration Number | SJN9077C |
| **Insured/Policyholder** | |
| Name Of Registered Owner | DZULQARNAIN BIN MOHAMAD NASIR |
| NRIC No | S1542540G |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-97312519 |
| Alternative Phone No | OTHERS-97312519 |
| **Vehicle Particulars** | |
| Manufacturer | HONDA |
| Model | CIVIC 1.8L 5AT |
| Exact Purpose for which vehicle was being used at time of accident | PTE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |
| **Insurance Company** | |
| Name of Insurance Company | CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | DMPCSN3024361801 |
| Cover Note Number | |
| **Driver** | |
| Name of Driver | NURUL ATIQAH BINTE DZULQARNAIN |
| NRIC No | S9241668B |
| Date Of Birth | 11/11/1992 |
| Occupation | INDOOR |
| Date Of Driving Pass | 12/06/2012 |
| Driving Experience | 6 YEARS AND 2 MONTHS |
| Gender | FEMALE |
| Mobile Number | (LOCAL) +65-97314813 |
| Fax Number | |
| Contact Number | |
| EMail Address | ATIQAH92@HOTMAIL.SG |

| | |
|---|---|
| Address | BLOCK 150 PASIR RIS STREET 13 #04-60 |
| Postcode | 510150 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | CHILDREN |
| Vehicle Registration Number of Driver's Own Vehicle | -<br>-<br>- |
| Insurance Company of Driver's Own Vehicle | -<br>-<br>- |

**General Information of the Accident**

| | |
|---|---|
| Type Of Accident | CHAIN COLLISION |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

**Other Information**

| | |
|---|---|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | 2 |
| Was any body injured in the Accident? | YES |
| Was any injured conveyed to hospital by ambulance? | YES |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

**Details of Police Action**

| | |
|---|---|
| Was the accident reported to the police? | YES |
| If Yes,Please state which Police Station | |
| POLICE STATION NAME [OTHER] | NANYANG N.P.C |
| Was notice of intended Prosecution given? | NO |
| If Yes,against whom? | |

**Circumstances of Accident**

On the 16/08/2018 at around 0855hrs, I was driving my car bearing registration no. SJN9077C and was travelling on the lane of BKE towards the direction of PIE before Mandai Rd Exit. Out of sudden, one Silver Cab who was traveling in front of me had came to a halt. I applied my emergency break and managed to stop in time however one white colour car bearing registration no. SLR9066P who was traveling behind me had collided onto the rear of my car. Due to the collision, my car's rear bumper is seriously damaged. I had injured my back and neck and I was conveyed to Ng Teng Fong Hospital by the Ambulance. The traffic police attended to us with reference to incident no. J/20180816/0081 under 10 Khairil. I was given 2 days of medical leave with reference to MC No. 44574196.That's all.

**Attachment(s)**

| | |
|---|---|
| Are accident photos available for attachment? | NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

**DETAILS OF OTHER VEHICLE PROPERTY 1**

| | |
|---|---|
| Vehicle Registration Number | SLR9066P |
| Vehicle Make/Model/Colour | AUDI A5 |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | THIA LIANG KEE |
| NRIC/Passport Number | S7939728H |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |

| | |
|---|---|
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

## DETAILS OF OTHER VEHICLE PROPERTY 2

| | |
|---|---|
| Vehicle Registration Number | SKS1291P |
| Vehicle Make/Model/Colour | MERCEDES E200 |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | XU QIUJIE |
| NRIC/Passport Number | S8323817H |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

## DETAILS OF INJURED PERSON 1

| | |
|---|---|
| Name | NURUL ATIQAH BINTE DZULQARNAIN |
| Approximate Age | |
| Injuries Sustain | |
| Injured person in which vehicle? | SJN9077C |
| Were seat belts worn? | |
| Was this injured conveyed to hospital by ambulance? | YES |
| Address | BLOCK 150 PASIR RIS STREET 13 #04-60 |
| Postcode | 510150 |

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

   I understand, acknowledge, agree and consent that:

   (a) My insurer, my workshop and the General Insurance Association of Singapore (**"GIA"**) may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer [collectively the **"Personal Information"**] and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the **"Insurers"**), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

   (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

   (ii) investigating the accident and/or my claims;

   (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

   (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

   (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the **"Purposes"**)

   (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

   (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

   (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

   (e) the information so collected under (d) above may be shared / disclosed:

   (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

   (ii) for complying with requirements under any regulations, laws or court orders

| Policyholder's Signature<br>Date & Time: | Driver's Signature<br>(If driver is not the policyholder)<br>Date & Time: 18/8/2018 | Reporting Centre Personnel's Signature<br>Name: Cassandra<br>NRIC/FIN No.: |
|---|---|---|

## Accident Sketch Plan

**SKETCH PLAN**

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

Please refer to Police Report No. T/20180816/2080.

Insured vehicle still in compound of Traffic Police, photos attached are scene photos provided by driver.

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

| Policyholder's Signature<br>Date & Time: | Driver's Signature<br>(If driver is not the policyholder)<br>Date & Time: 18/8/2018 | Reporting Centre Personnel's Signature<br>Name: Cassandra<br>NRIC/FIN No.: |
|---|---|---|

SINGAPORE POLICE FORCE

T/20180816/2080



Report No. T/20180816/2080

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

**REPORT OF A TRAFFIC ACCIDENT**

| Date/Time Report Made: | Vide Report No.: | Station Diary No.: |
|---|---|---|
| 16/08/2018 14:25 | J/20180816/0081 | 117 |

**Informant's Particulars**

| | | | | |
|---|---|---|---|---|
| Name of Informant: NURUL ATIQAH BINTE DZULQARNAIN | | | Address: APT BLK 150 PASIR RIS STREET 13 #04-60 SINGAPORE 510150 | |
| ID Type / ID No.: NRIC NO / S9241668B | | | Contact No.: Home/Office: | Mobile: 97314613 |
| Nationality: SINGAPORE CITIZEN | | | Email: | |
| Sex: Female | Age: 25 | Date of Birth: 11/11/1992 | Type of Informant: Driver | |
| Race: Malay | | | Language: English | Institution / School Name: |
| Occupation: ENGINEER | | | Driving Licence Information: Class: 3 | Date of Expiry: |

**General Information of the Accident**

| Type of Accident: | Injury Conveyed By Ambulance | Drink Drive: No | Date/Time of Accident: 16/08/2018 08:55 | Type of Location: Straight Road |
|---|---|---|---|---|

Location:
Along Road 1
BUKIT TIMAH EXPRESSWAY

BKE towards PIE before Mandai Rd Exit

| | | |
|---|---|---|
| Weather: Clear | Road Surface: Dry | Road Speed Limit: |
| Traffic Flow: One Way | Traffic Control: Not Controlled | Traffic Volume: Moderate |
| Type of Collision: Between Moving Vehicles - Head To Rear | | Anyone conveyed by ambulance: No |

**Details of Vehicle Involved**

| Vehicle No. | Type | Make | Model | Color | Condition | No of Passenger |
|---|---|---|---|---|---|---|
| SJN9077C | Car | HONDA | Civic | Blue | Seriously Damaged | 0 |

**Details of Person Involved**

| | |
|---|---|
| Any Pedestrian Involved: No | |
| No. of Pedestrians Injured: NIL | Use of Pedestrian Crossing: NA |

SINGAPORE POLICE FORCE

T/20180816/2080



Report No. T/20180816/2080

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

CONTINUATION OF REPORT

| Driver | | | |
|---|---|---|---|
| Name | NURUL ATIQAH BINTE DZULQARNAIN | ID No. | S9241668B |
| Related Vehicle | SJN9077C (Car) | Contact No. | 97314613 |
| Hospital/Clinic | NG TENG FONG GENERAL HOSPITAL | Class of Driving Licence & Expiry Date | Class: 3<br>Date of Expiry: NIL |
| Date Treatment | 16/08/2018 | Date Discharge | 16/08/2018 |
| No. of Days granted Medical Leave | 02 | Degree of Injury | Slight |

**Brief Details.**

On the 16/08/2018 at around 0855hrs, I was driving my car bearing registration no. SJN9077C and was travelling on the 4th lane of BKE towards the direction of PIE before Mandai Rd Exit.
Out of sudden, one Silver Cab who was traveling in front of me had came to a halt. I applied my emergency break and managed to stop in time however one white colour car bearing registration no. SLR89066P who was traveling behind me had collided onto the rear of my car.
Due to the collision, my car's rear bumper is seriously damaged. I had injured my back and neck and I was conveyed to Ng Teng Fong Hospital by the Ambulance. The traffic police attended to us with reference to incident no. J/20180816/0081 under IO Khairil. I was given 2 days of medical leave with reference to MC No. 44574196.That's all.

SINGAPORE POLICE FORCE

T/20180816/2080



Report No. T/20180816/2080

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference

| | |
|---|---|
| Signature Of Officer Recording The Report:<br>J /<br>Staff Sgt MUHAMMAD HAFIZ BIN DARIS | Signature Of Informant: |
| Signature Of Interpreter:<br>Not applicable | Date/Time:<br>16/08/2018 14:25 |
| Officer In Charge Of Case:<br>TP / GIT /<br>SI NG CHWEE THENG<br>Contact No.: 65476397 | Classification Of Case: |

Authentication Stamp
NP165
Signature :
Singapore Police Force

> Back to OneMotoring

# Enquire PARF/COE Rebate for Registered Vehicle

| | |
|---|---|
| **Vehicle Owner Particulars** | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 2540G |
| **Vehicle Details** | |
| Vehicle No.: | SJN9077C |
| Vehicle to be Exported: | No |
| Intended De-registration Date: | 24 Aug 2018 |
| Vehicle Make: | HONDA |
| Vehicle Model: | HONDA CIVIC 1.8L 5AT |
| Primary Colour: | Blue |
| Manufacturing Year: | 2008 |
| Engine No.: | R18A14010750 |
| Chassis No.: | JHMFD16309S201754 |
| Maximum Power Output: | 103.0 kW (138 bhp) |
| Open Market Value: | $28,040.00 |
| Original Registration Date: | 04 Mar 2009 |
| First Registration Date: | 04 Mar 2009 |
| Transfer Count: | 2 |
| Actual ARF Paid: | $28,040.00 |
| **Intended PARF Rebate Details** | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 03 Mar 2019 |
| PARF Rebate Amount: | $14,020.00 |
| **Intended COE Rebate Details** | |
| COE Expiry Date: | 03 Mar 2019 |
| COE Category: | B - Car (1601cc & above) |
| COE Period(Years): | 10 |
| QP Paid: | $4,889.00 |
| COE Rebate Amount: | $254.00 |
| **Total Rebate Amount:** | **$14,274.00** |

The information contained herein is correct as at 23 Aug 2018

OK

SGCARMART.COM

Login Sign up

New Cars Used Cars Sell My Car Directory Products Insurance Articles Forum Resources

onefm 913

TOP 913 GREATEST HITS OF ALL TIME COUNTDOWN

WHAT'S YOUR NO.1 SONG OF ALL TIME? SUBMIT NOW

Honda Civic | Price Range | Depreciation | 2009 | Vehicle Type | Submit | Advanced Search

Home » Used Cars » Lake View Credit Pte Ltd » Honda Civic 1.8A VTi-S

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

# Honda Civic 1.8A VTi-S

Overview Financial Accessories Similar Research Photos Map PREMIUM AD

## Lake View Credit Pte Ltd

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

| | |
|---|---|
| **Price** | **$18,500** |
| **Depreciation** | $8,250 /yr<br>View models with similar depreciation |
| **Reg Date** | 24-Mar-2009<br>(7mths COE left) |
| **Manufactured** | 2009 |
| **Mileage** | 112,790 km (12k /yr) |
| **Transmission** | Auto |
| **Engine Cap** | 1,799 cc |
| **Road Tax** | $978 /yr |
| **Power** | 103.0 kW (138 bhp)<br>View specs of the Honda Civic (2006-2012) |
| **Curb Weight** | 1,219 kg |
| **Features** | 1.8L 16 Valves I-VTEC Engine, 138 BHP, 5 Speed Auto With Paddle Shifters, ABS, Airbags, Digital Climatic Aircon Controls, Immobilizer Remote Keys. |
| **Accessories** | Sports Rims, Leather Seats, Factory Fitted Audio System With Steering Controls, Retractable Side Mirrors, Solar Film, Reverse Sensors, Fog Lights. |
| **Description** | Ideal For Future COE Renewal! Rare 9.5 Years Old Car In Such Tip Top Condition, Test Drive To Believe! $600 Plus Monthly Deprecation Only. Low Mileage Clocked Of 11800km. 100% Accident Free. Call Now! |
| **COE** | $5,101 |
| **OMV** | $27,417 |
| **ARF** | $27,417 |
| **Dereg Value** | $14,005 as of today (change) |
| **No. of Owners** | 2 |
| **Type of Veh** | Mid-Sized Sedan |
| **Category** | PARF Car, Premium Ad Car |
| **Availability** | Available |

PREMIUM AD

Add to Shortlist Add to Compare Add a Note

Price Analysis

Seller Information

| | |
|---|---|
| **Company** | Lake View Credit Pte Ltd<br>» dealer's pricelist<br>» 151 vehs sold \| 52 vehs available |
| **Address** | 61 Ubi Avenue 2 #05-10<br>Search cars nearby this location |
| **Location** | Automobile Megamart |
| **Website** | www.lakeviewcredit.com.sg |
| **Office No** | 67459995 |
| **Contact Person(s)** | Chun Kit 81338870<br>Mr How 97279995 |

Car Tyres

Top Coworking Space in SG

THE WORKING CAPITOL

Collaborative Workspaces. Professional Community, Events & Growth - All under one roof

Compare

SGCARMART.COM

Login Sign up

New Cars Used Cars Sell My Car Directory Products Insurance Articles Forum Resources

onefm 913

TOP 913 GREATEST HITS OF ALL TIME COUNTDOWN

WHAT'S YOUR NO. 1 SONG OF ALL TIME? SUBMIT NOW

Honda Civic | Price Range | Depreciation | 2009 | Vehicle Type | Submit | Advanced Search

Home » Used Cars » Dickson Automobile » Honda Civic 1.8A

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

# Honda Civic 1.8A

Overview Financial Accessories Similar Research Photos Map

## DICKSON AUTOMOBILE PTE LTD

A member of DICKSON AUTO GROUP

Established since 1988

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

| | |
|---|---|
| **Price** | **$18,800** |
| **Depreciation** | $8,640 /yr<br>View models with similar depreciation |
| **Reg Date** | 27-Mar-2009<br>(7mths 3days COE left) |
| **Manufactured** | 2009 |
| **Mileage** | 99,000 km (10.5k /yr) |
| **Transmission** | Auto |
| **Engine Cap** | 1,799 cc |
| **Road Tax** | $978 /yr |
| **Power** | 103.0 kW (138 bhp)<br>View specs of the Honda Civic (2006-2012) |
| **Curb Weight** | 1,219 kg |
| **Features** | Powerful And Responsive 1.8L I-Vtec Engine, 5 Speed Auto Transmission, Dual Airbag, ABS, 4 x Disc Brakes, Electrical Retractable Side Mirrors. |
| **Accessories** | Original CD Audio System, Solar Film, Fog Lamp, Sport Rims, Leather Seats, Reverse Sensors. |
| **Description** | Extremely Low Mileage! Very Good Condition! Extended Warranty Available! A Sporty And Powerful Sedan Designed To Give You Superb Handling Enhancing Your Driving Experience. Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Come Appreciate It In Pristine Condition At Our Air-conditioned Showroom Now, Don't Miss It! |
| **COE** | $5,101 |
| **OMV** | $27,417 |
| **ARF** | $27,417 |
| **Dereg Value** | $14,009 as of today (change) |
| **No. of Owners** | 2 |
| **Type of Veh** | Mid-Sized Sedan |
| **Category** | PARF Car |
| **Availability** | Available |

Location Map | Price Analysis

Seller Information

| | | |
|---|---|---|
| **Company** | Dickson Automobile<br>» dealer's pricelist<br>» 101 vehs sold \| 111 vehs available | |
| **Address** | 31 Kaki Bukit Road 3 #01-01<br>Search cars nearby this location | |
| **Location** | Techlink | |
| **Website** | dicksonauto.com.sg | |
| **Office No** | 68447667 | |
| **Contact Person(s)** | Tank Ong<br>Jonathan Quah<br>Ting Ting | 85265670<br>91901666<br>83946026 |

Car Tyres

Top Coworking Space in SG

THE WORKING CAPITOL

Collaborative Workspaces, Professional Community, Events & Growth - All under one roof

Compare

Commercial Vehicle




# Honda Civic 1.8A

Overview | **Financial** | **Accessories** | **Similar** | **Research** | **Photos** | **Map**

**DICKSON AUTOMOBILE PTE LTD**
A member of **DICKSON AUTO GROUP**
Established since 1988

Add to Shortlist | Add to Compare | Add a Note | Report Error | More Actions | Share

## Car Details

| | |
|---|---|
| **Price** | **$20,800** |
| **Depreciation** | $12,040 /yr<br>View models with similar depreciation |
| **Reg Date** | 27-Mar-2009<br>(7mths 3days COE left) |
| **Manufactured** | 2009 |
| **Mileage** | - |
| **Transmission** | Auto |
| **Engine Cap** | 1,799 cc |
| **Road Tax** | $978 /yr |
| **Power** | 103.0 kW (138 bhp)<br>View specs of the Honda Civic (2006-2012) |
| **Curb Weight** | 1,219 kg |
| **Features** | 1.8L I-VTEC Engine, 5 Speed Auto Transmission, SRS Airbags, Paddle Shifter, Multi Function Steering Control, Cruise Control, ABS, 4x Disc Brakes. |
| **Accessories** | Sport Rims, Factory Fitted Audio System, Electrical Retractable Side Mirrors With Indicator, Upholstery Leather Seats, Reverse Sensor. |
| **Description** | Only 1 Owner! Affordable Down Payment At $6K Plus Only! High PARF Value! Extended Warranty And Professional Evaluation Available! A Stylish Sedan That You Must Not Miss! Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Come Visit Us At Our Aircon Showroom To Appreciate It In Pristine Condition Now, Before Its Gone! |
| **COE** | $4,889 |
| **OMV** | $27,417 |
| **ARF** | $27,417 |
| **Dereg Value** | $13,996 as of today (change) |
| **No. of Owners** | 1 |
| **Type of Veh** | Mid-Sized Sedan |
| **Category** | PARF Car |

Location Map | Price Analysis

## Seller Information

| | | |
|---|---|---|
| **Company** | Dickson Automobile<br>• dealer's pricelist<br>• 101 vehs sold \| 111 vehs available | |
| **Address** | 31 Kaki Bukit Road 3 #01-01<br>Search cars nearby this location | |
| **Location** | Techlink | |
| **Website** | dicksonauto.com.sg | |
| **Office No** | 68447667 | |
| **Contact Person(s)** | Jonathan Quah<br>Beatrice Teo<br>Jez Teo | 91901666<br>81287619<br>90044370 |

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

**CLAIM SUBFOLDER TRACKING**

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
|---|---|---|---|---|---|---|---|
| Main | 17 Aug 2018 | | 27 Aug 2018 10:20 Edit Adj Rpt | **S$0.00** Edit Estimates | **S$0.00** View Rpt | | **Pending for Survey Report** Cancel Case |

Main | Reference | Claim Details | Documents | Show All

**CLAIM SUBFOLDER DETAILS** **[Created by insurer]**

| | | | |
|---|---|---|---|
| Insured: | **THIA LIANG KEE**, ID: S7939728H, Tel: +6594594806, Email: NOEMAIL | | |
| Main Claimant: | **DZULQARNAIN BIN MOHAMAD NASIR**, ID: S1542540G | | |
| Vehicle Reg. No.: | **SJN9077C** | Date of Loss: | 16/08/2018 08:00 - :59 [**113** Months and **12** Days From LTA Reg Date (Man Yr)] |
| Claim Type: | **TP** / 567995 | Policy/Cover Note No.: | A80452773QMY (Comprehensive) Coverage: 05/01/2018 - 25/01/2019 |
| Vehicle Reg. No. (Insured): | **SLR9066P** | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | **Jin Auto Services Pte Ltd (Defu)** Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126 | | |
| Handling Insurer: | **MSIG Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: +65 6827 7888 ... [Handled by **Elaine Ngu Siau Mei** - 6594 2540] | | |
| Adjuster: | **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **MARCUS CHUA**] ... [**Final Rpt** due 26/09/2018] | | |
| Driver/Custodian (Insured): | THIA LIANG KEE (38 / Male), NRIC: S7939728H, Tel: +6594594806 | | |
| Adj Asg. Remarks: | Liability 100% - Chain Collision. TP Agree to use LKK. Contact Person: Jouis Seow / 6289 8126. | | |

**ASSOCIATED MAIL RECEIVED** View All | Compose Case Mail

There are no mail for this case.

**ALL ASSOCIATED TASKS** View All | Search Tasks | Create New Task | Complete

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|---|---|---|---|---|---|---|---|---|---|

No results.

# Claim Documents

***SJN9077C (567995)**
**[SLR9066P]**
**TP**
**DZULQARNAIN BIN MOHAMAD NASIR**
**Aug 16 2018 8:00AM**
**[THIA LIANG KEE]**
**Jin Auto Services Pte Ltd**

Upload Documents | Upload Photos | Compose New Letter

View: View in Browser

**Assessment Reports** — 1 per page

| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | | Thumbnail | Print |
|---|---|---|---|---|---|
| 1 | 23/08/18 10:44 | **Accident Statement**<br>From:SC - Reg. No: SLR9066P, Claimant: THIA LIANG KEE | 1 | Load HTM | |
| No | Finalized On | **LKK Auto Consultants Pte Ltd (HQ)** | | Thumbnail | Print |
| 1 | 29/08/18 10:46 | **Adjuster Immediate Advice** | 1 | Load HTM | |

**Photos/Images** — 3 per page

| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
|---|---|---|---|---|---|
| 1 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 2 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 3 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 4 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 5 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 6 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 7 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 8 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 9 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 10 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 11 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 12 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 13 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 14 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 15 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 16 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 17 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 18 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 19 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 20 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 21 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 22 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 23 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 24 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 25 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 26 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 27 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 28 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 29 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 30 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 31 | 29/08/18 10:50 | **General View** | 1 | Load JPG | ☑ |
| 32 | 29/08/18 10:50 | **General View** | | Load JPG | |

| Assessment Reports | | | 1 per page | | |
|---|---|---|---|---|---|
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | | Thumbnail | Print |
| | | | | | |
| 33 | 29/08/18 10:50 | General View | | Load JPG | |
| 34 | 29/08/18 10:50 | General View | | Load JPG | |
| 35 | 29/08/18 10:50 | General View | | Load JPG | |
| 36 | 29/08/18 10:50 | General View | | Load JPG | |
| 37 | 29/08/18 10:50 | General View | | Load JPG | |
| 38 | 29/08/18 10:50 | General View | | Load JPG | |
| 39 | 29/08/18 10:50 | General View | | Load JPG | |
| 40 | 29/08/18 10:50 | General View | | Load JPG | |
| 41 | 29/08/18 10:50 | General View | | Load JPG | |
| 42 | 29/08/18 10:50 | General View | | Load JPG | |
| 43 | 29/08/18 10:50 | General View | | Load JPG | |
| 44 | 29/08/18 10:50 | General View | | Load JPG | |

| Documentation | | | 1 per page | | |
|---|---|---|---|---|---|
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | | Thumbnail | Print |
| 1 | 23/08/18 10:44 | SJN9077C E-FILE REPORT<br>From:SC - Reg. No: SLR9066P, Claimant: THIA LIANG KEE | | Load PDF | |
| 2 | 23/08/18 10:44 | SKS1291P E-FILE REPORT<br>From:SC - Reg. No: SLR9066P, Claimant: THIA LIANG KEE | | Load PDF | |
| 3 | 23/08/18 10:54 | TP PRI REQUEST EMAIL | | Load PDF | |

## Documents Checklist

**DOCUMENTS CHECKLIST** Reset Save Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG18015293/URBE2
**Date:** 05/09/2018

REFERENCE

| | | | | |
|---|---|---|---|---|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | A80452773QMY | |
| **Claimant Vehicle No :** | SJN9077C | **Insured Vehicle No :** | SLR9066P | |
| Date of Loss: | 16/08/2018 | Nature of Claim: | TP | Claim No: 567995 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|---|---|---|---|
| Reg No: | **SJN9077C** | | |
| Make & Model: | HONDA CIVIC, 1.8 L 5AT (A) | Engine No: | R18A14010750 |
| Reg. Date: | 04/03/2009 (Man. Year: 2008) | Chassis No: | JHMFD16309S201754 |
| Colour: | Blue | Odometer: | 179462 km |
| Engine Capacity: | 1799 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S$): | **Market Value/New Car Price** | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|---|---|---|---|---|---|
| General Condition: | | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|---|---|---|---|
| Front Tyre Size: | 205/55 R16 | Rear Tyre Size: | 205/55 R16 |
| Front Left Side: | Habilead 8 mm | Rear Left Side: | Habilead 8 mm |
| Front Right Side: | Habilead 8 mm | Rear Right Side: | Habilead 8 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|---|---|---|---|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| **Nett Amount (S$)** | **0.00** | **0.00** | **0.00** | |

INSPECTION

| | | | |
|---|---|---|---|
| Date of Assignment: | 27/08/2018 | | |
| Date Inspected: | 23/08/2018 | Inspected At: | Jin Auto Services Pte Ltd (Defu)<br>Blk 14 Defu Lane 10, #01-410/412<br>Singapore 539195 |
| Estimated Period of Repair: | 0.0 days | | |

**Adjuster:** MARCUS CHUA **Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value : $18,500.00
OMV : $28,040.00
PARF Rebate (1) : $14,020.00
Quota Premium Paid : $4,889.00
COE Rebate (2) : $254.00
Total Rebate (1) + (2) = : $14,274.00

The total amount incurred will be Market Value $18,500.00 minus Total Rebate $14,274.00 = $4,226.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

# REPAIR DETAILS

## Reference

| | | |
|---|---|---|
| **Part Source:** | MRM-SG | Version: 1.0 (Last Synchronised: 05 Sep 2018) |
| **Parts:** | 143 | HONDA CIVIC 1.8 L 5AT (A) (Catalogue:Merimen Singapore 1.0) |
| **Labour:** | Repairer's | (Price-denominated Standard List) |
| **Print Code:** | (Unsubmitted, no print-code for SJN9077C) | |
| **Validity:** | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| **Further Info:** | Items/values not in reference catalogue are prefixed with an asterisk *. | |

## Recommended Parts

**There are no new parts selected.**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

**There are no new miscellaneous items selected.**

## Recommended Labour

**There are no labour items selected.**

| Report was unsubmitted during this print-out. |
|---|

**< END OF ESTIMATES >**