ASS. REC. BY: | REF: CS3/AIG18015687/R124d3e2

Surveyor: Raisul

Merman

ASSIGNMENT (Office)

From (Person): Chin Lee Ying of: AIG Date/Time: 28/8/18 @ 10.32am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLR 3657Z Insured: SLZ1788A

at Workshop m/s: Celebrity Auto Tel: 90222411

of: 176 Sin Ming Drive # 03-17

Policy No: Claim No: 18389879885G

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A: 26/8/2018

CA / REV / REP. / REV 24 HRS: Cups

H.O.D. Endorsement:

Date/Time: 11.37am @ 28/8/18 Person Contacted: Mr. Yeo Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SLR 3657Z - X
	SLZ1788A - X
5/9/18	After Repair

(08/11/13) . wef

ASS. REC. BY: Jason

REF: AIG

PRS

ASSIGNMENT

From: Date: 28/8/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLR 36572

at Workshop m/s Celebrity Auto

of 176 Sin Ming Drive #03-17

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record) Pls call before go

Make of Veh: Mr-Yeo 90222411

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLR 36572 Yr Regn: Aug / 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA CHR c.c 1797

Colour yellow A/C: Insured / Std / NI / NA

Sp.Reading 40457 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ZYX102047136

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R16

R: 〃

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. D.O.I. 28/08/18

Survey held at CELEBRITY AUTO

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
13/9/18	Submit DAR report — DAR and no. of days.
	Repair days 7

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:	180
Transportation: ___S + RS, ___SI	
Photos	
Others	20
TOTAL	200

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18015687/R1z4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 28-08-2018

Code : AIG

1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	SLZ 1788A	Veh. Inspected	SLR 3657Z
	Policy No.		Coverage ($)	0.00
	Claim No.		Excess ($)	0.00
	Assign From	CHIN LEE YING	Assign Date	28/08/2018

2.	Vehicle Particulars & Condition			
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			

3.	Conditions of Tyres			
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

4.	Description of Damages

5.	General Information			
	Accident Date	26/08/2018	Inspection Date	28/08/2018
	Survey held at	CELEBRITY AUTO BLK 176 SIN MING DRIVE #03-18 SIN MING AUTOCARE SINGAPORE 575721		

5a.	Remarks
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 28/8/2018 10:32:41 AM
Attachments: tmp2C0D.TIF

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Date: 27/08/18

6 835 7416

To: AIG

Motor Claim Department

RE: **Pre repair Inspection**

Yours Vehicle SLZ 1788A involve in accident on 17:00 @ DE TOWARD Changi.

With my client vehicle SLR 3657Z.

Vehicle is ready for inspection at **176 sin Ming drive #03-17 S575721**

Vehicle will be park at 6th car park

Please contact Mr. **Leslie Yeo** for location and Keys

Pls email us a list of your appointed surveyors

Celebrityautosg@gmail.com

Many Thank

CELEBRITY AUTO

Hp: **90222411**

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SLR3657Z
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model :	C-HR HYBRID 1.8G CVT
Chassis No. :	ZYX102047136
Propellant :	Petrol-Electric
Engine No. :	2ZR8128111
Motor No. :	20A317421820
Engine Capacity :	1797 cc
Power Rating :	53.0 kW
Maximum Power Output :	90.0 kW (120 bhp)
Maximum Laden Weight :	1715 kg
Unladen Weight :	1440 kg
Year Of Manufacture :	2017
Original Registration Date :	11 Aug 2017
Lifespan Expiry Date :	-
COE Category :	E - Open - all except motorcycle
Quota Premium :	$52,751.00
COE Expiry Date :	10 Aug 2027
Road Tax Expiry Date :	10 Feb 2019
PARF Eligibility Expiry Date :	10 Aug 2027
Inspection Due Date :	10 Aug 2020
Intended Transfer Date :	04 Sep 2018
CO2 Emission :	91.00 (g/km)
CEV/VES Rebate Utilised Amount :	$30,000.00
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S$)	GST Amount (S$)	Amount After GST (S$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			**25.00**

You may print this page for reference.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4368D
Vehicle Details	
Vehicle No.:	SLR3657Z
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.8G CVT
Primary Colour:	Yellow
Manufacturing Year:	2017
Engine No.:	2ZR8128111
Chassis No.:	ZYX102047136
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	$35,446.00
Original Registration Date:	11 Aug 2017
First Registration Date:	11 Aug 2017
Transfer Count:	0
Actual ARF Paid:	$11,625.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Aug 2027
PARF Rebate Amount:	$8,718.00
Intended COE Rebate Details	
COE Expiry Date:	10 Aug 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	$52,751.00
COE Rebate Amount:	$47,121.00
Total Rebate Amount:	**$55,839.00**

The information contained herein is correct as at 04 Sep 2018

OK

MALM18110929 / Ah Lim Motor Company - AMK
ENTRY DATE & TIME: 27/08/2018 16:34
SUBMITTED BY: Meili Tan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/08/2018 16:34
Date Of Accident	26/08/2018 16:30
Exact Location Of Accident	PIE TWDS CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR3657Z
Insured/Policyholder	
Name Of Registered Owner	TAN CHENG THOE
NRIC No	S1244368D
Email Address	ALLOYSIUS.COM@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90884303
Alternative Phone No	Office-NOPHONE
Vehicle Particulars	
Manufacturer	TOYOTA
Model	C-HR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	HL ASSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MP307770
Cover Note Number	
Driver	
Name of Driver	ALOYSIUS WONG MING SHEN
NRIC No	S9026214I
Date Of Birth	28/07/1990
Occupation	INDOOR
Date Of Driving Pass	13/01/2015

Driving Experience	3 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90884303
Fax Number	
Contact Number	
EMail Address	ALLOYSIUS.COM@GMAIL.COM
Address	APT BLK 302D PUNGGOL PLACE #10-211
Postcode	824302
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	Name: : LIM HUILI Gender: : Female
Passenger 2	Name: : LIM CHENG NGUAN Gender: : Male
Passenger 3	Name: : LIM YEOH HWANG Gender: : Female
Passenger 4	Name: : ANG LEE CHU Gender: : Female

Details of Police Action

Was the accident reported to the police?	YES
If Yes,Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	**ROAD**: 10 UBI AVENUE 3 , **POSTCODE:** 408865 , **COUNTRY**: SINGAPORE
Police Station Contact	**TEL NO**: 65470000 - **FAX NO**:
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN & POLICE REPORT NO. T/20180827/7010 DD. 27/08/2018

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLZ1788A
Vehicle Make/Model/Colour	MERCEDES BENZ GLA180-YELLOW
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKZ9011P
Vehicle Make/Model/Colour	TOYOTA CAMRY-BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SJD6922K
Vehicle Make/Model/Colour	BMW-BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	E118T
Vehicle Make/Model/Colour	SSANGYONG STAVIC-SILVER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number	SKZ2275T
Vehicle Make/Model/Colour	HONDA-SILVER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 6

Vehicle Registration Number	SMC4177C
Vehicle Make/Model/Colour	VOLKSWAGEN-SILVER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 7

Vehicle Registration Number	SKZ517J
Vehicle Make/Model/Colour	KIA-RED
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 8

Vehicle Registration Number	SLT7609B
Vehicle Make/Model/Colour	HONDA-WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 9

Vehicle Registration Number	SHC1608E
Vehicle Make/Model/Colour	HYUNDAI SONATA -BLUE
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 10

Vehicle Registration Number	SLL4772Z
Vehicle Make/Model/Colour	MAZDA 3 -GREY
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	ALLOYSIUS WONG MING SHEN
Approximate Age	
Injuries Sustain	HEADACHE, STIFF NECK & BACKACHE
Injured person in which vehicle?	SLR3657Z
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	LIM HUILI
Approximate Age	
Injuries Sustain	STIFF NECK & BACK PAIN
Injured person in which vehicle?	SLR3657Z
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

DETAILS OF INJURED PERSON 3

Name	LIM CHENG NGUAN
Approximate Age	
Injuries Sustain	HIT HEAD ON THE BACK OF FRONT SEAT
Injured person in which vehicle?	SLR3657Z
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

DETAILS OF INJURED PERSON 4

Name	LIM YEOH HWANG
Approximate Age	
Injuries Sustain	UNKNOWN-UNDER OBSERVATION
Injured person in which vehicle?	SLR3657Z
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

DETAILS OF INJURED PERSON 5

Name	ANG LEE CHU
Approximate Age	
Injuries Sustain	UNKNOWN -UNDER OBSERVATION
Injured person in which vehicle?	SLR3657Z

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

IMPORTANT NOTICE

HL

SLR 3857Z

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be **as truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

   I understand, acknowledge, agree and consent that:

   (a) My insurer, my workshop and the General Insurance Association of Singapore ("**GIA**") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

   (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

   (ii) investigating the accident and/or my claims;

   (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

   (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal date about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

   (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")

   (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

   (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

   (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

   (e) the information so collected under (d) above may be shared / disclosed:

   (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

   (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/FIN No.: Hel 27/08/18

vl 8 18 11:20m DIE Fraud check i

Date of accident: [illegible] Time: 7.50pm Location: PIE [illegible]

My Vehicle A: SLR 36572 Vehicle B: SLZ 1788A Vehicle C: SKZ 9110P

SKETCH PLAN refer to Drawing



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

There was road works going on and I slowed down to a complete stop. immediately after I stopped, my vehicle was hit multiple times from behind.

☐ Claim OD/TP at Ah Lim Motor ☑ Claim OD/TP at other workshop ☐ Reporting Only

Remarks : Please forward a copy of my efile accident report to :

My workshop : Celebrity Auto

Email address :

& myself :

Email address : Alloysius.Goms@gmail.com

Note : Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Vehicle : SLR 36572

AH LIM MOTOR CO. • SINCE 1918 •

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
26/08/18

Driver's Particulars

HL Assurance

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1996
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

Form X1

CERTIFICATE NUMBER : MP307770

Type of Coverage	: Comprehensive	Own Damage Excess	: SGD600.00
Sum Insured	: **Market Value**	Windscreen Excess	: SGD100.00

1. Index Mark and Registration Number of Vehicle — SLR3657Z
   Chassis Number of Vehicle — ZYX102047136
2. Name of Policyholder — TAN, CHENG THOE
3. Effective date of the Commencement of Insurance for the purposes of the Act — 11 Aug 2018
4. Date of Expiry of Insurance — 10 Aug 2019
5. Persons or Classes of Persons entitled to drive*

01. TAN, CHENG THOE	02. N/A
03. N/A	04. N/A
05. N/A	06. N/A

(b) Any other person who is driving on the Policyholder's order or with his/her permission.

*Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business or profession. The Policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 96 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Please note that the Own Damage Excess will be halved if claims related repairs are done at HL Assurance Approved Workshops listed in the attached.

This Certificate is not transferable to a new owner of the Motor Vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to HL Assurance Pte. Ltd. Within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

Hire Purchase Company : **United Overseas Bank Ltd**

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

HL ASSURANCE PTE. LTD.

Issued on: 11 Jul 2018

Authorized Signature

HL Assurance Pte. Ltd.
11 Keppel Road, #11-01 AIA Plaza, Singapore 089057 Tel: 65 6702 0202 Fax: 65 6822 6032

REPUBLIC OF SINGAPORE DRIVING LICENCE
S9026214I
ALOYSIUS WONG MING SHEN
(HUANG MINGSEN)
28 Jul 1990
13 Jan 2019


REPUBLIC OF SINGAPORE
IDENTITY CARD NO S9026214I
ALOYSIUS WONG MING SHEN
(HUANG MINGSEN)
黄 铭 森
CHINESE
28-07-1990 M
SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)
EFFECTIVE DATE

S9026214I
25-08-2003
APT BLK 3020 PUNGGOL PLACE #10-211
SINGAPORE 824302

SINGAPORE POLICE FORCE

T/20180827/7010

Report No. T/20180827/7010

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:	Vide Report No.:	Station Diary No.:
27/08/2018 16:14		

Informant's Particulars

Name of Informant: ALOYSIUS WONG MING SHEN			Address: APT BLK 302D PUNGGOL PLACE #10-211 SINGAPORE 824302	
ID Type / ID No.: NRIC NO / S9026214I			Contact No.: Home/Office:	Mobile: 90884303
Nationality: SINGAPORE CITIZEN			Email: aloysius.wms@gmail.com	
Sex: Male	Age: 28	Date of Birth: 28/07/1990	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: Embedded systems engineer			Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 26/08/2018 16:30	Type of Location: Pan Island Expressway
Location: PAN ISLAND EXPRESSWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 80 Km/h
Traffic Flow: One Way		Traffic Control: Controlled by Others e.g. Workmen		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
E118T	Car	SSANGYONG	STAVIC	Silver		0
SHC1608E	Car	HYUNDAI	SONATA	Blue		0
SJD6922K	Car	BMW		Black		0
SKZ2275T	Car	HONDA		Silver		0

SINGAPORE POLICE FORCE

T/20180827/7010

Report No. T/20180827/7010

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKZ517J	Car	KIA		Red		0
SKZ9110P	Car	TOYOTA	Camry	Black	Totally Damaged	0
SLL4772Z	Car	MAZDA	MAZDA3	Grey		0
SLR3657Z	Car	TOYOTA	C-HR	Yellow	Slightly Damaged	4
SLT7609B	Car	HONDA		White		0
SLZ1788A	Car	MERCEDES BENZ	GLA180	Yellow	Seriously Damaged	1
SMC4177C	Car	VOLKSWAGON		Silver		0

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger			
Name	Lim Cheng Nguan	ID No.	S0008176J
Related Vehicle	SLR3657Z (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	Lim Yeoh Hwang	ID No.	S1188205F
Related Vehicle	SLR3657Z (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Driver			
Name	ALOYSIUS WONG MING SHEN	ID No.	S9026214I
Related Vehicle	SLR3657Z (Car)	Contact No.	90884303
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	26/08/2018	Date Discharge	26/08/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Passenger			
Name	ANG LEE CHU	ID No.	S2009028F
Related Vehicle	SLR3657Z (Car)	Contact No.	97773260
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	Lim Huili	ID No.	S9317935H
Related Vehicle	SLR3657Z (Car)	Contact No.	85883707
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	26/08/2018	Date Discharge	26/08/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	Li Chao	ID No.	S7589745F
Related Vehicle	SLZ1788A (Car)	Contact No.	83102729
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Brief Details.

On PIE Towards Chanig just after Sims ave exit, and before Paya lebar exit, there were road works going on.

As I travelled, I noticed the car infront of me suddenly jam braked to a halt, and I had to do the same. After my vehicle has come to a stop, the whole car was shaken and hit multiple times from behind. I noticed that the caution sign for the road works were only situated less than 50 metres away from the actual works going on as well.

I have videos exceeding 2MB in size from my dashcam to show how the accident took place from the 1st vehicle onwards.

There were about 11 vehicles involved in the accident.

SINGAPORE POLICE FORCE

T/20180627/7010

Report No. T/20180627/7010

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 27/08/2018 16:14
Officer in Charge Of Case: TP / TPHQ / WONG SIEU LUI Contact No.: 65476151	Classification Of Case:

Authentication Stamp

NP168

Accident Photo

Accident Photo

Accident Photo

Accident Photo



Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

(1)Replace (✓) (2)Repair(X) (3)Check (?)
(4)Not Consistent (FC)

(7)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

Rear Portion

Vehicle No: SLR 3657Z

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993085	Rear Bumper Upper	DD	✓	
1143	993017	Rear Bumper Lower	DD	✓	
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	KUT	✓	
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	?		
1149	993045	Rear Bumper Reinforcement	?		
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	?		
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler	?		
1158	994023	Reverse Sensor	KUT	✓	
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish	?		
1161	993333	Rear End Panel Inner Trim	?		
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD	✓	
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

13/9/18

No of Items: 13 Assessor:

TGLM 12/9/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Aug 2018 Edit Reg		28 Aug 2018 00:00 Edit Adj Rpt	**S$0.00** Edit Estimates	**S$0.00** View Rpt		**Pending for Survey Report** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS			**[Created by adjuster]**
Insured:	**LI CHAO**, ID: S7589745F		
Main Claimant:	**TAN CHENG THOE**, ID: S1244368D		
Vehicle Reg. No.:	**SLR3657Z**	Date of Loss:	26/08/2018 00:00 - :59 [**12** Months and **15** Days From LTA Reg Date (Man Yr)]
Claim Type:	**TP** / 1838987988SG	Policy/Cover Note No.:	(Comprehensive) Coverage: 17/07/2018 - 16/07/2019
Vehicle Reg. No. (Insured):	**SLZ1788A**	Policy No. (Claimant):	
		Excess:	
Repairer:	**Celebrity Auto - Sin Ming (HQ)** 176 SIN MING DRIVE, #03-17, 575721 Sin Ming - Tel:		
Handling Insurer:	**AIG Asia Pacific Insurance Pte. Ltd. (Express)** - Tel: 65-6419-3000 ... [Handled by **MdNoor, Norsiah**] Norsiah.MdNoor@aig.com		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **MOHD RASUL**] ... [**Final Rpt** due 06/09/2018]		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

- AIG_SG (29/08/2018): **Request To Upload TP GIA Report**

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLR3657Z (1838987988SG)**
[SLZ1788A]
TP
TAN CHENG THOE
Aug 26 2018 12:00AM
[LI CHAO]
Celebrity Auto - Sin Ming

Upload Documents | Upload Photos | Compose New Letter | Upload Video | Upload Audio

View: View in Browser

Photos/Images 3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/08/18 14:26	**General View**		Load JPG	☑
2	30/08/18 14:26	**General View**		Load JPG	☑
3	30/08/18 14:26	**General View**		Load JPG	☑
4	30/08/18 14:26	**General View**		Load JPG	☑
5	30/08/18 14:26	**General View**		Load JPG	☑
6	30/08/18 14:26	**General View**		Load JPG	☑
7	30/08/18 14:26	**General View**		Load JPG	☑
8	30/08/18 14:26	**General View**		Load JPG	☑
9	30/08/18 14:26	**General View**		Load JPG	☑
10	30/08/18 14:26	**General View**		Load JPG	☑
11	30/08/18 14:26	**General View**		Load JPG	☑
12	30/08/18 14:26	**General View**		Load JPG	☑
13	30/08/18 14:26	**General View**		Load JPG	☑
14	30/08/18 14:26	**General View**		Load JPG	☑
15	30/08/18 14:26	**General View**		Load JPG	☑
16	30/08/18 14:26	**General View**		Load JPG	☑
17	30/08/18 14:26	**General View**		Load JPG	☑
18	30/08/18 14:26	**General View**		Load JPG	☑
19	30/08/18 14:26	**General View**		Load JPG	☑
20	30/08/18 14:26	**General View**		Load JPG	☑
21	30/08/18 14:26	**General View**		Load JPG	☑
22	30/08/18 14:26	**General View**		Load JPG	☑
23	30/08/18 14:26	**General View**		Load JPG	☑
24	30/08/18 14:26	**General View**		Load JPG	☑
25	30/08/18 14:26	**General View**		Load JPG	☑
26	30/08/18 14:26	**General View**		Load JPG	☑
27	30/08/18 14:26	**General View**		Load JPG	☑
28	30/08/18 14:26	**General View**		Load JPG	☑
29	30/08/18 14:26	**General View**		Load JPG	☑
30	30/08/18 14:26	**General View**		Load JPG	☑
31	30/08/18 14:26	**General View**		Load JPG	☑
32	30/08/18 14:26	**General View**		Load JPG	☑
33	30/08/18 14:26	**General View**		Load JPG	☑
34	30/08/18 14:26	**General View**		Load JPG	☑
35	30/08/18 14:26	**General View**		Load JPG	☑
36	30/08/18 14:26	**General View**		Load JPG	☑
37	30/08/18 14:26	**General View**		Load JPG	☑

Photos/Images			3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	30/08/18 14:26	General View		Load JPG	
39	30/08/18 14:26	General View		Load JPG	
40	30/08/18 14:26	General View		Load JPG	
41	30/08/18 14:26	General View		Load JPG	
42	30/08/18 14:26	General View		Load JPG	
43	30/08/18 14:26	General View		Load JPG	
44	30/08/18 14:26	General View		Load JPG	
45	30/08/18 14:26	General View		Load JPG	
46	30/08/18 14:26	General View		Load JPG	
47	30/08/18 14:26	General View		Load JPG	
48	30/08/18 14:26	General View		Load JPG	
49	30/08/18 14:26	General View		Load JPG	
50	30/08/18 14:26	General View		Load JPG	
51	30/08/18 14:26	General View		Load JPG	
52	30/08/18 14:26	General View		Load JPG	
53	30/08/18 14:26	General View		Load JPG	
54	30/08/18 14:26	General View		Load JPG	
55	30/08/18 14:26	General View		Load JPG	
56	30/08/18 14:26	General View		Load JPG	
57	30/08/18 14:26	General View		Load JPG	
58	30/08/18 14:26	General View		Load JPG	
59	30/08/18 14:26	General View		Load JPG	
60	30/08/18 14:26	General View		Load JPG	
61	30/08/18 14:26	General View		Load JPG	
62	30/08/18 14:26	General View		Load JPG	
63	30/08/18 14:26	General View		Load JPG	
64	30/08/18 14:26	General View		Load JPG	
65	30/08/18 14:26	General View		Load JPG	
66	30/08/18 14:26	General View		Load JPG	
67	30/08/18 14:26	General View		Load JPG	
68	30/08/18 14:26	General View		Load JPG	
69	13/09/18 15:56	Photo After Spray		Load JPG	
70	13/09/18 15:56	Photo After Spray		Load JPG	
71	13/09/18 15:56	Photo After Spray		Load JPG	
72	13/09/18 15:56	Photo After Spray		Load JPG	
73	13/09/18 15:56	Photo After Spray		Load JPG	
74	13/09/18 15:56	Photo After Spray		Load JPG	
75	13/09/18 15:56	Photo After Spray		Load JPG	
76	13/09/18 15:56	Photo After Spray		Load JPG	
77	13/09/18 15:56	Photo After Spray		Load JPG	
78	13/09/18 15:56	Photo After Spray		Load JPG	
79	13/09/18 15:56	Photo After Spray		Load JPG	

Documentation			1 per page		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	29/08/18 10:47	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18015687/R1Z4D3E2
Date: 17/09/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:			
Claimant Vehicle No :	SLR3657Z	**Insured Vehicle No :**	SLZ1788A		
Date of Loss:	26/08/2018	Nature of Claim:	TP	Claim No:	1838987988SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SLR3657Z**		
Make & Model:	TOYOTA C-HR, 1.8 HYBRID ICON/DYNAMIC (A)	Engine No:	2ZR8128111
Reg. Date:	11/08/2017 (Man. Year: 2017)	Chassis No:	ZYX102047136
Colour:	Yellow	Odometer:	40457 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50 R16	Rear Tyre Size:	225/50 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S$)	**0.00**	**0.00**	**0.00**	

INSPECTION

Date of Assignment:	28/08/2018		
Date Inspected:	28/08/2018	Inspected At:	Celebrity Auto - Sin Ming (HQ) 176 SIN MING DRIVE, #03-17 Singapore 575721
Estimated Period of Repair:	7.0 days		

Adjuster: MOHD RASUL **Manager:** Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER UPPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER LOWER	Dented	0.00 F	*- F
3	1		*REAR BUMPER TOW COVER	Cut	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*REAR BUMPER SIDE RETAINER	* Check	0.00 F	*- F
6	1		*REAR BUMPER REINFORCEMENT	* Check	0.00 F	*- F
7	1		*REAR BUMPER SPONGE	* Check	0.00 F	*- F
8	1		*REAR BUMPER LOWER SPOILER	* Check	0.00 F	*- F
9	1		*REVERSE SENSOR	Cut	0.00 F	*- F
10	1		*REAR END PANEL	Dented	0.00 F	*- F
11	1		*REAR END PANEL TOP GARNISH	* Check	0.00 F	*- F
12	1		*REAR END PANEL INNER TRIM	* Check	0.00 F	*- F
13	1		*TAILGATE	Dented	0.00 F	*- F
				Total Parts (S$)	**0.00**	**0.00**

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >