ASS. REC. BY: | REF: CS/ICS18016234/ R/Sd3 | N2 Special Instructions:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Janice Goh of: ICS Date/Time: 5/9/18 @ 9.13am

Estimated Cost: Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLQ 8873M Insured:

at Workshop m/s: Auto Germany Tel: 9247 8842

of: 23 Kaki Bkt Ave 4 #04-01

Policy No: Claim No: DMPC1800342H

Sum Insured: Excess: $500.00

Make of Veh: (Client's Record) D.O.A. 24/08/2018

CA / REV / REP. / REV 24 HRS 6/9/18 @ After 10am

H.O.D. Endorsement:

Date/Time: 9:43am @ 5/9/18 Person Contacted: Vincent Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLQ 8873M - X
	No policy Number. cannot open in mainer.
10/09/18	@ 11:13 a.m. revised IA to Janice via mainer.
10/09/18	@ 11:14 a.m. mandate requested authorize repair to Janice via mainer.
10/09/18	@ 17:04 p.m. mandate approved by Janice via mainer.

(08/11/23) wel
ASS REC. BY: Rahul

REF: ICS CS/ICS18016234/Rlsd3

1336 A

ASSIGNMENT

From: Date: 6/9/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLQ 8873 M

at Workshop m/s: Auto Germany

of: 23 Kaki Bkt Ave 4 #04-01

Insured:

Policy No:

Claims No:

Sum Insured: Excess: $500.00

(Client's Record) After 10 am.

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 82K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLQ8873M Yr Regn: 2017 / July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: OPEL ASTRA ST 1.0 AT c.c 999

Colour: Blue A/C: Insured / Std / NI / NA

Sp.Reading: 33476 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: W0LBE8EA3H8058349

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 24/08/18 D.O.I. 06/09/18

Survey held at: Auto Germany

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
10/09/18	@17:46 p.m. revert authorised repair to Vincent (repairer) via email
04/04/19	Confirmed p/p $ 10,732.60 @ 5 days with Rasul ($ 8,952.00 Red - 46%)

RECEIVED 05 APR 2019

RECEIVED 05 APR 2019

4/4/2019

Date/Time, File Pass to? 05/04/19
1) Typist

Date/Time, File Return to?
2)

☐ : Preli. Report
☑ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($)
☐ : Interview ($)
☐ : Tech. Invs ($)
☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($ 10,732.60 p/p)

Survey Fee:	
Transportation:	450
S + RS, SI	10
Photos	
Others	
TOTAL	460

REC BY: Rahul | REF: ICS | 1336 A

ASSIGNMENT

From: Date: 6/9/18

Estimated Cost:

TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLQ 8873 M

Workshop m/s: Auto Germany

23 Kaki Bkt Ave 4 # 04-01

Insured:

Policy No:

Claims No:

Sum Insured: Excess: $500.00

(Client's Record) After 10 am.

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S O/S

Val. or Market Value: 82K

DAC Accident Rport: Consistent? : Yes or No

IA / PR Seen: Consistent? Yes or No

Est. Repairs: days Res.: Yes or No

Sum Sum: % 3 Val.: Yes or No

A / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLQ8873M Yr Regn: 2017 / July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: OPEL ASTRA ST 1.0 AT c.c 999

Colour: Brown A/C: Insured / Std / NI / NA

Sp.Reading: 33476 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: W0LBE8EA348058349

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	24/08/18	D.O.I.	06/09/18

Survey held at: AUTO GERMANY

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Time, File Pass to? : Preli. Report

Days Of Repair:

Required No. of Trips: Survey Fee:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS/ICS18016234/R1sd3

10 EUNOS ROAD 8
SINGAPORE POST CENTRE #09-04A SINGAPORE 408600

Date : 05-09-2018

Code : ICS

1.	Policy Particulars :- OWN DAMAGE			
	Insured Veh.		Veh. Inspected	SLQ 8873M
	Policy No.	MPC18A00190801	Coverage ($)	0.00
	Claim No.	DMPC1800342H	Excess ($)	500.00
	Assign From	JANICE GOH	Assign Date	05/09/2018

2.	Vehicle Particulars & Condition			
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			

3.	Conditions of Tyres			
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

4.	Description of Damages

5.	General Information			
	Accident Date	24/08/2018	Inspection Date	06/09/2018
	Survey held at	23 KAKI BUKIT AVE 4 # 04-01		
	Repairer	AUTO GERMANY PTE LTD		

5a.	Remarks
	A)THE MARKET VALUE IS S$----------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 07 Sep 2018

Preliminary Advice

Vehicle No	: SLQ8873M	Accident Date	: 24/08/2018
Make	: OPEL ASTRA ST	Policy No.	: MPC18A00190801
Assignment Date	: 07/09/2018	Excess	: S$0.00
Date of Inspection	: 06/09/2018	Est. Duration of Repair	: 5 days
Inspection At	: Auto Germany Pte Ltd (HQ) 7 Ubi Close,, Alpine Centre Singapore 408604		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S$	19,684.60
Revised Amount	:S$	9,619.30
Check Items (Estimated)	:S$	2,193.30
Total	:S$	11,812.60
Lump Sum Repair	:S$	

Total Loss Consideration

New for Old Value	:S$	
Pre-Accident Value	:S$	82,000.00
COE / PARF Rebate	:S$	41,764.00
Salvage Value	:S$	
Margin for Repair	:S$	40,236.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( ) Other comments :

Catherine Chong (LKK Auto)

From: motorsurvey <motorsurvey@ecics.com.sg>
Sent: Wednesday, 5 September, 2018 9:13 AM
To: vincent.sim@alpinemotors.sg; assignments
Cc: Kelvin Chew; suhaimi@alpinemotors.sg; motorsurvey
Subject: RE: SLQ8873M - OPEL ASTRA -OWN DAMAGED - ECICS DOA 24-8-2018

Hi Vincent

Thank you for your email.
We will appoint LKK for the OD survey.

Aside to LKK

Please assist to arrange for OD survey.
Policy excess is $500.00.
Our claim no DMPC1800342H.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg **directly.**

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

From: Vincent Sim [mailto:vincent.sim@alpinemotors.sg]
Sent: Wednesday, 5 September, 2018 8:50 AM
To: motorsurvey
Cc: Kelvin Chew; suhaimi@alpinemotors.sg
Subject: SLQ8873M - OPEL ASTRA -OWN DAMAGED - ECICS DOA 24-8-2018

Janice,
Kindly let us know who have you appointed for the survey , owner is still driving the vehicle ,
hereby summit the estimate for your action, will call owner to arranged date and time for survey .

Regards,
Vincent Sim- Claims Dept - Auto Germany Pte Ltd.

65113022 ext 343

H/P 9247-8842

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 5 April 2019 11:58 AM
To: Kelvin.chew@alpinemotors.sg; SUR
Cc: suhaimi@firstautoworks.com.sg
Subject: RE: SLQ 8873 M OPEL ASTRA ECICS OD DOA 24.08.2018

Dear Mr Boo,

Confirmed final fig $10,732.60 @ 5 days of repairs before excess $500/- & GST.

Final invoice and all supporting documents sent over to ECICS LTD.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kelvin Chew [mailto:Kelvin.chew@alpinemotors.sg]
Sent: Friday, 22 March 2019 11:05 AM
To: sur@lkkauto.com
Cc: suhaimi@firstautoworks.com.sg
Subject: SLQ 8873 M OPEL ASTRA ECICS OD DOA 24.08.2018

Hi Lkk,

attach is finalize report.
vehicle survey by Mr. Rasul.
part by part $10,732.60 before excess $500.00 @ 5 working days.
kindly please check & confirm with me.
thanks.

from,
kelvin chew
8292 5595

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 10 September 2018 5:46 PM
To: vincent.sim@alpinemotors.sg
Cc: suhaimi@alpinemotors.sg; 'mailto:Kelvin.chew@alpinemotors.sg'; 'SUR'
Subject: SLQ 8873M OD (ECICS)

Dear Vincent,

As instructed by our client, please proceed to repair the insured vehicle **SLQ 8873M (Excess $ 500/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLQ8873M (DMPC1800342H)**
OD
Aug 24 2018 9:00AM
[KHOO HUN KIONG]
Auto Germany Pte Ltd

Reply | Reply All | Mark as Unread | Print Message | Delete Message | Forward

From **ECICS Limited (HQ) (ECICS)**, sent on **10/09/2018 17:04 PM.**
To LKK_HQ
Subject **Alert - Adj Mandate Approved (S$11812.60) - SLQ8873M - Claim Handler: Janice Goh**

Approved:11812.60.

DOCUMENTS SUMMARY

There are no documents.

onefm 913

Post an Advertisement
Sell it yourself! Advertise it at just
$58 until it's SOLD!

Post an Ad | Advertiser Login | Ways of Selling

Classic Promo!Best Deal!Fast Selling!Hurry Down Now!

Plus Value 1 Owner Trade In Accepted! Call/Viber/sms/SMS Sales Consultant Today!
Classic Credit

PRIME MOTOR & LEASING
(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes

Browse by Category | Sort by Date Posted | 20 results/page

4 vehicles

opel astra

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	opel astra		Any	Any	2017	Any	Any	Any	Available

Opel Astra 1.0A $76,000 $8,290 /yr 14-Jul-2017 999 cc 26,000 km Hatchback Available

Up To 90% Loan And Interest Rate From 1.99%! European Car Of The Year 2016! Comes With Agent Warranty And 5 Years Free Servicing! Original Condition Maintained By Single Owner! Big Savings On Road Tax...

Posted: 25-Aug-2018 Tags: 2017 Opel Astra, Opel Astra, Opel, Astra, Used Opel

Opel Astra 1.0A $79,800 $8,400 /yr 13-Nov-2017 999 cc 7,700 km Hatchback Available

1 Owner, Low Mileage Done! Comes With Agent Warranty And 3 Years Free Servicing! Fuel Efficiency Up To 23Km/L! Spacious Cabin And Boot! High Loan And High Trade In Welcome! Call For Appointment Now!

CONSIGNMENT

Posted: 10-Aug-2018 Tags: 2017 Opel Astra, Opel Astra, Opel, Astra, Used Opel

Opel Astra 1.0A $80,000 $8,400 /yr 20-Nov-2017 999 cc 15,000 km Hatchback Available

Owned By 1 Owner Selling Due To Upgrading. Superb Handling, Spacious Cabin And Huge Cabin. Low Petrol Consumption Yet Good Pickup And Stable On The Highways. Schedule A Test Drive Today. Viewing Is St...

CONSIGNMENT

Carro

Posted: 10-Jul-2018 Tags: 2017 Opel Astra, Opel Astra, Opel, Astra, Used Opel

Opel Astra 1.0A $80,000 $8,700 /yr 28-Jul-2017 999 cc 13,700 km Hatchback Available

Cool, Funky And Unique Continental Lifestyle Opel Astra Sports Tourer 1.0A Owned By 1 Owner Selling Due To Upgrading. Superb Handling, Spacious Cabin And Huge Cabin. Service And Maintenance By Agent W...

PREMIUM AD

Posted: 10-Jul-2018 Tags: 2017 Opel Astra, Opel Astra, Opel, Astra, Used Opel

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used opel astra, opel astra Singapore, used opel astra Singapore, used opel astra, used vehicles Singapore or even buy used opel astra Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2018 sgCarMart. All rights reserved.

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1336A
Vehicle Details	
Vehicle No.:	SLQ8873M
Vehicle to be Exported:	Yes
Intended De-registration Date:	31 Aug 2018
Vehicle Make:	OPEL
Vehicle Model:	ASTRA ST 1.0 AT
Primary Colour:	Gold
Manufacturing Year:	2017
Engine No.:	B1170167HRXX0173
Chassis No.:	W0LBE8EA3H8058349
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	$19,889.00
Original Registration Date:	26 Jul 2017
First Registration Date:	26 Jul 2017
Transfer Count:	0
Actual ARF Paid:	$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jul 2027
PARF Rebate Amount:	$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	25 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	$42,801.00
COE Rebate Amount:	$34,240.00
Total Rebate Amount:	**$37,990.00**

The information contained herein is correct as at 31 Aug 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: 6858 3256	1336A
Vehicle Details	
Vehicle No.:	SLQ8873M
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Sep 2018
Vehicle Make:	OPEL
Vehicle Model:	ASTRA ST 1.0 AT
Primary Colour:	Gold
Manufacturing Year:	2017
Engine No.:	B1170167HRXX0173
Chassis No.:	W0LBE8EA3H8058349
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	$19,889.00
Original Registration Date:	26 Jul 2017
First Registration Date:	26 Jul 2017
Transfer Count:	0
Actual ARF Paid:	$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jul 2027
PARF Rebate Amount:	$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	25 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	$42,801.00
COE Rebate Amount:	$38,014.00
Total Rebate Amount:	**$41,764.00**

The information contained herein is correct as at 07 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	24/08/2018 15:57
Date Of Accident	24/08/2018 09:15
Exact Location Of Accident	NUS CAR PARK 5
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLQ8873M
Insured/Policyholder	
Name Of Registered Owner	KHOO HUN KIONG
NRIC No	S8181336A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97731178
Alternative Phone No	OFFICE-97731178
Vehicle Particulars	
Manufacturer	OPEL
Model	ASTRA GT-999CC (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC18A00190801
Cover Note Number	
Driver	
Name of Driver	KHOO HUN KIONG
NRIC No	S8181336A
Date Of Birth	13/03/1981
Occupation	INDOOR
Date Of Driving Pass	22/04/2009
Driving Experience	9 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97731178
Fax Number	
Contact Number	OFFICE-97731178
EMail Address	NOEMAIL

Address	666A JURONG WEST
Postcode	641666
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

REFER TO REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SME8300B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24/8/2018 around 9.30am, I was in the NUS Car Park 5 to look for a parking lot. I switched on the hazard light and reversing to the other area of the car park. My car bumped into SMF8206B while reversing.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 24/8/2018 3.13pm

Driver's Signature
(If driver is not the policyholder)
Date & Time

Repairing Centre Personnel's Signature
Name
NRIC/FIN No.

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

(e) the information so collected under (d) above may be shared / disclosed:

(i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: 24/8/2018 3:13pm	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

Driving License

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8181336A

KHOO HUN KIONG

CHINESE

13-03-1961

MALAYSIA

REPUBLIC OF SINGAPORE DRIVING LICENCE

Identification Card

ECICS INSURANCE

CERTIFICATE OF INSURANCE

OPEL WORKSHOPS

Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 96)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1945
Road Traffic (Part II) Act (Cap. 276, Section 4)
Motor Vehicles (Third-Party Risks and Exclusions) Rules, 1950 (Rule 2)

NOTICE
CONDITIONS
OVERLEAF

CERTIFICATE No.: MPK/IA/0020/0001
Agency Name: SETINC INSURANCE AGENCY PTE LTD
Agency Code: A0000002

Claim No.: WRD/IER/L/0000/0000
Policy No.: [illegible]

1. Index Mark and Registration Number of Vehicle: SLQ8875M

2. Name of Policyholder: KUOCHEN SHONG

3. Period of Insurance (00.01 hrs to 24.00 hrs): 28 July 2018 to 28 July 2019

4. Persons or Classes of Persons entitled to drive
   a) The Policyholder and all persons specified under the policy
   b) Any other person who is driving on the Policyholder's order or with his permission

   Provided that the person driving is permitted in accordance with the licensing or other law or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

5. Limitation as to Use
   Use for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover use for hire or reward, tuition, driving test, race, hare-coursing, reliability trial, speed-testing, the carriage of goods (not ancillary to business) or use for any purpose in connection with the motor trade.

6. EXCESS APPLICABLE
   WHICHEVER: [illegible]
   SECTION I - DRIVER/OWNER DRIVES: [illegible]
   ADDITIONAL EXCESS UNDER THIS SECTION: [illegible]
   SECTION I - AGE <[illegible], AGE NOT [illegible] 2 YEARS OLD: [illegible]

7. Hire Purchase Company: MAYBANK

Signature of the Authorised Officer of ECICS Insurance

Chief Executive Officer

Important Notice:

i) Policyholder is hereby notified that it could be an offence for any person to use or permit any other person to use a motor vehicle without a valid insurance under the Act.

ii) On the sale of the motor vehicle, Policyholder must provide all insurance papers including the Certificate of Insurance and the Policy to the purchaser. If the vehicle dealer has been fined or convicted of a Statutory Breach or has had a Court Order made against him for failure to comply with the obligations in relation under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 96).

iii) The Certificate of Insurance and the Policy will cease to be evidence that the motor vehicle has been sold or transferred.

iv) The Premium Holiday Cover Warranty or Premium Payment Warranty found in the Policy must be complied with failure to which could be an offence under the Policy and Certificate of Insurance.

Addendum Sheet

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09.00 – 17.00
UEN: S66SS0030G / GST Reg. No. M400017739

IMPORTANT NOTE: Please submit the completed Addendum form to the **same** Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MAP/81/19/N2 Vehicle Registration No: SLO 3874M

Name(as shown in NRIC) : Chee Hua Kiang NRIC/FIN/Passport No : S7718536A

(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate

Address : _____ Singapore( )

Contact (Tel) : _____ Mobile No. : _____

Email Address : _____

Date of Accident : 28/8/2018 Time of Accident : 09:15

Place of Accident : NKD CAR PARK 5

Insurance Company : (GICS Limited)

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

From Reporting to Own Damaged Claim

Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name: See ex pee
NRIC/FIN No.: S7236127A
Date: 30/8/2018

AG GERMANY PTE LTD

Repair Estimate

Date :04/09/2018

Reference: OPEL
Make: ASTRA

To Whom It May Concern

Dear Sir,

RE: VEHICLE .:SLQ8873M
CHASSIS NO.: W0LBE8EA3H8058349
ENGINE NO.: B1170167HRXX0173

Name of insured .: KHOO HUN KIONG
Date of accident.: 24.08.2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description		Price (SGD)	
1	1	Rear Tailgate		$ 2,100.00	Pt ✓
2	1	Opel emblem		$ 70.00	✓
3	1	Lettering "ASTRA"		$ 53.00	✓
4	1	Lettering "Turbo"		$ 108.00	✓
5	1	Rear Windscreen With Moulding		$ 883.00	✓
6	1	LHR Tailgate Lamp		$ 431.00	CRA ✓
7	1	RHR Tailgate Lamp		$ 431.00	X
8	1	Tailgate Inner Trim Board		$ 357.00	? ✓
9	1	LHR Tailgate Hinge		$ 45.00	X
10	1	RHR Tailgate Hinge		$ 45.00	X
11	1	Rear Tailgate Latch		$ 328.00	X
12	1	Rear Tailgate Striker		$ 25.00	X
13	1	LHR Taillamp		$ 738.00	? X
14	1	RHR Taillamp		$ 738.00	X
15	1	Rear Bumper Upper		$ 1,740.00	DE ✓
16	1	Rear Bumper Lower		$ 307.00	DE ✓
17	1	Rear Bumper Towing Cover		$ 110.00	X
18	1	LHR Bumper Reflector		$ 55.00	CRA ✓
19	1	RHR Bumper Reflector		$ 55.00	X
20	1	Rear Bumper Absorber		$ 180.00	? ✓
21	1	Rear Bumper Reinforment Bar		$ 700.00	? ✓
22	1	Rear Bumper Air Ventilator		$ 65.00	? X
23	1	LHR Bumper Bracket, Guide		$ 85.00	Re ✓
24	1	RHR Bumper Bracket, Guide		$ 85.00	X
25	1	LHR Bumper Bracket		$ 45.00	✓
26	1	RHR Bumper Bracket		$ 45.00	X
27	1	Rear Bumper Bracket Centre		$ 65.00	? X
28	1	Rear End Panel		$ 701.00	repair ✓
29	1	Rear End Panel Trim		$ 190.00	X
30	4	Reverse sensor - for centre		$ 332.00	? X
31	1	LHR Fender		$ 2,182.00	X

Parts Total: $ 13,294.00
Less10%: $ 1,329.40
Total : $ 11,964.60

Auto Germany Pte Ltd
7 Ubi Close, Alpine Centre
Singapore 408604

Sales Tel: 6922-3288 Fax: 6922-3289
Service Tel: 6922-3282 Fax: 6922-3283
Parts Tel: 6922-3285 Fax: 6922-3286

Opel Passenger and Commercial Vehicles
Email: enquiry@autogermany.sg
Web: opel.com.sg

Labour

No.		Labour Description	Price (SGD)	
1		To dismantle / renew the accident damaged portion,to panel beating,reshape,straighten,orientate and align repair /replacement parts.	$ ~~3,900.00~~	1625
2		Carry out spray painting on affected area,RR TAILGATE, RR BUMPER, RR END PANEL, LHR FENDER	$ ~~1,950.00~~	1650
3		To disconnect front wire harness of electrical component to facilitate repairs,reconnect and check electrical function after repair	$ ~~180.00~~	120
4		Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	$ ~~650.00~~	325
5		To conduct transfer of parts from old tailgate to new tailgate	$ 650.00	325
6		To remove and refix rear tail gate windscreen	$ ~~220.00~~	180

Labour Total : $ 7,550.00

Others

No.		Other Description	Price (SGD)	
1		RR NUMBER PLATE	$ 65.00	X
2		RR WINDSCREEN INNER SEAL	$ 40.00	ne
3		RR WINDSCREEN SEALANT	$ 65.00	ne

Other Total: $ 170.00

TOTAL: $ 19,684.60
GST (7%): $ 1,377.92

GRAND TOTAL : $ 21,062.52

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Advisor

Rasul
Hp 90010068
5 days
P/P
06/09/18 @ 11am
Resurvey b4 paint
Excess: 500
Revert
10/9/18

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

AUTO GERMANY PTE LTD

Repair Estimate

Date :04/09/2018

Reference: OPEL
Make: ASTRA

To Whom It May Concern

Dear Sir,

RE: VEHICLE .:SLQ8873M
CHASSIS NO.: W0LBE8EA3H8058349
ENGINE NO.: B1170167HRXX0173

Name of insured .: KHOO HUN KIONG
Date of accident.: 24.08.2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description		Price (SGD)	
1	1	Rear Tailgate		$ 2,100.00	BF ✓
2	1	Opel emblem		$ 70.00	✓
3	1	Lettering "ASTRA"		$ 53.00	✓
4	1	Lettering "Turbo"		$ 108.00	✓
5	1	Rear Windscreen With Moulding		$ 883.00	✓
6	1	LHR Tailgate Lamp		$ 431.00	CRA ✓
7	1	RHR Tailgate Lamp		$ 431.00	X SUC
8	1	Tailgate Inner Trim Board		$ 357.00	?.CRA ✓
9	1	LHR Tailgate Hinge		$ 45.00	X
10	1	RHR Tailgate Hinge		$ 45.00	X } X SUC
11	1	Rear Tailgate Latch		$ 328.00	X
12	1	Rear Tailgate Striker		$ 25.00	X
13	1	LHR Taillamp		$ 738.00	?. X SUC
14	1	RHR Taillamp		$ 738.00	X M
15	1	Rear Bumper Upper		$ 1,740.00	DE ✓
16	1	Rear Bumper Lower		$ 307.00	DE ✓
17	1	Rear Bumper Towing Cover		$ 110.00	X M
18	1	LHR Bumper Reflector		$ 55.00	CRA ✓
19	1	RHR Bumper Reflector		$ 55.00	X SUC
20	1	Rear Bumper Absorber		$ 180.00	?.CRA ✓
21	1	Rear Bumper Reinforment Bar		$ 700.00	?.BF ✓
22	1	Rear Bumper Air Ventilator		$ 65.00	?.X SUC
23	1	LHR Bumper Bracket, Guide		$ 85.00	✓
24	1	RHR Bumper Bracket, Guide		$ 85.00	X SUC
25	1	LHR Bumper Bracket		$ 45.00	✓
26	1	RHR Bumper Bracket		$ 45.00	X SUC
27	1	Rear Bumper Bracket Centre		$ 65.00	?.X SUC
28	1	Rear End Panel		$ 701.00	repair
29	1	Rear End Panel Trim		$ 190.00	X SUC
30	4	Reverse sensor - for centre		$ 332.00	?.X SUC
31	1	LHR Fender		$ 2,182.00	X SUC

Parts Total: $ 13,294.00
Less10%: $ 1,329.40
Total : $ 11,964.60

Auto Germany Pte Ltd
7 Ubi Close, Alpine Centre
Singapore 408604

Sales Tel: 6922-3288 Fax: 6922-3289
Service Tel: 6922-3282 Fax: 6922-3283
Parts Tel: 6922-3285 Fax: 6922-3286

Opel Passenger and Commercial Vehicles
Email: enquiry@autogermany.sg
Web: opel.com.sg

Labour

Labour Description

No.			Price (SGD)	
1		To dismantle / renew the accident damaged portion,to panel beating,reshape,straighten,orientate and align repair /replacement parts.	$ ~~3,900.00~~	1625
2		Carry out spray painting on affected area,RR TAILGATE, RR BUMPER, RR END PANEL, LHR FENDER	$ ~~1,950.00~~	1650
3		To disconnect front wire harness of electrical component to facilitate repairs,reconnect and check electrical function after repair	$ ~~180.00~~	120
4		Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	$ ~~650.00~~	325
5		To conduct transfer of parts from old tailgate to new tailgate	$ 650.00	325
6		To remove and refix rear tail gate windscreen	$ ~~220.00~~	180

Labour Total : $ 7,550.00

Others

Other Description

No.			Price (SGD)	
1		RR NUMBER PLATE	$ 65.00	XMM
2		RR WINDSCREEN INNER SEAL	$ 40.00	Ne
3		RR WINDSCREEN SEALANT	$ 65.00	Ne

Other Total: $ 170.00

TOTAL: $ 19,684.60
GST (7%): $ 1,377.92

GRAND TOTAL : $ 21,062.52

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Advisor

Rasul
Hp 90010068
5 days
P/P
06/09/18 @ 11AM

Resurvey b4 paint
Excess: 500
Revert

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

FINALIZE

ECICS LIMITED

GST Ref. No: 20-0000274-Z

Vehicle No: SLQ8873M
Chasis No : W0LBE8EA3H8058349
Engine No: B1170167HRXX0173
Date of accident :24/08/2018

Invoice No:

Invoice Date:

DESCRIPTION — AMOUNT SGD

Parts

No.	Qty.	Description		Price (SGD)
1	1	REAR TAILGATE		$ 2,100.00
2	1	OPEL EMBLEM		$ 70.00
3	1	LETTERING " ASTRA "		$ 53.00
4	1	LETTERING " TURBO "		$ 108.00
5	1	REAR WINDSCREEN WITH MOULDING		$ 883.00
6	1	LHR TAILGATE LAMP		$ 431.00
7	1	TAILGATE INNER TRIM BOARD		$ 357.00
8	1	REAR BUMPER UPPER		$ 1,740.00
9	1	REAR BUMPER LOWER		$ 307.00
10	1	LHR BUMPER REFLECTOR		$ 55.00
11	1	REAR BUMPER ABSORBER		$ 180.00
12	1	REAR BUMPER REINFORCEMENT BAR		$ 700.00
13	1	LHR BUMPER BRACKET , GUIDE		$ 85.00
14	1	LHR BUMPER BRACKET		$ 45.00

Supplementry

1	-			$ -

Total: $ 7,114.00
Less 10%: $ 711.40
Parts Total: $ 6,402.60

Labour

No.			Price (SGD)
1		TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIRED / REPLACEMENT PARTS.	$ 1,625.00

2		CARRY OUT SPRAY PAINTING OF ACCIDENT AFFECTED AREA.RR TAILGATE , RR BUMPER , RR END PANEL , LHR FENDER	$	1,650.00
3		TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	$	120.00
4		REMOVE AND REFIX SEAT CUSHION / UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS	$	325.00
5		TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE	$	325.00
6		TO REMOVE AND REFIX REAR TAILGATE WINDSCREEN	$	180.00

Labour Total : $ 4,225.00

Other

No.				Price (SGD)	
1	1	RR WINDSCREEN INNER SEAL		$	40.00
2	1	RR WINDSCREEN INNER SEAL		$	65.00

Other Total : $ 105.00

Total : $ 10,732.60
Excess: $ 500.00
GST (7%) : $ 716.28
Grand Total : $ 10,948.88

Yours Faithfully,

Kelvin Chew
Service Advisor
Tel: 68441985 Fax:68445185

Please check and finalize with me

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS18016234/R1SD3N2
Date: 08/04/2019

REFERENCE

Insured/Claimant: KHOO HUN KIONG **Policy No:** MPC18A00190801
Date of Loss: 24/08/2018 **Nature of Claim:** OD **Claim No:** DMPC1800342H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ8873M**
Make & Model: OPEL ASTRA ST, 999cc (A)
Reg. Date: 26/07/2017 (Man. Year: 2017)
Colour: Brown
Engine Capacity: 999 cc
Market Value/New Car Price: S$82,000.00
Sum Insured (S$): **Market Value/New Car Price**

Engine No: B1170167HRXX0173
Chassis No: W0LBE8EA3H8058349
Odometer: 33476 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:
Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 225/45R17
Front Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm

Rear Tyre Size: 225/45R17
Rear Left Side: Michelin 6 mm
Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,134.60	6,507.60	5,627.00	46.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,550.00	4,225.00	3,325.00	44.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**19,684.60**	**10,732.60**	**8,952.00**	**45.48**
- Excess (S$)	500.00	500.00	0.00	0.00
(S$)	19,184.60	10,232.60	8,952.00	46.66
+ GST 7.00/7.00% (S$)	1,342.92	716.28	626.64	46.66
Nett Amount (S$)	**20,527.52**	**10,948.88**	**9,578.64**	**46.66**

INSPECTION

Date of Assignment: 05/09/2018
Date Inspected: 06/09/2018 **Inspected At:** 23 Kaki Bukit Ave 4 # 04-01
Repairer: Auto Germany Pte Ltd (HQ)
7 Ubi Close,, Alpine Centre
Singapore 408604

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL **Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Apr 2019)
Parts:	144	OPEL ASTRA ST 999cc (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ8873M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	2,100.00 FL	*2,100.00 FL
2	1		*OPEL EMBLEM	Necessary	70.00 FL	*70.00 FL
3	1		*LETTERING ASTRA	Necessary	53.00 FL	*53.00 FL
4	1		*LETTERING TURBO	Necessary	108.00 FL	*108.00 FL
5	1		*REAR WINDSCREEN WITH MOULDING	Necessary	883.00 FL	*883.00 FL
6	1		*LHR TAILGATE LAMP	Cracked	431.00 FL	*431.00 FL
7	1		*RHR TAILGATE LAMP	Serviceable	431.00 FL	*- FL
8	1		*TAILGATE INNER TRIM BOARD	Cracked	357.00 FL	*357.00 FL
9	1		*LHR TAILGATE HINGE	Serviceable	45.00 FL	*- FL
10	1		*RHR TAILGATE HINGE	Serviceable	45.00 FL	*- FL
11	1		*REAR TAILGATE LATCH	Serviceable	328.00 FL	*- FL
12	1		*REAR TAILGATE STRIKER	Serviceable	25.00 FL	*- FL
13	1		*LHR TAILLAMP	Serviceable	738.00 FL	*- FL
14	1		*RHR TAILLAMP	Not Necessary	738.00 FL	*- FL
15	1		*REAR BUMPER UPPER	Deformed	1,740.00 FL	*1,740.00 FL
16	1		*REAR BUMPER LOWER	Deformed	307.00 FL	*307.00 FL
17	1		*REAR BUMPER TOWING COVER	Not Necessary	110.00 FL	*- FL
18	1		*LHR BUMPER REFLECTOR	Cracked	55.00 FL	*55.00 FL
19	1		*RHR BUMPER REFLECTOR	Serviceable	55.00 FL	*- FL
20	1		*REAR BUMPER ABSORBER	Cracked	180.00 FL	*180.00 FL
21	1		*REAR BUMPER REINFORCEMENT BAR	Bent	700.00 FL	*700.00 FL
22	1		*REAR BUMPER AIR VENTILATOR	Serviceable	65.00 FL	*- FL
23	1		*LHR BUMPER BRACKET,GUIDE	Necessary	85.00 FL	*85.00 FL
24	1		*RHR BUMPER BRACKET,GUIDE	Serviceable	85.00 FL	*- FL
25	1		*LHR BUMPER BRACKET	Necessary	45.00 FL	*45.00 FL
26	1		*RHR BUMPER BRACKET	Serviceable	45.00 FL	*- FL
27	1		*REAR BUMPER BRACKET CENTRE	Serviceable	65.00 FL	*- FL
28	1		*REAR END PANEL	Repair	701.00 FL	*- FL
29	1		*REAR END PANEL TRIM	Serviceable	190.00 FL	*- FL
30	4		*REVERSE SENSOR-FOR CENTRE	Serviceable	332.00 FL	*- FL
31	1		*LHR FENDER	Serviceable	2,182.00 FL	*- FL
32	1		*RR NUMBER PLATE	Not Necessary	65.00 FS	*- FS
33	1		*RR WINDSCREEN INNER SEAL	Necessary	40.00 FS	*40.00 FS
34	1		*RR WINDSCREEN SEALANT	Necessary	65.00 FS	*65.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S$)	**13,464.00**	**7,219.00**
- List Item Discount on L Items 10.00/10.00% (S$)	1,329.40	711.40
Total Parts (S$)	**12,134.60**	**6,507.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION,TO PANEL BEATING,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	3,900.00	1,625.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA,RR TAILGATE,RR BUMPER,RR END PANEL,LHR FENDER	New	1,950.00	1,650.00
3	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS,RECONNECT AND CHECK ELECTRICAL AFTER REPAIR	New	180.00	120.00
4	REMOVE AND REFIX SEAT CUSHION/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS	New	650.00	325.00
5	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE	New	650.00	325.00
6	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN	New	220.00	180.00
		Gross Labour Cost (S$)	**7,550.00**	**4,225.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >