22/03/2002

ASS. REC. BY: | REF: CS3 / CTL18016248 / R1 Cbet | Special Instruction:

Surveyor Rasul

Merimen

ASSIGNMENT (Office)

From (Person): Irene Tay of CTL Date/Time: 05092018 4:48pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGZ 2338T Insured: WC 6387G

at Workshop m/s SKM motor Tel: 6636 0738

of 10 Kuki Bukit Rd 2 #03-31

Policy No: DMCVSN1637531802 Claim No: SNM18D04313C03

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 04092018

06092018

CA / REV / REP. / REV 24 HRS 'wp' H.O.D. Endorsement:

Date/Time: 05092018 5.01pm Person Contacted: Ah Heng Vehicle IN / OUT

Date/Time	Action/Instruction (x) Estimate.	
	SGZ 2338T - CC6/MG/30111/07 / PG2939Q	DOA: 13062013
	WC 6387G - CS/CTL/80162416 / tb	DOA: 04092018
	Dismantle: 7/9/2018.	

(08/11/19) wef

ASS. REC. BY: Jason

REF: CTI

ASSIGNMENT

From: Date: 6/9/18

Estimated Cost:

On (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGZ 2338T

at Workshop m/s SKM Motor

of 10 Kaki Bkt Rd 2 # 03-31

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: - Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 11 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS / wp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SGZ 2338T Yr Regn: Oct / 07

Type: (M.Car) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Civic c.c 1998

Colour White A/C: Insured / Std / NI / NA

Sp.Reading 136472 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMFD 2540 7S20 1736

Gen. Cond: Good / (Fair) / Poor / Burnt

Steering: (Inorder) / Jammed / Leaked / Burnt or

Brake: (Inorder) / Jammed / Leaked / Burnt or

Modi : Nil / (S/Rim) / STD A/Rim or

Tyre Size: F: 225/45ZR17

R: " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Kumho

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	06/09/18

Survey held at SKM MOTOR

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Estimated repair range $6,000 – $7,000
	10/9/2018

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 11

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format : PRQ

Lump Sum / I.B.I: ($)

Survey Fee:	150
Transportation:	
__S + RS, __SI	
Photos	
Others	
TOTAL	150

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Ref : CS3/CTI18016248/R1cb

Date : 05-09-2018

Code : CTI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	WC 6387G	Veh. Inspected	SGZ 2338T
Policy No.	DMCVSN1637531802	Coverage ($)	0.00
Claim No.	SNM18D04313C03	Excess ($)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	05/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

5. General Information

Accident Date	04/09/2018	Inspection Date	06/09/2018
Survey held at	SKM MOTOR WORKS 10 KAKI BUKIT ROAD 2 #03-31 FIRST EAST CENTRE SINGAPORE 417868		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	*Status*
Main	05 Sep 2018		05 Sep 2018 16:48 Assign				***New Assignment*** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured:			
Main Claimant:	**MUHAMMAD FAIZ BIN BAHARUDIN**		
Vehicle Reg. No.:	**SGZ2338T**	Date of Loss:	04/09/2018 08:00 - :59
Claim Type:	**TP** / SNM18D04313C03	Policy/Cover Note No.:	DMCVSN1637531802
Vehicle Reg. No. (Insured):	**WC6387G**	Policy No. (Claimant):	
		Excess:	S$0.00
Repairer:	**SKM Motor Works (HQ)** 10 Kaki Bukit Road 2 #03-31 First East Centre, 417868 Kaki Bukit - Tel:		
Handling Insurer:	**China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 ... [Handled by **Irene Tay Hui Ping** - 638986192]		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [**Final Rpt** due 14/09/2018]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SGZ2338T
Vehicle Type :	Z10 - Private Hire (Chauffeur) Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	HONDA
Vehicle Model :	CIVIC 2.0L M
Chassis No. :	JHMFD25407S201736
Propellant :	Petrol
Engine No. :	K20Z22501736
Engine Capacity :	1998 cc
Maximum Power Output :	114.0 kW (152 bhp)
Maximum Laden Weight :	1730 kg
Unladen Weight :	1282 kg
Year Of Manufacture :	2007
Original Registration Date :	23 Oct 2007
Lifespan Expiry Date :	-
COE Category :	B - Car (1601cc & above)
PQP Paid :	$26,246.00
COE Expiry Date :	31 May 2022
Road Tax Expiry Date :	22 Oct 2018
Inspection Due Date :	22 Oct 2018
Intended Transfer Date :	10 Sep 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

The current road tax expiry is 22 Oct 2018. You may renew the road tax from 23 Jul 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 22 Oct 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 23 Oct 2018 to 22 Apr 2019)

	Amount Before GST (S$)	GST Amount (S$)	Amount After GST (S$)
Transfer Fee :	25.00	-	25.00
Sub Total :			**25.00**
Nett Road Tax Amount (After Offsetting Over Payment) :	726.00	-	726.00
Total Amount Payable :			**751.00**

Amount Payable (From 23 Oct 2018 to 22 Oct 2019)

	Amount Before GST (S$)	GST Amount (S$)	Amount After GST (S$)
Transfer Fee :	25.00	-	25.00
Sub Total :			**25.00**

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7252E
Vehicle Details	
Vehicle No.:	SGZ2338T
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 2.0L M
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	K20Z22501736
Chassis No.:	JHMFD25407S201736
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	$20,720.00
Original Registration Date:	23 Oct 2007
First Registration Date:	23 Oct 2007
Transfer Count:	3
Actual ARF Paid:	$22,792.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	$26,246.00
COE Rebate Amount:	$19,543.00
Total Rebate Amount:	**$19,543.00**
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 10 Sep 2018

OK

MVA318114515 / VAC - Kaki Bukit
ENTRY DATE & TIME: 04/09/2018 12:05
SUBMITTED BY: Norhaini Bte Abdul Majid

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	04/09/2018 12:05
Date Of Accident	04/09/2018 09:00
Exact Location Of Accident	UPPER CHANGI ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGZ2338T
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD FAIZ BIN BAHARUDIN
NRIC No	S8637252E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98005632
Alternative Phone No	OTHERS-98005632
Vehicle Particulars	
Manufacturer	HONDA
Model	CIVIC 2.0L M
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5100808772 CLASSIC
Cover Note Number	
Driver	
Name of Driver	MUHAMMAD FAIZ BIN BAHARUDIN
NRIC No	S8637252E
Date Of Birth	02/12/1986
Occupation	OUTDOOR
Date Of Driving Pass	20/01/2011
Driving Experience	7 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98005632
Fax Number	
Contact Number	OTHERS-98005632
EMail Address	NOEMAIL

Address	BLK 769 YISHUN AVENYE 3 #02-275
Postcode	760769
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

I WAS DRIVING ALONG UPPER CHANGI ROAD, ON THE CENTRE LANE. AS I WAS APPROACHING THE RED TRAFFIC LIGHT, ALL VEHICLES STARTED TO SLOW DOWN AND STOPPED. I ALSO SLOWED DOWN AND STOPPED. SUDDENLY A LORRY(WC6387G) CAME FROM BEHIND, HIT ONTO THE REAR OF MY CAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WC6387G
Vehicle Make/Model/Colour	ISUZU CYH52S
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Rear

R-file

DECLARATION

I/We declare the foregoing particulars are true & correct to the best

[illegible]
22 Kaki Bukit Ave 1
Singapore 415933
Tel: 67416697 Fax: 67[illegible]
Email: vackh@singnet.com.sg

Policyholder's Signature
Date [illegible] 4 SEP 2018

Driver's Signature
Name [illegible]
Date of Birth

Witnessing Policyholder's Director
Name
[illegible]

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

   I understand, acknowledge, agree and consent that:

   (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be, collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

   (i) processing, handling and/or dealing with any claims including the settlement of the claims and any necessary investigations relating to the claims;

   (ii) investigating the accident and/or my claims;

   (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

   (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

   (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

   (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

   (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

   (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management to present and all future claims.

   (e) the information so collected under (d) above may be shared / disclosed:

   (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

   (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 14 SEP 2016

Driver's Signature
(if driver is not the policyholder)
Date & Time:

MDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: kaki bukit@simnet.com.sg
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Sep 2018		05 Sep 2018 16:48 Edit Adj Rpt	**S$0.00** Edit Estimates	**S$0.00** View Rpt		**Pending for Survey Report** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured:	-, Co. Reg. No.: -		
Main Claimant:	**MUHAMMAD FAIZ BIN BAHARUDIN**		
Vehicle Reg. No.:	**SGZ2338T**	Date of Loss:	04/09/2018 08:00 - :59 [**130** Months and **12** Days From LTA Reg Date (Man Yr)]
Claim Type:	**TP** / SNM18D04313C03	Policy/Cover Note No.:	DMCVSN1637531802
Vehicle Reg. No. (Insured):	**WC6387G**	Policy No. (Claimant):	
		Excess:	S$0.00
Repairer:	**SKM Motor Works (HQ)** 10 Kaki Bukit Road 2 #03-31 First East Centre, 417868 Kaki Bukit - Tel:		
Handling Insurer:	**China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 ... [Handled by **Irene Tay Hui Ping** - 638986192]		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **MOHD RASUL**] ... [**Final Rpt** due 14/09/2018]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGZ2338T (SNM18D04313C03)**
[WC6387G]
TP
MUHAMMAD FAIZ BIN BAHARUDIN
Sep 4 2018 8:00AM
[-]
SKM Motor Works

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Photos/Images 3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/09/18 10:59	**General View**		Load PDF	
2	11/09/18 10:02	**Photographs of Damaged Items**		Load PDF	

Documentation 1 per page

No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	06/09/18 09:15	**PRS WITH TP GIA**		Load PDF	
2	06/09/18 09:16	**OI GIA**		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST Reset | Save | Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18016248/R1CBE2
Date: 11/09/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1637531802		
Claimant Vehicle No :	SGZ2338T	**Insured Vehicle No :**	WC6387G		
Date of Loss:	04/09/2018	Nature of Claim:	TP	Claim No:	SNM18D04313C03

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SGZ2338T**		
Make & Model:	HONDA CIVIC, 2.0 (M)	Engine No:	K20Z22501736
Reg. Date:	23/10/2007 (Man. Year: 2007)	Chassis No:	JHMFD25407S201736
Colour:	White	Odometer:	136472 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S$)	**0.00**	**0.00**	**0.00**	

INSPECTION

Date of Assignment:	05/09/2018		
Date Inspected:	06/09/2018	Inspected At:	SKM Motor Works (HQ) 10 Kaki Bukit Road 2 #03-31 First East Centre Singapore 417868
Estimated Period of Repair:	11.0 days		

Adjuster: MOHD RASUL **Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $6,000.00 -$8,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Sep 2018)
Parts:	143	HONDA CIVIC 2.0 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGZ2338T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >