22/03/2001

ASS. REC. BY: | REF: CS/FWD19001712/Ds d3 | Special Instruction:

Surveyor: Munimon

ASSIGNMENT (Office)

From (Person): Lionel Tan of FWD Date/Time: 25/1/19 @ 2:19pm

Bill to:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJR 1275D Insured:

at Workshop m/s Vin's Motor Tel: 6453 2121

of 160 Sin Ming Drive # 03-03

Policy No: PNPV2018-00015453 Claim No: 1201900003140

Sum Insured: Excess: 78A

Make of Veh: D.O.A. 23/01/19

(Client's Record) H.O.D. Endorsement: 28/01/19

CA / REV / REP. / REV 24 HRS

Date/Time: 3:11pm @ 25/1/19 Person Contacted: Raymond Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate Investigation (Fire Cause)
	Repairer agreed survey on 28/1/19
	SJR1275D - NA/AIG17019779/Y DOA: 9/10/2017
	mv: 14,000+
	LTA: 11,193
	NV: 2807.

REF: FWD

Investigation (Fire Case)

ASSIGNMENT

From: Date: 28/1/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJR1275D

at Workshop m/s: Vin's Motor

of: 160 Sin Ming Drive #03-03

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: assist to investigate and establish the cause of fire.

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR. Seen: Consistent? : Yes or No

Est. Repairs: – days Res.: Yes or No

Lum Sum: – % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJR1275D Yr Regn: June 2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Volkswagen New Golf c.c. 1390

Colour: Black A/C: Insured / Std / NI / NA

Sp Reading: N.A. T/Radio: Insured / Std / NI / NA

Eng/No: CAX211568

C/No: WVWZZZ1KZ9W517204

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16

R: — " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Yokohama

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm

D.O.A. 23/01/2019 D.O.I. 28/01/2019

Survey held at Vin's Motor Sin Ming

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle caught fire at interior

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	FWD OD
	MV 14K
	LTA 11.1K
	NL 2.9K

compartment. Cause of fire due to electrical nature to the wiring behind the front dashboard.

using average depreciation of 8K divided by 12 X 5 months.

RECEIVED 14 FEB 2019

Total loss. Not economical to repair.

Date/Time: File Pass to? ☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to?

2) 14/2 typist

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp ($ ☐ Interview ($ ☐ Tech. Invs ($ ☐ Weekend ($

Report Format: extensive

Lump Sum / I.B.I: ($

Survey Fee:	200
Transportation:	150
S+R:	
Photos:	
Other: Fire Report	$ 170.00
TOTAL	420.10

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Jan 2019 Sendback Est	25 Jan 2019 13:40 **S$0.00**	25 Jan 2019 14:19 Assign				**New Assignment** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS

Insured:	**LOO SAI SIONG WINSTON**, ID: S7442491J, Tel: +6591820212, Email: WINSTON@DIAMONTIF.COM		
Vehicle Reg. No.:	**SJR1275D**	Date of Loss:	23/01/2019 15:00 - :59 [**115** Months and **14** Days From LTA Reg Date (Man Yr)]
Claim Type:	**OD** / 1201900003140	Policy/Cover Note No.:	PNPV2018-00015453 (Comprehensive)
		Excess:	S$0.00
Repairer:	**Vin's Motor Pte Ltd (Sin Ming)** 160 Sin Ming Drive, #03-03, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64532121		
Handling Insurer:	**FWD Singapore Pte. Ltd. (HQ)** - Tel: 6727 5700 ... [Handled by **Lionel Tan**]		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [**Final Rpt** due 07/02/2019]		
Driver/Custodian:	LOO SAI SIONG WINSTON (44 / Male), NRIC: S7442491J, Tel: +6591820212		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

Nivitha (LKK Auto)

From: lionel.tan@fwd.com
Sent: Friday, 25 January 2019 2:19 PM
To: admin-d@lkkauto.com; ASSIGNMENTS@LKKAUTO.COM; admin-a@lkkauto.com
Cc: belliana@fwd.com; motorclaims.sg@fwd.com
Subject: New Assignment OD - Fire Case Vehicle Number: SLR 1275D DOA: 23/01/2019 Our Ref: 1201900003140/LT

Attn: LKK team

Please take note this case has been assigned to you in Merimen.

Please assist us to investigate and establish the cause of fire.

Thank you.

Best Regards,

Lionel Tan
Senior Executive, Claims

FWD insurance

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986
T (65) 6914 6824
E lionel.tan@fwd.com
W fwd.com.sg



Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg

<https://www.fwd.com.sg/car-insurance/comprehensive-motor-insurance/?utm_source=Internal&utm_medium=EmailSignature&utm_campaign=CarInsurance>

Attachments:

image007.jpg	(215 KB)
image008.png	(15 KB)
image009.jpg	(5 KB)

ATTENTION:
The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.
Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 29 Jan 2019

Preliminary Advice

Vehicle No	: SJR1275D	Accident Date	: 23/01/2019
Make	: VOLKSWAGEN NEW GOLF	Policy No.	: PNPV2018-00015453
Assignment Date	: 25/01/2019	Excess	: S$0.00
Date of Inspection	: 28/01/2019	Est. Duration of Repair	: 0
Inspection At	: Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages caught fire at interior compartment. Cause of fire due to electrical nature to the wiring behind the front dashboard and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S$	TOTAL LOSS
Revised Amount	:S$	TOTAL LOSS
Check Items (Estimated)	:S$	0.00
Total	:S$	TOTAL LOSS
Lump Sum Repair	:S$	

Total Loss Consideration

New for Old Value	:S$	
Pre-Accident Value	:S$	14,000.00
COE / PARF Rebate	:S$	11,193.00
Salvage Value	:S$	
Margin for Repair	:S$	2,807.00

Remarks

( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

(X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( ) Other comments :

MVA119011691 / Vin's Motor Pte Ltd - Sin Ming
ENTRY DATE & TIME: 24/01/2019 15:40
SUBMITTED BY: Tan Yin Lei

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/01/2019 15:40
Date Of Accident	23/01/2019 15:30
Exact Location Of Accident	BLK 119 ALJUNIED CRESCENT CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

29/01/2019 @ 1030hrs From home at Sukit Bedok drive to Paya Lebar square for lunch. Park for abt 45 min to 1 hr. Drove to Aljunied to buy stuff. At carpark, saw smoke coming out of driver air con vent. Continued driving forward and parked. off engine. open bonnet to check. No fire. Window saw fire at air con vent. Got help from people at workshop. Put out fire before SCDF came. bought abt 2 yrs ago. Regular maintained. Change mechanical air con compressor etc. No major mechanical problem. Head unit not original. came with car touch screen type.

Vehicle Registration Number	SJR1275D
Insured/Policyholder	
Name Of Registered Owner	LOO SAI SIONG WINSTON
NRIC No	S7442491J
Email Address	WINSTON@DIAMONTIF.COM
Mobile Phone No	(LOCAL) +65-91820212
Alternative Phone No	Office-91820212
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	NEW GOLF 1.4 AT 5K13G5
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00015453
Cover Note Number	
Driver	
Name of Driver	LOO SAI SIONG WINSTON
NRIC No	S7442491J
Date Of Birth	28/12/1974
Occupation	INDOOR
Date Of Driving Pass	01/11/2010
Driving Experience	8 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91820212

Fax Number	
Contact Number	OFFICE-91820212
EMail Address	WINSTON@DIAMONTIF.COM
Address	BLK241 BUKIT BATOK EAST AVENUE 5 #04-257
Postcode	650241
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	FIRE, EXPLOSION OR LIGHTNING
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : CHEW Gender: : Male

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("**GIA**") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims,

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

(e) the information so collected under (d) above may be shared / disclosed:

(i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

VIN'S MOTOR PTE LTD

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



A: SJR 1275D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At around 3:20pm, after having lunch at Paya Lebar Square. I & my collegues took my car from Paya Lebar Square Multi-Storey car park & depreparing to go to Blk 119 Alijuned crescent to buy so stuffs from the market there.

While I was driving & approaching the Car Park Entry just outside Blk 119 Alijuned Crescent, I saw smokes coming out from all 4 Air con vents, quickly I wind down my driver seat window & also saw smoke coming in.

Without hesitation, I quickly drove my car in further into the carpark (As not to obstruct traffic) & I quickly off my car. However within secs after getting out, turn. I saw FIRE BURNING INSIDE from the extreme Right Aircon Vents (beside driver seat). In panic trying to find fire extinguisher, the Fire escalate outside to my driver seater Right Aircon vent area. The Fire was furious & big, however the coffeeshop staffs were kindly enough to pass me the Extinguisher & I manage to fight the fire for 2X then I manage to put out the FIRE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

MIN'S MOTOR PTE LTD

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2491J
Vehicle Details	
Vehicle No.:	SJR1275D
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jan 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	NEW GOLF 1.4 AT 5K13G5
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	CAX211568
Chassis No.:	WVWZZZ1KZ9W517204
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	$21,841.00
Original Registration Date:	09 Jun 2009
First Registration Date:	09 Jun 2009
Transfer Count:	1
Actual ARF Paid:	$21,841.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Jun 2019
PARF Rebate Amount:	$10,920.00
Intended COE Rebate Details	
COE Expiry Date:	08 Jun 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	$7,589.00
COE Rebate Amount:	$273.00
Total Rebate Amount:	**$11,193.00**

The information contained herein is correct as at 29 Jan 2019

OK

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo



Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo



View Received Message

This mail is associated with :

SJR1275D (1201900003140)
OD
Jan 23 2019 3:00PM
[LOO SAI SIONG WINSTON]
Vin's Motor Pte Ltd

Reply | Reply All | Mark as Unread | Print Message | Delete Message | Forward

From **FWD Singapore Pte. Ltd. (HQ) (FWD_SG)**, sent on **13/02/2019 13:03 PM**.
To LKK_HQ
Subject **Alert - Adj Mandate Approved (S$0.00) - SJR1275D - Claim Handler: Lionel Tan**

Approved:0.00:To upload survey & investigation bills.

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE CIVIL DEFENCE FORCE
91 UBI AVENUE 4
SINGAPORE 408827
TELEPHONE: 6280 0000
GST REG NO: MG-8400000-5

TAX INVOICE/RECEIPT

Name : HIEW MAY FUNG
Address : BLK 51 UBI AVENUE 1
#02-25
Singapore 408933

Receipt No : 5488287186636982404038
Date/Time : 30/01/2019 14:07
eService ID : FR2019013002656

S/No	Payment Mode	Description	Reference No	Net Amount	GST (7% GST)	Gross Amount
1	Credit Card	Fire Report	FR2019013002656	170.00	0.00	170.00
					Total Amount (SGD)	**170.00**

REMARKS:
Date and Time [23/01/2019 15:30] - Location of Fire [BLK 119 ALJUNIED CRESCENT CAR PARK]

Note: This is a computer generated receipt. No signature is required. Receipt is void if payment is dishonoured.

SCDF The Life Saving Force

Singapore Government Integrity · Service · Excellence

Fire Report Application

Your request for the Fire Report has been confirmed and the amount of SGD170.00 will be deducted from your account. You will receive the report within 8 working days upon completion of investigations. Please quote the following transaction number when making enquiries.

Download Tax Invoice/Receipt

Transaction Number: FR2019013002656 **Date/Time:** 30/01/2019 14:07

INCIDENT DETAILS						
Date and Time	23/01/2019 15:30					
Location of Fire	BLK 119 ALJUNIED CRESCENT CAR PARK					
Fire Involved	SJR 1275D					
REQUESTOR DETAILS						
Requestor Type	Insurance Companies					
Requestor ID Type	Foreign International		**Requestor ID**	G2706880X		
Name of Applicant	HIEW MAY FUNG					
Company Name	LKK AUTO CONSULTANT PTE LTD					
Company UEN						
Company Reference Number						
CONTACT DETAILS						
Mode of Collection	Email					
Main Contact No.	62563561		**Office No.**			
Handphone No.			**Fax No.**			
Email Address	sur@lkkauto.com					
Address	**Block No.**	BLK 51	**Floor No.**	02	**Unit No.**	25
	Street Name	UBI AVENUE 1				
	Building Name				**Postal Code**	408933
PAYMENT DETAILS						
Payment Mode	Credit/Debit Card					
EP Reference No.	548828718663698240403 8					
PSI Reference No.	a02d0bb8-f1d0-40eb-9810-4c75a0c71f7c					
Total Fees	SGD170.00					

...CLAIM SUBFOLDER...(Pending for Survey Report)

Total Loss

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Jan 2019 Sendback Est	25 Jan 2019 13:40 **S$0.00**	25 Jan 2019 14:19 Edit Adj Rpt	**S$0.00** Edit Estimates	**S$0.00** View Rpt		**Pending for Survey Report** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS

Insured:	**LOO SAI SIONG WINSTON**, ID: S7442491J, Tel: +6591820212, Email: WINSTON@DIAMONTIF.COM		
Vehicle Reg. No.:	**SJR1275D**	Date of Loss:	23/01/2019 15:00 - :59 [**115** Months and **14** Days From LTA Reg Date (Man Yr)]
Claim Type:	**OD** / 1201900003140	Policy/Cover Note No.:	PNPV2018-00015453 (Comprehensive)
		Excess:	S$0.00
Repairer:	**Vin's Motor Pte Ltd (Sin Ming)** 160 Sin Ming Drive, #03-03, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64532121		
Handling Insurer:	**FWD Singapore Pte. Ltd. (HQ)** - Tel: 6727 5700 ... [Handled by **Lionel Tan**]		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **BRYAN TANI**] ... [**Final Rpt** due 07/02/2019]		
Driver/Custodian:	LOO SAI SIONG WINSTON (44 / Male), NRIC: S7442491J, Tel: +6591820212		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

- FWD_SG (13/02/2019): **Alert - Adj Mandate Approved (S$0.00) - SJR1275D - Claim Handler: Lionel Tan**

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

Claim Documents

SJR1275D (1201900003140)
OD
Jan 23 2019 3:00PM
[LOO SAI SIONG WINSTON]
Vin's Motor Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View: View in Browser

Assessment Reports — 1 per page

No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	25/01/19 13:40	**Repairer Estimates**		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/01/19 15:56	**Adjuster Immediate Advice**		Load HTM	

Photos/Images — 3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	31/01/19 10:04	**Front View Left**		Load JPG	✔
2	31/01/19 10:04	**Front View Right**		Load JPG	✔
3	31/01/19 10:04	**General View**		Load JPG	✔
4	31/01/19 10:04	**General View**		Load JPG	✔
5	31/01/19 10:04	**General View**		Load JPG	✔
6	31/01/19 10:04	**General View**		Load JPG	✔
7	31/01/19 10:04	**General View**		Load JPG	✔
8	31/01/19 10:04	**General View**		Load JPG	✔
9	31/01/19 10:04	**General View**		Load JPG	✔
10	31/01/19 10:04	**General View**		Load JPG	✔
11	31/01/19 10:04	**General View**		Load JPG	✔
12	31/01/19 10:04	**General View**		Load JPG	✔
13	31/01/19 10:04	**General View**		Load JPG	✔
14	31/01/19 10:04	**General View**		Load JPG	✔
15	31/01/19 10:07	**General View**		Load JPG	✔
16	31/01/19 10:07	**Rear View Left**		Load JPG	✔
17	31/01/19 10:07	**Rear View Right**		Load JPG	✔
18	31/01/19 10:07	**Chassis Number**		Load JPG	✔

Documentation — 1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/01/19 16:05	**SJR 1275D GIA REPORT.pdf**		Load PDF	
2	14/02/19 10:50	**INVESTIGATION REPORT**		Load PDF	
3	14/02/19 10:50	**SCDF FIRE REPORT**		Load PDF	
4	14/02/19 10:52	**LTA REBATE**		Load PDF	

Linked Accident Report Documents

View: View in Browser

Assessment Reports — 1 per page

No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	24/01/19 16:52	**Accident Statement**		Load HTM	

Assessment Reports 1 per page ▼ ☑

No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)		Thumbnail	Print

Photos/Images 3 per page ▼ ☑

No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	24/01/19 16:43	**Accident Photo**	ℹ	Load JPG	☑
2	24/01/19 16:43	**Accident Photo**	ℹ	Load JPG	☑
3	24/01/19 16:43	**Accident Photo**	ℹ	Load JPG	☑
4	24/01/19 16:43	**Accident Photo**	ℹ	Load JPG	☑
5	24/01/19 16:43	**Accident Photo**	ℹ	Load JPG	☑
6	24/01/19 16:43	**Accident Photo**	ℹ	Load JPG	☑
7	24/01/19 16:43	**Accident Photo**	ℹ	Load JPG	☑
8	24/01/19 16:43	**Accident Photo**	ℹ	Load JPG	☑
9	24/01/19 16:43	**Accident Photo**	ℹ	Load JPG	☑
10	24/01/19 16:43	**Accident Photo**	ℹ	Load JPG	☑
11	24/01/19 16:43	**Accident Photo**	ℹ	Load JPG	☑
12	24/01/19 16:43	**Accident Photo**	ℹ	Load JPG	☑
13	24/01/19 16:43	**Accident Photo**	ℹ	Load JPG	☑
14	24/01/19 16:43	**Accident Photo**	ℹ	Load JPG	☑

Documentation 1 per page ▼ ☑

No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	24/01/19 16:45	**Sketch Plan**	ℹ	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD19001712/DSD3S2
Date: 14/02/2019

REFERENCE

Insured/Claimant:	LOO SAI SIONG WINSTON	Policy No:	PNPV2018-00015453		
Date of Loss:	23/01/2019	Nature of Claim:	OD	Claim No:	1201900003140

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SJR1275D**		
Make & Model:	VOLKSWAGEN NEW GOLF, 1.4 TSI 5K14Q5 (A)	Engine No:	CAX211568
Reg. Date:	09/06/2009 (Man. Year: 2009)	Chassis No:	WVWZZZ1KZ9W517204
Colour:	Black	Odometer:	0 km
Engine Capacity:	1390 cc		
Market Value/New Car Price:	S$14,000.00		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S$)	**0.00**	**0.00**	**0.00**	

INSPECTION

Date of Assignment:	25/01/2019		
Date Inspected:	28/01/2019	Inspected At:	Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	0.0 days		

Adjuster: BRYAN TANI **Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	$14,000.00
OMV :	$21,841.00
PARF Rebate (1) :	$10,920.00
Quota Premium Paid :	$7,589.00
COE Rebate (2) :	$273.00
Total Rebate (1) + (2) = :	$11,193.00

The total amount incurred will be Market Value $14,000.00 minus Total Rebate $11,193.00 = $2,807.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Feb 2019)
Parts:	144	VOLKSWAGEN NEW GOLF 1.4 TSI 5K14Q5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR1275D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >