22/03/2002

ASS. REC. BY: | REF es/CTI19001923/ RItd3 02 | Special Instruction:

Surveyor: Rasu

Meriman

ASSIGNMENT (Office)

From (Person): Catherine thia of: CTI Date/Time: 29/1/19 @ 4:33pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGE 9500E Insured: GZ 63792

at Workshop m/s Cycle & Carriage Automotive Tel: 6568 4501

of 209 Pandan Garden

Policy No: Claim No: SNM19D200449

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 23/01/2019

CA / REV / REP. / REV 24 HRS tup H.O.D. Endorsement:

Date/Time: 4:51pm @ 29/1/19 Person Contacted: Mr. Tay Vehicle IN / OUT

| Date/Time | Action/Instruction (✓) Estimate |
|---|---|
| | SGE 9500E - NBA (CTI17018287/y DUA: 22/11/17 |
| | GZ 63792 - CS3/CTI18021044/Ud652 DUA: 15/11/18 |
| | |
| | Confirm final figure $4993.1 Cred: 1200; 19%) |
| | |
| | |

Panel

REF:

44750

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGE 9500E

at Workshop m/s CYCLE & CARRIAGE

of 209, PANDAN GARDENS

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

after 10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| N/S | O/S |
|---|---|
| | |

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SGE 9500E Yr Regn: 2016 MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: MITSUBISHI ATTRAGE 1.2 c.c 1193

Colour: GREY A/C: Insured / Std / NI / NA

Sp Reading: 038414 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MMBSTA13AFH018933

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55R15

R: " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

| Front | | Rear | |
|---|---|---|---|
| R/Bal. | 5 mm | R/Bal. | 5 mm |
| L/Bal. | 5 mm | L/Bal. | 5 mm |
| D.O.A. | 23/01/19 | D.O.I. | 13/02/19 |

Survey held at CBC (PG)

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or N/S FRT

The U/C / Chassis frame / Body Structure affected due to collision

| Date / Time | Action / Instruction |
|---|---|
| | |

RECEIVED 08 MAY 2019

8/5/2019

Date/Time, File Pass to? 8/5 Typist

Date/Time, File Return to?

☐ : Preli. Report

☑ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp ($ ☐ Interview ($ ☐ Tech. Invs ($ ☐ Weekend ($

Photos

Other

TOTAL

220

Report Format : TP

Lump Sum / I.B.I: ($ 4993

# ...CLAIM SUBFOLDER...(New Assignment)

**CLAIM SUBFOLDER TRACKING**

| Case | Notified | Est. Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
|---|---|---|---|---|---|---|---|
| Main | 25 Jan 2019 | | 29 Jan 2019 16:33 Assign | | | | **New Assignment** Cancel Case |

Main | Reference | Claim Details | Documents | Show All

| **CLAIM SUBFOLDER DETAILS** | | | **[Created by insurer]** |
|---|---|---|---|
| Insured: | | | |
| Main Claimant: | **LIM MEI YING VERONICA** | | |
| Vehicle Reg. No.: | **SGE9500E** | Date of Loss: | 23/01/2019 00:00 - :59 |
| Claim Type: | **TP** / SNM19D200449 | Policy/Cover Note No.: | NA |
| Vehicle Reg. No. (Insured): | **GZ6379Z** | Policy No. (Claimant): | |
| | | Excess: | S$0.00 |
| Repairer: | **Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)** 209 Pandan Gardens, 609339 West Coast - Tel: 65684501/65684518 | | |
| Handling Insurer: | **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 ... [Handled by **Catherine Thia**] | | |
| Adjuster: | **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [**Final Rpt** due 11/02/2019] | | |

**ASSOCIATED MAIL RECEIVED** View All | Compose Case Mail

There are no mail for this case.

**ALL ASSOCIATED TASKS** View All | Search Tasks | Create New Task | Complete

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|---|---|---|---|---|---|---|---|---|---|

No results.

## Nivitha (LKK Auto)

| | |
|---|---|
| **From:** | Catherine Thia <catherine.thia@sg.cntaiping.com> |
| **Sent:** | Tuesday, 29 January 2019 2:54 PM |
| **To:** | assignments |
| **Cc:** | Tay Jian Ye |
| **Subject:** | PRI survey (SGE9500E) (OIV GZ6379Z) |
| **Attachments:** | 20190129145142.pdf |

Dear LKK oic

- Without Prejudice –

Please assist on PRI assignment. We will create in Merimen shortly

Thanks

Dear Jian Ye

We are agreeable to direct settlement, subject to insured concurrence on damages and quantum as well as our surveyor recommendation

Thanks

**Catherine Thia**
Senior Executive
Motor Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6193
www.sg.cntaiping.com

*Disclaimer :*
*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** slnx@sg.chinataiping.com [mailto:slnx@sg.chinataiping.com]
**Sent:** Tuesday, 29 January, 2019 2:52 PM
**To:** Catherine Thia <catherine.thia@sg.cntaiping.com>
**Subject:**

## Denise Tay (LKKAuto)

**From:** Denise Tay (LKKAuto)
**Sent:** Wednesday, 8 May 2019 10:17 AM
**To:** Loi Ai Ting; Rasul (LKKAuto)
**Cc:** Cheng Jo Jo; Songcuan JR Lauro Araos; Andre Chow En De; Admin A; Admin-D (LKKAuto)
**Subject:** RE: SGE9500E, finalisation (Mit WIP: 35688)

Dear Ms Loi,

Confirm final figure at $4993, 5days. Excluding gst.

Please submit your relevant document to China Tai Ping .

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>
**Sent:** Monday, 22 April 2019 7:07 PM
**To:** Rasul (LKKAuto) <Rasul@lkkauto.com>
**Cc:** Cheng Jo Jo <jojo.cheng@cyclecarriage.com.sg>; Songcuan JR Lauro Araos <lauro.songcuan@cyclecarriage.com.sg>; Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
**Subject:** SGE9500E, finalisation (Mit WIP: 35688)

Hi, Rasul,

Please confirm finalised amount at $5,342.51.

Attached some photos for your reference.

Thanks.

**Best Regards,**

**Loi Ai Ting**
**Customer Service Advisor**

CYCLE & CARRIAGE | Exceptional Journeys

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4556 • F: +65 6565 1240 • www.cyclecarriage.com.sg

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| ACCIDENT STATEMENT | |
|---|---|
| Date Of Report | 24/01/2019 14:30 |
| Date Of Accident | 23/01/2019 11:40 |
| Exact Location Of Accident | CARPARK@BLK 86 LOR 4 TOA PAYOH |
| Country/State of Loss | SINGAPORE |
| **DETAILS OF OWN VEHICLE** | |
| Vehicle Registration Number | SGE9500E |
| **Insured/Policyholder** | |
| Name Of Registered Owner | LIM MEI YING VERONICA |
| NRIC No | S1174475C |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-98323963 |
| Alternative Phone No | HOME-63525226 |
| **Vehicle Particulars** | |
| Manufacturer | MITSUBISHI |
| Model | ATTRAGE-1.2 CVT (A) |
| Exact Purpose for which vehicle was being used at time of accident | PERSONAL TRIP |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |
| **Insurance Company** | |
| Name of Insurance Company | AIG ASIA PACIFIC INSURANCE PTE. LTD. |
| Type Of Coverage | THIRD PARTY |
| Fleet Policy | NO |
| Policy Number | 2100455706 |
| Cover Note Number | |
| **Driver** | |
| Name of Driver | SEET CHIM SENG CHARLES |
| NRIC No | S1543952A |
| Date Of Birth | 01/06/1962 |
| Occupation | INDOOR |
| Date Of Driving Pass | 18/06/1990 |
| Driving Experience | 28 YEARS AND 7 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-98323963 |
| Fax Number | |
| Contact Number | |
| EMail Address | CHARLES.SEET@GMAIL.COM |

| | |
|---|---|
| Address | 316B THOMSON ROAD |
| Postcode | 307660 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | FRIEND |
| Vehicle Registration Number of Driver's Own Vehicle | -<br>-<br>- |
| Insurance Company of Driver's Own Vehicle | -<br>-<br>- |

## General Information of the Accident

| | |
|---|---|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

## Other Information

| | |
|---|---|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 2 |
| Passenger 1 | NAME: : LEE SEOW KIANG FRIEDA<br>GENDER: : FEMALE |

## Details of Police Action

| | |
|---|---|
| Was the accident reported to the police? | NO |
| If Yes,Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes,against whom? | |

## Circumstances of Accident

REFER TO ATTACHMENT COLLISION-TP REVERSED,HIT INSURED CAR.

## Attachment(s)

| | |
|---|---|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Was there any audio recorded? | NO |

## DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|---|---|
| Vehicle Registration Number | GZ6379Z |
| Vehicle Make/Model/Colour | TOYOTA VAN |
| Details Of Properties | SCRATCH ON BUMPER |
| Vehicle Category | COMMERCIAL VEHICLE |
| Name of Driver | TING KOK CHOON |
| NRIC/Passport Number | S1171455B |
| Contact Number | 98379672 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

## SKETCH PLAN

## IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

   I understand, acknowledge, agree and consent that:

   (a) My insurer, my workshop and the General Insurance Association of Singapore ("**GIA**") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

   (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

   (ii) investigating the accident and/or my claims;

   (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

   (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

   (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")

   (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

   (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

   (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

   (e) the information so collected under (d) above may be shared / disclosed:

   (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

   (ii) for complying with requirements under any regulations, laws or court orders.

| Policyholder's Signature<br>Date & Time: | Driver's Signature<br>(If driver is not the policyholder)<br>Date & Time: 24/01/2019<br>12:40 | Reporting Centre Personnel's Signature<br>Name:<br>NRIC/FIN No.: |
|---|---|---|

**SKETCH PLAN**




**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

I was driving the vehicle SGE9500E out of a car park at Block 86, Lorong 4, Toa Payoh. A van which was parked on the left started reversing out.
I pressed the brake and the horn to avoid a collision with the van, but the van did not stop.
The left rear corner of the van hit the left front corner of the car.
The driver of the van came out and apologised to me for causing the accident.

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

| Policyholder's Signature | Driver's Signature | Reporting Centre Personnel's Signature |
|---|---|---|
| Date & Time: | (If driver is not the policyholder) | Name: |
| | Date & Time: 24/01/2019 12:50 | NRIC/FIN No.: |

AIG

# CERTIFICATE OF INSURANCE

## CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

| | | | |
|---|---|---|---|
| **Name of Policyholder** | : Lim Mei Ying Veronica | **Vehicle No.** | : SGE9500E |
| **Period of Insurance** | : 10 Mar 2018 To 09 Mar 2019 | **Policy No.** | : 2100455706-02 |
| **Engine No.** | : 3A92UCX1877 | **Endorsement No.** | : |
| **Chassis No.** | : MMBSTA13AFH018933 | **Issued Date** | : 19 Feb 2018 |

## ABOUT THE COVER

Make/Model : MITSUBISHI ATTRAGE 1.2 CVT

Engine Capacity/Tonnage : 1,193.00 CC | Sum Insured : Market Value | First Year of Registration : 2016

Driver Restriction : NA | Off Peak Car : No | Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of $3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

## EXCESS

**Section 1**
Fire - $0 Own Damage - $600 Theft - $0 Flood Cover - $0

**Section 2**
Property Damage - $0

**Windscreen :** $100

Named Driver and Excess (where applicable)

Lim Mei Ying Veronica - $600 (Own Damage)

## APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1.Cycle & Carriage Customer Service Centres (For windscreen claim only) Add: 20 Leng Kee Rd Singapore 189094 64708886
2.Cycle & Carriage Customer Service Centre (For windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
3.Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65884501

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

## IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

1000837863/AC4

0500720721

CYCLE & CARRIAGE - LO (MIT)
239 ALEXANDRA ROAD
SINGAPORE 159930 ANSP - MOTOR
**Underwritten by AIG Asia Pacific Insurance Pte. Ltd.**

**AIG Asia Pacific Insurance Pte. Ltd.**
AUTHORISED REPRESENTATIVE
AIGSGMOBILEAPP

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S1543952A

Name

SEET CHIM SENG CHARLES

Birth Date: 01 Jun 1962

Issue Date: 11 Feb 2004

001116429B

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1543952A

Name

SEET CHIM SENG CHARLES

薛 深 成

Race

CHINESE

Date of birth

01-06-1962

Sex

M

Country/Place of birth

MALAYSIA

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

| | | PASS DATE |
|---|---|---|
| Class 3 | Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms | 18 Jun 1990 |

FOR C&C USE ONLY

Licence No: S1543952A

NP 428A

5750376

NRIC No. S1543952A

Date of issue

01-06-2017

Address

316B THOMSON ROAD
SINGAPORE 307660

CYCLE & CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI MOTORS

## ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | |
|---|---|---|
| Lim Mei Ying Veronica | Cust No/Name | /Lim Mei Ying Veronica |
| 21 Cluny Hill | Reg No/Reg Date | SGE9500E / 10/03/201 |
| Singapore 259660 | Date In/Mileage | / 0 |
| | Chassis No | MMBSTA13AFH018933 |
| | Engine No | 3A92UCX1877 |
| Contact No Mobile: 98500200 | Make/Model | MIT/ATTRAGE 1.2 CVT MIVEC |
| | Colour/Trim | U01 / BK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|---|---|---|---|---|---|
| CSM00041 | Cash | 24/01/2019/ 13:55 | | 465 / Tay Jian Ye | 35688 |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|---|---|---|---|---|
| E PNT88000 | | | | 1100 ~~1680.00~~ |
| TO RENEW FRT BUMPER . FRT LH FENDER | | | | |
| E PNT98000 | | | | 840 ~~1260.00~~ |
| PAINT WORK SPRAY FRT BUMPER, FRT LH FENDER | | | | |
| A 54900099 | | | | 30.00 |
| CHECK WIRING AND CHASSIS ELECTRICALSYSTEM | | | | |
| A 10028901 | | | | 200.00 |
| TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST | | | | |
| USING HI-SCAN PRO TEST | | | | |
| A WHEELALIGNMENTBP | | | | 120.00 |
| To Conduct Computerize Full Wheel Alignment | | | | |
| M SUNDRY | | | | 50 ~~60.00~~ |
| TO TRANSFER FRT LH TYRE TO NEW RIM AND BALANCING | | | | |
| M SUNDRY | | | | 40.00 |
| TO APPLY ANTI COROSSION | | | | |
| M SUNDRY | | | | 20.00 |
| SUNDRIES new | | | | |
| M FACE,FR BUMPER ~~DE~~ | 1.00 | 696.00 | 00.00 | 696.00 |
| M BRACKET,FR BUMPER,LH new | 1.00 | 13.00 | 00.00 | 13.00 |
| M GARNISH,FR BUMPER,LH ? X SU | 1.00 | 126.00 | 00.00 | 126.00 |
| M CLIP,FR BUMPER new | 10.00 | 3.00 | 00.00 | 30.00 |
| M FENDER,FR LH BF | 1.00 | 458.00 | 00.00 | 458.00 |
| M EMBLEM ECO (~~LH & RH~~) X | 1.00 | 34.00 | 00.00 | 34.00 |
| M HEADLAMP ASSY,LH CRA | 1.00 | 654.00 | 00.00 | 654.00 |
| M WHEEL,DISC FRT LH cut | 1.00 | 680.00 | 00.00 | 680.00 |

14/2/19

SURVEYOR NAME : RASUL-Hp 90010068

SURVEYOR SIGNATURE :

DATE : 13/02/19 @1510

REMARKS : 5 days

Reserve bk parts

Confirm & accepted by

6133

| | | |
|---|---|---|
| | Nett | 6,071.00 |
| 7% GST on | 6071.00 | 424.97 |
| | Total Payable | 6,495.97 |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

CYCLE & CARRIAGE | Exceptional Journeys

Surveyor : RASUL - LKK
Company : TP CHINA TAIPING
Emailed : 22/04/19, 10am
Date survey : 13.02.2019

VEHICLE NO : SGE 9500 E

MODEL : MIT ATTRAGE 1.2

WIP : 35688

| | | |
|---|---|---|
| Material | : $ | 2,593.00 |
| Labour | : $ | 2,400.00 |
| Sub-Total | : $ | 4,993.00 |
| | : | - |
| Less Excess | : $ | - |
| Total | : $ | 4,993.00 |
| GST 7% | : $ | 349.51 |
| Grand Total | : $ | 5,342.51 |
| Finalise By/Date | : | LOI / 22/04/2019 |

[✓] REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

[ ] SURVEYOR'S REPORT REQUIRED

[✓] REPAIR TOOK 5 WORKING DAYS + 2 Days ( 1 ) Weekends
+ 0 Days ( 0 ) Public Holiday
TOTAL DAYS REPAIR TOOK = 7

[✓] TP claim GZ6379Z

[✓] Claim GIA / LTA fee $2.00

[✓] Claim Loss of [ ] Use / [✓] Rental

[ ] Claim Medical Fee / Others

[ ] Third Party Report -

CYCLE & CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI MOTORS

## PRO-FORMA INVOICE

Co Reg No : 197701469G **THIS IS NOT AN OFFICIAL TAX INVOICE** GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | |
|---|---|---|
| Lim Mei Ying Veronica | Cust No/Name | /Lim Mei Ying Veronica |
| | Reg No/Reg Date | SGE9500E / 10/03/2016 |
| 21 Cluny Hill | Date In/Mileage | 13/02/2019/ 38414 |
| Singapore 259660 | Chassis/Package | MMBSTA13AFH018933 |
| | Engine No | 3A92UCX1877 |
| Contact No *Mobile: 98500200 | Make/Model | MIT/ATTRAGE 1.2 CVT MIVEC |
| 13/02/ | Colour/Trim | U01 / BK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|---|---|---|---|---|---|
| CTP00040 | Cash | 22/04/2019/ 18:57 | TLT | 260 / AiTing | 35688 |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|---|---|---|---|---|
| E PNT88000<br>REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, LH FRONT FENDER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME | | | | 1100.00 |
| E PNT98000<br>RESPRAY FRONT BUMPER, LH FRONT FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME | | | | 840.00 |
| A 54900099<br>CHECK WIRING AND CHASSIS ELECTRICALSYSTEM | | | | 30.00 |
| A 10028901<br>CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE | | | | 200.00 |
| A WHEELALIGNMENTBP<br>CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT | | | | 120.00 |
| M SUNDRY<br>APPLY ANTI COROSSION | | | | 40.00 |
| M SUNDRY<br>SUNDRIES | | | | 20.00 |
| S SPECIALISTJOB<br>REPLACE LH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING | | | | 50.00 |
| X FACE,FR BUMPER | 1.00 | 696.00 | 00.00 | 696.00 |
| X BRACKET,FR BUMPER,LH | 1.00 | 13.00 | 00.00 | 13.00 |
| X CLIP,FR BUMPER | 10.00 | 3.00 | 00.00 | 30.00 |
| X FENDER,FR LH | 1.00 | 458.00 | 00.00 | 458.00 |
| X HEADLAMP ASSY,LH | 1.00 | 654.00 | 00.00 | 654.00 |
| X WHEEL,DISC FRT LH | 1.00 | 680.00 | 00.00 | 680.00 |
| X COVER,HEADLAMP SUPT PANEL → Supp. | 1.00 | 62.00 | 00.00 | (A) 62.00 |
| Z TEXT<br>TP CLAIM CHINA TAIPING GZ6379Z<br>DOA : 23.01.19<br>SURVEYOR RASUL LKK 13.02.19<br>REPAIR 05 DAYS | | | | |

*Cycle & Carriage celebrates 120 years.*
*Visit www.cyclecarriage.com/120 for more info!*

Pro Forma

| | | | |
|---|---|---|---|
| Parts | 2,593.00 | Nett | 4,993.00 |
| Labour | 2,290.00 | 7% GST on 4993.00 | 349.51 |
| Standard Menu | 0.00 | | |
| Specialist Job | 50.00 | Total Payable | 5,342.51 |
| Diagnostics Job | 0.00 | | |
| Sundry/Others | 60.00 | | |
| Total(w/o GST) | 4,993.00 | | |

This is not an official tax invoice.
This is a computer generated document, no signature is required.

CYCLE & CARRIAGE | Exceptional Journeys

INSURANCE CO. : **CHINA TAIPING**

Supplementary Parts For Registration No.: **SGE 9500 E**

| | Material | Cost ($) |
|---|---|---|
| 1 | Cover, headlamp supt panel | 62.00 |
| | Total Taxable | 62.00 |
| | 7% GST | 4.34 |
| | **Grand total** | **66.34** |

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

LOI AI TING
CUSTOMER SERVICE ADVISOR
DID : 6568 45556 / 6568 4501
FAX : 6567 5258 / 6565 1240

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI19001923/R1TD3N2
**Date:** 13/05/2019

## REFERENCE

| | | | | | |
|---|---|---|---|---|---|
| **Handling Insurer:** | China Taiping Insurance (Singapore) Pte. Ltd. | **Policy No:** | NA | | |
| **Claimant Vehicle No :** | SGE9500E | **Insured Vehicle No :** | GZ6379Z | | |
| **Date of Loss:** | 23/01/2019 | **Nature of Claim:** | TP | **Claim No:** | SNM19D200449 |

## DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|---|---|---|---|
| **Reg No:** | **SGE9500E** | | |
| **Make & Model:** | MITSUBISHI ATTRAGE, 1.2 CVT (A) | **Engine No:** | 3A92UCX1877 |
| **Reg. Date:** | 10/03/2016 (Man. Year: 2015) | **Chassis No:** | MMBSTA13AFH018933 |
| **Colour:** | Grey | **Odometer:** | 38414 km |
| **Engine Capacity:** | 1193 cc | | |
| **Market Value/New Car Price:** | N/A | | |
| **Sum Insured (S$):** | **Market Value/New Car Price** | | |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|---|---|---|---|---|---|
| **General Condition:** | | **Steering (Serviceable):** | Yes | **Footbrake (Serviceable):** | Yes |
| **Handbrake (Serviceable):** | Yes | **Engine Modification:** | No | **Pre-accident Condition:** | |

## CONDITION OF TYRES

| | | | |
|---|---|---|---|
| **Front Tyre Size:** | 185/55R15 | **Rear Tyre Size:** | 185/55R15 |
| **Front Left Side:** | Yokohama 5 mm | **Rear Left Side:** | Yokohama 5 mm |
| **Front Right Side:** | Yokohama 5 mm | **Rear Right Side:** | Yokohama 5 mm |

*The above values represent the remaining tyre treads depth*

| **COST OF CLAIMS** | **Repairer's** | **Adjuster's** | **Difference** | **Diff %** |
|---|---|---|---|---|
| Parts | 2,773.00 | 2,613.00 | 160.00 | 5.77 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,360.00 | 2,380.00 | 980.00 | 29.17 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| **Gross Total (S$)** | **6,133.00** | **4,993.00** | **1,140.00** | **18.59** |
| **+ GST 7.00/7.00% (S$)** | 429.31 | 349.51 | 79.80 | 18.59 |
| **Nett Amount (S$)** | **6,562.31** | **5,342.51** | **1,219.80** | **18.59** |

## INSPECTION

**Date of Assignment:** 29/01/2019
**Date Inspected:** 13/02/2019 **Inspected At:** Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339

**Estimated Period of Repair:** 5.0 days

**Adjuster:** MOHD RASUL

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

| | | |
|---|---|---|
| **Part Source:** | | (Last Synchronised: 13 May 2019) |
| **Parts:** | N/A | MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database) |
| **Labour:** | Repairer's | (Price-denominated Standard List) |
| **Print Code:** | (Unsubmitted, no print-code for SGE9500E) | |
| **Validity:** | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| **Further Info:** | Items/values not in reference catalogue are prefixed with an asterisk *. | |

## Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|---|---|---|---|---|---|---|
| 1 | 1 | | ***FACE,FR BUMPER** | Deformed | 696.00 FS | *696.00 FS |
| 2 | 1 | | ***BRACKET,FR BUMPER,LH** | Necessary | 13.00 FS | *13.00 FS |
| 3 | 1 | | ***GARNISH,FR BUMPER,LH** | Serviceable | 126.00 FS | *- FS |
| 4 | 10 | | ***CLIP,FR BUMPER** | Necessary | 30.00 FS | *30.00 FS |
| 5 | 1 | | ***FENDER,FR LH** | Bent | 458.00 FS | *458.00 FS |
| 6 | 1 | | ***HEADLAMP ASSY,LH** | Cracked | 654.00 FS | *654.00 FS |
| 7 | 1 | | ***WHEEL,DISC FRT LH** | Cut | 680.00 FS | *680.00 FS |
| 8 | 1 | | ***COVER,HEADLAMP SUPT PANEL** | Cracked | 62.00 FS | *62.00 FS |
| 9 | 1 | | ***SUNDRIES** | Necessary | 20.00 FS | *20.00 FS |
| 10 | 1 | | ***EMBLEM ECO** | Not Necessary | 34.00 FS | *- FS |
| | | | | **Total Parts (S$)** | **2,773.00** | **2,613.00** |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

**There are no new miscellaneous items selected.**

## Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---|---|---|---|---|
| **Labour Items** | | | | |
| 1 | TO RENEW FRT BUMPER,FRT LH FENDER | New | 1,650.00 | 1,100.00 |
| 2 | PAINT WORK SPRAY FRT BUMPER,FRT LH FENDER | New | 1,260.00 | 840.00 |
| 3 | CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM | New | 30.00 | 30.00 |
| 4 | TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | New | 200.00 | 200.00 |
| 5 | TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT | New | 120.00 | 120.00 |
| 6 | TO TRANSFER FRT LH TYRE TO NEW RIM AND BALANCING | New | 60.00 | 50.00 |
| 7 | TO APPLY ANTI COROSSION | New | 40.00 | 40.00 |
| | | **Gross Labour Cost (S$)** | **3,360.00** | **2,380.00** |

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**