22/03/2002

ASS. REC. BY: | REF: CS/QBE 19062126/T/sd3 | Special Instruction:

Surveyor: Tauhich

ASSIGNMENT (Office)

From (Person): Joyce Foo of QBE Date/Time: 1/2/19 @ 9-50am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLS125G Insured:

at Workshop m/s performance Tel: 91165600

of 303 Alexandra Road

Policy No: Claim No: VC012280

Sum Insured: Excess: $600.00

Make of Veh: D.O.A 29/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 10.06am @ 1/2/19 Person Contacted: Kevin Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLS125G-x

Surveyor: Taylor | REF: QBE

ASSIGNMENT

From: | Date: 1/2/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLS125G

at Workshop n/s: Performance Motor

of: 303 Alexandra Rd

Insured:

Policy No:

Claims No:

Sum Insured: | Excess: $600.00

(Client's Record)

Make of Veh: Kevin

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: $220K.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / RF / REP. / 24 HRS

Vehicle: IN / OUT

Date: | Person Contacted: Kevin

Veh No: SLS125G | Yr Regn: 2016 Sep

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: BMW 730 SR. | c.c: 1998

Colour: Black | A/C: Insured / Std / NI / NA

Sp.Reading: — | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA7E02070G245220

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/50R18

R: " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Hankook.

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	1/2/19@2.45pm

Survey held at: PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Not Authorise, may claim TP, checking Liability. Please be inform that we are recommending total loss for this vehicle as we find both chassis of vehicle was badly damaged and needs to be replaced as they are made of aluminium.
	Submit Total Loss as chassis unsafe to repair. MV - $220k, CTA - $120,536.00 } Nett - $99,464.00
	26/2/2019

Date/Time, File Pass to?: 26/02/19 Typ.st

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☑ : Final Report

RECEIVED 26 FEB 2019

Days Of Repair: 20

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp ($ ☐ Interview ($ ☐ Tech. Invs ($ ☐ Weekend ($

Survey Fee: 300

Transportation:

1) S + RS S

2) Photos

3) Other

4)

TOTAL

Report Format: Total Loss

Lump Sum / I.B.I: ($

Shirley Hiew (LKK Auto)

From: Kevin Leong Wai Kit <kevin.leong.waikit@simedarby.com.sg>
Sent: Thursday, 21 February 2019 3:40 PM
To: SUR
Subject: RE: Accident involving : SLS125G
Attachments: 2ac62709-0850-4ac1-94dd-8c1ae9f6173e.jpg; 2b021249-4ecd-431a-84ea-1952ecaf3bd0.jpg; 73fe9ab5-2c84-4665-8094-3f9bd21233e3.jpg; 99cbf8b5-8e31-41ab-84a4-9f122747aa94.jpg; 301d8166-e4c3-46f4-955d-afdfcba7f25d.jpg; a05adb70-f919-423b-9034-b50c4aaf81f2.jpg; b4335136-f887-43dc-8a49-5a76de3009d1.jpg; bf9e8db1-71fa-4a23-822e-5f1b84ca5899.jpg; bf895eab-6123-46a2-911f-47e39623f655.jpg; d2e6ad79-c43f-44ff-81c9-7414bfc55162.jpg; d22b5c18-70ee-493a-8914-82e137ba2590.jpg

Dear All,

Just to inform that we are unable to continue to repair this vehicle as both of the front chassis is badly damaged.
We will need to replace both front chassis to continue for completion of repair.
However, we understand that, LTA only allow to replace either one side of the front chassis only.
We have also inform the surveyor to take photo on the damage.
Kindly inform QBE on current situation.

Thank you

Regards,

Kevin Leong
Customer Service Advisor | Body and Paint
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Hp (+65) 9116 5600 | Fax (+65) 6479 4601
Kevin.leong.waikit@simedarby.com.sg



From: Syaheeda Nacah Binte Mohamed Othman [mailto:syaheeda.othman@qbe.com]
Sent: Friday, February 01, 2019 10:09 AM
To: Mervyn Fong; Kevin Leong Wai Kit
Cc: Young May
Subject: RE: Accident involving SLS125G

Received with thanks, sir.

Best Regards,

Syaheeda Othman
Senior Executive, Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
Direct Line: +65- 6477 1130
Email: syaheeda.othman@qbe.com
Visit us on the web at www.qbe.com.sg

From: Mervyn Fong <fongmervyn@hotmail.com>
Sent: Friday, 1 February 2019 10:02 AM
To: kevin.leong.waikit <kevin.leong.waikit@simedarby.com.sg>; Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>
Cc: Young May <youngmay88@hotmail.com>
Subject: Accident involving SLS125G

Hi Kevin and Eda

Attached please find the downloaded attachment of the accident.

Let me know if you need anything else.

Thanks
Mervyn Fong/Young Woo Cheng

--
Sent from myMail for Android

-------- Forwarded Message -------- From: Mervyn Fong fongmervyn@hotmail.com To: Mervyn Fong fongmervyn@hotmail.com Date: Friday, 01 February 2019, 09:56am +08:00 Subject: Document from Mervyn

> 44858138_286041495403571_5643181065154796783_n.mp4
>
> --
> Sent from myMail for Android

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 22 February 2019 10:26 AM
To: 'Joyce Foo'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: ODUL Claim - SLS125G - D.O.A : 29/01/19

Dear Joyce,

Please be inform that the vehicle recommended total loss due to the front chassis is badly damaged.

We will submit our report accordingly.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Thursday, 7 February 2019 3:40 PM
To: 'Joyce Foo' <joyce.foo@qbe.com>
Cc: SUR <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: ODUL Claim - SLS125G - D.O.A : 29/01/19

Dear Joyce,

Enclosed preliminary revised of vehicle SLS 125G
Date of survey: 01/02/2019
Number of days : 20 days

We have authorise repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 7 February 2019 3:40 PM
To: 'Joyce Foo'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: ODUL Claim - SLS125G - D.O.A : 29/01/19
Attachments: SLS 125G - Preli Advise.pdf

Dear Joyce,

Enclosed preliminary revised of vehicle SLS 125G
Date of survey: 01/02/2019
Number of days : 20 days

We have authorise repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 1 February 2019 10:11 AM
To: 'Joyce Foo' <joyce.foo@qbe.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: ODUL Claim - SLS125G - D.O.A : 29/01/19

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupei@lkkauto.com>
Sent: Friday, 1 February 2019 9:50 AM
To: assignments
Subject: FW: ODUL Claim - SLS125G - D.O.A : 29/01/19
Attachments: SAS2545095.PDF; C.IDL.pdf; est.pdf

Best Regards,

Shu Pei| Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupei@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joyce Foo <joyce.foo@qbe.com>
Sent: Friday, 1 February 2019 9:49 AM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: ODUL Claim - SLS125G - D.O.A : 29/01/19

Our Ref. VC012280

Hi

Please assist to arrange for OD survey. Policy excess - $600.00

Kindly survey and authorise.

Thanks & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg

From: Syaheeda Nacah Binte Mohamed Othman
Sent: Friday, 1 February 2019 9:40 AM
To: Joyce Foo <joyce.foo@qbe.com>
Subject: FW: ODUL Claim - SLS125G - D.O.A : 29/01/19

Best Regards,

Syaheeda Othman
Senior Executive, Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
Direct Line: +65- 6477 1130
Email: syaheeda.othman@qbe.com
Visit us on the web at www.qbe.com.sg

From: Kevin Leong Wai Kit <kevin.leong.waikit@simedarby.com.sg>
Sent: Friday, 1 February 2019 7:40 AM
To: claims-singapore@qbe.com
Cc: Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>
Subject: ODUL Claim - SLS125G - D.O.A : 29/01/19

Dear All,

Kindly refer to above attach ODUL Claim for : SLS125G
Please arrange for survey by today.
Car already in workshop.

Thank you

Regards,

Kevin Leong
Customer Service Advisor | Body and Paint
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Hp (+65) 9116 5600 | Fax (+65) 6479 4601
Kevin.leong.waikit@simedarby.com.sg



"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or

other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 7 February 2019 3:40 PM
To: 'Kevin Leong Wai Kit'
Cc: 'sur@lkkauto.com'; 'PBSP'
Subject: SLS 125G OD (QBE)

Dear Kevin,

As instructed by our client, please proceed to repair the insured vehicle **SLS 125G (Excess $ 600/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: VC012280

Date: 07 February 2019

Our Ref: CS/QBE19002126/T1sd3

The Motor Claims Department
QBE INSURANCE (SINGAPORE) PTE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLS 125G .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 01/02/2019 at the premises of M/s Performance Motors Limited and have the following to report:-

Workshop Estimate Amount	: S$ 69,802.40 .
Revised Estimate Amount	: S$ 50,121.90 .
"Check" Items Amount	: S$ 15,731.45 .
Total	: S$ 65,853.35 .
Market Value	: S$ 220,000.00 .
LTA Reimbursement Value	: S$ 120,536.00 .
Nett Value	: S$ 99,464.00 .

Description of Damage:
The vehicle sustained damages at the front portion.



Comments/ Present Status:
Damages Consistent.
Repair cost economical, we have authorise repair
Repair days: 20 Days

Yours faithfully,
Mohamad Taufikh
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	30/01/2019 11:15
Date Of Accident	29/01/2019 19:55
Exact Location Of Accident	JUNCTION OF HENDERSON RD & JLN BUKIT MERAH
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLS125G
Insured/Policyholder	
Name Of Registered Owner	YOUNG WOO CHENG
NRIC No	S1284885D
Email Address	YOUNGMAY88@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-81388399
Alternative Phone No	OFFICE-64021111
Vehicle Particulars	
Manufacturer	BMW
Model	730LI-3.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	QBE INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	8-V0018542-MVA
Cover Note Number	
Driver	
Name of Driver	YOUNG WOO CHENG
NRIC No	S1284885D
Date Of Birth	12/06/1958
Occupation	INDOOR
Date Of Driving Pass	01/01/1980
Driving Experience	39 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-81388399
Fax Number	
Contact Number	OFFICE-64021111
EMail Address	YOUNGMAY88@HOTMAIL.COM

Address	38 DUCHESS AVENUE
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TAN SIEW NGOH CHRISTINA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes,Please state which Police Station	
Police Station Name	BUKIT TIMAH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	**ROAD**: 1 DUKE ROAD , **POSTCODE:** 268914 , **COUNTRY**: SINGAPORE
Police Station Contact	**TEL NO**: 1800-4629999 - **FAX NO**: 64628933
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

REFER TO STATEMENT & POLICE REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA9457G
Vehicle Make/Model/Colour	HYUNDAI AE IONIQ
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	LIM HOCK KEE
NRIC/Passport Number	S7109611D
Contact Number	
Address	
Postcode	

Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1	
Name	YOUNG WOO CHENG
Approximate Age	61
Injuries Sustain	RIGHT ARM
Injured person in which vehicle?	SLS125G
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	38 DUCHESS AVENUE
Postcode	269110

DETAILS OF INJURED PERSON 2	
Name	TAN SIEW NGOH, CHRISTINA
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLS125G
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Henderson Road in the direction of Telok Blangah. The traffic light at the junction of Henderson Road + Jln Bukit Merah was showing "green" for me so I proceeded on. Suddenly a Comfort taxi SHA9457G appeared from the Jalan Bukit Merah side, even though I had the "green" light + right of way. I tried to brake, but it was too late and my car collided with the taxi. Subsequently I was told by the driver that he had made a mistake and was not concentrating + assumed the road was green in his favor. He apologised for his mistake.

Police arrived on the scene, and they called an ambulance to send me and my passenger to the hospital.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORTDELGRO ENGINEERING PTE LTD
383 SIN MING DRIVE
SINGAPORE 575717

Policyholder's Signature	Driver's Signature	Reporting Centre Personnel's Signature
Date & Time: 30/1/19 11.05am	(If driver is not the policyholder)	Name:
	Date & Time:	NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

   I understand, acknowledge, agree and consent that:

   (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

   (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

   (ii) investigating the accident and/or my claims;

   (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

   (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

   (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")

   (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

   (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

   (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

   (e) the information so collected under (d) above may be shared / disclosed:

   (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

   (ii) for complying with requirements under any regulations, laws or court orders.

COMFORTDELGRO ENGINEERING PTE LTD
383 SIN MING DRIVE
SINGAPORE 575717

Policyholder's Signature Date & Time: 30/1/19 11.05am	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: Mary NRIC/FIN No.:

SINGAPORE POLICE FORCE

T/20190130/2031

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

Report No. T/20190130/2031

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:	Vide Report No.:	Station Diary No.:
30/01/2019 10:20	D/20190129/0118	38

Informant's Particulars

Name of Informant: YOUNG WOO CHENG			Address: 38 DUCHESS AVENUE SINGAPORE 269110	
ID Type / ID No.: NRIC NO / S1284885D			Contact No.: Home/Office:	Mobile: 81388399
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Female	Age: 60	Date of Birth: 12/06/1958	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: HOUSEWIFE			Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 29/01/2019 19:55	Type of Location: X-Junction

Location:
Along Road 1
HENDERSON ROAD

At the junction of Henderson Road and Jalan Bukit Merah

Weather:	Road Surface:	Road Speed Limit:
Clear	Dry	50 Km/h
Traffic Flow: One Way	Traffic Control:	Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side		Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHA9457G	Car	HYUNDAI	AE IONIQ HEV 1.6 DCT	Yellow	Seriously Damaged	1
SLS125G	Car	BMW	730LI LED NAV HUD SR	Black	Seriously Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date

SINGAPORE POLICE FORCE

T/20190130/2031

Report No. T/20190130/2031

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLS125G	QBE Insurance (Singapore) Pte Ltd	V0018542	30/09/2018	29/09/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LIM HOCK KEE	ID No.	S7109611D
Related Vehicle	SHA9457G (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	YOUNG WOO CHENG	ID No.	S1284885D
Related Vehicle	SLS125G (Car)	Contact No.	81388399
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details.

On 29/1/2019, at about 1955hrs while I am driving Black BMW 730LI LED NAV, SLS125G at the junction of Henderson Road and Jln Bukit Merah on the right of a two lane road. The traffic light signal Green and I wanted to proceed straight. While proceeding straight This Yellow Hyundai AE IONIQ, SHA9457G Suddenly came from the right even though the traffic light was red and my vehicle collided into his vehicle.

There is camera around the vicinity which focus at the collision place and there is In built camera inside the taxi too.

Both of us did exchange the particular after the scene.

At that point of time A TP was at scene and ambulance was called in to convey my passenger namely Tan Siew Ngoh, Christina was conveyed to SGH after the Collison.

Subsequently I felt pain as such I went to SGH and the doctor informed there was a fracture on my Right

SINGAPORE
POLICE FORCE

T/20190130/2031

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

CONTINUATION OF REPORT

wrist.

Damages to my vehicle
Front bumper, engine and bayonet seriously damaged and dented

Damages to the yellow taxi
Side left seriously dented and damaged

SINGAPORE POLICE FORCE

T/20190130/2031

Report No. T/20190130/2031

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: E / Sgt 2 LUI CHONGLU	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 30/01/2019 10:20
Officer In Charge Of Case: TP / AEIT / Sr Staff Sgt ONG YONG HOCK Contact No.: 65476436	Classification Of Case:
Authentication Stamp NP168	SIGNATURE

GENERAL INSURANCE ASSOCIATION
RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 – 17:00
UEN: S66SS0020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the **same** Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MCD 119014188 Vehicle Registration No: SLS 125G

Name(as shown in NRIC) : Young Woo Cheng NRIC/FIN/Passport No : S1284885D

(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate

Address : 38 Duchess Avenue Singapore(269110)

Contact (Tel) : Mobile No. : 81388399

Email Address : YOUNGMAY88@HOTMAIL.COM

Date of Accident : 29/1/19 Time of Accident : 19.55

Place of Accident : Junction of Henderson Rd & Jln Bukit Merah

Insurance Company : QBE

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Changing from : 3rd Party claim
↓
Own damage claim with uninsured losses

Policyholder / Driver's Signature
Date:

COMFORTDELGRO ENGINEERING PTE LTD
383 SIN MING DRIVE
SINGAPORE 575717

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	4885D

Vehicle Details

Vehicle No.:	SLS125G
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Jan 2019
Vehicle Make:	B.M.W.
Vehicle Model:	730LI LED NAV HUD SR
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	27849672B48B20B
Chassis No.:	WBA7E02070G245220
Maximum Power Output:	190.0 kW (254 bhp)
Open Market Value:	$72,535.00
Original Registration Date:	30 Sep 2016
First Registration Date:	30 Sep 2016
Transfer Count:	1
Actual ARF Paid:	$102,563.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2026
PARF Rebate Amount:	$76,922.00

Intended COE Rebate Details

COE Expiry Date:	29 Sep 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	$56,889.00
COE Rebate Amount:	$43,614.00
Total Rebate Amount:	**$120,536.00**

The information contained herein is correct as at 30 Jan 2019

OK

- GrabHitch/RYDE-car pooling services
- Volkswagen Sharan..
- Carpark that only accept cashcard (with chip)

Post an Advertisement
Sell it yourself! Advertise it at just
$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Sep 16 A200 AMG kit, 1 owner, 2.28% interest, PROMO

FREE Polishing & Coating + Grooming Worth $500+! 2.28% interest, Flexible loan!
Believ1n Automobile StarAd

Browse by Category

Sort by Date Posted | 20 results/page

5 vehicles

BMW 730

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	BMW 730		Any	Any	2016	Any	Any	Any	Available

BMW 7 Series 730i Sunroof $215,800 $22,220 /yr 29-Jul-2016 1,998 cc 13,500 km Luxury Available

Promotion 1.98% Interest Rate! 5 Years PML Warranty, Fully Maintained By PML. Nice Number Plate, Pristine White Paintwork With Posh Black Leather Interior. Expect BMW's Premium Quality Finishes In Thi...

PREMIUM AD

Auto Zoom Enterprise Pte Ltd

Posted: 30-Jan-2019 Tags: 2016 BMW 730i, 2016 bmw 730i, BMW 730i, bmw 730i, BMW, 730i, Used BMW

BMW 7 Series 730Li Sunroof $239,999 $24,100 /yr 28-Nov-2016 1,998 cc 62,000 km Luxury Available

1 Owner, Agent Warranty! Immaculate Condition! Sporty Brown Exterior And Beige Interior! Premium Owned 110 Points Check. Flexible Financing Package And Trade In. Please SMS Or Call Mobile For Viewing,...

PREMIUM AD

Premium Automobiles

Posted: 23-Jan-2019 Tags: 2016 BMW 730Li, 2016 bmw 730li, BMW 730Li, bmw 730li, BMW, 730Li, 730li, Used BMW

BMW 7 Series 730Li Sunroof $229,800 $24,140 /yr 29-Jul-2016 1,998 cc 19,138 km Luxury Available

Latest Certified Pre-owned BMW G12/730Li In The Market. The Epitome Of Luxury And Driving Dynamics Clad In Sapphire Black With Dakota Can Beige Interior. Soft Door Closing, BMW Comfort Access. View An...

PREMIUM AD

Posted: 20-Jan-2019 Tags: 2016 BMW 730Li, 2016 bmw 730li, BMW 730Li, bmw 730li, BMW, 730Li, 730li, Used BMW

BMW 7 Series 730Li Sunroof $248,800 $26,400 /yr 23-Aug-2016 1,998 cc 16,000 km Luxury Available

Latest G12 Model, 1 Owner, 100% Accident Free, Low Mileage Done 6400Km Annually, 3 Years Or 100000km Warranty By PML Motor, Sporty Black In Colour, Condition Like New, Please Call For Viewing And Enqu...

Hin Lung Auto Pte Ltd

Posted: 20-Jan-2019 Tags: 2016 BMW 730Li, 2016 bmw 730li, BMW 730Li, bmw 730li, BMW, 730Li, 730li, Used BMW

BMW launches the all new 7 Series

The new BMW 7 Series sets out its stall as the ultimate vehicle for luxurious driving pleasure with more technological advancements.

Read this article

BMW 7 Series 730Li Sunroof $248,888 $25,580 /yr 21-Oct-2016 1,998 cc 26,000 km Luxury Available

Full Agent Serviced, Genuine Mileage, Latest Model BMW G12/730Li, Owner Consignment. Strictly By Appointment. Call Now.

Posted: 29-Nov-2018 Tags: 2016 BMW 730Li, 2016 bmw 730li, BMW 730Li, bmw 730li, BMW, 730Li, 730li, Used BMW

Save this search criteria, to get email alerts whenever a match is found.

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status

For Compare ired ads

20 results/page

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

01 FEB 2019

E S T I M A T E

Estimate No. : b1 49972
Date Estimated : 31/01/2019
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 7

- ESTIMATE REPAIR FOR -
Young Woo Cheng
38 Duchess Avenue

Singapore 269110

- ACCOUNT - 84
QBE Insurance (Singapore) Pte Ltd
1 Raffles Quay
#29-10 South Tower
Singapore 048583

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS125G	G245220	30/09/2016	730Li	0

DESCRIPTION		VALUE
To replace frt bumper, bonnet, support, reinforcement, both frt side panels, both chassis support, both fog lights, air ducts, air flaps and all attachments cause by accident.	5950.	6,800.00
Painting on frt bumper, bonnet , both frt side panel & LH 'A' pillar	4301	4,779.00
To replace radiator assembly, fan housing with fan including to conduct pressure test, bleed bleed cooling system and check for leak.	photo ? 710	826.00
To replace charge air cooler including conduct checks for leak and proper function.	photo ? 451	531.00
To replace air con condenser and air con hose including to vacuum system, top up freon gas and check for leak.	852.	1,003.00
To mount accident vehicle on celette bench to facilitate re-alignment of body/chassis according to BMW specification	photo. ?	2,950.00
To replace front dashboard panel and conduct checks for proper function.	677	797.00
To check electrical wiring systems at the front section for proper function.	150.	177.00
To replace left & right headlight.	817	962.00
To replace both front seat belts and tensioners including reset and checks for proper function.	451	531.00
To replace both rear seat belts and tensioners including reset and checks for proper functions.	451	531.00
To replace front dashboard passenger air bag including reset and checks for proper function.	451	531.00

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/630 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49972
Date Estimated : 31/01/2019
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS125G	G245220	30/09/2016	730Li	0

DESCRIPTION		VALUE
To replace front seat crash-active head restraint air bags including reset and conduct check for function.	451	531.00
To replace roof top headlining and both ITS head air bags including reset and checks for proper function.	865	1,018.00
To replace steering wheel and air bag including reset and checks air bag system for proper function.	451	531.00
To carry out body cavity preservation. (Per panel) Bonnet	100	118.00
To carry out body cavity preservation. (Both panel) Frt RH & LH side panel RH-Y LH ✓	~~200~~ 100	236.00
To supply front emboss number plate.	bt✓	83.00
To tow accident vehicle to PML workshop.	/	195.00
Sundries.	/	150.00
Total Labour 1:		**23,280.00**

DESCRIPTION	QTY	PRIC	VALUE
Screw	10	1.85	?18.50
BLIND RIVET	2	1.55	? 3.10
Hex bolt	4	10.90	? 43.60
HEX BOLT M8X75	2	3.05	? 6.10
ISA SCREW M8X100	4	3.45	? 13.80
RADIATOR	1	1,032.65	? 1,032.65
COVER TOP	1	74.95	74.95
COVERING LOWER	1	74.95	74.95
COVERING RH	1	46.50	46.50
COVERING LH	1	46.50	? 46.50
RADIATOR	1	1,147.40	? 1,147.40
HOSE RADIATOR TRANMISSION OIL COOLE	1	100.10	? 100.10
FAN HOUSING WITH FAN	1	1,446.85	? 1,446.85
LH ENGINE HOOD HINGE	1	92.75	bt✓ 92.75
RH ENGINE HOOD HINGE	1	92.75	bt✓ 92.75
FRT LH SIDE PANEL ALUMINIUM	1	1,292.75	bt✓ 1,292.75
FRT RH SIDE PANEL ALUMINIUM	1	1,292.75	RY 1,292.75
FRT LH SIDE PANEL BRACKET 2	1	34.25	wu✓ 34.25
FRT RH SIDE PANEL BRACKET 2	1	34.25	x 34.25
FRT SIDE PANEL BRACKET 3	2	57.05	? 114.10
ALUMINIUM BONNET	1	3,012.85	bt✓ 3,012.85
SET MOUNTS PDC SENSOR FRT	1	69.00	wu✓ 69.00

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49972
Date Estimated : 31/01/2019
Prepared By : Kevin Leong Wai Kit

Page No. : 3 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS125G	G245220	30/09/2016	730Li	0

DESCRIPTION	QTY	PRIC	VALUE
FRT BUMPER BOTTOM CARRIER	1	461.60	461.60
VERTICAL CONNECTION LH	1	19.40	19.40
VERTICAL CONNECTION RH	1	19.40	19.40
GUIDE TOP LH	1	30.35	30.35
GUIDE TOP RH	1	30.35	30.35
ADAPTER LH	1	77.00	77.00
ADAPTER RH	1	77.00	77.00
LH SUPPORT FOG LAMP	1	61.90	61.90
RH SUPPORT FOG LAMP	1	61.90	61.90
IMPACT ABSORBER TOP	1	84.45	84.45
FRT BOTTOM IMPACT ABSORBER	1	70.45	70.45
FRT BUMPER CARRIER	1	839.25	839.25
LH PROTECTIVE STRIP BOTTOM	1	53.25	53.25
RH PROTECTIVE STRIP BOTTOM	1	53.25	53.25
PROTECTIVE STRIP TOP LH	1	86.40	86.40
PROTECTIVE STRIP TOP RH	1	86.40	86.40
BUMPER GUARD CENTRE	1	81.05	81.05
DAMPER KERB DESCENT	2	5.25	10.50
FRT BUMPER PANEL PRIMED (PDC/PMA)	1	1,571.70	1,571.70
FRT BUMPER TOWING LUG COVER PRIMED	1	57.10	57.10
LICENCE PLATE BASE	1	70.65	70.65
GRILLE AIR INLET MIDDLE (PURE EXCEL	1	81.45	81.45
GRILLE AIR INLET LH (PURE EXCELLENC	1	85.10	85.10
GRILLE AIR INLET RH (PURE EXCELLENC	1	85.10	85.10
LH TRIM AIR DUCT SIDE PANEL	1	54.60	54.60
TRIM GRILLE I-CAM	1	21.70	21.70
FRT LH GRILLE (PURE EXCELLENCE)	1	232.30	232.30
FRT RH GRILLE (PURE EXCELLENCE)	1	290.35	290.35
AIR FLAPS TOP	1	330.50	330.50
EMBLEM GROMMET	2	0.80	1.60
BMW EMBLEM	1	71.25	71.25
LOCK LH	1	120.05	120.05
LOCK RH	1	120.05	120.05
HEADLINING LIFT UP & SLIDE BACK SUN	1	1,974.10	1,974.10
INSTRUMENT PANEL (SCHWARZ/COGNAC)	1	4,273.05	4,273.05
CONNECTION REAR TOP	1	147.55	147.55
CONNECTION FRT TOP	1	252.05	252.05
AIR DUCT BOTTOM	1	39.00	39.00
LH HEADLIGHT MOUNTING	1	121.20	121.20
RH HEADLIGHT MOUNTING	1	121.20	121.20
CROSSLINK FRONT	1	220.55	220.55
SUPPORT FRONT PANEL	1	109.95	109.95
Y STRUT	1	27.45	27.45
FRT LH WHEEL ARCH COVER FRT SECTION	1	144.05	144.05
FRT RH WHEEL ARCH COVER FRT SECTION	1	144.05	144.05
COVER BULB REPLACEMENT	2	10.30	20.60
RH TRIM AIR DUCT SIDE PANEL	1	54.60	54.60
COVERING CROSS MEMBER (ECE)	1	33.50	33.50
AIR DUCT RADIATOR TOP	1	61.50	61.50

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 49972**
Date Estimated : **31/01/2019**
Prepared By : **Kevin Leong Wai Kit**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS125G	G245220	30/09/2016	730Li	0

DESCRIPTION	QTY	PRIC	VALUE
AIR DUCT RADIATOR BOTTOM	1	61.50	? 61.50
LH LOCK PANEL	1	29.00	? 29.00
LH LOCK PANEL	1	29.00	? 29.00
LH COVER BOTTOM	1	55.95	? 55.95
RH COVER BOTTOM	1	55.95	? 55.95
SEAL ENGINE HOOD FRT	1	79.25	? 79.25
BONNET SIDE LH GASKET	1	33.70	? 33.70
BONNET SIDE RH GASKET	1	33.70	? 33.70
SEALING SIDE PANEL LH	1	59.45	? 59.45
SEALING SIDE PANEL RH	1	59.45	? 59.45
COVER OF CENTRE ENGINE COMPARTMENT	1	91.00	? 91.00
COVER OF CENTRE ENGINE COMPARTMENT	1	91.00	? 91.00
(DG) REPAIR KIT CRASH ACTIVE HEAD R	2	163.80	act 327.60
LH HEADLIGHT LED AHL HIGH (ICON LIG	1	5,847.60	ona 5,847.60
RH HEADLIGHT LED AHL HIGH (ICON LIG	1	5,847.60	ona 5,847.60
LED MODULE TURN INDICATOR	1	786.65	? 786.65
LED MODULE DAYTIME DRIVING LIGHTS	2	229.10	ant 458.20
CONTROL UNIT FRT LIGHT ELECTRONICS	2	893.90	? 1,787.80
LH FOG LAMP LED	1	459.65	? 459.65
RH FOG LAMP LED	1	459.65	? 459.65
ULTRASONIC SENSOR BLACK	3	248.70	? 746.10
ULTRASONIC SENSOR BLACK	1	248.70	? 248.70
DECOUPING RING PDC TORQUE CONVERTER	2	5.05	ant 10.10
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	ant 20.20
(DG) FRT LH UPPER BELT (SCHWARZ)	1	1,019.45	ant 1,019.45
(DG) FRT RH UPPER BELT (SCHWARZ)	1	1,019.45	ant 1,019.45
RR SAFETY BELT UPPER STRAP (SCHWARZ	2	386.35	ant 772.70
(DG) HEAD AIRBAG LH	1	699.95	ant 699.95
(DG) HEAD AIRBAG RH	1	699.95	ant 699.95
(DG) AIR BAG MODULE FOR PASSENGER S	1	1,399.85	ant 1,399.85
		Total Parts :	**46,522.40**

Claim: OD / 3rd Party / Uninsured losses / Direct Settlement
Regn No. _____ Claim No. _____
Date&Time 1/2/19 @ 2.45pm Excess S$ 600
Surveyor's Name taufiq Sign _____
Surveyor's Tel 97495749 Authorised Yes / No
Authorised Date _____ Time _____
ESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No
taufiq@ikhanto.com
20 days

1/2/19

Labour 1	:	**23,280.00**
Parts	:	**46,522.40**
Labour 2	:	**0.00**
Excess	:	**0.00**
Total GST @ 7%	:	**4,886.17**
Grand Total	:	**74,688.57**

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **