ASS. REC. BY: | REF: CS/CTZ190064435/ Esd3 | Special Instructions:

Sat Veyan Steve

ASSIGNMENT (Office)

From (Person): Chong Boon Sn of CTI Date/Time: 10/4/19 @ 4:00pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV7CS

To Inspect Vehicle No: SKS 2443L Insured: GBC 2807L

at Workshop m/s: Teamwork Tel: 6844 2475

of 53 ubi Ave 1 #01-25

Policy No: Claim No: SNM19D201529

Sum Insured: Excess:

Make of Vehicle (Client's Record): D.O.A. 03/04/2019

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 9.42am @ 11/4/19 Person Contacted: Darren Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	SKS 2443L - VA/INC/19006029/24	DOA - 03/04/2019
	GBC 2807L - VA/INC/19006029/24	DOA - 03/04/2019

Surveyor: Steve | REF: CTI

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s:

of:

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKS 2443L Yr Regn: 31/3/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Volkswagen Jetta cc: 1.4

Colour: White A/C: Insured / Std / NI / NA

Sp.Reading: 95367 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVWZZZ16ZFM002431

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Pirelli

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	3/4/19	D.O.I.	10/4/19

Survey held at: Teamwork

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

MV - SBK

17/4/19 Finalize Contin $2050. 3 days

($3,609.6+ Red - 81%)

18/4/2019

RECEIVED 18 APR 2019

Date/Time: File Pass to? 18/04/19

1) Typist

Date/Time: File Return to?

2)

☐ : Prell. Report

☑ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($

☐ : Interview ($

☐ : Tech Invs ($

☐ : Weekend ($

Survey Fee:

Transportation

) S.R.

) Photos

) Miles

Report Format :

Lump Sum / I.B.I. ($ 2,050/- H/S

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 10 April 2019 4:20 PM
To: claims@teamworkgarage.com
Cc: 'assignments'
Subject: RE: OUR REF: SNM19D201529 -GBC2807L & YR 1904-16 // CCIDENT INVOLVING GBC2807L AND SKS2443L (PRI)

Without Prejudice

Dear Daniel,

Thank you for choosing LKK.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Chong Boon Sen
Sent: Friday, 5 April, 2019 5:22 PM
To: 'claims@teamworkgarage.com' <claims@teamworkgarage.com>
Subject: RE: OUR REF: SNM19D201529 -GBC2807L & YR 1904-16 // CCIDENT INVOLVING GBC2807L AND SKS2443L (PRI)

We refer to the above matter.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG

We refer to the above matter and enclosed herewith our client's GIA report and notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction-Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention.

Regards,

Shu Shan

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0040Z
Vehicle Details	
Vehicle No.:	SKS2443L
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Apr 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA GP 1.4 TSI 90 A/T TL 1632G5
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	CAXF15777
Chassis No.:	WVWZZZ16ZFM002431
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	$17,864.00
Original Registration Date:	31 Mar 2015
First Registration Date:	31 Mar 2015
Transfer Count:	0
Actual ARF Paid:	$7,864.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Mar 2025
PARF Rebate Amount:	$5,898.00
Intended COE Rebate Details	
COE Expiry Date:	30 Mar 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	$64,700.00
COE Rebate Amount:	$38,628.00
Total Rebate Amount:	**$44,526.00**

The information contained herein is correct as at 10 Apr 2019

OK

Post an Advertisement
Sell it yourself! Advertise it at just
$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.5A RSZ

GV Credit Pte Ltd

PRIME MOTOR & LEASING
SCHENG YONG CHEOW ENTERPRISES PTE LTD GROUP OF COMPANIES
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Date Posted | 20 results/page

11 vehicles

Volkswagen Jetta

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Volkswagen Jetta		Any	Any	2015	Any	Any	Any	Availabl

Volkswagen Jetta 1.4A TSI $56,800 $9,000 /yr 27-Jan-2015 1,390 cc 80,000 km Sedan Availabl

Price Negotiable, New Megatronic Unit Done By Agent Volkswagen Singapore With 2 Years Warranty, New Brakes, Tyres And Battery All Changed, No Repair Required, Accident Free. No Dealers Please.

Posted: 29-Mar-2019 Tags: 2015 Volkswagen Jetta, 2015 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen, Jetta, jetta, Used Volkswagen

Volkswagen Jetta 1.4A TSI $58,000 $9,210 /yr 27-Jan-2015 1,390 cc 43,000 km Sedan Availabl

One Of The Most Popular Sedan With Great Fuel Efficiency And Great Power! Maintained Meticulously By Fervent Owner Only With Agent. Well Kept Interior, Always Parked Under Shelter! Low Depreciation! L...

Posted: 05-Mar-2019 Tags: 2015 Volkswagen Jetta, 2015 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen, Jetta, jetta, Used Volkswagen

Volkswagen Jetta 1.4A TSI $58,800 $9,130 /yr 18-Mar-2015 1,390 cc 41,000 km Sedan Availabl

1 Owner, Low Mileage Done, Well Maintained By Previous Owner, 1 Year Warranty Cover Engine And Gear Box, Drive With Peace Of Mind! High Trade In And Loan Available, Please Call/SMS Our Sales Consultan...

Accendore Autolution Pte Ltd

Posted: 16-Mar-2019 Tags: 2015 Volkswagen Jetta, 2015 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen, Jetta, jetta, Used Volkswagen

Volkswagen Jetta 1.4A TSI $54,888 $8,320 /yr 27-Apr-2015 1,390 cc 41,000 km Sedan Availabl

Flexi-Loan Available! From $880 Monthly. One Owner, Genuine Low Mileage! German Super Brand, Classy Oak Brown Exterior On White. Diligently Maintained, Spanking New! Selling Due To Relocation. 100% Ac...

Cars 88 Pte Ltd

Posted: 04-Apr-2019 Tags: 2015 Volkswagen Jetta, 2015 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen, Jetta, jetta, Used Volkswagen

Toyota Camry takes on Volkswagen's Passat

The Toyota Camry offers more legroom for rear passengers, is sportier around corners and has more safety systems but the Volkswagen Passat is more affordable and feels more premium overall.

Find out more!

Volkswagen Jetta GP 1.4A TSI $83,000 $12,760 /yr 29-May-2015 1,390 cc 85,000 km Sedan Availabl

Single Owner. Original Paintwork Since Day 1, Accident Free, Immaculate Condition. Volkswagen Center Singapore (VCS) Serviced And Maintained. Tagged Together With VCS Service Repair Package, Free 24-h...

Posted: 23-Mar-2019 Tags: 2015 Volkswagen Jetta, 2015 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen, Jetta, jetta, Used Volkswagen

Compare **Volkswagen Jetta GP 1.4A TSI** $57,800 $8,750 /yr 11-Jun-2015 1,390 cc 60,000 km Sedan Availabl

Steve Chen (LKK Auto)

From: claims@teamworkgarage.com
Sent: Wednesday, April 17, 2019 1:48 PM
To: Steve Chen (LKK Auto)
Cc: 'TEAMWORK GARAGE CLAIMS'
Subject: finalised SKS2443L

Importance: High

We confirm COR @ $ 2050 AND Dor @ 3days

Thank you and have a nice day!

Regards,
Lolitia Tan

Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore (408934)
Tel: 6844 2475 Fax: 6844 2474

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	04/04/2019 18:02
Date Of Accident	03/04/2019 16:50
Exact Location Of Accident	JUNC YISHUN AVE 10
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKS2443L
Insured/Policyholder	
Name Of Registered Owner	MOHAMED ILYAS FAKRUDEEN S/O ABDUL SALAM
NRIC No	S7690040Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91120805
Alternative Phone No	OFFICE-91120805
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	JETTA GP 1.4 TSI 90 A/T TL 1632G5
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107587525
Cover Note Number	
Driver	
Name of Driver	PARVEEN BANU BINTE ABU HANIFAH
NRIC No	S8134431J
Date Of Birth	14/10/1981
Occupation	INDOOR
Date Of Driving Pass	27/01/2005
Driving Experience	14 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91120805
Fax Number	
Contact Number	OFFICE-91120805
EMail Address	NOEMAIL

Address	BLK 357A ADMIRALTY DRIVE #14-154
Postcode	751357
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC2807L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	PARVEEN BANU BINTE ABU HANIFAH
Approximate Age	
Injuries Sustain	NECK
Injured person in which vehicle?	SKS2443L
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1) Please report **correctly** on the details of the accident to speed up the claims process.
2) This form must **be completed by the policy holder and/or the authorised driver.**
3) Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4) The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5) **Any false reporting may be referred to the police for investigation.**
6) The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7) By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8) **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore (**"GIA"**) may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in the [form] and any other personal information provided by me or possessed by my insurer (collectively the **"Personal Information"**) and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the **"Insurers"**), the insurers' lawyers/law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as police), for the purpose(s) of :

(i) Processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) Investigations the accident and/or my claims;
(iii) Carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) Administering my claims (including the mailing of correspondence, statement, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelops/mail packages); and/or
(v) Complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the **"purposes"**)

(b) All insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my personal information for one or more of the above purposes; and
(c) My personal information may/can be disclosed by any of the insurer and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above purposes.
(d) My personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
(e) The information so collected under (d) above may be shared / disclosed:

(i) To all insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposed stated, or
(ii) For complying with requirements under my regulations, laws or court orders.

Policy holder's signature **Date / time:**	**Driver's signature** **(If driver is not policy holder)** **Date / time:**	**reporting centre personnel's Signature** **Date / time:**

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling on my own lane and came to a stop with a safe distance from the front vehicle. All of a sudden, I felt an huge impact from my vehicle rear portion. After I came down for my car the rear that vehicle B had collided with me.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policy holder's signature Date & time:	Driver's signature (If driver is not policy holder) Date & time:	reporting centre personnel's Signature Name: NRIC/FIN No.:

TeamWork Garage Pte Ltd

Steve (LKK) W/H Rejuvik 10/4/19 3.30pm

12/4/19

TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
Register number : 201015366H

Repair Performa Invoice

China Taiping Insurance (Singapore) Pte Ltd
105 Cecil Street #19-00
The Octagon
Singapore 069534

3 days
L/S
Rq AF spray

Vehicle n	SKS2443L
Make / Model	VOLKSWAGEN/JETTA
Chassis number	WVWZZZ16ZFM002431
Accident date	03 April 2019
Reference	1904-16

Qty	Particulars	Unit Price - SGD $
	PARTS REPLACEMENT - LIST ITEMS	
1	BOOTLID × NAI	1713.50 ×
1	BOOTLID EMBLEM × NAI	103.50 ×
1	BOOTLID EMBLEM - JETTA × NAI	59.51 ×
1	BOOTLID EMBLEM - TSF ✓ NAI	57.75 ×
1	BOOTLID LOCK × NAI	169.22 ×
1	BOOTLID RUBBER × NAI	303.13 ×
1	END PANEL × R	1062.50 ×
1	EMD PANEL TOP GARNISH × NAI	219.24 ×
1	REAR BUMPER / DD	1292.31 /
1	REAR BUMPER LOWER GARNISH / CUT	219.25 /
2	REAR BUMPER SIDE RETAINER / RH - LH BR	110.00 /
1	REAR BUMPER REINFORCEMENT ? (inner foam) BR /	577.50 170 /
1	SPARE TYRE TOP BOARD × NAI	377.50 ×
1	REAR EXHAUST SILENCER × NAI	963.75 ×
2	REAR EXHAUST MOUNTING × NAI	40.00 ×
1 A	PDC SENSOR Shd /	717.60 179.40 /
4	SENSOR HOLDER ? NEC /	80.00 /
		8066.26 2050.96
	Less 10%	806.62 -10%
	Subtotal	7259.64 1845.86
	Balance C/F	7259.64
	PARTS REPLACEMENT - SPECIAL NETT ITEMS	
	Balance B/F	7259.64
1 SET	REAR BUMPER CLIP NEC	30 40.00
1	JOINT SEALANT NAI	× 150.00
	Subtotal	190.00
	Balance C/F	7449.64

30 /

S/No	LABOUR AND MISCELLANEOUS CHARGES	
	Balance B/F	7449.64
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	30 60.00
2	DIAGNOIS CHECK AND CLEAR FAULT CODE	X 300.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	30 150.00
4	REMOVE AND RENEW REAR EXHAUST SILENCER	X 150.00
5	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	X 200.00
6	PANEL BEATING ON AFFECTED AREAS	300 1200.00
7	SPRAY PAINTING ON AFFECTED AREAS	300 1000.00
8	APPLY ANTI RUST ON AFFECTED AREAS\	30 150.00
	Subtotal	3210.00
		670
	Grand total	10659.64

Total – 2545.86
L/S – 2,036.68
= 2050

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Apr 2019		12 Apr 2019 09:22 Edit Adj Rpt	**S$2,050.00** Edit Estimates	**S$2,050.00** View Rpt		**Pending for Survey Report** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS **[Created by Insurer]**

Insured:	-, ID: -		
Main Claimant:	**MOHAMED ILYAS FAKRUDEEN S/O ABDUL SALAM**, ID: S7690040Z		
Vehicle Reg. No.:	**SKS2443L**	Date of Loss:	03/04/2019 16:00 - :59 [**48** Months and **3** Days From LTA Reg Date (Man Yr)]
Claim Type:	**TP** / SNM19D201529C02	Policy/Cover Note No.:	DMCVSN30303518000
Vehicle Reg. No. (Insured):	**GBC2807L**	Policy No. (Claimant):	5107587525
		Excess:	S$0.00
Repairer:	**Teamwork Garage Pte Ltd (HQ)** 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475		
Handling Insurer:	**China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 ... [Handled by **Chong Boon Sen**]		
Claimant's Insurer:	**NTUC Income Insurance Co-operative Ltd (HQ)** - Tel:		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **CHEN TSUE YEE**] ... [**Final Rpt** due 24/04/2019]		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

Claim Documents

***SKS2443L (SNM19D201529C02)**
[GBC2807L]
TP
MOHAMED ILYAS FAKRUDEEN S/O ABDUL SALAM
Apr 3 2019 4:00PM
[-]
Teamwork Garage Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View: View in Browser

Assessment Reports — 1 per page

No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	04/04/19 18:10	**Accident Statement**		Load HTM	

Photos/Images — 3 per page

No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	04/04/19 18:07	**Accident Photo** [Linked Accident Report Documents]		Load JPG	☑
2	04/04/19 18:07	**Accident Photo** [Linked Accident Report Documents]		Load JPG	☑
3	04/04/19 18:07	**Accident Photo** [Linked Accident Report Documents]		Load JPG	☑
4	04/04/19 18:07	**Accident Photo** [Linked Accident Report Documents]		Load JPG	☑
5	04/04/19 18:07	**Accident Photo** [Linked Accident Report Documents]		Load JPG	☑
6	04/04/19 18:07	**Accident Photo** [Linked Accident Report Documents]		Load JPG	☑
7	04/04/19 18:07	**Accident Photo** [Linked Accident Report Documents]		Load JPG	☑
8	04/04/19 18:07	**Accident Photo** [Linked Accident Report Documents]		Load JPG	☑
9	04/04/19 18:07	**Accident Photo** [Linked Accident Report Documents]		Load JPG	☑
10	04/04/19 18:07	**Accident Photo** [Linked Accident Report Documents]		Load JPG	☑
11	04/04/19 18:07	**Accident Photo** [Linked Accident Report Documents]		Load JPG	☑
12	04/04/19 18:07	**Accident Photo** [Linked Accident Report Documents]		Load JPG	☑
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/04/19 10:41	**General View**		Load JPG	☑
2	18/04/19 10:41	**General View**		Load JPG	☑
3	18/04/19 10:41	**General View**		Load JPG	☑
4	18/04/19 10:41	**General View**		Load JPG	☑
5	18/04/19 10:41	**General View**		Load JPG	☑
6	18/04/19 10:41	**General View**		Load JPG	☑
7	18/04/19 10:41	**General View**		Load JPG	☑
8	18/04/19 10:41	**General View**		Load JPG	☑
9	18/04/19 10:41	**General View**		Load JPG	☑
10	18/04/19 10:41	**General View**		Load JPG	☑
11	18/04/19 10:41	**General View**		Load JPG	☑
12	18/04/19 10:41	**General View**		Load JPG	☑
13	18/04/19 10:41	**General View**		Load JPG	☑
14	18/04/19 10:41	**General View**		Load JPG	☑
15	18/04/19 10:41	**General View**		Load JPG	☑
16	18/04/19 10:41	**General View**		Load JPG	☑
17	18/04/19 10:41	**General View**		Load JPG	

Assessment Reports			1 per page		☑
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
					☑
18	18/04/19 10:41	General View		Load JPG	☑
19	18/04/19 10:41	General View		Load JPG	☑
20	18/04/19 10:41	General View		Load JPG	☑
21	18/04/19 10:41	General View		Load JPG	☑
22	18/04/19 10:41	General View		Load JPG	☑
23	18/04/19 10:42	Reinspection Photo		Load JPG	☑
24	18/04/19 10:42	Reinspection Photo		Load JPG	☑
25	18/04/19 10:42	Reinspection Photo		Load JPG	☑
26	18/04/19 10:42	Reinspection Photo		Load JPG	☑
27	18/04/19 10:42	Reinspection Photo		Load JPG	☑
28	18/04/19 10:42	Reinspection Photo		Load JPG	☑
29	18/04/19 10:42	Reinspection Photo		Load JPG	☑
30	18/04/19 10:42	Reinspection Photo		Load JPG	☑
31	18/04/19 10:42	Reinspection Photo		Load JPG	☑
32	18/04/19 10:42	Reinspection Photo		Load JPG	☑
33	18/04/19 10:42	Reinspection Photo		Load JPG	☑
34	18/04/19 10:42	Reinspection Photo		Load JPG	☑
35	18/04/19 10:42	Reinspection Photo		Load JPG	☑

Documentation			1 per page		☑
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	12/04/19 09:23	pri contact		Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	04/04/19 18:08	Accident Sketch Plan [Linked Accident Report Documents]		Load JPG	☑
2	04/04/19 18:08	Accident Sketch Plan [Linked Accident Report Documents]		Load JPG	☑

Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page		☑
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	04/04/19 18:10	Accident Statement		Load HTM	

Photos/Images			3 per page		☑
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	04/04/19 18:07	Accident Photo		Load JPG	☑
2	04/04/19 18:07	Accident Photo		Load JPG	☑
3	04/04/19 18:07	Accident Photo		Load JPG	☑
4	04/04/19 18:07	Accident Photo		Load JPG	☑
5	04/04/19 18:07	Accident Photo		Load JPG	☑
6	04/04/19 18:07	Accident Photo		Load JPG	☑
7	04/04/19 18:07	Accident Photo		Load JPG	☑
8	04/04/19 18:07	Accident Photo		Load JPG	☑
9	04/04/19 18:07	Accident Photo		Load JPG	☑
10	04/04/19 18:07	Accident Photo		Load JPG	☑
11	04/04/19 18:07	Accident Photo		Load JPG	☑
12	04/04/19 18:07	Accident Photo		Load JPG	☑

Documentation			1 per page		☑
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print

Assessment Reports			1 per page		
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	04/04/19 18:08	Accident Sketch Plan		Load JPG	☑
2	04/04/19 18:08	Accident Sketch Plan		Load JPG	☑

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19006435/ESD3Q2
Date: 06/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30303518000
Claimant Vehicle No :	SKS2443L	**Insured Vehicle No :**	GBC2807L
Date of Loss:	03/04/2019	Nature of Claim:	TP

Claim No: SNM19D201529C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SKS2443L**		
Make & Model:	VOLKSWAGEN JETTA, 1.4 (A)	Engine No:	CAXF15777
Reg. Date:	31/03/2015 (Man. Year: 2014)	Chassis No:	WVWZZZ16ZFM002431
Colour:	White	Odometer:	95367 km
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Firelli 6 mm	Rear Left Side:	Firelli 6 mm
Front Right Side:	Firelli 6 mm	Rear Right Side:	Firelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,449.63	1,875.86	5,573.77	74.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,210.00	670.00	2,540.00	79.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**10,659.63**	**2,545.86**	**8,113.77**	**76.12**
Approved Total (Overridden) (S$)		**2,050.00**		
(S$)	10,659.63	2,050.00	8,609.63	80.77
+ GST 7.00/7.00% (S$)	746.17	143.50	602.67	80.77
Nett Amount (S$)	**11,405.80**	**2,193.50**	**9,212.30**	**80.77**

INSPECTION

Date of Assignment:	12/04/2019		
Date Inspected:	10/04/2019	Inspected At:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	3.0 days		

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2019)
Parts:	143	VOLKSWAGEN JETTA 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS2443L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		***BOOTLID**	Not Necessary	1,713.50 FL	*- FL
2	1		***BOOTLID EMBLEM**	Not Necessary	103.50 FL	*- FL
3	1		***BOOTLID EMBLEM -JETTA**	Not Necessary	59.51 FL	*- FL
4	1		***BOOTLID EMBLEM -TSF**	Not Necessary	57.75 FL	*- FL
5	1		***BOOTLID LOCK**	Not Necessary	169.22 FL	*- FL
6	1		***BOOTLID RUBBER**	Not Necessary	303.13 FL	*- FL
7	1		***END PANEL**	Repair	1,062.50 FL	*- FL
8	1		***END PANEL TOP GARNISH**	Not Necessary	219.24 FL	*- FL
9	1		***REAR BUMPER**	Dented	1,292.31 FL	*1,292.31 FL
10	1		***REAR BUMPER LOWER GARNISH**	Cut	219.25 FL	*219.25 FL
11	2		***REAR BUMPER SIDE RETAINER**	Broken	110.00 FL	*110.00 FL
12	1		***REAR BUMPER REINFORCEMENT (INNER FOAM)**	Broken	577.50 FL	*170.00 FL
13	1		***SPARE TYRE TOP BOARD**	Not Necessary	377.50 FL	*- FL
14	1		***REAR EXHAUST SILENCER**	Not Necessary	963.75 FL	*- FL
15	2		***REAR EXHAUST MOUNTING**	Not Necessary	40.00 FL	*- FL
16	4		***PDC SENSOR**	Shorted (1 PCS ONLY)	717.60 FL	*179.40 FL
17	4		***SENSOR HOLDER**	Necessary	80.00 FL	*80.00 FL
18	1		***SET REAR BUMPER CLIP**	Necessary	40.00 FS	*30.00 FS
19	1		***JOINT SEALANT**	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S$)	**8,256.26**	**2,080.96**
- List Item Discount on L Items 10.00/10.00% (S$)	806.63	205.10
Total Parts (S$)	**7,449.63**	**1,875.86**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	DIAGNOIS CHECK AND CLEAR FAULT CODE	New	300.00	0.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	20.00
4	REMOVE AND RENEW REAR EXHAUST SILENCER	New	150.00	0.00
5	TRANSFER PARTS ,ATTACHMENT FROM OLD BOOTLID TO NEW	New	200.00	0.00
6	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	300.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	300.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	20.00
		Gross Labour Cost (S$)	**3,210.00**	**670.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >