ASS. REC. BY: | REF: CS/AGI19012141/04F3N2 | Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Ivy Ratilla of AGI Date/Time: 9.7.19 3:48 p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLW 9870H Insured: FBM 26507

at Workshop m/s Fastech Auto Tel: 67465405

of 1 Kaki Bukit Ave 6 #01-46/48/50

Policy No: Claim No: C 20003431/JW

Sum Insured: Excess:

Make of Veh: D.O.A. 5.7.19

(Client's Record)

CA / REV / REP. / REV 24 HRS Tap H.O.D. Endorsement:

Date/Time: 9.7.19 4.58 p.m Person Contacted: Nancy Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	FBM 26507: X
	SLW 9870H: X

(08/11/13), wef

ASS. REC. BY: Marcus

REF: A 61

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 8870H

at Workshop m/s A.

of

Insured: FBM 2650T

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GI / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

LYA 60 667

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLW 8870H Yr Regn: 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or A1

Make: BMW 318i c.c 1499

Colour blue A/C: Insured / Std / NI / NA

Sp.Reading 43062 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA8E36030NT38750

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R17

R:

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	5/7/19	D.O.I.	9/7/19

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
24/7/19	Done G.A 2/5 @ 1400 Confirmed with Ah.

RECEIVED 25 JUL 2019

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($) $ + RS $

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($) 250

TOTAL

Report Format :

Lump Sum / I.B.I: ($)

Nivitha (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Tuesday, 9 July 2019 3:48 PM
To: Admin-D (LKKAuto)
Cc: SUR; Justin Wong
Subject: TPPD Survey: Claim ref:C20003432/JW || OI- FBM2650T (black) TP- SLW9870H || Est:0.00 || Fastech Auto

Hi Team,

We would like to arrange TP PRS for SLW9870H. They have chose Mr. Marcus Chua to conduct survey.

Kindly confirm.

Regards,

Ivy
Admin Executive, Claims

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg

Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may

be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Nancy Lam <nancy.lam@fastechauto.com.sg>
Sent: Tuesday, 9 July 2019 1:02 PM
To: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Cc: Justin Wong <justin.wong@budgetdirect.com.sg>
Subject: RE: Request for PRS SLW 9870H || C20003432

WITHOUT PREJUDICE

Dear Ivy,

Please arrange. Marcus Chua LKK Auto Consultants Pte Ltd to survey the car.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

From: Nancy Lam <nancy.lam@fastechauto.com.sg>
Sent: Tuesday, 9 July 2019 11:35 AM
To: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Subject: RE: Request for PRS SLW 9870H

WITHOUT PREJUDICE

Dear Ivy,

Attached LTA search for your reference.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

From: Nancy Lam <nancy.lam@fastechauto.com.sg>
Sent: Tuesday, 9 July 2019 10:31 AM
To: Claims <claims@budgetdirect.com.sg>
Subject: Request for PRS SLW 9870H

Without Prejudice

Hi Sir

My client claiming your insured FBM 2650T.

Please kindly arrange PRS for SLW 9870H.

Date of accident 05.07.2019.

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are require to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards,
Nancy Lam
FASTECH Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.
This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.
This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

SGCARMART.COM

Login Sign up

New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Articles | Forum | Resources

SAVE $$ ON UR CAR INSURANCE RENEWAL

Compare 10+ Insurers

CLICK HERE ›

Post an Advertisement
Sell it yourself! Advertise it at just
$58 until it's SOLD!

Post an Ad | Advertiser Login | Ways of Selling

2019 BMW 530 Touring M-Sport Plus At $233k Only.

Rare! Only One In SG, Full M-Sport Plus Package, Perfect Showroom Condition!
Direct Owner StarAd

PRIME MOTOR & LEASING
(CHUNG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category | Sort by Date Posted | 20 results/page

6 vehicles

bmw 318

Advanced Search | Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	bmw 318		Any	Any	2015	Any	Any	Any	Available

BMW 3 Series 318i Sport $91,988 $12,510 /yr 17-Sep-2015 1,499 cc 41,000 km Luxury **Available**

Well Maintained And Agent Serviced. Flexible Loan Packages Available From Low Interest Rate Of 1.99%. Excellent And Well Maintained...

Posted: 07-Jul-2019 Tags: 2015 BMW 318i, 2015 bmw 318i, BMW 318i, bmw 318i, BMW, 318i, Used BMW

BMW 3 Series 318i Sport $90,800 $11,950 /yr 27-Nov-2015 1,499 cc 60,200 km Luxury **Available**

Cheapest In The Market! No Gimmicks! Well Maintained And Agent Serviced! Original BMW Parts Only Used By Previous Owner! Flexible...

Posted: 06-Jul-2019 Tags: 2015 BMW 318i, 2015 bmw 318i, BMW 318i, bmw 318i, BMW, 318i, Used BMW

BMW 3 Series 318i Sport $96,800 $12,800 /yr 28-Dec-2015 1,499 cc 66,534 km Luxury **Available**

Beautiful Metallic Black, 1 Careful Owner, Regular Service And Maintain By Agent, Under Warranty., Seldom Used,Accident-Free, Underg...

Jia Leong Trading Enterprise

Posted: 05-Jul-2019 Tags: 2015 BMW 318i, 2015 bmw 318i, BMW 318i, bmw 318i, BMW, 318i, Used BMW

BMW 3 Series 318i $90,800 $12,160 /yr 25-Sep-2015 1,499 cc 43,000 km Luxury **Available**

Own A Most Impressive German Ever Built For The Past Generation And Give You Ultimate Sheer Driving Pleasure, Great For Young Exe...

Car Buyers Automotive Pte Ltd

Posted: 05-Jul-2019 Tags: 2015 BMW 318i, 2015 bmw 318i, BMW 318i, bmw 318i, BMW, 318i, Used BMW

New Citroen C5 Aircross lands in Singapore

The new Citroen C5 Aircross promises to be the most modular and the most comfortable model in its segment, thanks to a progressive hydraulic suspension system.

Find out more!

BMW 3 Series 318i Sport $93,800 $12,380 /yr 18-Dec-2015 1,499 cc 61,000 km Luxury **Available**

1 Owner. Serviced And Maintained By Agent PML. High COE Value Of $60,001. Authorized Bank Loan. Enjoy Exclusive Low Interest Rate...

Republic Auto

Posted: 30-Jun-2019 Tags: 2015 BMW 318i, 2015 bmw 318i, BMW 318i, bmw 318i, BMW, 318i, Used BMW

BMW 3 Series 318i $95,000 $12,870 /yr 30-Sep-2015 1,499 cc 12,681 km Luxury **Available**

Fully PML Maintained, Low Mileage, 3 Series Sedan For Sale. 100% Accident Free, Immaculate Condition Inside Out, Worry Free Car, Lo...

Posted: 01-Jun-2019 Tags: 2015 BMW 318i, 2015 bmw 318i, BMW 318i, bmw 318i, BMW, 318i, Used BMW

Save this search criteria, to get email alerts whenever a match is found.

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status

Compare
For old advertisements, view Expired ads

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6920G
Vehicle Details	
Vehicle No.:	SLW9870H
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jul 2019
Vehicle Make:	B.M.W.
Vehicle Model:	318I SEDAN LED NAV
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	F3411196B38B15A
Chassis No.:	WBA8E36030NT38750
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	$31,110.00
Original Registration Date:	30 Oct 2015
First Registration Date:	30 Oct 2015
Transfer Count:	1
Actual ARF Paid:	$30,554.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2025
PARF Rebate Amount:	$22,915.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2025
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	$60,000.00
COE Rebate Amount:	$37,752.00
Total Rebate Amount:	**$60,667.00**

The information contained herein is correct as at 09 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/07/2019 13:28
Date Of Accident	05/07/2019 07:55
Exact Location Of Accident	ALONG TELOK AYER STREET AND BOON TAT ST JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW9870H
Insured/Policyholder	
Name Of Registered Owner	YUNG KWING TAI
NRIC No	S8156920G
Email Address	VIC1833@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96383584
Alternative Phone No	OTHERS-96383584
Vehicle Particulars	
Manufacturer	BMW
Model	318I SEDAN LED NAV
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01008911
Cover Note Number	NA
Driver	
Name of Driver	YUNG KWING TAI
NRIC No	S8156920G
Date Of Birth	27/09/1981
Occupation	INDOOR
Date Of Driving Pass	28/06/2016
Driving Experience	3 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96383584
Fax Number	
Contact Number	OTHERS-96383584
EMail Address	VIC1833@YAHOO.COM

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

I was driving my along Telok Ayer Street and Boon tat Street junction. When I was stationary at the junction to checking my blind spot and turning to the right. Suddenly a motorcycle hit onto my car rear right side position. Damages of my car rear right side position. No injuries were involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBM2650T
Vehicle Make/Model/Colour	KAWASAKI / EJ800A
Details Of Properties	NA
Vehicle Category	MOTORCYCLE
Name of Driver	ABDUL KADIR BIN MOHAMED KASSIM
NRIC/Passport Number	S1586376E
Contact Number	90616788
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Passenger 1

NAME: : PASSENGER 1

GENDER: : FEMALE

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "**Purposes**")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER
JOHNNY VOO

Policyholder's Signature / Date & Time | Driver's Signature (if driver is not the policyholder) / Date & Time | Witnessed by Reporting Centre Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was driving my along Telok Ayer Street and Boon tat Street junction. When I was stationary at the junction to checking my blind spot and turning to the right. Suddenly a motorcycle hit onto my car rear right side position. Damages of my car rear right side position. No injuries were involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER - JOHNNY VOO CHEON YEE

MARS Officer

Registered Owner or Driver's Signature

Job Complete Date/Time

6 July 2019 at 11:29 AM

Date/Time:

6 July 2019 at 11:29 AM

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063 / 67467158 Fax No: 67458520
Tax Reg No : 20-0006262-D

SLW 9870H

not Authorised
Hale
L/S # 1400
2 day.
9/7/19

1 REAR BUMPER ASSY	1	$	1,532.80
1 REAR BUMPER TOWING COVER	11	$	42.60
2 REAR BUMPER PDC SENSOR	11	$	740.60
1 REAR R/H BUMPER REFLECTOR	11	$	39.40
1 REAR BUMPER CENTRE GUIDE	11	$	94.60
2 REAR BUMPER SIDE GUIDE	11	$	302.40
1 REAR BUMPER ADAPTER	11	$	82.30
1 REAR BUMPER REINFORCEMENT	11	$	694.50
2 REAR BUMPER BRACKET	11	$	124.60
1 REAR RH Bootlid reflector 485.00	SCR	$	798.20
1 REAR R/H TAILLAMPS ASSY	SCR	$	658.10
1 REAR R/H DRIP RAIL COVER	11	$	23.60
1 REAR BOOT LOCK	11	$	246.60
1 REAR PDC CONTROL UNIT	11	$	443.50
		$	5,823.80
LESS 10%.....		$	582.38
		$	5,241.42

LABOUR CHANGES			
TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS	$	1,000.00	300
TO PUTTY AND RESPRAY DAMAGED PORTION	$	1,000.00	400
TO RESET CONTROL UNIT AFTER REPAIR	$ 11	120.00	
TO DISM/~~RENEW PDC SENSOR~~ refix PDC sensor & check wiring	$	100.00	30
TO DISM/REPAIR REAR EXHAUST BOX	$ 11	100.00	
TO SPRAY UNDERCOATING IN REPAIR	$ 11	150.00	
	$	7,711.42	

P-1143.1
102
1028.79
1758.79
1407.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI19012141/Utf3n2

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 29-07-2019

Code : AGI

1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	FBM 2650T	**Veh. Inspected**	SLW 9870H
	Policy No.		**Coverage ($)**	0.00
	Claim No.	C20003432/JW	**Excess ($)**	0.00
	Assign From	IVY RATILLA	**Assign Date**	09/07/2019

2.	Vehicle Particulars & Condition			
	Make & Model	BMW 318I (A)	**c.c**	1499
	Engine No.	HIDDEN	**Year of Reg.**	2015
	Chassis No.	WBA8E36030NT38750	**Colour**	BLUE
	Odometer	43062	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	SPORTS RIM
	General	GOOD		

3.	Conditions of Tyres			
		Size	**Make**	**Balance**
	R/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm
	L/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm
	R/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm
	L/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm

4.	Description of Damages
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.

5.	General Information			
	Accident Date	05/07/2019	**Inspection Date**	09/07/2019
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a.	Remarks
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b.	Estimate Days of Repair	
	ESTIMATED NORMAL PERIOD FOR REPAIR:	**2 Working Days**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 9870H

Qty	Description of Parts	Condition	Estimate By Workshop ($)	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	REAR BUMPER ASSY	TO REPAIR SEE LABOUR	1,532.80	-
1	REAR BUMPER TOWING COVER	NOT NECESSARY	42.60	-
2	REAR BUMPER PDC SENSOR	NOT NECESSARY	740.60	-
1	REAR R/H BUMPER REFLECTOR	NOT NECESSARY	39.40	-
1	REAR BUMPER CENTRE GUIDE	NOT NECESSARY	94.60	-
2	REAR BUMPER SIDE GUIDE	NOT NECESSARY	302.40	-
1	REAR BUMPER ADAPTER	NOT NECESSARY	82.30	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	694.50	-
2	REAR BUMPER BRACKET	NOT NECESSARY	124.60	-
1	REAR RH BOOTLID REFLECTOR	SCRATCHED	798.20	485.00
1	REAR R/H TAILLAMPS ASSY	SCRATCHED	658.10	658.10
1	REAR R/H DRIP RAIL COVER	NOT NECESSARY	23.60	-
1	REAR BOOT LOCK	NOT NECESSARY	246.60	-
1	REAR PDC CONTROL UNIT	NOT NECESSARY	443.50	-
	LESS 10% DISCOUNT		-582.38	-114.31
			5,241.42	1,028.79
	LABOUR			
	TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER ASSY.		1,000.00	300.00
	TO PUTTY AND RESPRAY DAMAGED PORTION.		1,000.00	400.00
	TO RESET CONTROL UNIT AFTER REPAIR.	NOT NECESSARY	120.00	-
	TO DISM/REFIX PDC SENSOR & CHECK WIRING.		100.00	30.00
	TO DISM/REPAIR REAR EXHAUST BOX.	NOT NECESSARY	100.00	-
	TO SPRAY UNDERCOATING IN REPAIR.	NOT NECESSARY	150.00	-
			2,470.00	730.00
	GRAND TOTAL		**7,711.42**	**1,758.79**

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			**1,400.00**

Report Ref No. CS/AGI19012141/Utf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.