22/03/2000

ASS. REC. BY: | REF: CS/CTI19021993/Hfd352 | Special Instruction:

Surveyor: Hock Ann

**ASSIGNMENT (Office)**

From (Person): Chong Boon Sen of CTI Date/Time: 13/12/19 @ 11.09am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLD 3340K Insured: SMG 979K

at Workshop m/s SK Automomibe Tel: 6789 5155.

of 8 Kaki Bukit Ave 4 #08-46 Premier

Policy No: OMHCSN192139190 00 Claim No: SNM19D203804C02

Sum Insured: Excess:

Make of Veh: D.O.A. 15/8/2019.
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Denise

Date/Time: 2.33pm @ 13/12/19 Person Contacted: Huey Lee Vehicle IN / OUT

| Date/Time | Action/Instruction Estimate ✓ |
|---|---|
| | SLD 3340K - NBA/CTI19017348/Y DA: 15/8/19 |
| | SMG 979K - NBA/CTI19017348/Y DA: 15/8/2019 |
| * | SLD 3340K Fine line Amt L/lamp con $3250 Non 6 days |
| | Agree by workshop incharge person (HUEY Lee) Red: 1131.50: 77% |

REG. BY: H. NW | REF: cf1

# ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLD 3340K

at Workshop m/s: S/K Automobile

of: 8 Kallang Bahru Ave 4 #08-46

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| N/S | O/S |
|---|---|
| | |

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs. days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLD 3340K Yr Regn: 14/06/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: H-wee c.c 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp.Reading: 90525 km T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: NU1/11/2791

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R: 215/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

| Front | | Rear | |
|---|---|---|---|
| R/Bal. | 5 mm | R/Bal. | 5 mm |
| L/Bal. | 5 mm | L/Bal. | 5 mm |
| D.O.A. | 15/8/19 | D.O.I. | 13/12/19 |

Survey held at: S/K Automobile

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|---|---|
| | Hock Ann, * SLD 3340K |
| | Do Submit for Extra case |
| | Pls check parts prices. |
| | 13/3/2020 |
| | MV - 47000 |
| | PV - 37239 RECEIVED 18 DEC 2019 |
| | NV - 9700 RECEIVED 13 MAR 2020 17/12 8/2/0478 |

Date/Time File Pass to? 13/3 Typist

Date/Time File Return to?

: Prell. Report

: Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: : Site Insp ($ )

: Interview ($ )

: Tech. Invs ($ )

: Waiting ($ )

Survey Fee:

Transportation: S + RS SI

Photos

Other

TOTAL

Report Formats :

Lump Sum / I.B.J. : 3250

## Hock Ann (LKK Auto)

**From:** Hock Ann (LKK Auto)
**Sent:** Thursday, 12 March, 2020 4:55 PM
**To:** SK Admin
**Cc:** Denise Tay (LKKAuto)
**Subject:** RE: SLD 3340K ~~AFTER PAINT PHOTO.~~

***'WITHOUT PREJUDICE'***
***SAVE AS TO COSTS***

Dear huey lee,

Good day, o.k will be process base on finalized total amount COR $ 3250 L/SUMP REPAIR and DOR 6 days close.

Noted : All finalized document > LOA ,LOD,DV,LTA need direct send to (CHINA TAIPING INSURANCE CLAIM DEPT)

Thanks.

Best Regards,
**Hock Ann|** Assistant Automotive Assessor
**LKK Auto Consultants**
Phone: 6741 3061 | Email: **HockAnn**@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** SK Admin [mailto:admin@skauto.com.sg]
**Sent:** Thursday, 12 March, 2020 12:47 PM
**To:** Hock Ann (LKK Auto)
**Cc:** Denise Tay (LKKAuto); simon koh; JING XIONG KHOO; KY Leong; Tyson Koh
**Subject:** Re: SLD 3340K AFTER PAINT PHOTO.

Dear Hock Ann,

Thanks for your reply.

We confirmed accept COR@S$3,250.00

Regards,
*Huey Lee*
SK Automobile Pte Ltd

On Thu, Mar 12, 2020 at 12:06 PM Hock Ann (LKK Auto) <HockAnn@lkkauto.com> wrote:

***'WITHOUT PREJUDICE'***

***SAVE AS TO COSTS***

Dear huey lee,

Good day, received!

Kindly refer vehicle SLD 3340K finalized adjustment update extimate total L/sump amount

COR $ 3250

DOR 6 DAYS

if agree total L/SUMP amount and repair days, will be to close case.

Please update soon asap

Thanks.

## Nivitha (LKK Auto)

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
**Sent:** Friday, 13 December 2019 11:09 AM
**To:** admin@skauto.com.sg
**Cc:** assignments
**Subject:** RE: OUR REF: SNM19D203804/SMG979K/CBS- Arrange surveyor for SLD3340K & Your Ref:SMG979K

WITHOUT PREJUDICE

Dear Huey Lee,

Thank you for confirming that your workshop taking over vehicle.

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

**Chong Boon Sen**
Claims Executive
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Claims Dept of CTI
**Sent:** Friday, December 13, 2019 10:58 AM
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; admin@skauto.com.sg
**Subject:** OUR REF: SNM19D203804/SMG979K/CBS- Arrange surveyor for SLD3340K & Your Ref:SMG979K

Dear Boon Sen,

Please conduct PRS for SLD3340K.

Note : officer in charge – Boon Sen 63896171.

****** Kindly quote our reference number when replying.***

Thank You.

Regards,

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**
3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

**W:** www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** SK Admin [mailto:admin@skauto.com.sg]
**Sent:** Thursday, 12 December, 2019 2:44 PM
**To:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>
**Cc:** JING XIONG KHOO <xiongskauto@gmail.com>; md daud nadzim <mddaudn731@gmail.com>
**Subject:** Arrange surveyor for SLD3340K & Your Ref:SMG979K

Dear Sir / Mdm,

We the repairers of motor vehicle no. SLD3340K
Kindly arrange surveyor to conduct a pre-repair inspection

Location : 8 Kaki Bukit Ave 4#08-46
Premier @ Kaki Bukit
Singapore 415875

Contact No : 8121 0478 Xiong

We appreciate your early reply.
Thanks.

--

*Regards,*
*Huey Lee*

*SK Automobile Pte Ltd*

*Tel: 6789 5155 Fax: 6783 5155*

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit http://www.symanteccloud.com

Chua Jaipy

MMCC19107390 / Motorway Car Care Centre Pte Ltd - HQ
ENTRY DATE & TIME: 16/08/2019 13:52
SUBMITTED BY: Tew Ai Nee

# SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| ACCIDENT STATEMENT | |
|---|---|
| Date Of Report | 16/08/2019 13:52 |
| Date Of Accident | 15/08/2019 18:40 |
| Exact Location Of Accident | SLE TWDS SEMBAWANG NEAR PUNGGOL EXIT |
| Country/State of Loss | SINGAPORE |
| **DETAILS OF OWN VEHICLE** | |
| Vehicle Registration Number | SLD3340K |
| **Insured/Policyholder** | |
| Name Of Registered Owner | ASPIRE GREEN TRADERS |
| Co Reg No | 53400171L |
| Email Address | NOEMAIL |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-97961562 |
| **Vehicle Particulars** | |
| Manufacturer | HONDA |
| Model | VEZEL-1.5 (A) |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |
| **Insurance Company** | |
| Name of Insurance Company | LIBERTY INSURANCE PTE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | SD19V09432/VPE/R00 |
| Cover Note Number | |
| **Driver** | |
| Name of Driver | PERRY LEE XAVIER |
| NRIC No | S8212601E |
| Date Of Birth | 11/05/1982 |
| Occupation | INDOOR |
| Date Of Driving Pass | 22/06/2016 |
| Driving Experience | 3 YEARS AND 1 MONTH |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-97961562 |
| Fax Number | |
| Contact Number | |
| EMail Address | NOEMAIL |

| | |
|---|---|
| Address | APT BLK 124 BEDOK NORTH ROAD<br>#09-155 SINGAPORE |
| Postcode | 460124 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | -<br>-<br>- |
| Insurance Company of Driver's Own Vehicle | -<br>-<br>- |

**General Information of the Accident**

| | |
|---|---|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

**Other Information**

| | |
|---|---|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | YES |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | NO |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 3 |
| Passenger 1 | NAME: : NONAME<br>GENDER: : MALE |
| Passenger 2 | NAME: : NONAME<br>GENDER: : FEMALE |

**Details of Police Action**

| | |
|---|---|
| Was the accident reported to the police? | YES |
| If Yes,Please state which Police Station | |
| Police Station Name | SEMBAWANG NEIGHBOURHOOD POLICE CENTRE |
| Police Station Address | **ROAD**: 4 SEMBAWANG CRESCENT , **POSTCODE:** 757633 , **COUNTRY**: SINGAPORE |
| Police Station Contact | **TEL NO**: 1800-5549999 - **FAX NO**: 68522499 |
| Was notice of intended Prosecution given? | NO |
| If Yes,against whom? | |

**Circumstances of Accident**

PLEASE REFER TO POLICE REPORT

**Attachment(s)**

| | |
|---|---|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

**DETAILS OF OTHER VEHICLE PROPERTY 1**

| | |
|---|---|
| Vehicle Registration Number | SMG979K |
| Vehicle Make/Model/Colour | KIA / CERATO FORTE 1.6SX AT ABS D/AB 2WD 4DR |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | |

| | |
|---|---|
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

**DETAILS OF INJURED PERSON 1**

| | |
|---|---|
| Name | PERRY LEE XAVIER |
| Approximate Age | 37 |
| Injuries Sustain | |
| Injured person in which vehicle? | SLD3340K |
| Were seat belts worn? | YES |
| Was this injured conveyed to hospital by ambulance? | NO |
| Address | APT BLK 124 BEDOK NORTH RD #09-155 SINGAPORE |
| Postcode | 460124 |

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

   I understand, acknowledge, agree and consent that:

   (a) My insurer, my workshop and the General Insurance Association of Singapore ("**GIA**") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

   (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

   (ii) investigating the accident and/or my claims;

   (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

   (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

   (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")

   (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

   (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

   (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

   (e) the information so collected under (d) above may be shared / disclosed:

   (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

   (ii) for complying with requirements under any regulations, laws or court orders.

ASPIRE GREEN TRADERS 53400171L

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Our Care Centre Pte Ltd Authorised

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

**Sketch Plan #2 Pg. 1**

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report

DECLARATION

I/We declare the following particulars are true in every respect.

ASPIRE GREEN TRADERS 53400171L

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

| | |
|---|---|
| **Vehicle Owner Particulars** | |
| Owner ID Type: | Business |
| Owner ID: | 171L |
| **Vehicle Details** | |
| Vehicle No.: | SLD3340K |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 16 Dec 2019 |
| Vehicle Make: | HONDA |
| Vehicle Model: | VEZEL 1.5X CVT |
| Primary Colour: | Black |
| Manufacturing Year: | 2015 |
| Engine No.: | L15B4032795 |
| Chassis No.: | RU11112791 |
| Maximum Power Output: | 96.0 kW (128 bhp) |
| Open Market Value: | $19,821.00 |
| Original Registration Date: | 14 Jun 2016 |
| First Registration Date: | 14 Jun 2016 |
| Transfer Count: | 2 |
| Actual ARF Paid: | $9,821.00 — 4910 |
| **Intended PARF Rebate Details** | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 13 Jun 2026 |
| PARF Rebate Amount: | $7,365.00 |
| **Intended COE Rebate Details** | |
| COE Expiry Date: | 13 Jun 2026 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | $46,009.00 |
| COE Rebate Amount: | $29,874.00 |
| **Total Rebate Amount:** | **$37,239.00** |

The information contained herein is correct as at 16 Dec 2019

OK

| | Make | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type | Status |
|---|---|---|---|---|---|---|---|---|---|
| **Search Selection** | **Honda Vezel** | | Any | Any | **2016** | Any | Any | Any | **Available** |

**Honda Vezel 1.5A X** **$58,800** $8,310 /yr 25-May-2016 1,496 cc - SUV **Available**

1 Owner Only, Non PHV Unit, Just Arrival, Well Maintained, Regular Serviced, New 6 Month Road Tax, Attractive Loan Package Available, View Now!

Posted: 08-Dec-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel 1.5A X** **$62,800** $8,950 /yr 25-May-2016 1,496 cc 47,012 km SUV **Available**

Confirm Best Deal.Best Colour.1 Owner.100% Accident Free.Low Mileage.Free Extended Warranty.100% Flexible Loan.We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivaled Warranty Complete With Certificate And Test Repo...

Classic Credit Pte Ltd

Posted: 19-Nov-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel 1.5A X (OPC)** **$49,800** $6,870 /yr 02-Jun-2016 1,496 cc 32,293 km SUV **Available**

1 Owner! Beautiful Pearl White Paintwork. 1 Year Warranty Provided. STA/VICOM Inspection Welcome. Flexible Loan And Trade In Available. Able To Convert To Normal Scheme. No Gimmicks, Call Or Whatsapp For More Details. CaseTrust Accredited Dealer.

Posted: 13-Nov-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel 1.5A X** **$61,800** $8,760 /yr 03-Jun-2016 1,496 cc 46,394 km SUV **Available**

1 Owner Peace Of Mind. Bank/In House Loan 100% Available. Well Taken Care Car, Mileage Running Only At 46394Km And Look At The Price We Are Selling Right Now! 100% No Gimmicks Or Hidden Costs. Buy With A Trusted Peace Of Mind With Us Establish Since 1984....

Ka-Hup Vehicles Trading

Posted: 10-Dec-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Uber's fire-prone Honda Vezels fixed**

All of Uber's 1,220 faulty Honda Vezels have been recalled and have had their fire-prone parts replaced, according to the Land Transport Authority.

Read this article

**Honda Vezel Hybrid 1.5A X Honda Sensing** **$62,800** $9,310 /yr 03-Jun-2016 1,496 cc 56,041 km SUV **Available**

**Fuel Type:** Petrol-Electric

New Arrival! 1 Owner, Low Mileage, Accident Free, Free STA Evaluation For A Peace Of Mind. Call For Viewing Appointment.

Posted: 30-Nov-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel 1.5A X** **$61,800** $8,730 /yr 15-Jun-2016 1,496 cc 74,441 km SUV **Available**

Special Offer Till 31 December Only. Vehicle Viewing At AML Building. Come With 2 Years Third Party Warranty, Easy And Flexible In House Loan And Balloon Scheme Available, No Gimmicks! DVD/Bluetooth, Reverse Camera, Auto Start/Stop, Electric Park Brake, Auto Br...

DOA : 15/8/19

MV - 47000
PV - 37239
NV - 9700

Balance → 6yr 10 mth
Depre → 8000 yr
8000÷12 = 666
36000+6666+4910
= 47576

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

| | | | |
|---|---|---|---|
| TO | : CHINA TAIPING | DATE | 11-Dec-19 |
| ATTENTION | : MOTOR CLAIMS DEPT | JOB TYPE | T/P CLAIM |
| ESTIMATE REPORT | : | | |

**OWNER'S PARTICULAR**

NAME :

ADDRESS :

TEL. NO. :

**VEHICLE DETAILS**

VEHICLE NO : SLD3340K

MODEL : HONDA VEZEL

CHASSIS NO :

**ACCIDENT DETAILS** DATE :
TIME :

81210478 – Xiong

THIRD PARTY REQUESTOR / CONTACT : DAUD/9391482 xiongskauto@gmail.com

**QUOTATION SUMMARY**

**CLAIM DETAIL : PARTS**

| S/N | DESCRIPTION | QTY | UNIT LIST PRICE | TOTAL LIST PRICE | |
|---|---|---|---|---|---|
| 1 | TAILGATE X (R) | 1 | $ 1,542.00 | $ 1,542.00 | |
| 2 | TAILGATE GLASS MOULDING X (SVC) | 4 | $ 168.00 | $ 672.00 | |
| 3 | TAILGATE LOWER LOCK X (SVC) | 1 | $ 24.00 | $ 24.00 | |
| 4 | TAILGATE WEATHER STRIP ✓ (CRA) | 1 | $ 154.00 | $ 154.00 | ✓ |
| 5 | TAILGATE EMBLEM 'VEZEL' ✓ new | 1 | $ 56.00 | $ 56.00 | ✓ |
| 6 | TAILGATE STOPPER X SVC | 2 | $ 18.00 | $ 36.00 | |
| 7 | REAR BUMPER ✓ cut | 1 | $ 689.00 | $ 689.00 | 510.50 ✓ |
| 8 | REAR BUMPER SIDE UPPER R/H only ✓ CRA | 1 ~~2~~ | $ 450.00 | $ 900.00 | 280.80 ✓ |
| 9 | REAR BUMPER SIDE RETAINER R/H only ✓ CRA | 1 ~~2~~ | $ 55.00 | $ 110.00 | 55 ✓ |
| 10 | REAR BUMPER REFLECTOR R/H only ✓ CRA | 1 ~~2~~ | $ 45.00 | $ 90.00 | 45 ✓ |
| 11 | REAR FENDER INNER COWLING X SVC | 2 | $ 187.00 | $ 374.00 | |
| 12 | REAR WHEEL ARCH GARNISH R/H only ✓ CRA | 1 ~~2~~ | $ 312.00 | $ 624.00 | 150.80 ✓ |
| 13 | REAR FENDER INNER TRIM R/H only ✓ CRA | 1 ~~2~~ | $ 548.00 | $ 1,096.00 | 386.20 ✓ |
| 14 | REAR END PANEL ✓ ← BLC | 1 | $ 630.00 | $ 630.00 | 490.50 ✓ |
| 15 | REAR END PANEL TOP GARNISH ✓ CRA | 1 | $ 189.00 | $ 189.00 | 143.50 ✓ |
| 16 | REAR FLOOR PANEL TOP BOARD X SVC | 1 | $ 300.00 | $ 300.00 | |
| 17 | REAR FLOOR PANEL UNDER COVER ✓ CRA | 1 | $ 254.00 | $ 254.00 | 156.80 ✓ |
| 18 | REAR FLOOR PANEL TOOLS BOX SPONGE X (SVC) | 1 | $ 258.00 | $ 258.00 | |

| | | | | | |
|---|---|---|---|---|---|
| 19 | REAR REVERSE SENSOR SPEAKER ✓ CRA | 1 | $ 141.00 | $ 141.00 | ✓ |
| 20 | REAR EXHAUST PIPE X (SVC) | 1 | $ 1,221.00 | $ 1,221.00 | |

| | |
|---|---|
| TOTAL PRICE | $9,360.00 |
| LESS 20% | $1,872.00 |
| **SUB TOTAL PRICE** | **$7,488.00** |

| S/N | DESCRIPTION | QTY | UNIT S/NETT | TOTAL S/NETT | |
|---|---|---|---|---|---|
| 1 | REAR BUMPER CLIPS ✓ new | 10 | $ 6.50 | $ 65.00 | 20 ✓ |
| 2 | REAR BUMPER SIDE UPPER CLIP ✓ new | 8 ~~6~~ | $ 6.50 | $ 39.00 | 6 |
| 3 | REAR BUMPER DIFFUSER ✓ CRA | 1 | $ 1,600.00 | $ 1,600.00 | 250 ✓ |
| 4 | TAILGATE SEALANT X SVC | 1 | $ 80.00 | $ 80.00 | |
| 5 | TAILGATE RUBBER SEAL X SVC | 1 | $ 100.00 | $ 100.00 | |
| 5 | TAILGATE INNER TRIM CLIP ✓ new | 8 ~~12~~ | $ 6.50 | $ 78.00 | 15 ✓ |
| 6 | TAILGATE WINDSCREEN SEALANT X SVC | 1 | $ 80.00 | $ 80.00 | |
| 7 | TAILGATE WINDSCREEN INNER SEAL X SVC | 1 | $ 50.00 | $ 50.00 | |
| 8 | TAILGATE PROTECTOR CLIPS X SVC | 10 | $ 6.50 | $ 65.00 | |
| 9 | TAILLAMP CLIP X SVC | 4 | $ 8.00 | $ 32.00 | |
| 10 | REAR FENDER INNER COWLING CLIP X SVC | 15 | $ 6.50 | $ 97.50 | |
| 11 | REAR FENDER INNER TRIM CLIPS ✓ new | 10 ~~12~~ | $ 6.50 | $ 78.00 | 20 ✓ |
| 12 | REAR WHEEL ARCH GARNISH CLIP ✓ R/H only new | ~~10~~ 5 | $ 6.50 | $ 65.00 | 20 ✓ |
| 13 | REAR END PANEL TOP GARNISH CLIPS ✓ new | 4 | $ 8.50 | $ 34.00 | 10 ✓ |
| 14 | REAR END PANEL INSULATION SEAL ✓ new | 1 | $ 150.00 | $ 150.00 | 25 ✓ |
| 15 | REAR FLOOR PANEL INSULATION SEAL X SVC | 1 | $ 150.00 | $ 150.00 | |
| 16 | EXHAUST CHROME X SVC | 1 | $ 300.00 | $ 300.00 | |
| 17 | REVERSE SENSOR ✓ Short | 1 | $ 220.00 | $ 220.00 | 200 ✓ |

**TOTAL** **$3,283.50**

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

| S/N | JOB DESCRIPTION | PRICE | ADJUSTED COST | APPROVED |
|---|---|---|---|---|
| 1 | TO PANEL BEAT, REMOVE AND REPLACE PARTS | $1,200.00 | 700 ✓ | |
| 2 | TO SPRAY PAINT AFFECTED AREA | $1,000.00 | 600 ✓ | |
| 3 | WIRING CHECK | $80.00 | 20 ✓ | |
| 4 | REMOVE AND REFIX REAR WINDSCREEN | X $150.00 | | |

| | | | | |
|---|---|---|---|---|
| 5 | CONDUCT LEAKAGE TEST ON TAILGATE | ✓ $80.00 | 30 ✓ | |
| 6 | TUFF COTE | ✗ $250.00 | | |
| 7 | REMOVE AND REFIX EXHAUST TAILPIPE | ✗ $250.00 | | |
| 8 | REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY TO FACILIATE REPAIR | ✓ $350.00 | 50 ✓ | |
| 9 | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING | ✓ $250.00 | 30 ✓ | |

**TOTAL** **$3,610.00**

**ESTIMATE REPORT**

| | | |
|---|---|---|
| TOTAL PARTS COST | : | $10,771.50 |
| TOTAL LABOUR COST | : | $3,610.00 |
| TOTAL REPAIR COST | : | $14,381.50 |

**APPROVED DETAILS**

| | |
|---|---|
| EXCESS | : |
| NO. OF WORKING DAYS | : |
| RE-SURVEY | : |
| PART BY PART OR LUMP SUM | : |
| DATE & TIME OF SURVEY | : |
| SURVEYED BY | : |
| CONTACT NUMBER | : |
| FAX NUMBER | : |

| | |
|---|---|
| Parts | 2570.10 |
| Parts less | 20% |
| | 2056.08 |
| Spe mtrl | 566 |
| labour | 1430 |
| | 4052.08 |
| L/s less | 20% |
| | 3241.66 |

total L/s Amt → $3250

17/12/19

L/s repair without prejudice
6 days
Resurvey After part
Hock ANN
85311883 / 67418434 office
Hock ANN@lkkAuto.com
13/12/19 2.30pm

Resurvey on 13/12/19
H. ANN
3.00pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

**CLAIM SUBFOLDER TRACKING**

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
|---|---|---|---|---|---|---|---|
| Main | 11 Mar 2020 | | 11 Mar 2020 09:17 Edit Adj Rpt | **S$3,250.00** Edit Estimates | **S$3,250.00** View Rpt | | **Pending for Survey Report** Cancel Case |

Main | Reference | Claim Details | Documents | Show All

**CLAIM SUBFOLDER DETAILS** **[Created by insurer]**

| | | | |
|---|---|---|---|
| Insured: | -, Co. Reg. No.: - | | |
| Main Claimant: | **ASPIRE GREEN TRADERS,** Co. Reg. No.: 53400171L | | |
| Vehicle Reg. No.: | **SLD3340K** | Date of Loss: | 15/08/2019 18:00 - :59 [**38** Months and **1** Days From LTA Reg Date (Man Yr)] |
| Claim Type: | **TP** / SNM19D203804C02 | Policy/Cover Note No.: | DMHCSN19213919000 |
| Vehicle Reg. No. (Insured): | **SMG979K** | Policy No. (Claimant): | SD19V09432/VPE/R00 |
| | | Excess: | S$0.00 |
| Repairer: | **SK Automobile Pte Ltd (HQ)** 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre, 415933 Kaki Bukit - Tel: 67895155 | | |
| Handling Insurer: | **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 ... [Handled by **Chong Boon Sen**] | | |
| Claimant's Insurer: | **Liberty Insurance Pte Ltd (HQ)** - Tel: (65) 6221 8611 | | |
| Adjuster: | **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **LEE HOCK ANN**] ... [**Final Rpt** due 20/03/2020] | | |

**ASSOCIATED MAIL RECEIVED** View All | Compose Case Mail

There are no mail for this case.

**ALL ASSOCIATED TASKS** View All | Search Tasks | Create New Task | Complete

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|---|---|---|---|---|---|---|---|---|---|

No results.

# Claim Documents

***SLD3340K (SNM19D203804C02)**
**[SMG979K]**
**TP**
**ASPIRE GREEN TRADERS**
**Aug 15 2019 6:00PM**
**[-]**
**SK Automobile Pte Ltd**

Upload Documents | Upload Photos | Compose New Letter

View: View in Browser

**Assessment Reports** — 1 per page

| No | Finalized On | Motorway Car Care Centre Pte Ltd (HQ) | | Thumbnail | Print |
|---|---|---|---|---|---|
| 1 | 04/09/19 02:11 | **Accident Statement** | | Load HTM | |

**Photos/Images** — 3 per page

| No | Finalized On | Motorway Car Care Centre Pte Ltd (HQ) | | Thumbnail | Print |
|---|---|---|---|---|---|
| 1 | 16/08/19 14:01 | **Accident Photo** [Linked Accident Report Documents] | | Load JPG | |
| 2 | 16/08/19 14:01 | **Accident Photo** [Linked Accident Report Documents] | | Load JPG | |
| 3 | 16/08/19 14:01 | **Accident Photo** [Linked Accident Report Documents] | | Load JPG | |
| 4 | 16/08/19 14:01 | **Accident Photo** [Linked Accident Report Documents] | | Load JPG | |
| 5 | 16/08/19 14:01 | **Accident Photo** [Linked Accident Report Documents] | | Load JPG | |
| 6 | 16/08/19 14:01 | **Accident Photo** [Linked Accident Report Documents] | | Load JPG | |
| 7 | 16/08/19 14:01 | **Accident Photo** [Linked Accident Report Documents] | | Load JPG | |
| No | **Relabel/Reorder** | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 1 | 12/03/20 17:02 | **Chassis Number** | | Load JPG | |
| 2 | 12/03/20 17:02 | **Odometer Reading** | | Load JPG | |
| 3 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 4 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 5 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 6 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 7 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 8 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 9 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 10 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 11 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 12 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 13 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 14 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 15 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 16 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 17 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 18 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 19 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 20 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 21 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 22 | 12/03/20 17:03 | **General View** | | Load JPG | |

**Assessment Reports** 1 per page

| No | Finalized On | Motorway Car Care Centre Pte Ltd (HQ) | | Thumbnail | Print |
|---|---|---|---|---|---|
| 23 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 24 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 25 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 26 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 27 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 28 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 29 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 30 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 31 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 32 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 33 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 34 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 35 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 36 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 37 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 38 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 39 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 40 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 41 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 42 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 43 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 44 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 45 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 46 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 47 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 48 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 49 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 50 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 51 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 52 | 12/03/20 17:03 | **General View** | | Load JPG | |
| 53 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 54 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 55 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 56 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 57 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 58 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 59 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 60 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 61 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 62 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 63 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 64 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 65 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 66 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 67 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 68 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 69 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 70 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |

**Assessment Reports** 1 per page

| No | Finalized On | Motorway Car Care Centre Pte Ltd (HQ) | | Thumbnail | Print |
|---|---|---|---|---|---|
| 71 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 72 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 73 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 74 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 75 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 76 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 77 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 78 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 79 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 80 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 81 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 82 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 83 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 84 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 85 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 86 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 87 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 88 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 89 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 90 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 91 | 12/03/20 17:04 | **Reinspection Photo** | | Load JPG | |
| 92 | 12/03/20 17:05 | **After Repair Photo** | | Load JPG | |
| 93 | 12/03/20 17:05 | **After Repair Photo** | | Load JPG | |
| 94 | 12/03/20 17:05 | **After Repair Photo** | | Load JPG | |

**Documentation** 1 per page

| No | Finalized On | Motorway Car Care Centre Pte Ltd (HQ) | | Thumbnail | Print |
|---|---|---|---|---|---|
| 1 | 16/08/19 14:44 | **Sketch Plan** [Linked Accident Report Documents] | | Load TIF | |
| 2 | 16/08/19 14:44 | **Sketch Plan #2** [Linked Accident Report Documents] | | Load TIF | |
| 3 | 16/08/19 14:44 | **Sketch Plan #3** [Linked Accident Report Documents] | | Load TIF | |
| 4 | 16/08/19 14:44 | **Sketch Plan #4** [Linked Accident Report Documents] | | Load TIF | |
| 5 | 16/08/19 14:44 | **Sketch Plan #5** [Linked Accident Report Documents] | | Load TIF | |
| 6 | 16/08/19 14:44 | **Sketch Plan #6** [Linked Accident Report Documents] | | Load TIF | |

# Linked Accident Report Documents

**View** View in Browser

**Assessment Reports** 1 per page

| No | Finalized On | Motorway Car Care Centre Pte Ltd (HQ) | | Thumbnail | Print |
|---|---|---|---|---|---|
| 1 | 04/09/19 02:11 | **Accident Statement** | | Load HTM | |

**Photos/Images** 3 per page

| No | Finalized On | Motorway Car Care Centre Pte Ltd (HQ) | | Thumbnail | Print |
|---|---|---|---|---|---|
| 1 | 16/08/19 14:01 | **Accident Photo** | | Load JPG | |
| 2 | 16/08/19 14:01 | **Accident Photo** | | Load JPG | |
| 3 | 16/08/19 14:01 | **Accident Photo** | | Load JPG | |
| 4 | 16/08/19 14:01 | **Accident Photo** | | Load JPG | |

**Assessment Reports** 1 per page ▼

| No | Finalized On | Motorway Car Care Centre Pte Ltd (HQ) | | Thumbnail | Print |
|---|---|---|---|---|---|
| 5 | 16/08/19 14:01 | **Accident Photo** | ℹ | Load JPG | ☑ |
| 6 | 16/08/19 14:01 | **Accident Photo** | ℹ | Load JPG | ☑ |
| 7 | 16/08/19 14:01 | **Accident Photo** | ℹ | Load JPG | ☑ |

**Documentation** 1 per page ▼

| No | Finalized On | Motorway Car Care Centre Pte Ltd (HQ) | | Thumbnail | Print |
|---|---|---|---|---|---|
| 1 | 16/08/19 14:44 | **Sketch Plan** | ℹ | Load TIF | |
| 2 | 16/08/19 14:44 | **Sketch Plan #2** | ℹ | Load TIF | |
| 3 | 16/08/19 14:44 | **Sketch Plan #3** | ℹ | Load TIF | |
| 4 | 16/08/19 14:44 | **Sketch Plan #4** | ℹ | Load TIF | |
| 5 | 16/08/19 14:44 | **Sketch Plan #5** | ℹ | Load TIF | |
| 6 | 16/08/19 14:44 | **Sketch Plan #6** | ℹ | Load TIF | |

# Documents Checklist

**DOCUMENTS CHECKLIST** Reset Save Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI19021993/HTD3S2
**Date:** 13/03/2020

## REFERENCE

| | | | | | |
|---|---|---|---|---|---|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMHCSN19213919000 | | |
| **Claimant Vehicle No :** | SLD3340K | **Insured Vehicle No :** | SMG979K | | |
| Date of Loss: | 15/08/2019 | Nature of Claim: | TP | Claim No: | SNM19D203804C02 |

## DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|---|---|---|---|
| Reg No: | **SLD3340K** | | |
| Make & Model: | HONDA VEZEL, 1.5 (A) | Engine No: | L15B4032795 |
| Reg. Date: | 14/06/2016 (Man. Year: 2015) | Chassis No: | RU11112791 |
| Colour: | Black | Odometer: | 90525 km |
| Engine Capacity: | 1496 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S$): | **Market Value/New Car Price** | | |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|---|---|---|---|---|---|
| General Condition: | Good | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

## CONDITION OF TYRES

| | | | |
|---|---|---|---|
| Front Tyre Size: | 215/55 R17 | Rear Tyre Size: | 215/55 R17 |
| Front Left Side: | Bridgestone 5 mm | Rear Left Side: | Bridgestone 5 mm |
| Front Right Side: | Bridgestone 5 mm | Rear Right Side: | Bridgestone 5 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|---|---|---|---|
| Parts | 10,771.50 | 2,622.08 | 8,149.42 | 75.66 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,610.00 | 1,430.00 | 2,180.00 | 60.39 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| **Calculated Gross Total (S$)** | **14,381.50** | **4,052.08** | **10,329.42** | **71.82** |
| **Approved Total (Overridden) (S$)** | | **3,250.00** | | |
| **(S$)** | 14,381.50 | 3,250.00 | 11,131.50 | 77.40 |
| **+ GST 7.00/7.00% (S$)** | 1,006.71 | 227.50 | 779.21 | 77.40 |
| **Nett Amount (S$)** | **15,388.21** | **3,477.50** | **11,910.71** | **77.40** |

## INSPECTION

| | | | |
|---|---|---|---|
| Date of Assignment: | 11/03/2020 | | |
| Date Inspected: | 13/12/2019 | Inspected At: | 8 KAKI BUKIT AVE 4 #08-46 Premier Repairer: SK Automobile Pte Ltd |
| Estimated Period of Repair: | 6.0 days | | |

**Adjuster:** LEE HOCK ANN

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 13 Mar 2020)

**Parts:** M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLD3340K)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|---|---|---|---|---|---|---|
| 1 | 1 | | *TAILGATE | Repair | 1,542.00 FL | *- FL |
| 2 | 4 | | *TAILGATE GLASS MOULDING | Serviceable | 672.00 FL | *- FL |
| 3 | 1 | | *TAILGATE LOWER LOCK | Serviceable | 24.00 FL | *- FL |
| 4 | 1 | | *TAILGATE WEATHERSTRIP | Cracked | 154.00 FL | *154.00 FL |
| 5 | 1 | | *TAILGATE EMBLEM VEZEL | Necessary | 56.00 FL | *56.00 FL |
| 6 | 2 | | *TAILGATE STOPPER | Serviceable | 36.00 FL | *- FL |
| 7 | 1 | | *REAR BUMPER | Cut | 689.00 FL | *510.50 FL |
| 8 | 1 | | *REAR BUMPER SIDE UPPER | O/s Cracked | 900.00 FL | *280.80 FL |
| 9 | 1 | | *REAR BUMPER SIDE RETAINER | O/s Crushed | 110.00 FL | *55.00 FL |
| 10 | 1 | | *REAR BUMPER REFLECTOR | O/s Cracked | 90.00 FL | *45.00 FL |
| 11 | 2 | | *REAR FENDER INNER COWLING | Serviceable | 374.00 FL | *- FL |
| 12 | 1 | | *REAR WHEEL ARCH GARNISH | O/s Crushed | 624.00 FL | *150.80 FL |
| 13 | 1 | | *REAR FENDER INNER TRIM | O/s Cracked | 1,096.00 FL | *386.20 FL |
| 14 | 1 | | *REAR END PANEL | Buckled | 630.00 FL | *490.50 FL |
| 15 | 1 | | *REAR END PANEL TOP GARNISH | Crushed | 189.00 FL | *143.50 FL |
| 16 | 1 | | *REAR FLOOR PANEL TOP BOARD | Serviceable | 300.00 FL | *- FL |
| 17 | 1 | | *REAR FLOOR PANEL UNDER COVER | Cracked | 254.00 FL | *156.80 FL |
| 18 | 1 | | *REAR FLOOR PANEL TOOLS BOX SPONGE | Serviceable | 258.00 FL | *- FL |
| 19 | 1 | | *REAR REVERSE SENSOR | Cracked | 141.00 FL | *141.00 FL |
| 20 | 1 | | *REAR EXHAUST PIPE | Serviceable | 1,221.00 FL | *- FL |
| 21 | 10 | | *REAR BUMPER CLIPS | Necessary | 65.00 FS | *20.00 FS |
| 22 | 6 | | *REAR BUMPER SIDE UPPER CLIP | Necessary 3pcs Only | 39.00 FS | *6.00 FS |
| 23 | 1 | | *REAR BUMPER DIFFUSER | Crushed | 1,600.00 FS | *250.00 FS |
| 24 | 1 | | *TAILGATE SEALANT | Serviceable | 80.00 FS | *- FS |
| 25 | 1 | | *TAILGATE RUBBER SEAL | Serviceable | 100.00 FS | *- FS |
| 26 | 12 | | *TAILGATE INNER TRIM CLIP | Necessary 8pcs Only | 78.00 FS | *15.00 FS |
| 27 | 1 | | *TAILGATE WINDSCREEN SEALANT | Serviceable | 80.00 FS | *- FS |
| 28 | 1 | | *TAILGATE WINDSCREEN INNER SEAL | Serviceable | 50.00 FS | *- FS |
| 29 | 10 | | *TAILGATE PROTECTOR CLIPS | Serviceable | 65.00 FS | *- FS |
| 30 | 4 | | *TAILLAMP CLIP | Serviceable | 32.00 FS | *- FS |
| 31 | 15 | | *REAR FENDER INNER COWLING CLIP | Serviceable | 97.50 FS | *- FS |
| 32 | 1 | | *REAR FENDER INNER TRIM CLIPS 12pcs | Necessary 10pcs Only | 78.00 FS | *20.00 FS |
| 33 | 5 | | *REAR WHEEL ARCH GARNISH CLIP | O/s Necessary | 65.00 FS | *20.00 FS |
| 34 | 4 | | *REAR END PANEL TOP GARNISH CLIPS | Necessary | 34.00 FS | *10.00 FS |
| 35 | 1 | | *REAR END PANEL INSULATION SEAL | Necessary | 150.00 FS | *25.00 FS |
| 36 | 1 | | *REAR FLOOR PANEL INSULATION SEAL | Serviceable | 150.00 FS | *- FS |
| 37 | 1 | | *EXHAUST CHROME | Serviceable | 300.00 FS | *- FS |
| 38 | 1 | | *REVERSE SENSOR | Shorted | 220.00 FS | *200.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|---|---|
| **Sub Total (S$)** | **12,643.50** | **3,136.10** |
| **- List Item Discount on L Items 20.00/20.00% (S$)** | 1,872.00 | 514.02 |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|---|---|---|---|---|---|---|
| | | | | Total Parts (S$) | 10,771.50 | 2,622.08 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

**There are no new miscellaneous items selected.**

## Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---|---|---|---|---|
| **Labour Items** | | | | |
| 1 | TO PANEL BEAT, REMOVE AND REPLACE PARTS. | New | 1,200.00 | 700.00 |
| 2 | TO SPRAY PAINT AFFECTED AREA. | New | 1,000.00 | 600.00 |
| 3 | WIRING CHECK. | New | 80.00 | 20.00 |
| 4 | REMOVE AND REFIX REAR WINDSCREEN. | New | 150.00 | 0.00 |
| 5 | CONDUCT LEAKAGE TEST ON TAILGATE. | New | 80.00 | 30.00 |
| 6 | TUFF COTE. | New | 250.00 | 0.00 |
| 7 | REMOVE AND REFIX EXHAUST TAILPIPE. | New | 250.00 | 0.00 |
| 8 | REMOVE AND REFIX CUSHION SEAT / UPHOLSTERY TO FACILITATE REPAIR. | New | 350.00 | 50.00 |
| 9 | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING. | New | 250.00 | 30.00 |
| | | **Gross Labour Cost (S$)** | **3,610.00** | **1,430.00** |

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**