Invoice

REF: CS / MSG 20002925 / 697322

Special Instruction:
4sum : $ 16,500.00

ASSIGNMENT (Office)

From (Person): Chhia Myuk Rui of MSIG Date/Time: 19.2.2020 15.45pm

Estimated Cost: Bill to:

Third Parties:
Claimant:
Surveyor: Automax survey
Workshop: D's Graffiti Concepts Pte Ltd

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SGT 6336D Insured: SLN 41247

at Workshop m/s D's Graffiti Concepts Tel:

at 10 Ang Mo Kio Ind Park 2A AMK Autopoint # 03-12

Policy No: 2911 4756 Claim No: 603838

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 24/08/2019

9. March 2020 @ 1pm

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig. days (Red $ / %; Original 12 days)

Date/Time: 09/3 Submit Final Fig 6600 . 6 days (Red $ 9900 / 60 %; Original 12 days)

Date/Time	Action/Instruction
	SGT 6336D - CE/AIG 07004514/Gen DOA - 03/07/2007
	SLN 41247 - CS/GAI 170 20028/Collision DOA - 15/10/2017
	Spoken to ms chhia..
2/3/2020	Change to physical survey as kenneth says see no damage at outer, base on independent survey report.
	Inspection : 50 Serangoon North Ave 4 # 02-18
	Mr. Dave @ 8608 3456

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)

RECEIVED 11 MAR 2020

Do Not Finalise

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/ Evaluated by:

Fee Charged:	Date:
Basic & Add	200
Transport	
Photos	
Others	11
Total	211

1) Date/Time 10/3/20 File Pass to Inspector 2) Date/Time File Return to

3) Date/Time File Pass to 4) Date/Time File Return to

5) Date/Time File Pass to 6) Date/Time File Return to

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SGT6336D 1st Regn: 20 Feb 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Volkswagen Golf 1.4 c.c 1395

Colour Blue A/C: Insured / Std / NI / NA

Sp.Reading 67912 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVWZZZAUZHW119369

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIRELLI / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm
D.O.A.		D.O.I.	09/03/2020

Survey held at So Serangoon North Ave 4

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

9/3/2020

Date/Time, File Pass to?

1)

Date/Time, File Returns to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Inve ($)

☐ : Weekend ($)

Survey Fee:

Transportation: $ + RS $

Photo

Other:

Report Format :

Lump Sum / MB / Hrs

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner Information	
Owner ID Type:	Singapore NRIC
Owner ID:	301J
Vehicle Details	
Vehicle No.:	SGT6336D
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Mar 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF 1.4 TSI AT 5G13HZ
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	CZC161754
Chassis No.:	WVWZZZAUZHW119369
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	$20,460.00
Original Registration Date:	20 Feb 2017
First Registration Date:	20 Feb 2017
Transfer Count:	0
Actual ARF Paid:	$10,644.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Feb 2027
PARF Rebate Amount:	$7,983.00
Intended COE Rebate Details	
COE Expiry Date:	19 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	$48,401.00
COE Rebate Amount:	$33,621.00
Total Rebate Amount:	**$41,604.00**

The information contained herein is correct as at 09 Mar 2020

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	301J
Vehicle Details	
Vehicle No.:	SGT6336D
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Mar 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF 1.4 TSI AT 5G13HZ
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	CZC161754
Chassis No.:	WVWZZZAUZHW119369
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	$20,460.00
Original Registration Date:	20 Feb 2017
First Registration Date:	20 Feb 2017
Transfer Count:	0
Actual ARF Paid:	$10,644.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Feb 2027
PARF Rebate Amount:	$7,983.00
Intended COE Rebate Details	
COE Expiry Date:	19 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	$48,401.00
COE Rebate Amount:	$33,621.00
Total Rebate Amount:	**$41,604.00**

The information contained herein is correct as at 09 Mar 2020

OK

Post an Advertisement
Sell it yourself! Advertise it at just
$58 until it's SOLD!

Post an Ad | Advertiser Login | Ways of Selling

Honda HR-V 1.5A DX

Direct Owner

Browse by Category | Sort by Date Posted | 20 results/page

6 vehicles | Volkswagen Golf 1.4a

	Model	Price	Depreciation		Eng Cap	Mileage	Veh Type	
Search Selection	**Volkswagen Golf 1.4a**	Any	Any	**2017**	Any	Any	Any	**Available**

Volkswagen Golf 1.4A TSI EQP Sunroof | **$75,000** | $8,750 /yr | 17-Nov-2017 | 1,395 cc | 32,208 km | Hatchback | Available

Highest Spec "EQP" Model, Promo Offer Loan Interest At 2.28%, Extremely Well Maintained, Comes With Agent Warranty Of 5 Years And 3 Free Servicing Remaining, Battery Just Change On Oct 2019, Road Tax Renewed To May 2020, 80% Financing Of The Car Price Possib...

Posted: 05-Mar-2020 Tags: 2017 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf

Volkswagen Golf 1.4A TSI (OPC) | **$56,777** | $6,930 /yr | 16-Aug-2017 | 1,395 cc | - | Hatchback | Available

100% Loan Available! 1 Owner, Accident Free. Fabulous Unit With Extremely Neat Interior & Exterior, No Further Repairs Needed, Popular Hatchback Vehicle At 123bhp, Powerful, Good Handling, Smooth Transmission & Fuel Efficiency, Trade In Are Welcome. Don't Miss, Kind...

Posted: 04-Mar-2020 Tags: 2017 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf

Volkswagen Golf 1.4A TSI | **$68,888** | $8,420 /yr | 29-Sep-2017 | 1,395 cc | 72,000 km | Hatchback | Available

1 Owner, Accident-Free, Color Change Available, Fabulous Unit With Extremely Neat Interior And Exterior, No Further Repairs Needed, Popular Hatchback Vehicle At 123bhp, Powerful, Good Handling, Smooth Transmission And Fuel Efficiency, Trade In Are Welcome. Don't...

Posted: 01-Mar-2020 Tags: 2017 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf

Volkswagen Golf 1.4A TSI | **$72,800** | $9,030 /yr | 31-Aug-2017 | 1,395 cc | 39,000 km | Hatchback | Available

1st Owner. Interior Is Well Maintained With Beautiful Leather Seats. Get In Touch To View And Test Drive The Car.

Posted: 01-Mar-2020 Tags: 2017 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf

Monster Tune - Specialist for Volkswagen Car repair, servicing & maintenance

Full service custom tuning workshop with dealer-level diagnostic support, fleet management and performance modifications capability.

More info about this shop

Volkswagen Golf 1.4A TSI EQP Sunroof | **$78,000** | $9,410 /yr | 31-Aug-2017 | 1,395 cc | 31,000 km | Hatchback | Available

Come Drive Away The Renowned, Constantly Raved About VW Golf Today! Highest Specs EQP Model With All The Modern Features You Need In A Car! 5-Year Agent Warranty Valid Till Aug 2022 Making This An Absolute Worry-Free Buy! Flawless Bodywork With Ceramic C...

Car Buyers Automotive Pte Ltd

Posted: 28-Feb-2020 Tags: 2017 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf

Volkswagen Golf 1.4A TSI (OPC) | **$58,000** | $7,160 /yr | 26-Sep-2017 | 1,395 cc | 19,000 km | Hatchback | Available

Still Under Warranty With One Free Servicing By Agent. Pirelli P-Zero New Tyres, 1-Road Front And Rear Car Camera. 3M Window Film. Come With All Service Record And Handbook. Apple CarPlay.

Posted: 23-Jan-2020 Tags: 2017 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf

Save this search criteria, to get email alerts whenever a match is found.

	Price	Depreciation		Eng Cap	Mileage	Veh Type	

Compare

For s, View Ex

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Aug 2019		19 Feb 2020 15:45 Assign				**New Assignment** Cancel Case

Main | **Reference** | **Claim Details** | **Documents** | Show All

CLAIM SUBFOLDER DETAILS			**[Created by insurer]**
Insured:	**GRAB RENTALS PTE LTD**, Co. Reg. No.: 201617200G		
Main Claimant:	**HIN YUET YIN**, ID: S6876301J		
Vehicle Reg. No.:	**SGT6336D**	Date of Loss:	24/08/2019 11:00 - :59 [**30** Months and **4** Days From LTA Reg Date (Man Yr)]
Claim Type:	**TP** / 603838	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	**SLN4124J**	Policy No. (Claimant):	
		Excess:	
Repairer:	**- Not Applicable - (-)**		
Handling Insurer:	**MSIG Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: +65 6827 7888 ... [Handled by **Chhia Nyuk Pui** - 6594 2521]		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [**Imm.Advice** due 20/02/2020]		
Driver/Custodian (Insured):	LIM HOCK SENG ANTHONY () , NRIC: S1582892G, Tel: +6584826618 Email:		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

Denise Tay (LKKAuto)

From: Chhia Nyuk Pui <NyukPui_Chhia@sg.msig-asia.com>
Sent: Monday, 2 March 2020 10:32 AM
To: Dorothy Dylegal
Cc: SUR; Denise Tay (LKKAuto)
Subject: RE: Your ref: DY.08.0089.2019.dc. Our ref: 603838 (OI: SLN4124J)

Dear Dorothy

Without Prejudice
Save as to Costs

We would like to conduct a physical survey of your client's vehicle. Please make arrangement with our surveyor (copied) for a mutual suitable appointment.

Meanwhile, we note there is breach of nima protocol as your client's vehicle was repaired before we conduct pre-repair survey.

Aside to Denise, we just discussed this case. Thanks

Chhia Nyuk Pui
Senior Executive, Claims Services
Direct line +65 6594 2521 | Direct fax +65 6643 1349 | nyukpui_chhia@sg.msig-asia.com

From: Chhia Nyuk Pui
Sent: Wednesday, 19 February 2020 3:51 PM
To: Dorothy Dylegal <admin@dylegal.asia>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Your ref: DY.08.0089.2019.dc. Our ref: 603838 (OI: SLN4124J)

Dear Dorothy

Without Prejudice
Save as to Costs

Thanks for taking our call. We are looking into the claim and shall come back to you soon

Aside to LKK,
Please do paper survey. Thank you.

Please note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data for the purpose of assessing your claim. This may include disclosing and sharing your personal data with our service providers and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore, for the proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws (collectively, "the Purpose"). We may also need to disclose or share your personal data with service providers who are sited outside Singapore for the Purpose.

Chhia Nyuk Pui
Senior Executive, Claims Services
Direct line +65 6594 2521 | Direct fax +65 6643 1349 | nyukpui_chhia@sg.msig-asia.com

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Billing To: Hin Yuet Yin
c/o D's Graffiti Concepts Pte Ltd
10 ang mo kio ind park 2A
Amk autopoint #03-13
Singapore 568047

Invoice no.: TP19080078

Date: 13 Dec 2019

Vehicle no: SGT6336D

Model : VOLKSWAGEN GOLF 1.4 TSI

ITEM	DESCRIPTION	AMOUNT
1	Date of Inspection : 26 AUG 2019 copies of the inspection / survey report Correspondence, postages and etc.	$ 900.00
2	Photography Services Develop photographs Storage of digital photographs	
3.	To submit report by hand.	
4.	Charges on photocopies, posting, faxes and others incidental works entrusted.	
5	Transportation Charges	
6	Reinspection Charges	
	TOTAL :	$ 900.00

Notes :

1. All cheque payment should be "crossed" and made payable to "Automax Survey".
2. Please contact us if there are further enquiries on the invoice.

Official Stamp

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Report Ref : TP19080078

Date: 13 Dec 2019

Hin Yuet Yin
c/o D's Graffiti Concepts Pte Ltd
10 ang mo kio ind park 2A
Amk autopoint #03-13
Singapore 568047

THIRD PARTY SURVEY
ACCIDENT OCCCURED ON 24 AUG 2019

Workshop Name and Address

D's Graffiti Concepts Pte Ltd
10 ang mo kio ind park 2A
Amk autopoint #03-13
Singapore 568047

As per your instruction dated 26 AUG 2019 with regard to the above matter.
We have carried out a physicial inspection on the said SGT6336D
We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SGT6336D
Model : VOLKSWAGEN GOLF 1.4 TSI
Year / Capacity : Feb 2017 / ~~1398~~ cc 1395
Chassis No : WVWZZZAUZHW119369

Engine No : CZC161754
Mileage : 56 708 km
Colour : Metallic Blue

2. TYRES CONDITION

	Size	Made	Balance	Rim
FRONT O/S :	215/45/R17	Firestone	9.00 mm	Sport
REAR O/S :	215/45/R17	Firestone	9.00 mm	Sport
FRONT N/S :	215/45/R17	Firestone	9.00 mm	Sport
REAR N/S :	215/45/R17	Firestone	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the **rear side** portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 12 working days to complete

5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comprarison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SGT6336D

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S$)	Our Revised Estimation (S$)
	List Items			
1 pc	Rear fender	bend/distorted	$ 1,652.00	$ 1,652.00
1 pc	Rear knuckle arm	bent/distorted	$ 750.00	$ 750.00
1 pc	Rear lower arm	distorted	$ 350.00	$ 350.00
1 pc	Rear upper arm	distorted	$ 285.00	$ 285.00
1 pc	Rear control arm	bent/distorted	$ 200.00	$ 200.00
1 pc	Rear wheel bearing hup	bent/distorted	$ 525.00	$ 525.00
1 pc	Rear absorber	distorted	$ 368.00	$ 368.00
1 pc	Rear absorber mounting	wraped/deformed	$ 150.00	$ 150.00
1 pc	Rear track rod		$ 145.00	$ 145.00
1 pc	Rear axle guide with bracket		$ 168.00	$ 168.00
1 pc	Rear wish bone		$ 200.00	$ 200.00
1 pc	Rear bumper	bent	$ 680.00	$ 680.00
1 pc	Rear bumper side retainer	bent	$ 64.00	$ 64.00
1 pc	Rear bumper side bracket - top	bent	$ 65.60	$ 65.60
10 pcs	Rear bumper clips	necessary	$ 65.00	$ 65.00
		Parts Sub-Total	$ 5,667.60	$ 5,667.60
	Discount	10.00%	$ 566.76	$ 566.76
			$ 5,100.84	$ 5,100.84

Vehicle Number : SGT6336D

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S$)	Our Revised Estimation (S$)
	Special Nett Items			
1 pc	Rim assembly (sport)	grazed/distorted	$ 680.00	$ 680.00
1 pc	Tyre assembly	grazed/deformed	$ 380.00	$ 350.00
2 pcs	Front seat belt with tensioner — 1212.8 (-10%)	deployed	$ 2,200.00	$ 2,200.00
2 pcs	Front seat belt catch with sensor	deployed	$ 800.00	$ 800.00
1 pc	Head roof side air bag — 1325.83 (-10%)	deployed	$ 2,200.00	$ 2,200.00
1 pc	Seat air bg with trim — 1354.17 (-10%)	deployed	$ 1,970.00	$ 1,970.00
		Special Nett Sub-Total	$ 8,230.00	$ 8,200.00
		Spare Parts Total	$ 13,330.84	$ 13,300.84

6525.73

10% = 5873.15

LABOUR COST

S/No	JOB DESCRIPTIONS		Workshop Estimation (S$)		Our Revised Estimation (S$)
	Spare PartsTotal c/f	$	13,330.84	$	13,300.84
1	Towing	$	120.00	$	50 120.00
2	To remove and refix interior upholstery	$	200.00	$	60 180.00
3	To remove and replace undercarriage	$	380.00	$	200 350.00
4	To check and adjust computer wheel alignment	$	240.00	$	60 220.00
5	To remove and replace seat belt tensioner	$	300.00	$	100 280.00
6	To remove and replace side air bag	$	280.00	$	100 260.00
7	To remove and replace head roof air bag	$	800.00	$	200 700.00
8	To reprograme and cabiliation on airbag system incl reset	$	1,000.00	$	150 800.00
9	To respray affected areas	$	1,400.00	$	400 1,200.00
10	To renew damaged parts, straighten and repair rear chassis member, bootlid and aligned all parts	$	1,600.00	$	400 1,400.00
11	To tuff coat affected areas	$	180.00	$	X 150.00
	1720 Total	$	19,830.84	$	18,960.84

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of : $ **16,500.00**

6 Days

8273.15

20% : 6600

Fong Kok Heng
Qualified Appraiser

Enquire Vehicle & Owner Information (Vehicle No. SLN4124J As At 24 Aug 2019 / 11:40:00)

Search Reason:	Insurance claim in relation to traffic accident
Law Firm Case No.:	DY.08.0089.2019.DC

Owner ID Type:	Company
Owner ID:	201617200G
Owner Name:	GRAB RENTALS PTE. LTD.
Registered Address Type:	Private Residential (non-Condo Apt / non-House)
Registered Block/House No.:	6
Registered Street Name:	SHENTON WAY
Registered Unit No.:	# 38 - 01
Registered Building Name:	OUE DOWNTOWN
Registered Postal Code:	068809

Vehicle No.:	SLN4124J
Make Description/Model:	TOYOTA / PRIUS HYBRID 1.8 CVT
Insurance Company Name:	MSIG INSURANCE (SINGAPORE) PTE LTD

CASH SALE

No: 16

D.S. GRAFFITI CONCEPTS PTE LTD
REG 201631044K

Messrs: VOLKSWAGEN GOLF 1.4 TSI
SGT 6336 D

DATE: 13/DEC/2019

U-GRADE

ITEM	DESCRIPTION	QUANTITY	UNIT PRICE		TOTAL	
					$16,500	—
			SUB TOTAL :			
			:			
			TOTAL :		$16,500	—

E. & O. E.

ISSUE BY:

603838
CNP
REG / CS / FAY / FA
24 DEC 2019

DY

DY & Associates
Advocates & Solicitors

Our Ref: DY.08.0089.2019.dc

Your Ref: Please advise

20 December 2019

WITHOUT PREJUDICE

1. **MSIG INSURANCE (SINGAPORE) PTE. LTD.**
16 Raffles Quay
#24-01 Hong Leong Building
Singapore 048581

BY HAND
(with enclosures)

Attention: Motor Claims Department

2. **GRAB RENTALS PTE. LTD.**
6 Shenton Way
#38-01 OUE Downtown
Singapore 068809

VIA CERTIFICATE OF POSTING
(without enclosures)

Dear Sirs

CLAIMANT: HIN YUET YIN

ACCIDENT INVOLVING SGT 6336D AND SLN 4124J ALONG MOULMEIN ROAD / MOULMEIN RISE ON 24.08.2019

1. We act for Mdm Hin Yuet Yin, owner of vehicle registration no. SGT 6336D.

2. We are instructed to claim damages against you/your servant and/or agent/your insured in connection with the above-captioned accident involving our client(s) vehicle no. SLN 4124J owned and/or insured by you at the material time.

3. We are instructed that the accident was caused by your servant and/or agent/your insured's negligent driving and/or management of your/your insured's vehicle. As a result of the accident, our client(s) vehicle was damaged and our clients' had been put to loss and expense, particulars of which are as follows:

(a)	Costs of Repairs	S$16,500/-
(b)	Loss of use (12 days x S$80.00 per day)	S$960/-
(c)	Survey Report Fee	S$900/-
(d)	LTA/GIA Search/Reports	S$39/-
(e)	Costs	S$900/-
(f)	Incidentals	S$60/-
	TOTAL	**S$19,359/-**

Cont'd...2

David Yong Khung Lin
LLB (Hons) (University of Bristol)

Tel 6292 2388
Fax 6292 2088
admin@dylegal.asia

83 Kim Yam Road #03-01
Singapore 239378

$1500/12 \cancel{=708} \times 90$

$= 63750$

MV : 68K.

A copy of each of the following supporting documents is enclosed:-

(a) Our client's Singapore Accident Statement;

(b) LTA Search on SLN 4124J;

(c) Singapore Accident Statement on SLN 4124J;

(d) Repairs tax invoice no. 16 from D's Graffiti Concepts Pte Ltd; and

(e) Survey report, tax invoice and sixty-one (61) coloured photos of damages to our client(s) vehicle from M/s Automax Survey.

4. The demand herein is in respect of our client(s) claim for damages pertaining to their motor vehicle and any settlement following or subsequent to this demand shall not prejudice our client(s) claim in respect of damages and consequential loss in relation to his personal injuries.

5. Please note that:

(a) if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter to your insurer;

(b) you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which, our client(s) will have no alternative but to commence proceedings against you without further notice to you or your insurer;

(c) if you have a counterclaim against our client(s) arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully

DY & ASSOCIATES

Encls.

Cc MSIG Insurance (Singapore) Pte. Ltd. (insurers of SGT 6336D)
Please keep us informed should you receive any third party claim.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	26/08/2019 11:37
Date Of Accident	24/08/2019 11:40
Exact Location Of Accident	MOULMEIN ROAD / MOULMEIN RISE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGT6336D
Insured/Policyholder	
Name Of Registered Owner	HIN YUET YIN
NRIC No	S6876301J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92392028
Alternative Phone No	OFFICE-92392028
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	GOLF 1.4 TSI AT 5G13HZ
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 28897822 AVW (COMP)
Cover Note Number	
Driver	
Name of Driver	LIM WEI CONG
NRIC No	S9909278E
Date Of Birth	26/03/1999
Occupation	OUTDOOR
Date Of Driving Pass	19/01/2018
Driving Experience	1 YEAR AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90886339
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	50 YUNNAN CRESCENT
Postcode	638349
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLN4124J
Vehicle Make/Model/Colour	TOYOTA / PRIUS HYBRID 1.8 CVT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	LIM WEI CONG

Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SGT6336D
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

   I understand, acknowledge, agree and consent that:

   (a) My insurer, my workshop and the General Insurance Association of Singapore ("**GIA**") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

   (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

   (ii) investigating the accident and/or my claims;

   (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

   (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail package(s); and/or

   (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**").

   (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

   (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;

   (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;

   (e) the information so collected under (d) above may be shared / disclosed:

   (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or

   (ii) for complying with requirements under any regulations, laws or court orders.

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vack b@singnet.com.sg

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Name:
NRIC/FIN No.

26 AUG 2019

Sketch Plan #2

SLN 4129 J

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

After making a U-turn I straighten my vehicle on the second lane the other vehicle enter Moulmein Rd from Moulmein rise and hit me on the left back wheel area.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 26 AUG 2019

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Reporting Centre Personnel - Signature
Name
NRIC/FIN No.

A-HR CLINIC (PIONEER NORTH)
RONG WEST STREET 92
INGAPORE 640959

GST Reg No : 200900676M

Co Reg No : 200900676M

TAX INVOICE

LIM WEI CONG
50 YUNNAN CRESCENT
#
S(638349)

Invoice No. : 9273
Our Reference : 05078
Date : 24 Aug 2019

Patient : LIM WEI CONG (S9909278E)

Doctor : LOCUM

SINGAPORE

DESCRIPTION	QTY	FEE (S$)
SODEN(SYFLEX/NAPROXEN) 275MG	10.00 tabs	6.00
CONSULTATION		55.00
	Sub-Total	61.00
	Add GST 7.0%	4.27
	Rounding Adjustment	-0.07
	Total Amount Payable	65.20
Receipt No. 15791 - NETS	**Payment Received**	65.20
	Outstanding Balance	0.00

All cheques should be crossed and made payable to :

CENTRAL 24-HR CLINIC (PIONEER NORTH)

This is a computer generated invoice which does not require a signature
E. & O.E

For Health News and Updates : http://news.centralclinic.com.sg

24-Hour Clinics

HOUGANG	Blk 681 Hougang Ave 8 #01-531 Singapore 530681	Tel: 6287 6955
BEDOK	Blk 210 Bedok Central #01-124 Singapore 460210	Tel: 6287 6122
PASIR RIS	Blk 446 Pasir Ris Drive 6 #01-122 Singapore 510446	Tel: 6582 2640
TAMPINES	Blk 201D Tampines Street 21 #01-1101 Singapore 524201	Tel: 6859 7981
CLEMENTI	Blk 410 Clementi Ave 3 #01-391 Singapore 120410	Tel: 6773 2820
YISHUN	Blk 701A Yishun Ave 5 #01-04 Singapore 761701	Tel: 6754 7985
JURONG WEST	Blk 490 Jurong West Street 41 #01-04 Singapore 640490	Tel: 6265 7484
PIONEER NORTH	Blk 909 Jurong West Street 92 #01-100 Singapore 640909	Tel: 6254 2175
WOODLANDS	Blk 704 Woodlands Ave 6 #02-164 Woodlands Mart Singapore 730704	Tel: 6365 4055
MARSILING	Blk 303 Woodlands Street 31 #01-185 Singapore 730303	Tel: [illegible]

CENTRAL 24-HR CLINIC (PIONEER NORTH)
BLK 959 JURONG WEST STREET 92
#01-160 SINGAPORE 640959

Medical Certificate

Date : **24 Aug 2019**
MC No. : **0000016365**

This is to certify that :

Name : LIM WEI CONG
NRIC : S9909278E

is Unfit for Duty for 2 days

from 25/08/2019 to 26/08/2019 inclusive.

LOCUM

For Health News and Updates : http://news.centralclinic.com.sg

24-Hour Clinics

YISHUN	Blk 701A Yishun Ave 5 #01-04 Singapore 760701	Tel: 6758 7985
JURONG WEST	Blk 432 Jurong West Street 41 #01-04 Singapore 640432	Tel: 6265 7484
PIONEER NORTH	Blk 959 Jurong West Street 92 #01-160 Singapore 640959	Tel: 6253 2725
WOODLANDS	Blk 768 Woodlands Ave 4 #02-355 Woodlands Mart Singapore 730768	Tel: 6363 4895
MARSILING	Blk 303 Woodlands Street 31 #01-195 Singapore 730303	Tel: 6361 2968

This certificate is not valid for absence from court or other judicial proceedings unless specifically stated.

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo



Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

MBHH19111662 / Ajax Mars Pte Ltd - Bukit Merah
ENTRY DATE & TIME: 24/08/2019 15:05
SUBMITTED BY: Chai MiLin

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/08/2019 15:05
Date Of Accident	24/08/2019 11:45
Exact Location Of Accident	SINARAN DR TOWARDS MOULMEIN RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN4124J
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	2XXXXX200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-66550005
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS HYBRID 1.8 CVT
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29114756MKF
Cover Note Number	
Driver	
Name of Driver	LIM HOCK SENG ANTHONY
NRIC No	SXXXX892G
Date Of Birth	15/07/1963
Occupation	OUTDOOR
Date Of Driving Pass	13/05/1987
Driving Experience	32 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84826618

Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	Name: : P1 Gender: : Female
Passenger 2	Name: : P2 Gender: : Female

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

I SLN4124J was driving along Sinaran drive making a left turn to Moulmein rd.As I was making a left turn towards the main road,suddenly I saw the 3rd party SGT6336D was make a u-turn from the on coming direction and there was no time for me to react as both parties was making a turn on a same timing and collided with the 3rd party left side of his vehicle.I manage to take some photos and exchange particulars with the 3rd party,no injuries was involved at the scene.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	NA
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGT6336D
Vehicle Make/Model/Colour	VOLKSWAGEN GOLF
Details Of Properties	

Vehicle Category	PRIVATE CAR
Name of Driver	LIM EI CONG
NRIC/Passport Number	SXXXX278E
Contact Number	90886339
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available afterward.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to an insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER
MUHAMMAD SUMARDI BIN
MOHD AFFANDI

Policyholder's Signature / Date & Time | Driver's Signature (If driver is not the policyholder) / Date & Time | Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan #2

ACCIDENT STATEMENT (2000 characters)

I SLN4124J was driving along Sinaran drive making a left turn to Moulmein rd.As I was making a left turn towards the main road,suddenly I saw the 3rd party SGT6336D was make a u-turn from the on coming direction and there was no time for me to react as both parties was making a turn on a same timing and collided with the 3rd party left side of his vehicle.I manage to take some photos and exchange particulars with the 3rd party,no injuries was involved at the scene.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER - MUHAMMAD SUMARDI BIN MOHD AFFANDI

MARS Officer

Registered Owner or Driver's Signature

Job Complete Date/Time

24 August 2019 at 1:34 PM

Date/Time:

24 August 2019 at 1:34 PM

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo

Accident Photo



Accident Photo

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Aug 2019		19 Feb 2020 15:45 Edit Adj Rpt	**S$6,600.00** Edit Estimates	**S$6,600.00** View Rpt		**Pending for Survey Report** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS **[Created by Insurer]**

Insured:	**GRAB RENTALS PTE LTD**, Co. Reg. No.: 201617200G		
Main Claimant:	**HIN YUET YIN**, ID: S6876301J		
Vehicle Reg. No.:	**SGT6336D**	Date of Loss:	24/08/2019 11:00 - :59 [**30** Months and **4** Days From LTA Reg Date (Man Yr)]
Claim Type:	**TP** / 603838	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	**SLN4124J**	Policy No. (Claimant):	
		Excess:	
Repairer:	**- Not Applicable - (-)**		
Handling Insurer:	**MSIG Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: +65 6827 7888 ... [Handled by **Chhia Nyuk Pui** - 6594 2521]		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **XING GUO QIANG**] ... [**Imm.Advice** due 20/02/2020]		
Driver/Custodian (Insured):	LIM HOCK SENG ANTHONY () , NRIC: S1582892G, Tel: +658482661B Email:		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGT6336D (603838)**
[SLN4124J]
TP
HIN YUET YIN
Aug 24 2019 11:00AM
[GRAB RENTALS PTE LTD]

Upload Documents | Upload Photos | Compose New Letter

View: View in Browser

Assessment Reports — 1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	27/08/19 17:15	**Accident Statement** From:SC - Reg. No: SLN4124J, Claimant: GRAB RENTALS PTE LTD		Load HTM	

Photos/Images — 3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/03/20 13:26	**General View**		Load JPG	
2	10/03/20 13:26	**General View**		Load JPG	
3	10/03/20 13:26	**General View**		Load JPG	
4	10/03/20 13:26	**General View**		Load JPG	
5	10/03/20 13:26	**General View**		Load JPG	
6	10/03/20 13:26	**General View**		Load JPG	
7	10/03/20 13:26	**General View**		Load JPG	
8	10/03/20 13:26	**General View**		Load JPG	
9	10/03/20 13:26	**General View**		Load JPG	
10	10/03/20 13:26	**General View**		Load JPG	
11	10/03/20 13:26	**General View**		Load JPG	
12	10/03/20 13:26	**General View**		Load JPG	
13	10/03/20 13:26	**General View**		Load JPG	
14	10/03/20 13:26	**General View**		Load JPG	
15	10/03/20 13:26	**General View**		Load JPG	
16	10/03/20 13:26	**General View**		Load JPG	
17	10/03/20 13:26	**General View**		Load JPG	
18	10/03/20 13:26	**General View**		Load JPG	
19	10/03/20 13:26	**General View**		Load JPG	
20	10/03/20 13:26	**General View**		Load JPG	
21	10/03/20 13:26	**General View**		Load JPG	
22	10/03/20 13:26	**General View**		Load JPG	
23	10/03/20 13:26	**General View**		Load JPG	
24	10/03/20 13:26	**General View**		Load JPG	
25	10/03/20 13:26	**General View**		Load JPG	
26	10/03/20 13:26	**General View**		Load JPG	
27	10/03/20 13:26	**General View**		Load JPG	
28	10/03/20 13:26	**General View**		Load JPG	
29	10/03/20 13:26	**General View**		Load JPG	
30	10/03/20 13:26	**General View**		Load JPG	
31	10/03/20 13:26	**General View**		Load JPG	
32	10/03/20 13:26	**General View**		Load JPG	
33	10/03/20 13:26	**General View**		Load JPG	
34	10/03/20 13:26	**General View**		Load JPG	

Assessment Reports			1 per page		☑
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
35	10/03/20 13:26	General View		Load JPG	☑
36	10/03/20 13:26	General View		Load JPG	☑
37	10/03/20 13:26	General View		Load JPG	☑
38	10/03/20 13:26	General View		Load JPG	☑
39	10/03/20 13:26	General View		Load JPG	☑
40	10/03/20 13:26	General View		Load JPG	☑
41	10/03/20 13:26	General View		Load JPG	☑
42	10/03/20 13:26	General View		Load JPG	☑
43	10/03/20 13:26	General View		Load JPG	☑
44	10/03/20 13:26	General View		Load JPG	☑
45	10/03/20 13:26	General View		Load JPG	☑
46	10/03/20 13:26	General View		Load JPG	☑
47	10/03/20 13:26	General View		Load JPG	☑
48	10/03/20 13:26	General View		Load JPG	☑
49	10/03/20 13:26	General View		Load JPG	☑
50	10/03/20 13:26	General View		Load JPG	☑
51	10/03/20 13:26	General View		Load JPG	☑
52	10/03/20 13:26	General View		Load JPG	☑
53	10/03/20 13:26	General View		Load JPG	☑
54	10/03/20 13:26	General View		Load JPG	☑
55	10/03/20 13:26	General View		Load JPG	☑
56	10/03/20 13:26	General View		Load JPG	☑
57	10/03/20 13:26	General View		Load JPG	☑
58	10/03/20 13:26	General View		Load JPG	☑
59	10/03/20 13:26	General View		Load JPG	☑
60	10/03/20 13:26	General View		Load JPG	☑
61	10/03/20 13:26	General View		Load JPG	☑
62	10/03/20 13:26	General View		Load JPG	☑
63	10/03/20 13:26	Odometer Reading		Load JPG	☑
64	10/03/20 13:26	Chassis Number		Load JPG	☑

Documentation			1 per page		☑
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	27/08/19 17:15	TP SGT6336D E-REPORT From:SC - Reg. No: SLN41243, Claimant: GRAB RENTALS PTE LTD		Load PDF	
2	27/12/19 13:49	AK TP lawyer		Load HTM	
3	17/02/20 10:42	LOD from DY & Associates		Load PDF	
4	17/02/20 10:43	Cost of repair		Load PDF	
5	17/02/20 10:44	Survey fees. reports and photos		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/03/20 16:49	Colour Photo1		Load PDF	
2	11/03/20 16:49	Colour Photo2		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20002925/GQF3E2
Date: 11/03/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29114756		
Claimant Vehicle No :	SGT6336D	**Insured Vehicle No :**	SLN4124J		
Date of Loss:	24/08/2019	Nature of Claim:	TP	Claim No:	603838

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SGT6336D**		
Make & Model:	VOLKSWAGEN GOLF, 1.4 A7 TSI AT BMT 5G14JZ SR HID (A)	Engine No:	CZC161754
Reg. Date:	20/02/2017 (Man. Year: 2016)	Chassis No:	WVWZZZAUZHW119369
Colour:	Blue	Odometer:	67412 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,330.84	6,553.16	6,777.68	50.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,500.00	1,720.00	4,780.00	73.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**19,830.84**	**8,273.16**	**11,557.68**	**58.28**
Approved Total (Overridden) (S$)		**6,600.00**		
Nett Amount (S$)	**19,830.84**	**6,600.00**	**13,230.84**	**66.72**

INSPECTION

Date of Assignment:	19/02/2020		
Date Inspected:	09/03/2020	Inspected At:	50 Serangoon North Ave4 #02-18 Repairer : D'S GRAFFITI CONCEPTS PTE LTD
Estimated Period of Repair:	6.0 days		

Adjuster: XING GUO QIANG **Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Mar 2020)
Parts:	144	VOLKSWAGEN GOLF 1.4 A7 TSI AT BMT 5G14JZ SR HID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGT6336D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		***REAR FENDER**	Repaired	1,652.00 FL	*- FL
2	1		***REAR KNUCKLE ARM**	Replaced	750.00 FL	*750.00 FL
3	1		***REAR LOWER ARM**	Replaced	350.00 FL	*350.00 FL
4	1		***REAR UPPER ARM**	Serviceable	285.00 FL	*- FL
5	1		***REAR CONTROL ARM**	Serviceable	200.00 FL	*- FL
6	1		***REAR WHEEL BEARING HUP**	Replaced	525.00 FL	*525.00 FL
7	1		***REAR ABSORBER**	Replaced	368.00 FL	*316.32 FL
8	1		***REAR ABSORBER MOUNTING**	Replaced	150.00 FL	*91.61 FL
9	1		***REAR TRACK ROD**	Serviceable	145.00 FL	*- FL
10	1		***REAR AXLE GUIDE WITH BRACKET**	Serviceable	168.00 FL	*- FL
11	1		***REAR WISH BONE**	Serviceable	200.00 FL	*- FL
12	1		***REAR BUMPER**	Serviceable	680.00 FL	*- FL
13	1		***REAR BUMPER SIDE RETAINER**	Serviceable	64.00 FL	*- FL
14	1		***REAR BUMPER SIDE BRACKET - TOP**	Serviceable	65.60 FL	*- FL
15	10		***REAR BUMPER CLIPS**	Serviceable	65.00 FL	*- FL
16	1		***RIM ASSEMBLY (SPORT)**	Replaced	680.00 FS	*680.00 FS
17	1		***TYRE ASSEMBLY**	Serviceable	380.00 FS	*- FS
18	2		***FRONT SEAT BELT WITH TENSIONER** }	Replaced	2,200.00 F	*1,812.80 FN
19	2		***FRONT SEAT BELT CATCH WITH SENSOR** }	Replaced	800.00 F	*- FN
20	1		***HEAD ROOF SIDE AIR BAG**	Replaced	2,200.00 F	*1,325.83 FN
21	1		***SEAT AIR BG WITH TRIM**	Replaced	1,970.00 F	*1,354.17 FN

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S$)	**13,897.60**	**7,205.73**
- List Item Discount on L Items 10.00/10.00% (S$)	566.76	203.29
- Nett Item Discount on N Items 0.00/10.00% (S$)	0.00	449.28
Total Parts (S$)	**13,330.84**	**6,553.16**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	120.00	50.00
2	TO REMOVE AND REFIX INTERIOR UPHOLSTERY	New	200.00	60.00
3	TO REMOVE AND REPLACE UNDERCARRIAGE	New	380.00	200.00
4	TO CHECK AND ADJUST COMPUTER WHEEL ALIGNMENT	New	240.00	60.00
5	TO REMOVE AND REPLACE SEAT BELT TENSIONER	New	300.00	100.00
6	TO REMOVE AND REPLACE SIDE AIR BAG	New	280.00	100.00
7	TO REMOVE AND REPLACE HEAD ROOF AIR BAG	New	800.00	200.00
8	TO REPROGRAME AND CABILIATION ON AIRBAG SYSTEM INCL RESET	New	1,000.00	150.00
9	TO RESPRAY AFFECTED AREAS	New	1,400.00	400.00
10	TO RENEW DAMAGED PARTS, STRAIGHTEN AND REPAIR REAR CHASSIS MEMBER, BOOTLID AND ALIGNED ALL PARTS	New	1,600.00	400.00
11	TO TUFF COAT AFFECTED AREAS	New	180.00	0.00
		Gross Labour Cost (S$)	**6,500.00**	**1,720.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >