ASS. REC. BY: | REF: CS3/SPF20003220/Bt d3/27 Special Instruction:

Surveyor: TM

ASSIGNMENT (Office)

From (Person): Cui Fen Eng of SPF Date/Time: 26/2/2020 @ 3.08pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDL6611L Insured: QX 558E

at Workshop m/s Mylcar Consultant Tel: 88668832

of 53 ubi Avenue 1 #01-33

Policy No: Claim No: AEMD/105/009/2020/006

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 22/2/2020

CA / REV / REP. / REV 24 HRS (up) H.O.D. Endorsement:

Date/Time: 3.16pm @ 26/2/2020 Person Contacted: Hui Qin Vehicle IN / OUT

Date/Time	Action/Instruction Estimate (X)
	SDL 6611L - NA/MSG19017745/Z4 DOA: 7/10/19
	QX 588E - X
	Submit preli report
	Weekend - 1, Repair days 4 : Total: 5.

Do Not Finalise

ASS. REC. BY: | REF: SPF

ASSIGNMENT

From: | Date: 27/02/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDL 6611L

at Workshop m/s My Car Consultant

of 53 Ubi Avenue 1 # 01-33

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: 4 days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SDL 6611L | Yr Regn: 23/1/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Nissan Qashqai | c.c 1197

Colour Red | A/C: Insured / Std / NI / NA

Sp.Reading 94861 | T/Radio: Insured / Std / NI / NA

Eng/No: HRA2336745A

C/No: SJNFEAJ11U1800233

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60/17 Sumitomo

R: 215/60/17 Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / frt

TOYO / YOKO or Falken rear

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm

D.O.A. 22/2/2020 | D.O.I. 27/02/2020 1113AM

Survey held at LKK Auto Consultants

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range ~~2,000/2~~ 1750 - 3,000/2 88028832 (Range)
	RECEIVED 2020
	09/03/2020 COR seen. 2K as the higher COR.
	L/S 1750/2 TGuanHiu 6/3/2020
	MV 64,000.00 For lower COR to remove
	PV 45,286.00 Item 4, 5, 7, 8
	NV 18,714.00

Do Not Finalise

Date/Time, File Pass to? 1) 16/3 Typist

Date/Time, File Return to? 2)

☑ : Preli. Report

☐ : Final Report

Days of Repair: 4

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:	220
Transportation:	
S + RS, SI	
Photos	
Others	
TOTAL	220

Nivitha (LKK Auto)

From: Cui Fen ENG (SPF) <ENG_Cui_Fen@spf.gov.sg>
Sent: Wednesday, 26 February 2020 3:08 PM
To: Admin-D (LKKAuto); assignments; SUR
Cc: Frankie THAY (SPF); Hafizul Farhan RAHMAT (SPF); Lai Kuen LUI (SPF)
Subject: Pre-repair survey of SDL 6611L (vs QX 588E on 22 Feb 2020)

Importance: High

Our ref: AEMD/105/009/2020/006

Good Afternoon,

Kindly conduct pre-repair survey for SDL 6611L at:

My Car Consultant Pte Ltd
53 Ubi Ave 1
Paya Ubi Industrial Park #01-33
Singapore 408934
Contact: Huiqin, Tel: 88668832

Thank you.

Regards,

Eng Cui Fen (Ms)
1 Logistics Services Executive
Logistics Support and Services Division
Logistics Department
Singapore Police Force
DID: 68428401

SPF200
SALUTING THE PAST • SAFEGUARDING THE FUTURE

Singapore Police Force – *Commemorating 200 Years of Policing*

WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	24/02/2020 16:59
Date Of Accident	22/02/2020 00:35
Exact Location Of Accident	63 HILLVIEW AVE LAM SOON INDUSTRIAL BLDG
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SDL6611L
Insured/Policyholder	
Name Of Registered Owner	TENG KIM YUEN
NRIC No	SXXXX818J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97856655
Alternative Phone No	OFFICE-97856655
Vehicle Particulars	
Manufacturer	NISSAN
Model	QASHQAI
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA526749
Cover Note Number	
Driver	
Name of Driver	TENG ZI'AN KEVIN
NRIC No	SXXXX149B
Date Of Birth	27/12/1981
Occupation	OUTDOOR
Date Of Driving Pass	05/04/2002
Driving Experience	17 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91801433
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	79 TAI HWAN HEIGHTS
Postcode	555424
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes,Please state which Police Station	
Police Station Name	BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE
Police Station Address	**ROAD**: 21 BUKIT BATOK EAST AVE 4 , **POSTCODE:** 659840 , **COUNTRY**: SINGAPORE
Police Station Contact	**TEL NO**: 1800-6659999 - **FAX NO**: 66655793
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: J/20200222/2020.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX558E
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

(e) the information so collected under (d) above may be shared / disclosed:

(i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/FIN No.: 24/2/2020 15:10

Sketch Plan #2 Pg. 1

Veh A
SDL 6611 L

Veh B
QX 598 F



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Prefer to Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

LETTER OF UNDERTAKING

I/We, TENG KIM YMEN, the owner of vehicle no. SDL 6611L

My/Our Insurance is under M/s AXA Insurance Pte Ltd , I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Pte Ltd with all relevant facts and documents **within 14(fourteen) days of occurrence or discovery of damage.**

My/Our Third Party claim is handle by my/our preferred workshop, MY CAR

Signed and Acknowledge by:

.....	.....	24/03/2020
Nric no. & signature of policyholder	Company stamp	Date

SINGAPORE POLICE FORCE

J/20200222/2020

POLICE REPORT (NP299)

Report No. J/20200222/2020

Police Station Of Origin
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Date/Time Report Made	Vide Report No.	Station Diary No.
22/02/2020 04:51		19

Name Of Informant TENG ZI'AN KEVIN	Address 79 TAI HWAN HEIGHTS SINGAPORE 555424			
ID Type / ID No. NRIC NO / S8141149B	Contact No. Home/Office		Mobile 91801433	
Nationality SINGAPORE CITIZEN	Email Address			
Occupation Technical Manager	Sex Male	Age 38	Date of Birth 27/12/1981	Race Chinese
Institution/School Name	Language			
Date/Time Of Incident 22/02/2020 00:35	Location Of Incident 63 HILLVIEW AVENUE LAM SOON INDUSTRIAL BUILDING SINGAPORE 669569 6th floor, multi storey carpark			

Brief details.

On 22/02/2020 at about 0036hrs, I received a call from my father, Teng Kim Yuen who is the vehicle owner of SDL6611L (V1). He called to inform of an accident between V1 and a police car. My father called me as I am the only one driving V1.

On reaching at the incident location, I was told by police officer SGT Hamizan that his partner had reversed vehicle QX558E into V1 while V1 was parked. There is a scratch on the left portion of V1's front

Signature Of Officer Recording The Report: J / Staff Sgt MUSHAWWIR BIN ADRUS	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 22/02/2020 04:51
Officer In-Charge Of Case: J / Jurong Police Divisional Investigation Branch / SI RAMESH S/O SHANGKARAN Contact No.: 63167449	Classification Of Case:

Authentication Stamp

SINGAPORE POLICE FORCE
SAFEGUARDING EVERY DAY

SIGNATURE

SINGAPORE POLICE FORCE

J/20200222/2020

POLICE REPORT (NP299) CONTINUATION OF REPORT Report No. J/20200222/2020

bumper. There is also a slight detachment of the bumper at the affected portion.

Signature Of Officer Recording The Report: J / Staff Sgt MUSHAWWIR BIN ADRUS	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 22/02/2020 04:51
Officer In-Charge Of Case: J / Jurong Police Divisional Investigation Branch / SI RAMESH S/O SHANGKARAN Contact No.: 63167449	Classification Of Case:

Authentication Stamp

SINGAPORE POLICE FORCE
SAFEGUARDING EVERY DAY

SIGNATURE

MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z
Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934
HP: 98888885

Estimation

Date: 27 Feb 20
Vehicle: SDL6611L
Make / Model NISSAN/QASHQAI
Chassis:

No.	Description	Unit	Unit Price	Amount	
	Parts Replacement:				
1	FRONT BUMPER	1	$ 742.90	$ ~~742.90~~	CUT✓ 682.90
2	FRONT BUMPER LOWER GARNISH	1	$ 312.00	$ ~~312.00~~	ND X
2	FRONT BUMPER BRACKET LH	1	$ 71.47	$ 71.47	BR ✓✓
3	FRONT BUMPER RETAINER LH	1	$ 26.45	$ 26.45	NEC✓✓
~~4~~	~~FRONT BUMPER SPONGE TOP~~	~~1~~	~~$ 238.28~~	~~$ 238.28~~	~~BR✓ 195.70~~ NNX
5	FRONT GRILLE ASSY	1	$ 483.10	$ ~~483.10~~	ND X
~~5~~	~~FRONT BUMPER SPONGE BOTTOM~~	~~1~~	~~$ 75.67~~	~~$ 75.67~~	~~BR✓~~ ✓ NNX
6	FRONT LH HEADLAMP	1	$ 654.46	$ 654.46	CUT✓
~~7~~	~~FRONT LH FOG LAMP~~	~~1~~	~~$ 368.80~~	~~$ 368.80~~	~~BR✓ 258.00~~ NNX
~~8~~	~~FRONT LH FOG LAMP CHROME~~	~~1~~	~~$ 86.36~~	~~$ 86.36~~	~~CRA✓~~ ✓ NNX
				$ 3,059.49	1435.28
			Less 10%	$ 305.95	143.53
			Total	$ 2,753.54	1291.75
	S/Nett items:				
32	FRONT BUMPER CLIP	1 SET	$ 80.00	$ 30.00 ~~80.00~~	NEC✓
33	FRONT FENDER INNER TRIM CLIP	1 SET	$ 80.00	$ ~~80.00~~	NN X
				$ 30.00 160.00	
	Labour to:				
40	TO CHECK FRONT ELECTRICAL WIRING	1	$ 80.00	$ 30.00 ~~80.00~~	–
42	TO REMOVE AND REFIT WINDSCREEN MOULDING	1	$ 120.00	$ ~~120.00~~	X
43	TO RESPRAY UNDERCOATING	1	$ 100.00	$ ~~100.00~~	X
44	APPLY ANTI RUST ON AFFECTED AREAS	1	$ 120.00	$ ~~120.00~~	40.00 ✓
45	SPRAY PAINTING ON AFFECTED AREAS	1	$ 1,000.00	$ ~~1,000.00~~	400.00 ✓
46	PANEL BEATING ON AFFECTED AREAS	1	$ 1,000.00	$ ~~1,000.00~~	400.00
				$ 2,420.00	

Parts Replacement Amou	$ 2,913.54
Total Amount for Labour	$ 2,420.00
Total Amount	$ 5,333.54

survey on 27/2/2020
Tatim Hm
1030 hrs

Resurvey 27/2/2020
Tatim Hm
1300hrs

Lump sum repair
$1750/2

Parts 1291.75
S/N 30.00
Labour 870.00
2190.75
@20% 438.35
1753.40

(1)Dent (2)Scratched (3)Cut (4)Cracked (5)Cut (6)Scratched (07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary (12)Missing (13)Torn (14)Unconformed (15)Not Working

MOTOR CAR (Frt)

(1)Replace (✓) (2)Repair (X) (3)Check (?) (4)Not Consistant (NC)

Aug 2005

Front Portion

Vehicle No: SDL 6611L

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	CUT	✓	
1005	992341	Frt Bumper Clips			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	NEW	✓	
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge	BR	✓	
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover	CUT	✓	
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp	BR	✓	
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CUT	✓	
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
	NS	Wheel arch	DL	✓	
	Wheel	arch clips	NEW	✓	

No of Items: 8

Assessor: [illegible] 27/2/2020

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	818J
Vehicle Details	
Vehicle No.:	SDL6611L
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Mar 2020
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	HRA2336745A
Chassis No.:	SJNFEAJ11U1800233
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	$18,725.00
Original Registration Date:	23 Jan 2017
First Registration Date:	23 Jan 2017
Transfer Count:	0
Actual ARF Paid:	$13,725.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jan 2027
PARF Rebate Amount:	$10,293.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	$50,889.00
COE Rebate Amount:	$34,993.00
Total Rebate Amount:	**$45,286.00**

The information contained herein is correct as at 06 Mar 2020

OK

CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.
Find out more
SGCARMART CONNECT

Post an Advertisement
Sell it yourself! Advertise it at just
$58 until it's SOLD!

Post an Ad | Advertiser Login | Ways of Selling

2013 Toyota Auris At $39888.

Sporty And Rare Vehicle With Very Low Mileage.
Direct Owner StarAd

Browse by Category

« Back (1 2 3) Next »

Sort by Date Posted | 20 results/page

55 vehicles

Nissan Qashqai

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Nissan Qashqai		Any	Any	2017	Any	Any	Any	All

Nissan Qashqai 1.2A DIG-T - N.A 04-Jan-2017 1,197 cc - SUV **SOLD**

Tan Chong Unit. 1 Owner. Nissan Qashqai 1.2 Auto SUV, Very Low Mileage Only 29136 Km, Please Call Our Sales Consultant For More Enquiries Now.

Posted: 14-Dec-2019 Tags: 2017 Nissan Qashqai, Nissan Qashqai, Nissan, Qashqai

Nissan Qashqai 1.2A DIG-T Premium - N.A 13-Jan-2017 1,197 cc - SUV **SOLD**

Top Quality Masterpiece Firmly Not To Be Missed, Qashqai 1.2A With Lowest Mileage Done 35550km Only! Serviced At Tan Chong Motors With Proof, Last On Oct 19. Totally Like New. 1 Lady Owner. Nice Car Number. Road Tax Till Jul 20. 100% Accident Free. Call Now!

PREMIUM AD

Lake View Credit Pte Ltd

Posted: 23-Feb-2020 Tags: 2017 Nissan Qashqai, Nissan Qashqai, Nissan, Qashqai

Nissan Qashqai 1.2A DIG-T Premium - N.A 16-Jan-2017 1,197 cc - SUV **SOLD**

Comes With Select Approved 12 Months Warranty For Peace Of Mind! Stylish Crossover Equipped With A Powerful And Fuel Efficient 1.2L Engine And Mated To A CVT Gearbox! Spacious Cabin For 5 Passengers To Travel In Comfort! Large Boot Coupled With Split Fold Rear...

PREMIUM AD

Select By Performance Premium Selection

Posted: 31-Jan-2020 Tags: 2017 Nissan Qashqai, Nissan Qashqai, Nissan, Qashqai

Nissan Qashqai 1.2A DIG-T **$65,800** $8,580 /yr 18-Jan-2017 1,197 cc 80,000 km SUV **Available**

Price Offer Now + Free Servicing. Bank And In House 100% Can Be Arrange. Nice Looking Candy Blue New Paint Work, 7 Speed Transmission With Powerful Turbo And Good Stability Fuel Saving Car. Fuel Capacity 55L May Run Up To 17-18KM/L. Currently Going Of...

PREMIUM AD

Ka-Hup Vehicles Trading

Posted: 29-Feb-2020 Tags: 2017 Nissan Qashqai, Nissan Qashqai, Nissan, Qashqai

Top 20 cars with the lowest mark-up

Some car dealers willingly make lower profits to attract customers. Here's the top 20 cars with the lowest dealer profit margins - the best deals you can get!

Read this article

Nissan Qashqai 1.2A DIG-T - N.A 25-Jan-2017 1,197 cc - SUV **SOLD**

90% Loan At 2.28%, Guaranteed Loan For Bad Credit/Ex-Bankruptcy, View After Lunch Till 11PM Daily.

Posted: 03-Feb-2020 Tags: 2017 Nissan Qashqai, Nissan Qashqai, Nissan, Qashqai

Nissan Qashqai 1.2A DIG-T Premium - N.A 25-Jan-2017 1,197 cc - SUV **SOLD**

Pristine Condition. Fully Serviced By Nissan. 1 Owner Unit, Well Maintained, Spacious And Powerful With Comfortable Interior, Practical For Daily Use. Low On Maintenance! Flexible Loan And High Trade In Available. Call Our Friendly Salesman Now For A Viewing Appoint...

PREMIUM AD

Mayfair Motoring

Posted: 31-Jan-2020 Tags: 2017 Nissan Qashqai, Nissan Qashqai, Nissan, Qashqai

Nissan Qashqai 1.2A DIG-T - N.A 25-Jan-2017 1,197 cc - SUV **SOLD**

CONSIGNMENT

Compare

Consignment Code: A553. Flexible And Attractive Loan Available. Trade In Available For Your Car! No Hidden Costs. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGINEERING & MGT DIVISION

ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1
HEMMANT ROADSINGAPORE 438675

ATTN : CUI FEN ENG

Ref: CS3/SPF20003220/Btd3e2

Date: 31-03-2020

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	QX 558E	Veh. Inspected	SDL 6611L
Policy No.		Coverage ($)	0.00
Claim No.	AEMD/105/009/2020/006	Excess ($)	0.00
Assign From	CUI FEN ENG	Assign Date	26/02/2020

2. Vehicle Particulars & Condition

Make & Model	NISSAN QASHQAI	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	SJNFEAJ11U1800233	Colour	RED
Odometer	94861 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R17	SUMITOMO	7 mm
L/H Front Tyre	215/60 R17	SUMITOMO	7 mm
R/H Rear Tyre	215/60 R17	FALKEN	7 mm
L/H Rear Tyre	215/60 R17	FALKEN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/02/2020	Inspect Date / Time	27/02/2020 (11:13 AM)
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

OPINION ON REPAIR COST FOR VEHICLE NO. SDL 6611L

Qty	Description of Parts	Condition	Recommended ($)
	REPLACEMENT OF PARTS		
1	FRONT BUMPER	CUT	682.90
1	FRONT BUMPER LOWER GARNISH	NOT DAMAGED	-
1	FRONT BUMPER BRACKET LH	BROKEN	71.47
1	FRONT BUMPER RETAINER LH	NECESSARY	26.45
1	FRONT BUMPER SPONGE TOP	NOT NECESSARY	-
1	FRONT GRILLE ASSY	NOT DAMAGED	-
1	FRONT BUMPER SPONGE BOTTOM	NOT NECESSARY	-
1	FRONT LH HEADLAMP	CUT	654.46
1	FRONT LH FOG LAMP	NOT NECESSARY	-
1	FRONT LH FOG LAMP CHROME	NOT NECESSARY	-
	LESS 10% DISCOUNT		-143.53
			1,291.75
	SPECIAL NETT ITEMS		
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	30.00
1	SET FRONT FENDER INNER TRIM CLIP (SN)	NOT NECESSARY	-
			30.00
	LABOUR		
	TO CHECK FRONT ELECTRICAL WIRING.		30.00
	TO REMOVE AND REFIT WINDSCREEN MOULDING.	NOT NECESSARY	-
	TO RESPRAY UNDERCOATING.	NOT NECESSARY	-
	APPLY ANTI RUST ON AFFECTED AREAS.		40.00
	SPRAY PAINTING ON AFFECTED AREAS.		400.00
	PANEL BEATING ON AFFECTED AREAS.		400.00
			-
			-
			-
			-
			870.00
	GRAND TOTAL		**2,191.75**

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE)	**1,750.00**

Report Ref No. CS3/SPF20003220/Btd3e2

Report Ref No. CS3/SPF20003220/Btd3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF $1,750-$3,000

RECOMMENDED REPAIR DAYS : 4
WEEKEND : 1
TOTAL DAYS : 5

LIM TEOW GUAN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.