NS/INC20011447/Eqf3

ASS. REC. BY: Steve REF: NTUC

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. 5102373754-02 (18/07/2020-17/07/2021)

Claims No. MT/1107221-002

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHB 6616O Yr Regn: 19/12/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Hyundai Tonia c.c 1580

Colour Blue A/C: Insured / Std / NI / N

Sp.Reading 81740 T/Radio: Insured / Std / NI / N

Eng/No:

C/No: KMHC851CVLU189897

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or $

Front		Rear	
R/Bal.	4 mm	R/Bal.	4 mr
L/Bal.	4 mm	L/Bal.	4 mr
D.O.A.	29/10/20	D.O.I.	21/12/20

Survey held at Comfort Delgro

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collisio

Date / Time	Action / Instruction
	Steve finalised final fig $14155.26, 6 days. (Red $4384.16, 24%)

Date/Time, File,Pass to? 03/11 Typist

Date/Time, File Return to?

: Prell. Report

: Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: : Site Insp ($)

: Interview ($)

: Tech. Invs ($)

: Weekend ($)

Survey Fee:

Transportation: S + RS SI

Photos

Others

TOTAL

Type of Forms: TP

Temp Sum / L.E.I.: 14155.26

Life

NTUC

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 20.10.2020
Time: 18:28:57
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO	:	305429061
REGN NO	:	SHB6616D
MILEAGE	:	0000000000
MAKE	:	HYUNDAI
MODEL	:	IONIQ(G3)
DATE OF REGN	:	19.12.2019
DATE/TIME IN	:	20.10.2020 11:40
ACCIDENT DATE	:	20.10.2020

PART REQUISITION

	JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT	
0001 04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	L	459.40	20.00	367.52	/ BR
0002 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10	L	22.00	20.00	17.60	/ NC
0003 04-01-0104-2533-G	IONIQV2-4 MOULDING ASSY-R	1	L	451.25	20.00	361.00	/ CRV
0004 04-01-0104-2370-G	IONIQVC LAMP ASSY-REAR FO	1	L	201.50	20.00	161.20	X
0005 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1	N	180.00	10.00	162.00	/ BR
0006 04-01-0104-1150-A	IONIQVC PROTECTOR MAT	1	N	50.00	1.00-	50.00	/ NC
0007 04-01-0104-2545-G	IONIQVC MOULDING-REAR BUM	1	L	155.00	20.00	124.00	X
0008 04-01-0104-2270-G	IONIQVC EMBLEM-HYBRID	1	L	24.30	20.00	19.44	/ NC
0009 04-01-0104-2271-G	IONIQVC EMBLEM-IONIQ	1	L	31.30	20.00	25.04	/ NC
0010 28-01-9999-2025-A	APP LOGO REAR BONNET CTPL	1	N	40.00	10.00	36.00	/ NC
0011 28-01-0103-0005-A	(I40)REAR BOOT LOGO CTPL	1	N	30.00	10.00	27.00	/ NC
0012 28-01-0103-0006-A	(I40)REAR BOOT TEL NUMBER	1	N	30.00	10.00	27.00	/ NC
0013 FNPS	NO PLATE(S) WITH TRIM COV	1	N	55.00	10.00	49.50	/ BR (Rear)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 20.10.2020
Time: 18:28:57
Page: 2

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305429061
REGN NO : SHB6616D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 19.12.2019
DATE/TIME IN : 20.10.2020 11:4
ACCIDENT DATE : 20.10.2020

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT	
0014 FNPS	NO PLATE(S) WITH TRIM COV	1	N	55.00	10.00	49.50	(fM) ✓ BR
0015 04-01-0104-2701-G	IONIQV4 MOULDING-FRT BPR	1	L	188.00	20.00	150.40	✗ ~~BR~~
0016 04-01-0104-0578-G	IONIQV4 COVER-FR BUMPER#	1	L	430.90	20.00	344.72	✓ BR
0017 04-01-0104-2419-G	IONIQVC BEAM COMPLETE-FR	1	L	1,075.10	20.00	860.08	?
0018 04-01-0104-2702-G	IONIQV4 ABSORBER-FRONT BU	1	L	86.90	20.00	69.52	✓ BR
0019 04-01-0104-2871-G	IONIQVC BRACKET-FR BUMPER	1	L	35.00	20.00	28.00	✓ BR
0020 04-01-0104-3818-G	IONIQVC BRACKET-FR BUMPER	1	L	28.00	20.00	22.40	✓ BR
0021 04-01-0104-2687-G	IONIQV4 MOULDING-FRONT BU	1	L	188.00	20.00	150.40	X
0022 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10	L	22.00	20.00	17.60	✓ REC
0023 04-01-0104-0574-G	IONIQVC PANEL-FENDER LH#	1	L	588.80	20.00	471.04	✓ DD
0024 04-01-0104-2834-G	IONIQVC GUARD ASSY-FRONT	1	L	114.70	20.00	91.76	X
0025 04-01-0104-3813-G	IONIQVC EMBLEM-BLUE DRIVE	1	L	26.60	20.00	21.28	✓ REC

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 20.10.2020
Time: 18:28:57
Page: 3

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO	:	305429061	
REGN NO	:	SHB6616D	
MILEAGE	:	0000000000	
MAKE	:	HYUNDAI	
MODEL	:	IONIQ(G3)	
DATE OF REGN	:	19.12.2019	
DATE/TIME IN	:	20.10.2020 11:4	
ACCIDENT DATE	:	20.10.2020	

	JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT	
0026 04-01-0104-3913-G	IONIQVC EMBLEM-BLUE DRIVE	1	L	26.60	20.00	21.28	/ NC
0027 04-01-0104-0572-G	IONIQVC PANEL ASSY HOOD#	1	L	2,253.80	20.00	1,803.04	X R
0028 04-01-0104-2696-G	IONIQV4 GRILLE ASSY-RADIA	1	L	1,409.10	20.00	1,127.28	/ BR
0029 04-01-0104-2835-G	IONIQV4 LAMP ASSY-HEAD LH	1	L	1,993.65	20.00	1,594.92	/ BR
0030 04-01-0104-4894-G	IONIQV4 LAMP ASSY-DAY RUN	1	L	642.50	20.00	514.00	X
0031 04-01-0104-2685-G	IONIQV4 MOULDING-FRONT BU	1	L	93.60	20.00	74.88	X
0032 04-01-0104-2417-G	IONIQVC MOULDING-FRT BUMP	1	L	44.00	20.00	35.20	X
0033 04-01-0104-0634-G	IONIQVC GRILLE-FRONT BUMP	1	L	186.90	20.00	149.52	/ BR

SUB-TOTAL : 9,024.12

JOB NATURE

0000 23-01	TOWING FEE	/ NC	60.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 20.10.2020
Time: 18:28:57
Page: 4

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 30542906\
REGN NO : SHB6616D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 19.12.2019
DATE/TIME IN : 20.10.2020 11:4
ACCIDENT DATE : 20.10.2020

	JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001 L	PANEL BEATING(REAR)	700.00				640
0002 23-502	SPRAYPAINT ON AFFECTED AREA			450.00		400
0003 17-01	CHECK ALL LIGHTING	50.00				30
0004 20-22	REMOVE/REFIX REVERSE SENSOR			120.00		30
0005 L	PANEL BEATING(FRT)(repair fender Rh)			960.00		640
0006 23-502	SPRAYPAINT ON AFFECTED AREA			850.00		800
0007 17-01	CHECK ALL LIGHTING	50.00				X
0008 20-00	TUFF COAT ON AFFECTED PARTS.			50.00		30

SUB-TOTAL : 3,290.00

TOTAL : 12,314.12

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

Steve (LKK) WL Pte L
21/10/20, 10.30 am
P/P
My Bol Sdn
6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755
Workshops
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Qi Road Singapore 208649
24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 768732

Date/Time: 20.10.2020 16:33 Page : 1

ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 4037698 JC NO.:305429061

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)

NTUC

REGN NO.: SHB6616D	MILEAGE
MAKE : HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G3)	DATE/TIME IN 20.10.2020 11:40
YR OF MANU. 19.12.2019	TARGET DATE
CHASSIS CODE KMHC851CVLU189897	COMPLETION DATE/TIME:

NT CARD NO.

cident Date: 20.10.2020
TURE: 3P 20.10.2020

JOB DESCRIPTION

NO	LABOR CODE	DESCRIPTION
0010	23-01	TOWING FEE - $60



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ledgement Slip

No.: SHB6616D LKE STEVE

f Service Advisor

Signature/Date

turned to Service Reception upon collection

Exit Pass

Vehicle No.: SHB6616D

Name of Service Advisor

Date

To be kept by Security Guard

LGRO
EERING
OMFORTDELGRO

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Hotline +65 6383 6280 Facsimile +65 6280 9755
Service Centres
205 Braddell Road Singapore 579701 — 69 Loyang Drive Singapore 508969
46 Pandan Road Singapore 609286 — 383 Sin Ming Drive Singapore 5757
7 Sungei Kadut Way Singapore 728791 — 320 Ubi Road 3 Singapore 408649
24 Senoko Loop Singapore 758158
6553 1111
SPARK Assist Recovery • Towing • Accident
Appointed Partners

JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Requisition

Date: 20/10/20 Time Received: 1220

☐ New ☐ SPARK Kakis

Name of Customer : Mr. Roger Tan

Contact No. : 91785275

Vehicle No. : SJB6616D

Make / Model / Colour : Ionic

Email :

3. Vehicle Type:
- ☐ Private
- ☑ Taxi (CTPL/CCPL)
- ☐ Fleet
- ☐ STK (Boon Lay)

4. Type of Towing:
- ☑ Normal Tow
- ☐ King Dolly
- ☐ Flat Bed
- ☐ Crane-up

5. Nature of Service:
- ☐ Jumpstart
- ☐ Recovery
- ☐ Change Tyre / Battery

6. Parts Replaced/Remarks:

7. Location: Shell, Moulmein Rd

8. Vehicle Tow - In Workshop:
- ☐ Smoky Exhaust
- ☐ Overheating
- ☐ Brake Faulty
- ☐ Starting Problem
- ☑ Accident
- ☐ Return Taxi
- ☐ Wheel Jammed
- ☐ Steering Faulty
- ☐ Alternator Faulty
- ☐ Loss Power
- ☐ Engine Stalled

9. Preferred Workshop:
- ☐ Braddell
- ☐ Sin Ming
- ☐ Senoko
- ☑ Loyang
- ☐ Sungei Kadut
- ☐ Komoco (UBI / Leng Kee)
- ☐ Pandan
- ☐ Ubi
- ☐ Cycle & Carriage (PD)
- ☐ Others:

10. Odometer Reading :

Fuel Level : F | 1/4 | 1/2 | 3/4 | E

11. Radio / CD Player
- ☐ OK
- ☐ Faulty
- ☑ Not tested



#: Cracked X: Dented
/: Scatched O: Missing

Signature of Customer

Job Attended

12. Tow Truck / Recovery Van : ☐ VRS ☐ QA ☑ GAO ☐ TZ ☐ YISHUN TOWING ☐ OTHERS

Name of Driver : Vimal

Vehicle No. : YN3663Y

Time Dispatch : 1220

Time of Arrival : 1252

Time Completed : 1346

Cash Invoice Details (if applicable)

13. Cash Invoice No. :

Customer Acknowledgement

a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.

b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.

c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

20/10/20 — Date

1252 — Time

Signature of Customer

14. WORKSHOP

Name of Attending Staff/Guard

Date & Time of Arrival

Signature of Attending Staff/Guard

WORKSHOP CO

SINGAPORE ACCIDENT STATEMENT

...ANT NOTICE

...report correctly the details of the accident to speed up the claims process.
...Form must be completed by the Policyholder and/or the Authorised Driver.
...rmation provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to ...iate policy liability.
...he issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
Any false reporting may be referred to the Police for investigation.
...This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for ...rchiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available ...aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/10/2020 15:30
Date Of Accident	20/10/2020 11:40
Exact Location Of Accident	CTE (SLE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB6616D
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	1XXXXX821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	IONIQ
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
Driver	
Name of Driver	ROGER TAN KIM HENG (ROGER CHEN JINXING)
NRIC No	SXXXX755B
Date Of Birth	20/02/1974
Occupation	OUTDOOR
Date Of Driving Pass	23/03/1993
Driving Experience	27 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91785275
Fax Number	
Contact Number	
EMail Address	TANROGER1724@GMAIL.COM

	182 07-319 RIVERVALE CRESCENT
	540182
f an employee of the Insured's Company	NO
lationship of the Driver with the Insured	OTHER - TAXI DRIVER
Registration Number of Driver's Own le	- - -
surance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH5832S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

...ration Number	SMT7474K
...e/Model/Colour	
...Properties	
...Category	PRIVATE CAR
...of Driver	
...I/Passport Number	
...ntact Number	
...Address	
...Postcode	
Insurance Company Name	
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

PLAN

A - SHB 6616D
B - GBH 5832S
C - SMT 7474K



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

* Statement attached *

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time: 20.10.2020
1430hrs

Reporting Centre Personnel's Signature
Name:
NRIC/Fin No.: Larry Ng

Describe Circumstances of the Accident.

On 20.10.2020, at about 1140hrs, I was driving my Comfort taxi, SHB6616B, on lane 4 along CTE towards SLE with no pax.

Somewhere near the end of the tunnel before the Moulmein exit, the front vehicles suddenly brake and stopped. I applied brake too and collided with the front car, C, and split second later, was hit by a van, B, from the rear.

No injury at the time of accident.

Photos taken at the scene.

1C

Declaration

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature/Date & Time

Driver's Signature(If driver is not the policyholder)/Date & Time 20.10.2020

Larry Ng

Witnessed by Reporting Centre Personnel