ASS. REC. BY: Taufikh | REF: GS/CT/2100 3901/Tiq.f3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD **TP** WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLF 5265X

at Workshop m/s RICO 60 AUTO

of _____

Insured: GBF 2685E

Policy No. _____

Claims No. SNM21D201305/C02

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 45SK.

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLF5265X Yr Regn: 2016 Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Mazda 3 c.c 1496

Colour Grey A/C: Insured / Std / NI / NA

Sp.Reading 14552 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BM42H8G7034695.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/55R16.

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	26/3/21

Survey held at Rico 60.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Frt N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	12/4/2021@12.25PM REVISED TO PAULINE THAM VIA EMAIL.
	Taufikh finalised LS $3950, 4 days (Red $16584, 81%)

Date/Time, File Pass to? 1) 25/08 Typist

☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to? 2) _____

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Survey Fee:

Transportation: ___$ + RS.___SI

Photos

Others

TOTAL

Report Format : MER-TP

Lump Sum / ~~Hrly~~ ($ 3950)

RICO60 AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	

TO: CT
Vehicle No : SLF 5265 X
Make & Model : MAZDA 3
DATE: 16/3/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	FRONT BUMPER	1	$ 1,083.00	$ 1,083.00
2	FRONT BUMPER TOP PAD	1	$ 458.00	$ 458.00
3	FRONT BUMPER TOP PAD BASE	1	$ 286.00	$ 286.00
4	FRONT BUMPER TOWING COVER	1	$ 45.60	$ 45.60
5	FRONT BUMPER LOWER ABSOBER	1	$ 308.50	$ 308.50
6	FRONT BUMPER LOWER SUPPORT BEAN	1	$ 215.00	$ 215.00
7	FRONT BUMPER REINFORCEMENT	1	$ 750.10	$ 750.10
8	FRONT BUMPER REINFORCEMENT GARNISH	1	$ 285.60	$ 285.60
9	FRONT BUMPER SIDE RETAINER RHXnn LHdc	2	$ 115.00	$ 230.00
10	FRONT BUMPER LOWER COVER	1	$ 189.20	$ 189.20
11	FRONT FOG LAMP RHXnn LHcvr	1	$ 321.00	$ 321.00
12	FRONT FOG LAMP GARNISH RHXnn LHcover	1	$ 277.80	$ 277.80
13	FRONT GRILLE	1	$ 970.10	$ 970.10
14	FRONT GRILLE CHROME MOULDING RHXnn LH-cvr	2	$ 276.40	$ 552.80
15	FRONT GRILLE EMBLEM	1	$ 104.90	$ 104.90
16	FRONT GRILLE TOP GARNISH	1	$ 320.50	$ 320.50
17	FRONT GRILLE SUPPORT BRACKET PIN	2	$ 89.00	$ 178.00
18	BONNET	1	$ 1,120.00	$ 1,120.00
19	BONNET SEAL	1	$ 31.90	$ 31.90
20	BONNET LOCK	1	$ 208.60	$ 208.60
21	HEADLAMP RHXnn LHcvr	2	$ 3,289.00	$ 6,578.00
22	FRONT FENDER INNER SHIELD RHXnn LHcvr	2	$ 115.30	$ 230.60
23	FRONT SUPPORT TOP PANEL	1	$ 448.00	$ 448.00
24	FRONT SUPPORT PANEL	1	$ 886.90	$ 886.90
25	RADIATOR AIR GUIDE LH	1	$ 135.30	$ 135.30
26	A/C CONDENSER	1	$ 976.30	$ 976.30

27	AIR INTAKE DUCT ASSY	1	$ 188.90	$ × 188.90
28	HORN *w/x RH LHorn ✓*	2	$ 96.30	$ 192.60
29	WIPER WASHER TANK	1	$ 169.30	$ × 169.30
30	RADIATOR	1	$ 1,527.50	$ × 1,527.50

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Subtotal :	**$ 19,270.00**
Less 20%	**$ 3,854.00**
Parts Total :	**$ 15,416.00**

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	NUMBER PLATE	2	$ 50.00	$ × 100.00
2	FRONT BUMPER CLIP SET	1	$ 65.00	$ *30 ✓* 65.00
3	BONNET INSULATOR CLIP SET	1	$ 65.00	$ × 65.00
4	FRONT GRILLE CLIP SET	1	$ 30.00	$ *20 ✓* 30.00
5	FRONT FENDER INNER COWLING CLIP SET	1	$ 78.00	$ *15 ✓* 78.00
6	FRONT SUPPORT PANEL SEALANT	1	$ 80.00	$ × 80.00
7	RADIATOR COOLANT	1	$ 150.00	$ × 150.00
	SPECIAL NETT			**$ 568.00**

LABOUR (FRONT)	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS *500/400*	$ 1,600.00
TO SPRAY PAINT AFFECTED AREA *400.*	$ 1,600.00
DISMENTLE AND REPLACE A/C CONDENSER ASSY. REFILL, RECHARGE A/C REFRIGERANT GAS AND PERFORM PRESSURE TEST.	$ × 150.00
REMOVE AND INSTALL RADIATOR ASSY. PERFORMED RADIATOR PRESSURE TEST	$ × 150.00
ADJUST AND FOCUS FRONT LIGHTING SYSTEM. PERFORM HEADLAMP ADJUSTMENT TO POSITION	$ *30.* 550.00
REMOVE AND INSTALL ENGINE WIRE HARNESS. RESET ENGINE WARNING LIGHT SYSTEM WITH ON-BOARD DIAGNOSTIC COMPUTER.	$ × 500.00
LABOUR TOTAL	**$ 4,550.00**

Tanphin 97495749
wp 26/3/21 @ 1130
L/S [illegible] after repair
[illegible]

Total Parts Cost	**$ 15,984.00**
Total Labour Cost	**$ 4,550.00**
Total Repair Cost	**$ 20,534.00**

APPROVED DETAILS
NO. OF WORKING DAYS
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	250D
Vehicle Details	
Vehicle No.:	SLF5265X
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Mar 2021
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	P520376359
Chassis No.:	JM6BM42A8G0346965
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	$16,723.00
Original Registration Date:	30 Aug 2016
First Registration Date:	30 Aug 2016
Transfer Count:	2
Actual ARF Paid:	$11,723.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2026
PARF Rebate Amount:	$8,792.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	$53,334.00
COE Rebate Amount:	$29,075.00
Total Rebate Amount:	**$37,867.00**

The information contained herein is correct as at 16 Mar 2021

OK

Your NCD will be affected due to late reporting

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE
1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	10/03/2021 13:03 (SGT)
Date of Accident	05/03/2021 21:25 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	OPEN CARPARK OF CARPARK NO.TPBR4
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF5265X

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	GOH KOK CHUAN
NRIC No	SXXXX250D
Email Address	CYRTUSGOH77@GMAIL.COM
Mobile Phone No	(Phone) +65-87210779
Alternative Phone No	+65-87210779

VEHICLE PARTICULARS

Manufacturer	Mazda
Model	MAZDA / MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	NTUC
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5114344790-01
Cover Note Number	-

DRIVER

Name of Driver	GOH KOK CHUAN
NRIC No	SXXXX250D
Date Of Birth	07/07/1989
Occupation	Indoor

Date Of Driving Pass	30/07/2013
Driving experience	7 YEARS AND 8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-87210779
Alt. Phone Number	+65-87210779
Email Address	CYRTUSGOH77@GMAIL.COM
Address	BLK 845 #12-221 JURONG WEST STREET 81
Address complement	-
Postcode	640845
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Parked Vehicle
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	ONG SHIYI
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER ATTACHED;

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF2685E
Vehicle Manufacturer	Fiat
Vehicle Model	FIAT / DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-

Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	GOH KOK CHUAN
Address	BLK 845 #12-221 JURONG WEST STREET 81
Address Complement	-
Post Code	640845
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SLF5265X
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer , my workshop and the General Insurance Association of Singapore ("**GIA**") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "**Purposes**")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@vicom.com.sg

Witnessed by Reporting Centre Personnel

Sketch Plan



SKETCH PLAN #2

Describe Circumstances of the Accident



Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@vicom.com.sg

Witnessed by Reporting Centre Personnel

On 05.03.2021 at about 21:25 hours at Open Carpark of Car Park No. TPBR4. I parked my vehicle (A) on the carpark lot and I was inside my vehicle (A) with my friend. I wish to state that my car's engine was off at the moment of time.

Suddenly, I felt an impact. When I looked up, I saw it was vehicle (B) that collided onto the front left hand side portion of my vehicle (A) while reversing.

I wish to state that I have 1 passenger in my vehicle (A).

Vehicle (A): SLF 5265X

Vehicle (B): GBF2685E