ASS. REC. BY: TGLim | REF: CC4/AIG2100 5199/Tlqf3 | Jaslin

ASSIGNMENT

From: _____ Date: 27/4/2021

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLN 4768B

at Workshop m/s Jeam Autopro

of 160 Sin Ming Dr # 01-14

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 94,000/-

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 21 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLN 4768B Yr Regn: 5/5/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Mercedes Benz CLA 180 c.c 1595

Colour Black A/C: Insured / Std / NI / NA

Sp.Reading 61631 T/Radio: Insured / Std / NI / NA

Eng/No: 270910311877 93

C/No: WDD1179422N467236

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 225/40/18

R: 225/40/18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Continental

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 26/4/2021 D.O.I. 27/4/2021

Survey held at Jeam Autopro

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Recommended COR is L/S $31,550/- TGLim 15/5/2021
	MV 94,000/-
	PV 53,413/-
	NV 40,587/- TGLim 14/5/2021

Date/Time, File Pass to? ☐ : Preli. Report

1) _____ ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.I. (_____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Survey Fee:	
Transportation:	
___S + RS ___SI	
Photos	
Others	
TOTAL	

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722
Tel: 8269-9999 Email: estimate.tap@gmail.com /*teamautopl@gmail.com*

SJE :
Date of Survey :
Date of ReSurvey: **After-Paint:**
Contacts :

Vehicle Nos : SLN 4768 B
Model : Mercedes CLA180
Year :
Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day: 2017

Nos.	PARTS	Qty	Unit S$	TOTAL S$	
1	Bonnet	1	$ 2,582.60	$ ~~2,582.60~~	NDX R
2	Bonnet inner lock	1	$ 358.70	$ ~~358.70~~	NDX
3	Bonnet hinge	2	$ 257.00	$ ~~514.00~~	
4	Bonnet lock catch	1	$ 190.20	$ ~~190.20~~	NDX
5	Front bumper	1	$ 1,698.60	$ 1392.00 ~~1,698.60~~	BR ✓
6	Front bumper logo	1	$ 98.00	$ 65.00 ~~98.00~~	NEC ✓
7	Front bumper side retainer	2	$ 98.60 ~~198.60~~	$ 197.20 ~~397.20~~	NEC ✓
8	Front bumper inner sponge	1	$ 234.80	$ ✓ 234.80	BR ✓
9	Front bumper reinforcement	1	$ 688.00	$ 585.00 ~~688.00~~	BT ✓
10	Front bumper top bracket	1	$ 145.00	$ ~~145.00~~	NSX
11	Front bumper top rubber	2	$ 88.00	$ ~~176.00~~	NSX
12	Front bumper top beam	1	$ 320.00	$ 217.00 ~~320.00~~	BR ✓
13	Front bumper lower grille	1	$ 781.00	$ 257.50 ~~781.00~~	BR ✓
14	Front bumper lower chrome moulding	1	$ 543.20	$ ~~543.20~~	NSX
15	Front bumper tow cap	1	$ 110.00	$ 45.00 ~~110.00~~	MIS ✓
16	Front bumper fog lamp garnish	1	$ 172.60	$ ~~172.60~~	NSX
17	Front bumper lisence plate base	1	$ 121.40	$ 110.00 ~~121.40~~	DIS ✓
18	Front bumper parking sensor 2	~~6~~	$ 310.45	$ 620.90 ~~1,862.70~~	SC ✓
19	Front bumper radar sensor	1	$ 1,209.80	$ ~~1,209.80~~	NSX
20	Front grille	1	$ 1,528.90	$ 692.00 ~~1,528.90~~	BR ✓
21	Front grille logo	1	$ 188.00	$ 120.00 ~~188.00~~	NEC ✓
22	Front grille base	1	$ 198.60	$ ✓ 198.60	BR ✓
23	Front support panel	1	$ 1,705.60	$ 980.00 ~~1,705.60~~	BR ✓
24	Front support panel top garnish	1	$ 345.20	$ 318.00 ✓ ~~345.20~~	BR ✓
25	Front lower support panel	1	$ 240.90	$ ~~240.90~~	NSX
26	Front lower beam bracket	1	$ 254.80	$ ~~254.80~~	NSX
27	Front fender RH 1	~~2~~	$ 1,011.00	$ ~~2,022.00~~	OUT RX
28	Front fender inner cowling	2	$ 415.30	$ ~~830.60~~	NDX
29	Headlamp RH-BR, LH OUT	2	$ ✓2,610.20	$ ✓ 5,220.40	BR ✓
30	Headlamp lower bracket	2	$ 375.60	$ ~~751.20~~	NNX
31	Headlamp panel	2	$ ✓510.50	$ ✓ 1,021.00	DD ✓
32	Front brake assist function module	1	$ 780.00	$ ~~780.00~~	NDX
33	Airbag sensor	2	$ 270.30	$ ~~540.60~~	NNX
34	Air bag control unit	1	$ 1,180.50	$ ✓ 1,180.50	Activated
35	Front safety belt	2	$ 620.00 ~~1,608.70~~	$ 1240.00 ~~3,217.40~~	Activated
36	Front safety belt tensioner	2	$ 420.00	$ ~~840.00~~	NNX
37	Rear safety belt	2	$ 620.00 ~~1,568.00~~	$ 1240.00 3,136.00	Activated
38	Rear safety belt tensioner	2	$ 420.00	$ ~~840.00~~	NNX
39	Air intake duct	1	$ 310.00	$ 195.00 ~~310.00~~	BR ✓
40	Intercooler	1	$ 1,115.00	$ 950.00 ~~1,115.00~~	DD ✓

41	intercooler bracket	2	$ 136.20	$ ~~272.40~~		NSX
42	inter cooler intake duct	2	$ 40.00 ~~98.00~~	$ 80.00 ~~196.00~~		BR✓
43	A/C condenser	1	$ 1,280.00	$ ✓ ~~1,280.00~~		DD✓
44	A/C condenser high pressure pipe	1	$ 255.38	$ ~~255.38~~		ND✗
45	A/C condenser low pressure pipe	1	$ 324.00	$ ~~324.00~~		
46	Radiator	1	$ 1,277.00	$ ✓1,277.00		BT✓
47	Radiator side garnish	2	$ 72.00	$ ~~144.00~~		NSX
48	Radiator lower hose	1	$ 108.40	$ ~~108.40~~		NDX
49	Radiator reservoir pipe	1	$ 116.00	$ ~~116.00~~		NNX
50	Raidator fan cowling	1	$ 188.50	$ 188.50 ~~188.50~~		BR✓
51	Raidiator fan motor	1	$ 355.80	$ ~~355.80~~		ND✗
52	Radiator fan blade	1	$ 125.30	$ ~~125.30~~		
53	Engine lower cover	1	$ 369.50	$ ~~369.50~~		NDX
54	Tailgate	1	$ 2,487.90	$ 1681.72 ~~2,487.90~~		DD✓
55	Tailgate logo	1	$ 110.00	$ 68.00 ✓ 110.00		NEC✓
56	Tailgate emblem 'CLA180'	1	$ 84.00	$ ✓ 84.00		NEC✓
57	Tailgate emblem 'Cycle & Carriage'	1	$ 89.00	$ 55.00 ~~89.00~~		
58	Tailgate inner trim board	1	$ 1,682.90	$ 450.00 ~~1,682.90~~		BR✓
59	Tailgate weather strip	1	$ 168.00	$ ✓ 168.00		TN✓
60	Tailgate inner lock assy	1	$ 274.00	$ 225.00 ~~274.00~~		JM✓
61	Tailgate inner lock catch	1	$ 280.00	$ ~~280.00~~		NDX
62	Tailgate wiper motor assy	1	$ 480.00	$ ~~480.00~~		NDX
63	Tailgate number plate lamp	2	$ 98.00 ~~167.00~~	$ 196.00 ~~334.00~~		BR✓
64	Tailgate reverse camera	1	$ 670.80	$ ✓ 670.80		JM✓
65	Tailgate windscreen moulding	1	$ 287.90	$ ✓ ~~287.90~~		NEC✓
66	Tailgate auto damper assy	2	$ 1,054.00	$ ~~2,108.00~~		NDX
67	Rear bumper	1	$ 2,086.00	$ 1585.00 ~~2,085.00~~		BR✓
68	Rear bumper lower	1	$ 486.30	$ ✓ 486.30		BR✓
69	Rear bumper lower chrome moulding	1	$ 275.30	$ ✓275.30		BR✓
70	Rear bumper reinforcement	1	$ 698.00	$ ✓ 698.00		BT✓
71	Rear bumper lower cover	1	$ 336.50	$ ~~336.50~~		NSX
72	Rear bumper lower beam garnish	1	$ 113.90	$ ✓ 113.90		CR✓
73	Rear bumper bracket 2	~~3~~	$ ✓145.00	$ 290.00 ~~435.00~~		BT✓
74	Rear bumper side retainer	2	$ ✓56.00	$ ✓112.00		NEC✓
75	Rear bumper reverse sensor 4	~~5~~	$ ✓265.00	$ 1060.00 ~~1,590.00~~		SC✓
76	Rear bumper heat sheild	1	$ 288.00	$ ✓ 288.00		DIS✓
77	Rear bumper tow cap	1	$ 125.00	$ 70.00 ~~125.00~~		MIS✓
78	Rear end panel outer	1	$ 1,125.00	$ 950.00 ~~1,125.00~~		DD✓
79	Rear end panel inner	1	$ 995.00	$ 324.00 ~~995.00~~		
80	Rear end panel top garnish	1	$ 215.00	$ 156.00 ~~215.00~~		BR✓
81	Spare tyre panel	1	$ ~~2,215.00~~	$ 855.00 ~~2,215.00~~		DD✓
82	Spare tyre panel top board	1	$ 928.70	$ 340.00 ~~928.70~~		BR✓
83	Rear fender	2	$1,526.87 ~~2,958.60~~	$3053.74 ~~5,917.20~~		DD✓
84	Rear fender inner trim board	2	$ 908.90	$ ~~1,817.80~~		NDX
85	Rear fender inner cowling	2	$ 220.50	$ ~~441.00~~		NDX
86	Rear fender side glass moulding	2	$116.82 ~~238.00~~	$ 233.64 ~~476.00~~		NEC✓
87	Taillamp	2	$ 730.00	$ ✓ 1,460.00		BR✓
88	Taillamp outer garnish	2	$ 180.00	$ ~~360.00~~		NSX
89	Taillamp bracket	2	$ 49.00	$ ~~98.00~~		NSX
90	Taillamp panel	2	$ 85.30	$ ✓170.60		DD✓
91	Rear exhaust pipe chrome tip LH 1	~~2~~	$ 302.00 ~~345.00~~	$ 302.00 ~~690.00~~		DD✓
92	Rear exhaust pipe heat sheild	1	$ 181.60	$ ✓ 181.60		DD✓
			Parts Sub Total :	$ 76,176.18		
		10%	Discount	$ 7,617.62		
			PARTS TOTAL :	$ 68,558.56		

36,796.90
@10% 3 679.69
33,117.21

Nos.	SPECIAL NETT	Qty	Unit S$	TOTAL S$	
1	Sundries	1	$ 80.00	$ ~~80.00~~	NNX
2	Bonnet sealant	1	$ 100.00	$ ~~100.00~~	NNX
3	Front bumper clips	1	$ 50.00	$ 30.00 ~~50.00~~	NECV
4	Front bumper lower grille clips	1	$ 50.00	$ ~~50.00~~	NNX
5	Front bumper outer garnish clips	1	$ 50.00	$ ~~50.00~~	NNX
6	Front bumper parking sensor seal 2	~~6~~	$ 58.00	$ 116.00 348.00	NECV
7	Front grille clips	1	$ 50.00	$ 30.00 ~~50.00~~	NECV
8	Front support panel top garnish clips	1	$ 50.00	$ ~~50.00~~	NSX
9	Front fender sealant	2	$ 100.00	$ ~~200.00~~	NNX
10	Front fender inner cowling clips	2	$ 50.00	$ ~~100.00~~	NNX
11	Front number plate w/casing	1	$ 80.00	$ 50.00 ~~80.00~~	NECV
12	A/c fluid	1	$ 80.00	$ 40.00 ~~80.00~~	NECV
13	Radiator coolant	1	$ 80.00	$ 40.00 ~~80.00~~	NECV
14	Engine lower cover clips	1	$ 50.00	$ ~~50.00~~	NSX
15	Tailgate sealant	1	$ 100.00	$ 30.00 ~~100.00~~	NECV
16	Tailgate inner trim board clips	1	$ 50.00	$ ~~50.00~~	NNX
17	Tailgate windscreen sealant	1	$ 100.00	$ 60.00 ~~100.00~~	NECV
18	Tailgate windscreen clips	1	$ 50.00	$ ~~50.00~~	NSX
19	Tailgate windscreen inner seal	1	$ 60.00	$ 30.00 ~~60.00~~	NECV
20	Tailgate windscreen primer & cleaner	1	$ 80.00	$ ~~80.00~~	NNX
21	Rear bumper clips	1	$ 50.00	$ ~~50.00~~	NNX
22	Rear bumper lower clips	1	$ 50.00	$ ~~50.00~~	NNX
23	Rear bumper reverse sensor seal 4	~~6~~	$ 58.00	$ 232.00 ~~348.00~~	NECV
24	Rear end panel sealant	1	$ 100.00	$ 40.00 ~~100.00~~	NECV
25	Rear end panel top garnish clips	1	$ 50.00	$ 20.00 ~~50.00~~	NECV
26	Spare tyre panel sealant	1	$ 100.00	$ ~~100.00~~	NNX
27	Rear fender sealant	2	$ 100.00	$ ~~200.00~~	NNX
28	Rear fender inner trim board upper clips	2	$ 50.00	$ ~~100.00~~	NNX
29	Rear fender inner trim board lower clips	2	$ 50.00	$ ~~100.00~~	
30	Rear fender inner cowling clips	2	$ 50.00	$ 30.00 ~~100.00~~	NECV
31	Rear fender side glass sealant	2	$ 100.00	$ 60.00 ~~200.00~~	NECV
32	Rear fender side glass inner seal	2	$ 60.00	$ 40.00 ~~120.00~~	NECV
33	Rear fender side glass primer & cleaner	2	$ 80.00	$ ~~160.00~~	NNX
34	Taillamp clips	2	$ 50.00	$ ~~100.00~~	NSX
35	Taillamp seal	2	$ 60.00	$ 60.00 ~~120.00~~	NECV
36	Taillamp outer garnish clips	2	$ 50.00	$ ~~100.00~~	NNX
37	Taillamp panel sealant	2	$ 100.00	$ ~~200.00~~	
38	Rear number plate w/casing	1	$ 80.00	$ 50.00 ~~80.00~~	NECV
			SPECIAL NETT TOTAL :	$ 4,086.00	

958.00

Nos.	LABOUR	S$		
1	R&R front bumper parking sensor	$ 60.00	~~100.00~~	—
2	R&R front bumper radar sensor	$	~~100.00~~	NNX
3	Radar sensor alignment	$	~~300.00~~	NNX
4	R&R air bag control module	$ 80.00	~~150.00~~	—
5	R&R front safety belt & safety belt tensioner LH/RH	$ 120.00	~~300.00~~	—
6	R&R rear safety belt & safety belt tensioner LH/RH	$ 120.00	~~300.00~~	—
7	R&R intercooler	$ 60.00	~~150.00~~	—
8	R&R a/c condenser	$ 60.00	~~150.00~~	—
9	R&R radiator	$ 60.00	~~150.00~~	—
10	Front check wiring	$ 40.00	~~100.00~~	—
11	Front upholsterty	$	~~300.00~~	NNA
12	Front panel beating	$ 600.00	~~1,600.00~~	—
13	Front rust proofing	$	~~200.00~~	NNX
14	Front spray painting	$ 600.00	~~1,600.00~~	—
15	R&R tailgate component	$ 80.00	~~150.00~~	—
16	R&R tailgate windcsreen	$ 120.00	~~250.00~~	—
17	R&R tailgate reverse camera	$	~~150.00~~	NNX
18	R&R rear bumper reverse sensor	$ 60.00	~~100.00~~	—
19	R&R rear fender side glass LH/RH	$ 120.00	~~400.00~~	—
20	R&R rear fuel tank pipe	$ 70.00	~~150.00~~	—
21	R&R rear exhuast pipe	$	~~150.00~~	NNX
22	Chassis alignment	$	~~300.00~~	NNX
23	Mount Work bench	$	~~350.00~~	
24	Diagnotic reset fault code	$ 180.00	~~300.00~~	—
25	Rear check wiring	$ 40.00	~~100.00~~	—
26	Rear upholsterty	$ 100.00	~~300.00~~	—
27	Rear panel beating	$ 1600.00	~~2,400.00~~	—
28	Rear rust proofing	$	~~200.00~~	NNX
29	Rear spray painting	$ 1200.00	~~2,400.00~~	—
	LABOUR TOTAL :	$	13,200.00	
		5,370.00		

Survey
27/4/2021
1313 hrs
TGLim

Resurvey
29/4/2021
1330 hrs
TGLim

PARTS TOTAL :	$	68,558.56
SPECIAL NETT TOTAL :	$	4,086.00
LABOUR TOTAL :	$	13,200.00
GRAND TOTAL :	**$**	**85,844.56**

Lump Sum repair
Repair days. 21

PARTS	33,117.21
S/N	958.00
LABOUR	5,370.00
	39,445.21
@20%	7,889.04
	31,556.17

L/S 31,550/2

TGLim
15/5/2021

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

NOTE IF ACCIDENT REPORT SUBMITTED AFTER 24 HOURS NCD WILL BE AFFECTED

ACCIDENT STATEMENT

DATE OF REPORT: 26/4/21 ACCIDENT DATE & TIME: 24/4/21 @

ACCIDENT LOCATION: Junction of Fullerton Rd & Esplanade Dr (towards Shenton Way)

COUNTRY: SINGAPORE OR MALAYSIA

VEHICLE DETAILS/POLICYHOLDER DETAILS

VEHICLE NO: SLN 4766B

POLICYHOLDER NAME: Chou Siew Bee

NRIC NO: S1760758H

EMAIL:

POLICY NUMBER:

HP/OFFICE: 91793396

COVERAGE:

INSURANCE: NTUC DIRECT ASIA AXA HL FWD BUDGET

VEHICLE PARTICULARS

MODEL: Mirage. CA160

VEHICLE CATEGORY: PRIVATE OR COMMERCIAL

PURPOSE DURING ACCIDENT: Personal

CLAIM: OWN DAMAGE REPORTING ONLY THIRD PARTY

DRIVER DETAILS

NAME: Chou Siew Bee

NRIC NO: S1760758H

DATE OF BIRTH: 01/11/1966

OCCUPATION: INDOOR OR OUTDOOR

PASSED DATE: 07/12/1991

GENDER: FEMALE OR MALE

HP NUMBER:

ADDRESS (COMPULSARY): 60 Havelock Road #03-12

POSTCODE 169658

EMAIL:

R/S WITH POLICYHOLDER: Owner.

WEATHER CONDITION: DRY / CLEAR / WET / RAIN

INJURY: Yes.

POLICE REPORT: -

VIDEO FOOTAGE OR VOICE RECORD: check - Yes.

OFFER BY OTHER WORKSHOP:

NO OF VEHICLE INVOLVED: 04

WITNESS: IF YES – NAME&HP:

NO PPL IN CAR: 02.

PASSENGER NAME (NAME AND GENDER):

1) Tan Hui Min (F)

2)

3)

THIRD PARTY'S DETAILS

VEHICLE NO: GBF 1666 S

NAME: Kaler

NRIC NO:

HP NUMBER: 8296 8453

INSURANCE:

ADDRESS:

MODEL: T/Dyna

VEH CATEGORY:

GBE 7876T

SLF 5007 A

BAHA 5772

SKETCH PLAN

VEHICLE NO:
ACCIDENT DATE:

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

(e) the information so collected under (d) above may be shared / disclosed:

(i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

NOTE: DO NOTE THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION.

		CHARN'S CUSTOMCRAFT
Policyholder's Signature Date & Time: 26/4/21 1015 h.	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attached accident statement

OWN DAMAGE ( ) 3RD PARTY CLAIM (✓) REPORTING ONLY ( ) OWN WORKSHOP ( )

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 21/4/21 10:15h.

Driver's Signature
(If driver is not the policyholder)
Date & Time:

CHARN'S CUSTOMCRAFT

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Reporting (Charn's CustomCraft)

From: siew bee choo <jochoosb@gmail.com>
Sent: Monday, 26 April 2021 10:07 am
To: reporting@charnscustomcraft.com.sg
Subject: SLN4768B

Car accident 24 April 21 (chain collision 4 cars).

Location : 24 April 1145 h at junction of Fullerton road and Esplanade dr (towards Shenton Way) just before One Fullerton.

It was a 4 lane road (3 straight , 1 right turn). My car was on 3rd lane from left. I Stopped fully at traffic light. After about 3 Seconds , I felt my car being banged from behind and jerked forward. a pick up GBF 1666S couldn't stop in time and had rear ended my car which cause My car to collide into the front car SLF 5007A (GRAB). The GRAB car then collided into the van (GBE 7876T) in front. At the time of accident , ms tan hui Min was seated in the passenger seat next to me. Both of us suffered slight Injury :
Me - right shin bruise/ swollen , left calf bruised , right elbow abrasion.
Tan hui Min - right back sore
We have seen a doctor after the accident. (DTAP clinics 11 unity street , #02-06. Robertson walk. Dr Jonathan Ti)

The driver particulars are as follows:
GBF 1666S (1st pick up which rear ended me) culprit
Toyota dyna
Driver : kaler arashdeep Singh
SPASS : 0 38345079
FIN : G3346293Q (License)

SLF 5007A (GRAB CAR which I rear ended)
Blue Mazda 2
Driver : Mohd affandee bin Zainal
S1785030Z

The fourth vehicle (van GBE7876T) driver left without giving his particulars.

MY PASSENGER :
Tan hui Min
S8038105/J

CHOO SIEW BEE
S1760758 /H
91733396
SLN4768B

(1)Dented (3)Distorted (4)Damaged (5)Cut (6)Scratched (07)Deformed
(08)Shifted (09)Buckled (10)Broken (11)Necessary (12)Missing (13)Torn
(14)Unconfirmed (15)Not Working

MOTOR CAR (Frt)

Action taken:
(1)Replaced (✓) (2)Repair (X) (3)Check (?)
(4)Not Consistent (NC)

Aug 2005

Vehicle No: SLN 4768B

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	BR	✓	
1005	992341	Frt Bumper Clips			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	NEG	✓	2
1008	991433	Frt Bumper Reinforcement	BT	✓	
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge	BR	✓	
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille Lower	BR	✓	
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor	SC	✓	2
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	BR	✓	
1022	991328	Frt Grille Emblem	NEG	✓	2
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	BR	✓	
1026	992025	Frt Support Panel Top Garnish Cover	BR	✓	
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CUT	✓	
1030	991821	Frt RH Headlamp Assy	BR	✓	
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser	DD	✓	
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator	BT	✓	
1053	992738	Radiator Cowling	BR	✓	
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991932	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		Frt grille logo	BR	✓	
		Frt grille base	BR	✓	
		Headlamp panel	DD	✓	2
		Frt & rear safety belt	activated	✓	
		Air bag control unit	activated	✓	

No of Items: 20

Assessor: TGLim

15/5/2021

(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

(1)Replace(✓) (2)Repair(/) (3)Check (?)
(4)Not Consistent (NC)

Rear Portion

Vehicle No: - SLN 4768B

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp	BR	✓	2
1141	992958	Rear Bumper	BR	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	BR	✓	
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	MIG	✓	
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket	BT	✓	2
1148	993068	Rear Bumper Side Retainer	NEC	✓	2
1149	993045	Rear Bumper Reinforcement	BT	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	SC	✓	4
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish	BR	✓	
1161	993333	Rear End Panel Inner ~~Trim~~ panel	DD	✓	
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	BR	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel	DD	✓	
1166	995116	Rear RH Taillamp	BR	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel	DD	✓	
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bbotlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD	✓	
1182	991328	Tailgate Emblem	NEC	✓	3
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NEC	✓	
1196	994607	Tailgate Glass Sealant	NEC	✓	
1197	994629	Tailgate Lock	Jm	✓	
1198	994651	Tailgate ~~Rubber~~ weatherstrip	TN	✓	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel	DD	✓	
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover	BR	✓	
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender	DD	✓	
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender	DD	✓	
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass moulding	NEC	✓	2
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			
		Frt Intercooler	DD	✓	
		Intercooler intake duct	BR	✓	2
		Frt bumper Tow cap	MIG	✓	
		Rear bumper heat shield	DIS	✓	
		Rear exhaust pipe chrome tip LH	DD	✓	
		Rear exhaust pipe heat shield	DD	✓	

No of Items: 32 Assessor: TGrim

15/5/2021

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	758H
Vehicle Details	
Vehicle No.:	SLN4768B
Vehicle to be Exported:	No
Intended Deregistration Date:	14 May 2021
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CLA180 SB URBAN (R18 LED)
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	27091031187793
Chassis No.:	WDD1179422N467236
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	$32,043.00
Original Registration Date:	05 May 2017
First Registration Date:	05 May 2017
Transfer Count:	0
Actual ARF Paid:	$31,861.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 May 2027
PARF Rebate Amount:	$23,895.00
Intended COE Rebate Details	
COE Expiry Date:	04 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	$49,430.00
COE Rebate Amount:	$29,518.00
Total Rebate Amount:	**$53,413.00**

The information contained herein is correct as at 14 May 2021

OK

MV 94,800/-
PV 53,413/-
NV 40,587/-

14/5/2021

SGCARMART.COM

Login Sign up

New Cars Used Cars Rental Cars Sell My Car Directory Products Insurance Articles Forum Resources

RENT NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
$68 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

2009 Toyota Picnic, 7 Seater, 3 Row Aircon, Spacious.
Value Buy People Mover. Good For Big Family. 8 Years COE Left. $7k Depre Only.
Dynamic Motoring StarAd

KA-HUP
VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND
HOTLINE: 6741 9997 view our cars

Browse by Category

« Back (1 2 3) Next »

Sort by Reg. Date | 20 results/page

41 vehicles

Mercedes-Benz CLA180

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mercedes-Benz	CLA180	Any	Any	2017	Any	Any	Any	All

Mercedes-Benz CLA-Class CLA180 Urban - N.A 20-Jul-2017 1,595 cc - Luxury **SOLD**

Comes With Select Approved 12 Months Warranty. Sleek And Stylish CLA180 Where Style And Performance Gel Harmoniously! Equipped With A 1.6L Turbo Engine And Mated To A 7 Speed Dual Clutch Gearbox Providing Adequate Power On The Move, Yet...

Select By Performance Premium Selection

Posted: 25-Mar-2021 Tags: 2017 Mercedes-Benz CLA180, Mercedes-Benz CLA180, Mercedes-Benz, CLA180

Mercedes-Benz CLA-Class CLA180 Urban - N.A 20-Jul-2017 1,595 cc - Luxury **SOLD**

1 Owner Only! Full Agent Maintained Since Day 1! High Spec Mercedes CLA180! Free 6 Months Engine, Gearbox, Aircon Compressor, Alternator & Many More! Luxury White With Black Leather Interior! High Loan And Trade In Of Up To 90% Are Available Here! Call...

Euro Performance Asia Pte Ltd

Posted: 13-Mar-2021 Tags: 2017 Mercedes-Benz CLA180, Mercedes-Benz CLA180, Mercedes-Benz, CLA180

Mercedes-Benz CLA-Class CLA180 Urban - N.A 23-Jun-2017 1,595 cc - Luxury **SOLD**

Driven By 1 Lady Owner, Low Mileage Unit, C&C Unit, New SMY Plate, Beautiful Black Sedan With Beige Interior, Original Paintwork, Good Condition, Call Or WhatsApp Us For Viewing.

Posted: 18-Apr-2021 Tags: 2017 Mercedes-Benz CLA180, Mercedes-Benz CLA180, Mercedes-Benz, CLA180

Mercedes-Benz CLA-Class CLA180 Urban $98,787 $14,050 /yr 19-Jun-2017 1,595 cc 68,000 km Luxury **Available**

Excellent Conditions, Low Mileage. Highest Trade In Available, 100% Loan Approval Driveaway. Absolutely No Repairs Needed. STA/VICOM Reports, Any Workshop Inspection All Are Welcome. All Bank/Finance/In House Loan Are Available, Lowest Interest Rat...

Posted: 22-Apr-2021 Tags: 2017 Mercedes-Benz CLA180, Mercedes-Benz CLA180, Mercedes-Benz, CLA180

Mercedes-Benz expands EQA lineup

Mercedes-Benz extends the product line to include the EQA300 4MATIC and EQA350 4MATIC, with both variants equipped with all-wheel drive.

Read this article

Mercedes-Benz CLA-Class CLA180 Coupe AMG Line - N.A 16-Jun-2017 1,595 cc - Sports **SOLD**

C&C Unit, Fully Serviced By C&C, 1 Year Extended Mercedes-Benz Pre-Owned Warranty By C&C, 10 Years Engine Warranty By C&C, 33 Points Inspection Check Done At C&C,AMG Line, Enhance With A45 Body Kits, Panamericana Grille, A45 Air Dam & Brake Kits,18"...

Republic Auto

Posted: 08-May-2021 Tags: 2017 Mercedes-Benz CLA180, Mercedes-Benz CLA180, Mercedes-Benz, CLA180

Mercedes-Benz CLA-Class CLA180 AMG Line Sunroof $108,888 $15,200 /yr 16-Jun-2017 1,595 cc 66,000 km Luxury **Available**

1 Owner, Accident Free.

Posted: 04-May-2021 Tags: 2017 Mercedes-Benz CLA180, Mercedes-Benz CLA180, Mercedes-Benz, CLA180

Compare **Mercedes-Benz CLA-Class CLA180 Shooting Brake Urban** $95,900 $13,300 /yr 22-May-2017 1,595 cc 45,000 km Stationwagon **Available**