CATHERINE LIM LLC

林翠玲律師馆 ADVOCATES & SOLICITORS
NOTARY PUBLIC -公证官
COMMISSIONER FOR OATHS- 宣誓官

CATHERINE C.L.LIM
DIRECTOR
LL.B (HONS) SINGAPORE-法律系-律師
M.B.A. (BUSINESS LAW)-商业系-硕士

12 Eu Tong Sen Street
The Central (SOHO 2) #05-172
Singapore 059819
UEN No. 201310922K
Tel: (65) 6438 5500
Fax: (65) 6438 0111
www.catherinelimllc.com
Email: info@catherinelimllc.com
CATHERINE LIM LLC is a law corporation with limited liability

Our Ref: CL/220439/T/HH.sg

09 June 2022

M/s China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909
Attn: Motor Claims Dept

WITHOUT PREJUDICE

BY EMAIL

Dear Sir

ACCIDENT INVOLVING SMA 4439H / SMK 2100U ON 21.4.2022 ALONG TAMPINES AVE 5 TOWARDS PIE

We act for HUA HONG PTE LTD, the owner of motor vehicle No. SMA 4439H, which was involved in the above accident.

Our client has suffered loss and damage as a result of your negligence in the driving of motor vehicle No. SMK 2100U.

We quantify our client's claim as follows:-

1.	Cost of Repairs	$ 2,400.00
2.	Loss of use (3 days x $150)	$ 600.00
3.	Survey fee	$ 355.00
4.	GIA search	$ 33.00
5.	Incidentals, transport & photocopying etc	$ 53.50
6.	Cost contribution	$ 749.00
		$ 4,190.50

We enclose herewith photocopies of our client's accident report, GIA searches, repair bill, survey fee, survey report and colour photographs of our client's damaged vehicle for your immediate attention.

Please let us know within the next 14 days from the receipt of this letter, whether you are prepared to admit liability and revert with a settlement proposal, failing which our clients shall have no alternative but to commence legal proceedings against your insured.

Yours faithfully

Encs
cc: clients

(Please note that if your motor vehicle was not driven by you, there is a presumption in law that the said driver was driving as your agent/ servant unless you let us know the particulars of your driver if your motor vehicle was not driven by you.)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE
1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	22/04/2022 16:49 (SGT)
Date of Accident	21/04/2022 21:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	TAMPINES AVE 5 TOWARDS PIE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA4439H

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	HUA HONG PTE. LTD.
Company Reg No	200900309M
Email Address	claims@huahong.com.sg
Mobile Phone No	(Phone) +65-81182320
Alternative Phone No	(Office) +65-66619687

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	C-hr
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5109921641-03-000063
Cover Note Number	-

DRIVER

Name of Driver	MOHAMMAD SYAKIR BIN MOHAMMAD JUNID
NRIC No	S9120731A

Date Of Birth	17/06/1991
Occupation	Outdoor
Date Of Driving Pass	24/05/2017
Driving experience	4 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-87497534
Alt. Phone Number	-
Email Address	TYSONZARA64@GMAIL.COM
Address	BLK 326B SUMANG WALK #10-978
Address complement	-
Postcode	822326
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	Passenger
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Hougang Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18004890999
Alt. Police Station Phone No	(Fax) +65-63128989
Police Station Address	60 Hougang Ave 9 Singapore 538775
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN / POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE SIZE TOO BIG TO BE UPLOADED
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMK2100U

Vehicle Manufacturer	BMW
Vehicle Model	520i
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	UNKNOWN MALE CHINESE
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	MOHAMMAD SYAKIR BIN MOHAMMAD JUNID
Gender	Male
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SMA4439H
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

   I understand, acknowledge, agree and consent that:

   (a) My insurer, my workshop and the General Insurance Association of Singapore ("**GIA**") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

   (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

   (ii) investigating the accident and/or my claims;

   (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

   (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

   (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**")

   (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

   (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

   (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

   (e) the information so collected under (a) above may be shared / disclosed

   (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

   (ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name NRIC/FIN No

SKETCH PLAN



A- SMB 4428H
B- SMK 2100H

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident Date & Time : 21 04 2022 @ 21:20hrs

Accident Location : Tampines Ave 5 towards PIE

REFER POLICE REPORT T/2022 04/22 / 2006

☐ Reporting Only ☐ Own Damage ☐ Third Party ☐ Claim at other workshop (OD/TP)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*** IMPORTANT NOTE**

We had been advised by the workshop that in the event that you wish to claim against your own policy (Own Damage Claim) there is a **CLAIM PERIOD OF 14 days** (except where the claim must be made within the stipulated timeframe from the date of accident).

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/FIN No.

SINGAPORE POLICE FORCE

T/20220422/2006

Report No. T/20220422/2006

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:	Vide Report No.:	Station Diary No.:
22/04/2022 01:28		11

Informant's Particulars

Name of Informant: MOHAMMAD SYAKIR BIN MOHAMMAD JUNID			Address: APT BLK 326B SUMANG WALK #10-978 SINGAPORE 822326	
ID Type / ID No.: NRIC NO / S9120731A			Contact No.: Home/Office:	Mobile: 87497534
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 30	Date of Birth: 17/06/1991	Type of Informant: Driver	
Race: Malay			Language:	Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class:	Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 21/04/2022 21:20	Type of Location: Straight Road
Location: TAMPINES AVENUE 5				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SMA4439H	Car	TOYOTA	C-HR HYBRID 1.8S CVT	Red	Slightly Damaged	1
SMK2100U	Car	BMW	520I LED NAV	White		0

SINGAPORE
POLICE FORCE

T/20220422/2006

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20220422/2006

CONTINUATION OF REPORT

Brief Details.

On 21/04/2022 at about 2120hrs, I was driving (Vehicle registration no: SMA4439H) along Tampines Avenue 5 towards PIE, on the most left lane, when a vehicle (Vehicle registration no: SMK2100U) cut across 2 lanes from my right and tried to overtake me in the lane I am travelling. Vehicle SMK2100U was driving very closely to my vehicle to which I honked at him. He continued driving closely and the left back passenger door of his vehicle, grazed on the front right bumper of my vehicle. I then honked at him to stop and managed to overtake him and we both stopped at the roadside with my hazard light on. Another vehicle who witnessed the incident also stopped in front of my vehicle to assist.

After alighting from my vehicle to talk to the driver of SMK2100U, he did not alight from his vehicle and he immediately sped off. I managed to follow him and gestured him to stop however he ignored, to which I did not continue to attempt to stop him. I would also like to state that I have a car dash-cam footage of the incident. There are deep scratches on the front right bumper of my vehicle from this incident. I am unsure of the cost of the damages.

SINGAPORE POLICE FORCE

T/20220422/2006

Report No. T/20220422/2006

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature of Officer Recording The Report: F / Other SITI AISYAH UMAIRAH BINTE MOHAMAD MOKHTAR	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 22/04/2022 01:28
Officer In Charge Of Case: TP / HRT / SR STAFF SGT NEO ZHI YUAN Contact No. 65476079	Classification Of Case:

NP168

SINGAPORE POLICE FORCE

T/20220422/2006

1 of 3

Report No. T/20220422/2006

Police Station Of Origin
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:	Vide Report No.:	Station Diary No.:
22/04/2022 01:28		11

Informant's Particulars

Name of Informant: MOHAMMAD SYAKIR BIN MOHAMMAD JUNID			Address: APT BLK 326B SUMANG WALK #10-978 SINGAPORE 822326	
ID Type / ID No.: NRIC NO / S9120731A			Contact No.: Home/Office:	Mobile: 87497534
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 30	Date of Birth: 17/06/1991	Type of Informant: Driver	
Race: Malay			Language:	Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class:	Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 21/04/2022 21:20	Type of Location: Straight Road

Location:

TAMPINES AVENUE 5

Weather: Clear	Road Surface: Dry	Road Speed Limit:
Traffic Flow: One Way	Traffic Control: Traffic Light - Working	Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction		Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SMA4439H	Car	TOYOTA	C-HR HYBRID 1.8S CVT	Red	Slightly Damaged	1
SMK2100U	Car	BMW	520I LED NAV	White		0

SINGAPORE
POLICE FORCE

T/20220422/2006

Report No. T/20220422/2006

Police Station Of Origin
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

CONTINUATION OF REPORT

Sketch Plan
Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature of Officer Recording The Report: F / Other SITI AISYAH UMAIRAH BINTE MOHAMAD MOKHTAR	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 22/04/2022 01:28
Officer In Charge Of Case: TP / HRT / SR STAFF SGT NEO ZHI YUAN Contact No. 65476079	Classification Of Case:

NP168

IMAGES

IMAGES #2

IMAGES #3

IMAGES #4

IMAGES #5

Land Transport Authority
PRIVATE HIRE
A081308

INSURER ENQUIRY

Find insurer

Vehicle reg. no.

SMK2100U

Date of Accident

21/04/2022

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance ..... **China Taiping Insurance (Sing...**

Period of Insurance ..... **29/03/2022 - 28/03/2023**

Requested By ..... **Goh Sally (Catherine Lim LLC)**

Requested Date **25/04/2022 14:30**

Payment details
Request Amount: **S$1.87**
GST Amount: **S$0.13**
Total Amount Due (GST Inclusive): **S$2**

General Insurance Association
Records Management Centre
GST Registration No: **M400017735**

OohRay RENTAL

oohrayrental.com.sg

OohRay Rental Pte. Ltd.
10 Kaki Bukit Avenue 4,
Premier@Kaki Bukit, #04-63
Singapore 415874
finance@oohrayrental.com.sg
+65 6661 9688
UEN: 202120930W

INVOICE

Customer Name : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Address : Attention: Motor Claims Department
3 Anson Road #15-00 Springleaf Tower
079909
SINGAPORE

INVOICE NO. : INV2022-0016C.1
DATE : 07 Jun 2022
REFERENCE NO. : SMA4439H

DESCRIPTION	UNIT PRICE	AMOUNT SGD
ACCIDENT INVOLVING SMA4439H & SMK2100U ON 21/04/2022 ALONG TAMPINES AVE 5 TOWARDS PIE AT ABOUT 2120 HOURS		
Insured : HUA HONG PTE LTD		
Vehicle Make : TOYOTA		
Vehicle Model : C-HR HYBRID 1.8S CVT		
Vehicle Chassis No : ZYX102118735		
Policy No : 5109921641-03-000063		
Date of Accident : 21/04/2022		
Type of Claim : Third Party		
Lump sum repair for the damaged portion	2,400.00	2,400.00
	Invoice Total SGD	2,400.00
	Less: Deposit Paid SGD	0.00
	Amount Due SGD	**2,400.00**

PAYMENT DETAILS

Account Name: OohRay Rental Pte. Ltd.
Bank Name: DBS Bank Ltd
Bank Account: 072-522534-5
OR
PayNow: UEN 202120930W

K A A S
kelvin automotive appraising services
6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Claim Reference	: -
Insured Vehicle No.	: -
Thirty Party Veh No.	: -
Officer-In-Charge	: -
Our Reference	: KAAS/TA/6380/4439/TP/04.22
Invoice No.	: 6380
Date	: 31 May 2022

To: Hua Hong Pte Ltd
c/o 8 Kaki Bukit Ave 4
#06-31, Premier @ Kaki Bukit
Singapore 415875

INVOICE

PARTICULARS	AMOUNT
Vehicle No. : **SMA 4439H** Make/Model : Toyota C-HR Hybrid 1.8S CVT	
☑ Inspection of Vehicle	
☑ Appraisal Report	
☑ 15 Colored Photographs	SGD 355.00
☑ Transport charges	
☐ Re-inspection	
☐ Others (Specify)	
Total	**SGD 355.00**

Dollars: **Three Hundred and Fifty-Five Only**

(Cheque should be crossed and make payable to " **Kelvin Automotive Appraising Services** ")

Kelvin Automotive Appraising Services
K A A S

Kelvin Automotive Appraising Services

K A A S
kelvin automotive appraising services
6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Claim Reference	: -
Insured Vehicle No.	: -
Thirty Party Veh No.	: -
Officer-In-Charge	: -
Our Reference	: KAAS/TA/6380/4439/TP/04.22
Date	: 31 May 2022

To: Hua Hong Pte Ltd
c/o 8 Kaki Bukit Ave 4
#06-31, Premier @ Kaki Bukit
Singapore 415875

VEHICLE APPRAISAL REPORT

Name of Workshop	: Oohray Rental Pte Ltd
Place of inspection	: 8 Kaki Bukit Ave 4 #06-31, Premier @ Kaki Bukit, Singapore 415875
Date of Assignment	: 05 May 2022
Date of Accident	: 21 April 2022
Date of Inspection	: 05 May 2022

PARTICULARS OF INSPECTED VEHICLE

Registration No.	: **SMA 4439H**	Chassis Frame No.	: ZYX10-2118735
Make / Model	: Toyota C-HR Hybrid 1.8S CVT	Engine No. (Logcard)	: 2ZR8431654
Year of Manufacture/Reg	: 2018	Odometer Reading	: 218,337 KM
Colour	: Red		
Class / Type	: SUV		

CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)

General Condition	: Very Good
Paintwork	: Very Good
Market Value	: -
Scrap Value	: -

CONDITION OF TYRES ON VEHICLE

		Make/Size	Thread Balance
Front	L	WESTLAKE 215 / 60 R17	7 mm
Front	R	WESTLAKE 215 / 60 R17	7 mm
Rear	L	WESTLAKE 215 / 60 R17	7 mm
Rear	R	WESTLAKE 215 / 60 R17	7 mm

*The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee , any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.

K A A S
kelvin automotive appraising services
6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Our Reference : KAAS/TA/6380/4439/TP/04.22
Vehicle Number : **SMA 4439H**

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		LIST ITEMS:-			
1	1 pc	front bumper	deformed	$ 794.20	$ 794.20
2	1 pc	front bumper lower extension	scratched	$ 359.40	$ 359.40
3	1 pc	front bumper l/h side retainer	necessary	$ 87.10	$ 87.10
4	1 pc	front bumper r/h side retainer	necessary	$ 87.10	$ 87.10
5	1 set	front bumper clips	necessary	$ 35.00	$ 35.00
				$ 1,362.80	$ 1,362.80
		Less 25%			$ 340.70
				$ 1,362.80	**$ 1,022.10**
		SPECIAL NETT ITEMS:-			
6	1 pc	r/h front sports rim	distorted	$ 670.00	$ 670.00
7	1 pc	r/h front tyre @50% depreciation	scratched	$ 360.00	$ 180.00
				$ 1,030.00	**$ 850.00**
			Sub - Total	**$ 2,392.80**	**$ 1,872.10**

K A A S
kelvin automotive appraising services
6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Our Reference : KAAS/TA/6380/4439/TP/04.22
Vehicle Number : **SMA 4439H**

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		B/F		$ 2,392.80	$ 1,872.10
		LABOUR & OTHER CHARGES:-			
1		To panel beat and renewal of all necessary damaged body parts		$ 900.00	$ 600.00
2		To check wiring and rewire		$ 60.00	$ 50.00
3		To perform 4 wheel alignment		$ 120.00	$ 100.00
4		To putty and spray-paint of affected areas		$ 600.00	$ 400.00
				$ 1,680.00	$ 1,150.00
			Sub - Total	$ 4,072.80	$ 3,022.10

K A A S
kelvin automotive appraising services
6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Our Reference : KAAS/TA/6380/4439/TP/04.22
Vehicle Number : **SMA 4439H**

ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered **Diagonally to the RH Side from rear to front; right to left;** portion of the vehicle.



The general area of damages is at the **RH Side portion** .
(Please refer to the parts list and photographs as attached for more information)

ASSESSOR'S RECOMMENDATIONS

The estimated repair costs submitted by Messrs **Oohray Rental Pte Ltd** is $ 4,072.80 .
We have adjusted the cost to $ 3,022.10 and the repairer has agreed to undertake the repairs at a
Contract Lump Sum of $ 2,400.00 to a acceptable quality and standards.
However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of **3** working days.

15 photographs were taken at the time of static inspection.

This report is strictly done in a **Without Prejudice Basis**.

We are reverting the matter to you a decision.

We enclose herewith our Invoice No. **6380** for our services rendered and
we thank you for engaging our services.

KELVIN AUTOMOTIVE APPRAISING SERVICES

KELVIN TEO
Licensed Automotive Appraiser
Nitec in Automotive Technology
Cert. Crash Investigation & Reconstruction
Dip MS
MSAAA, AM SAE-A

NOTE : *This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company within Seven (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.*

SMA
4439H

SMA
4439H

TOYOTA MOTOR CORPORATION JAPAN
MODEL
ENGINE
FRAME No.
COLOR
TRIM
PAINT
OPTION
710
BAG SIDE AIRBAG

ECO
POWER
CHG
218337 km

Kenny Automotive Services Illinois
Appraisal

Kenny Automotive Services Illinois
Appraisal

Kenny Automotive Services Illinois
Appraisal

Kenny Automotive Services Illinois
Appraisal

TEMPERATURE