ASS. REC. BY: Taufih   REF: III

# ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

|  | N/S | O/S |
|---|---|---|

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days    Res.: Yes or No

Lum Sum: _____ %    3 Val.: Yes or No

WP

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: Inmon

Veh No: SHP4651D    Yr Regn: 2020 Jen

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Hyundai Louig    c.c 1580

Colour: Blue    A/C: Insured / Std / NI / NA

Sp.Reading 403981    T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHC851CVL4/88757

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size:  F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or  Westlake.

| Front | | Rear | |
|---|---|---|---|
| R/Bal. 6 | mm | R/Bal. 6 | mm |
| L/Bal. 6 | mm | L/Bal. 6 | mm |
| D.O.A. | | D.O.I. 19/7/22 | |

Survey held at Comfort Loying

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Fvt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|---|---|
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |

Date/Time, File Pass to?  ☐ : Preli. Report

1) _____  ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format : _____

Lump Sum / I.B.J. ( _____ )

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____ )
☐ : Interview ($ _____ )
☐ : Tech. Invs ($ _____ )
☐ : Weekend ($ _____ )

Survey Fee: _____

Transportation: _____

S + RS. __ SI _____

Photos _____

Others _____

TOTAL _____

# ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
59 Loyang Drive
Singapore 508969
Tel: 6214 8300

**(Jumani) PHP**

**TP INSURER:**      **India International Insurance Pte Ltd (HQ)**
**CTPL**

Singapore

## PARTICULARS OF CLAIM

| | | | |
|---|---|---|---|
| Claim Type: | THIRD PARTY | Ref. No: | |
| Policy No: | | Date of Loss: | 17/07/2022 |
| Vehicle Reg. No.: | **SHD4651D** | Driveable? | |
| Party At Fault: | UNKNOWN | | |

| | | | |
|---|---|---|---|
| Make/Model: | HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) | Vehicle Reg. Date: | 23/01/2020 |
| Vehicle Colour: | BLUE | | |
| Engine No: | G4LEKU404639 | Chassis No: | KMHC851CVLU188757 |
| Odometer: | 0 KM | | |

| | |
|---|---|
| Paint Type: | |
| List Item Discount: | 20.00 % |
| Total Loss? | **NO** |
| Est. Duration of Repair (day) | 4 |

Present Location:    COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

| COST OF CLAIMS | Amount |
|---|---|
| Parts | 2,611.04 |
| Miscellaneous Items | 11.00 |
| Labour | 1,500.00 |
| Paintwork Labour | 0.00 |
| Towing | 0.00 |
| **Gross Total (S$)** | **4,122.04** |
| **+ GST 7.00% (S$)** | 288.54 |
| **Nett Amount (S$)** | **4,410.58** |

**This claim is handled by: JUMANI BIN MASUDIN**

*Generated using **Merimen e-Claims Internet Estimation & Adjusting System***

## REPAIR DETAILS

# Reference

| | |
|---|---|
| **Part Source:** MRM-SG | Version: 1.0 (Last Synchronised: 18 Jul 2022) |
| **Parts:** 192 | HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0) |
| **Labour:** Repairer's | (Price-denominated Standard List) |
| **Print Code:** | ComfortDelGro Engineering Pte Ltd/SHD4651D/18/07/2022 14:01 |
| **Validity:** | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| **Further Info:** | Items/values not in reference catalogue are prefixed with an asterisk *. |

# Estimates on Parts

| No. | Qty | Part No. | Particulars | %Disc | %Depr | | Amount |
|---|---|---|---|---|---|---|---|
| 1 | 1 | | **\*FRT BUMPER ASSY** | 20.00 | 0.00 | _de_ | \*481.10 FL |
| 2 | 10 | | **\*FRT BUMPER CLIPS** | 20.00 | 0.00 | _nel_ | \*22.00 FL |
| 3 | 1 | | **\*FRT BUMPER SIDE BRACKET LH** | 20.00 | 0.00 | ? | \*35.00 FL |
| 4 | 1 | | **\*FRT FENDER LH** | 20.00 | 0.00 | _Rr_ | \*588.80 FL |
| 5 | 1 | | **\*FRT FENDER EMBLEM LH** | 20.00 | 0.00 | _nel_ | \*26.60 FL |
| 6 | 1 | | **\*HEADLAMP ASSY LH** | 20.00 | 0.00 | | \*2,110.30 FL |

F=Franchise part. L=ListItemDisc.

| | |
|---|---|
| **Sub Total (S$)** | **3,263.80** |
| **- List Item Discount on L Items (S$)** | 652.76 |
| **Total Parts (S$)** | **2,611.04** |

---

**ComfortDelGro Engineering Pte Ltd/SHD4651D/18/07/2022 14:01**. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

# Estimates on Miscellaneous Items

| No | Qty | Particulars | Amount |
|----|-----|-------------|--------|
| **Miscellaneous Items** | | | |
| 1 | 1 | **OD/TP Case (Insurer)** | 11.00 |
| | | **Sub Total (S$)** | 11.00 |

# Estimates on Labour

| No | Particulars | Lab.Type | Amount |
|----|-------------|----------|--------|
| **Labour Items** | | | |
| 1 | **PANEL BEATING** | New | 800.00 |
| 2 | **SPRAYPAINT** | New | 600.00 |
| 3 | **CHECK WIRING** | New | 50.00 |
| 4 | **TUFF KOTE** | New | 50.00 |
| | | **Gross Labour Cost (S$)** | **1,500.00** |

*(handwritten: 350, 500, X, X)*

**ComfortDelGro Engineering Pte Ltd/SHD4651D/18/07/2022 14:01**. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

*(handwritten notes)*
Tanphi 9749574 9
'WP' · 19/7/22e fpm
02 days
R/P Resivy before paint
tanphr @ lhkauto. wn

*(stamp)*
**LKK Auto Consultants** hence notify
the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by **Repairer**
Signature:
Date:

# COMFORTDELGRO NGINEERING

**ComfortDelGro Engineering Pte Ltd**
205 Braddell Road Singapore 579701
Mainline + 65 6383 6280  Facsimile + 65 6280 9755
**Workshops**
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717

8NS -

**JOB CARD** Sales Order:

um:  ARC Repair TP(CLSO)1

JC N 305523529

| | | |
|---|---|---|
| REGN NO.: **SHD4651D** | | MILEAGE |
| MAKE : **HYUNDAI** | | FUEL E...........1/2...........F |
| MODEL **IONIQ(G3)** | | DATE/TIME IN 17.07.2022 18:00 |
| YR OF MANU. **23.01.2020** | | TARGET DATE |
| CHASSIS CODE **KMHC851CVLU188757** | | COMPLETION DATE/TIME: |

TOMER

MS COMFORT TRANSPORTATION PTE LTD
TOMER NO.    7010045
RESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755                (O)
(P)

OUNT CARD NO.

cident Date: 17.07.2022
TURE: 3P 17.07.22/C

JOB DESCRIPTION

GBL 8731J

| NO | LABOR CODE | DESCRIPTION |
|---|---|---|

CKED & PASSED OUT BY:

_____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ledgement Slip

Exit Pass

No.: **SHD4651D**    JU INDIA

Vehicle No.:    **SHD4651D**

f Service Advisor            Signature/Date

turned to Service Reception upon collection

Name of Service Advisor            Date

To be kept by Security Guard