

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internationa	le Des Experts En	Automobile
MS	INCOME INSURAN		Ref:	CS/INC24080180/Uqh3
	75 BRAS BASAH R		Date:	28/08/2024
	INCOME CENTRE	SINGAPORE 189557	Code:	INC
1. Policy Particulars :- THIRD PARTY CLAIM				M
	Insured Veh.	SNA 1897B	Veh. Inspected	SND 9785Y
	Policy No.	-	Coverage	0
	Claim No.	MT/1290108-001	Excess	\$0.00
	Assign From	EILEEN LEE	Assign Date	12/08/2024
2. Vehicle Details				
	Make & Model	TOYOTA ALPHARD (A)	C.C	2493
	Engine No.	2AR2646099	Year of Reg.	14/02/2022
	Chassis No.	AGH309030879	Colour	BLACK
	Odometer	175128 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3.	Conditions of Tyres			
		Size	Make	Balance (mm)
	R/H Front Tyre	225/55R18	FIRENZA	6
	L/H Front Tyre	225/55R18	FIRENZA	6
	R/H Rear Tyre	225/55R18	BRIDGESTONE	6
	L/H Rear Tyre	225/55R18	BRIDGESTONE	6
4.	Description of Damages			
HE	VEHICLE SUSTAIN	ED DAMAGES AT THE REAR PORTIO	N.	
DAM	IAGES SEE DETAIL	S.		
5.	General Information			
	Accident Date	08/08/2024	Inspection Date	13/08/2024 (10:29)
	Survey held at	WE GARAGE – 11 KAKI BUKIT AVEN 417883	UE 6 #02-11 AUTOE	BAY @ KAKI BUKIT, SINGAPORE
5a. Remarks				
		AS CONDUCTED ON A"WITHOUT PRE YOUR INSTRUCTIONS, WE HAVE NO		EPAIRS

**Estimate Days of Repair**