

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0607/2024/KS  
**DATE** : 13-Aug-24  
**WIP** : 26710

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/7/2024**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Rasul,

4 Days - OK - Allan Boo

28-Aug-24

**OWNER'S NAME** : M/S JALALUDDIN TRAVEL & SERVICES PTE LTD  
**ADDRESS** : BLK 896A TAMPINES STREET 81  
#12-854  
SINGAPORE 521896  
**TELEPHONE** : HP +65 91006964  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 722007847-02  
**VEHICLE NO** : **SNE 419 J**  
**MODEL CODE** : Q2 1.5 TFSI S-TRONIC  
**MODEL YEAR** : 27/1/2022  
**ENGINE NO** : DPC D33433  
**CHASSIS NO** : WAUZZZGA1MA035451  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 10-Aug-24  
**PLACE OF ACCIDENT** : EAST COAST PARK.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SNE 419 J.**

| S/N                         | NATURE OF JOBS                                                                                                                                 |        | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|-------------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.                  | S/N \$ | 360.00               | \$ <b>360.00</b>              |
| 2                           | TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE                                                                             | S/N \$ | 400.00               | \$ <b>250.00</b>              |
| 3                           | TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$     | 2,800.00             | \$ <b>500.00</b>              |
| 4                           | TO RESPRAY FRONT BUMPER AND BONNET.                                                                                                            | \$     | 2,000.00             | \$ <b>1,100.00</b>            |
| 5                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                 | S/N \$ | 292.00               | \$ <b>292.00</b>              |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                | : \$   | <b>5,852.00</b>      | \$ <b>2,502.00</b>            |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNE 419 J.**

|                             |                                       |     | DAMAGED PARTS & PRICES |         |           |
|-----------------------------|---------------------------------------|-----|------------------------|---------|-----------|
| S/N                         | PARTS DESCRIPTION                     | QTY | S/NETT                 | REMARKS |           |
| 1                           | FRONT BUMPER                          | 1   | \$ 1,575.00            | \$      | 1,260.00  |
| 2                           | FRONT BUMPER ADAPTOR - RH             | 1   | \$ 54.00               |         |           |
| 3                           | FRONT BUMPER TRIM - RH                | 1   | \$ 116.00              | \$      | 92.80     |
| 4                           | FRONT BUMPER AIR GUIDE GRILLE- RH     | 1   | \$ 114.00              | \$      | 90.80     |
| 5                           | FRONT PARKING AID SENSOR BRACKET - RH | 1   | \$ 36.00               |         |           |
| 6                           | FRONT BUMPER LOWER COVER              | 1   | \$ 127.00              | \$      | 101.60    |
| 7                           | FRONT BUMPER CLOSING ELEMENT          | 1   | \$ 195.00              |         |           |
| 8                           | FRONT WHEEL SPOILER - LH / RH         | 2   | \$ 86.00               |         |           |
| 9                           | FRONT BUMPER SPOILER                  | 1   | \$ 374.00              | \$      | 298.80    |
| 10                          | FRONT BUMPER ADAPTOR - RH             | 1   | \$ 54.00               |         |           |
| 11                          | RADIATOR GRILLE                       | 1   | \$ 1,734.00            |         |           |
| 12                          | RADIATOR GRILLE STRIKER PLATE         | 1   | \$ 236.00              |         |           |
| 13                          | FRONT BUMPER GUIDE SECTION - RH       | 1   | \$ 45.00               |         |           |
| 14                          | LED HEADLIGHT - RH                    | 1   | \$ 6,915.00            | \$      | 5,532.00  |
| 15                          | LED HEADLIGHT POWER MODULE - RH       | 1   | \$ 904.00              |         |           |
| 16                          | LED HEADLIGHT MOUNTING - RH           | 1   | \$ 147.00              |         |           |
| 17                          | LIFT CYLINDER - RH                    | 1   | \$ 170.00              |         |           |
| 18                          | LIFT CYLINDER HOSE - RH               | 1   | \$ 97.00               |         |           |
| 19                          | FRONT WHEEL ARCH COVER - LH / RH      | 2   | \$ 802.00              | \$      | 640.80    |
| 20                          | FRONT NO PLATE                        | S/N | \$ 60.00               |         |           |
| <b>TOTAL SPARE PARTS</b>    |                                       | :   | \$ 13,841.00           | \$      | 8,016.80  |
| <b>TOTAL LABOUR CHARGES</b> |                                       | :   | \$ 5,852.00            | \$      | 2,502.00  |
| <b>GRAND TOTAL</b>          |                                       | :   | \$ 19,693.00           | \$      | 10,518.80 |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT