

WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

25 June 2024

REG NO. : SLC 4188 H
MAKE/MODEL : TOYOTA CAMRY

SUPPLEMENTARY ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

<u>QTY</u>	<u>DESCRIPTION</u>	<u>AMT(S\$)</u>
	<u>LIST ITEMS</u>	
1	Centre console box assy <i>su</i>	\$ 3,674.50 ^x
1	Centre console panel sub-assy <i>su</i>	\$ 3,193.20 ^x
1	Roof top panel inner trim board <i>worped / su</i>	\$ 1,875.20 ✓
		\$ 8,742.90
	Less 25%	\$ 2,185.73
		\$ 6,557.18

GRAND TOTAL :

\$ 6,557.18
