

**2020 SPRAY PAINTING PTE LTD**  
**8 KAKI BUKIT AVE 4**  
**#03-19 PREMIER @KAKI BUKIT**  
**SINGAPORE 415875**

*Hui Rong*

**ESTIMATED REPAIR CHECKLIST**

13-Aug-24

|                                   |                                           |
|-----------------------------------|-------------------------------------------|
| TO : ECICS                        | VEHICLE REGISTRATION NO.: SNL6143C (2016) |
| ATTENTION : MOTOR INSURANCE CLAIM | VEHICLE MAKE/MODEL: HONDA / CIVIC         |
| CLAIM TYPE : 3RD PARTY CLAIM      | CHASSIS NUMBER: MRHFC1660GT000037         |
| ACCIDENT DATE/TIME :              | CONTACT PERSON :                          |

| PARTS                                     | QTY | PER UNIT      | PRICES      |
|-------------------------------------------|-----|---------------|-------------|
| 1 ROCKER PANEL <i>Repair</i>              | 1   | \$ 755.80     | \$ 755.80   |
| 2 ROCKER PANEL OUTER SKIRTING <i>torn</i> | 1   | \$ 620.20     | \$ 620.20   |
| 3 REAR DOOR <i>Deribed</i>                | 1   | \$ 950.90     | \$ 950.90   |
| 4 REAR DOOR LOCK <i>new</i>               | 1   | \$ 272.80     | \$ 272.80   |
| 5 REAR DOOR WEATHERSTRIPE <i>new</i>      | 1   | \$ 198.50     | \$ 198.50   |
| 6 REAR DOOR INNER TRIM BOARD <i>new</i>   | 1   | \$ 469.80     | \$ 469.80   |
| 7 REAR DOOR GLASS REGULATOR GEAR          | 1   | \$ 294.10     | \$ 294.10   |
| 8 REAR DOOR GLASS REGULATOR MOTOR         | 1   | \$ 410.40     | \$ 410.40   |
| 9 REAR DOOR CHROME MOULDING               | 1   | \$ 89.50      | \$ 89.50    |
| 10 REAR DOOR STEP GARNISH                 | 1   | \$ 234.10     | \$ 234.10   |
| 11 REAR FENDER <i>Repair</i>              | 1   | \$ 920.80     | \$ 920.80   |
| 12 REAR FENDER GLASS MOULDING             | 1   | \$ 65.60      | \$ 65.60    |
| 13 REAR WINDSCREEN MOULDING               | 1   | \$ 156.70     | \$ 156.70   |
| 14 REAR LOWER ARM                         | 1   | \$ 384.40     | \$ 384.40   |
| 15 REAR SHOCK ABSORBER                    | 1   | \$ 324.10     | \$ 324.10   |
| 16 REAR KNUCKLE ARM                       | 1   | \$ 358.50     | \$ 358.50   |
| 17 REAR WHEEL HUB C/W BEARING             | 1   | \$ 290.40     | \$ 290.40   |
| 18 REAR CONTROL ARM                       | 1   | \$ 214.70     | \$ 214.70   |
| 19 REAR STAY ARM                          | 1   | \$ 220.40     | \$ 220.40   |
| 20 REAR TRAILING ARM                      | 1   | \$ 349.40     | \$ 349.40   |
| Sub to al                                 |     | SUBTOTAL :    | \$ 7,581.10 |
| Less 20%                                  |     | LESS 20% :    | \$ 1,516.22 |
| Total List                                |     | PARTS TOTAL : | \$ 6,064.88 |

| SPECIAL NETT                                   | QTY   | PER UNIT    | PRICES      |
|------------------------------------------------|-------|-------------|-------------|
| 1 ROCKER PANEL OUTER SKIRTING CLIPS <i>new</i> | 1 SET | \$ 50.00    | \$ 50.00    |
| 2 REAR DOOR INNER TRIM BOARD CLIPS <i>new</i>  | 1 SET | \$ 30.00    | \$ 30.00    |
| 3 REAR DOOR BLACK TAPE <i>new</i>              | 1     | \$ 60.00    | \$ 60.00    |
| 4 REAR FENDER GLASS SEALANT                    | 1     | \$ 40.00    | \$ 40.00    |
| 5 REAR WINDSCREEN SEALANT                      | 1     | \$ 60.00    | \$ 60.00    |
| 6 REAR WHEEL RIM <i>cut</i>                    | 1     | \$ 800.00   | \$ 800.00   |
| 7 REAR TYRE <i>new</i>                         | 1     | \$ 250.00   | \$ 250.00   |
| Sub total                                      |       | S/N TOTAL : | \$ 1,290.00 |

| LABOUR CHARGES                   | PRICES      | ADJUSTMENT  |
|----------------------------------|-------------|-------------|
| 1 PANEL BEATING                  | \$ 1,200.00 | <i>400</i>  |
| 2 SPRAY PAINTING                 | \$ 1,200.00 | <i>800</i>  |
| 3 WIRING                         | \$ 50.00    | <i>x</i>    |
| 4 TO APPLY TUFF COAT             | \$ 150.00   | <i>30</i>   |
| 5 TO REMOVE REAR WINDSCREEN      | \$ 180.00   | <i>x</i>    |
| 6 TO REMOVE UPHOLSTERY           | \$ 150.00   | <i>x</i>    |
| 7 TO REMOVE REAR FENDER GLASS    | \$ 120.00   | <i>x</i>    |
| 8 TO TRANSFER REAR DOOR FITTINGS | \$ 150.00   | <i>60</i>   |
| 9 TO REMOVE REAR UNDERCARRIAGE   | \$ 250.00   | <i>80</i>   |
| 10 TO PERFORM WHEEL ALIGNMENT    | \$ 150.00   | <i>80</i>   |
| LABOR TOTAL                      |             | \$ 3,700.00 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

LABOR TOTAL survey is on a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: *27/11/2024*



*total: 3249.20*  
*1/8: 2.6K*  
*04 Days*