

ASSIGNMENT

From: _____ Date: _____

Estn: _____

OD / TP RES / CD RES / EVA / INV / MV

To in Vehicle No: _____

at W/O m/s _____

of _____

Insured: _____

Policy No: _____

Claim's No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: Veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLJ86787 Yr Regn: 2014 Sept.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C180 C.D. 1595

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2050402 F03 7449

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50 R17

R: 215/50 R17

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 08/08/24

Survey held at JL Pectel

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ALG

COE Expiry

Estimate given during : Yes ☒ No ☐

1st Survey ☒ No ☐

MV: 16K Depreciation (2) 23K x 1/2 yr

PV: 14.7K + 14K $\approx$ 16K

Nett: 1.2K

455L

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Inve (\$

Survey Fee:

Transportation:

☐ S + RS ☐ SI

☐ Photos

☐ Others

Report Form 18:


1. Name of Insured / P.P. / C.

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 08.08.2024

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLJ8678Y**
MODEL : **MERCEDES C200**
DATE OF ACCIDENT : 07.08.2024
TIME OF ACCIDENT : 12:20 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>del</i>	1	\$ 2,191.00	\$ 2,299.00
2	REAR BUMPER CENTRE FRAME <i>new</i>	1	\$ 232.00	\$ 232.00
3	REAR BUMPER TOWING COVER <i>del</i>	1	\$ 88.00	\$ 88.00
4	REAR BUMPER EXHAUST COVER GARNISH <i>new</i>	1	\$ 138.00	\$ 532.00
5	REAR BUMPER REVERSE SENSOR <i>new</i>	4	\$ 265.00	\$ 1,060.00
6	REAR BUMPER REVERSE SENSOR HOLDER <i>del</i>	6	\$ 67.00	\$ 402.00
7	REAR BUMPER REVERSE SENSOR WIRE HARNESS <i>del</i>	1	\$ 798.00	\$ 798.00
8	REAR BUMPER CENTER UPPER BRACKET <i>new</i>	2	\$ 78.00	\$ 156.00
9	REAR BUMPER BOTTOM CENTER GARNISH <i>new</i>	1	\$ 185.00	\$ 185.00
10	REAR BUMPER LOWER GARNISH <i>lit</i>	1	\$ 285.00	\$ 399.00
11	REAR BUMPER LOWER GARNISH CHROME <i>lit</i>	1	\$ 346.00	\$ 380.00
12	REAR BUMPER UPPER CORNER BRACKET <i>del</i>	2	\$ 179.00	\$ 358.00
13	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 95.00	\$ 190.00
14	REAR BUMPER SMART SENSOR CONTROL UNIT <i>new</i>	1	\$ 374.00	\$ 374.00
16	REAR BUMPER SMART SENSOR C/W BRACKET <i>new</i>	1	\$ 279.00	\$ 279.00
17	REAR BUMPER REINFORCEMENT <i>new</i>	1	\$ 950.00	\$ 950.00
18	REAR FENDER DRAIN GARNISH <i>new</i>	2	\$ 247.00	\$ 494.00
19	TAILLAMP <i>del</i>	2	\$ 936.00	\$ 1,872.00
20	BOOTLID WEATHER STRIP <i>del</i>	1	\$ 258.00	\$ 258.00
21	REAR END PANEL <i>del</i>	1	\$ 2,014.00	\$ 2,014.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLJ8678Y**
 MODEL : **MERCEDES C200**
 DATE OF ACCIDENT : 07.08.2024
 TIME OF ACCIDENT : 12:20 HOURS

22	REAR END PANEL INNER GARNISH <i>new</i>	1	\$ 285.00	\$ 285.00
----	---	---	-----------	-----------

TOTAL PRICE \$ 13,605.00
 LESS 10% \$ 1,360.50
SUB TOTAL PRICE \$ 12,244.50

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER BOTTOM CENTER GARNISH CLIP (SET) <i>2</i>	1	\$ 50.00	\$ 50.00
3	REAR BUMPER LOWER GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00
4	REAR BUMPER EXHAUST COVER GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00
5	TAILLAMP CLIP (SET)	1	\$ 50.00	\$ 50.00
6	REAR FENDER DRAIN GARNISH CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
7	REAR FENDER COWLING CLIP (SET)	1	\$ 50.00	\$ 50.00
8	REAR FENDER INNER TRIM CLIP (SET)	1	\$ 50.00	\$ 50.00
9	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00
10	REAR END PANEL INNER GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00
11	REAR FLOOR UNDER SIDE GARNISH CLIP RH (SET)	1	\$ 80.00	\$ 80.00

TOTAL \$ 760.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,500.00	<i>250</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	<i>250</i>
3	TUFF COAT	\$ 350.00	<i>x</i>
4	WIRING CHECK	\$ 180.00	<i>x</i>
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 380.00	<i>x</i>
6	CONDUCT WATER LEAKAGE TEST	\$ 100.00	<i>x</i>

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLJ8678Y**
MODEL : **MERCEDES C200**
DATE OF ACCIDENT : 07.08.2024
TIME OF ACCIDENT : 12:20 HOURS

7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 650.00	X
---	--	-----------	---

TOTAL \$ 4,360.00

TOTAL PARTS COST : \$ 13,004.50
TOTAL LABOUR COST : \$ 4,360.00
TOTAL REPAIR COST : \$ 17,364.50

Adrian Lij
h/s 08/08/24
02 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: