

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3155/08/24

Your Ref:

Date: 10th August 2024

MS TAN BENG HOON
45, Toh Tuck Rd, #03-04,
The Beverly, S(596720)

Estimate cost of repair to HONDA CIVIC 1.6 (A) VVTi Saloon - SLJ 3287 A

1 pc front bumper	Cut/Torn		597.90	✓
2 pcs front bumper o/s & n/s side retainer	26.50	rec	53.00	✓
1 pc front bumper n/s top retainer		sc	49.50	✓
10 pcs front bumper clips	4.00	ner	40.00	✓
2 pcs front bumper o/s & n/s side bracket clips	4.50	ner	9.00	✓
1 pc front bumper beam	11		379.50	✓
1 pc front bumper sponge damper	11		105.00	✓
1 pc front bumper n/s airscoop garnish	scn		28.40	✓
1 pc front grille	scn		190.20	✓
1 pc front grille moulding	one		123.80	✓
8 pcs front grille clips	ner	4.00	32.00	✓
1 pc front grille 'H' emblem	ner		24.80	✓
1 pc n/s head lamp assy	holder one		708.80	✓
1 pc n/s head lamp top moulding	11		115.50	✓

Less 20%
\$ 2,457.40
\$ 491.48

\$ 1,965.92

1 pc front number plate & frame Sin 50.00 S.N

To wiring check up & adjust headlight alignment. 50.00 20

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front support panel & necessary parts, to weld, renew & align above parts. 750.00 300

To putty & respray painting on all affected accident parts. 800.00 300

To respray Tuff-Kote on all affected accident parts. 11 50.00 X

\$ 3,665.92
=====

Dollars : Three Thousand Six Hundred Sixty Five And Cents Ninety Two Only.

HUP MOTOR TRADING & SERVICE

LIK Auto Consultants hence notify the holder of the following:

- Third party survey before respray painting
- No display damaged parts before respray
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NOT Acknowledged
meras
14/8/24
3287 S.
Plus, Mr. Stanley
L/S \$ 1650
P-1798-S
202
1439.12
40
620
2099.12
232
1679