

**Strides Premier Accident Vehicle Repair Estimates**

|                                                   |
|---------------------------------------------------|
| Strides Premier Automotive Services Pte Ltd       |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 22/08/2024

User ID : PohSuan

**Section A - Accident Details**

|                                   |                              |
|-----------------------------------|------------------------------|
| Registration Number               | SHB1915Z                     |
| Case Reference Number             | TAX/08/24/2040               |
| Registration Date                 | 30/Nov/2021                  |
| Company Type                      | Strides Premier Taxi Pte Ltd |
| Make                              | MORRISGARAGES                |
| Model                             | MG5                          |
| Name of Driver                    | VASU S/O MUNUSAMY            |
| Type of Accident                  | Side Swipe                   |
| Accident Date and Time            | 13/Aug/2024 7:15 PM          |
| Accident Reported Date and Time   | 14/Aug/2024 10:51 AM         |
| Is Surveyor Required?             | Yes                          |
| Survey by                         |                              |
| Vehicle is Towed Back?            | No                           |
| Towed Back Date and Time          |                              |
| Replacement Vehicle issued?       | No                           |
| Job Card Number                   | 24122084                     |
| Special Instruction to ARC,if any | TP/ LEFT REAR PORTION        |
| Prepared Date and Time            | 14/Aug/2024 11:01 AM         |
| Chassis Number                    |                              |
| Mileage                           |                              |
| Work Shop                         |                              |
| Repair Completion Date and Time   |                              |

**Section B - Summary of Repair Estimates**

| Summary of Repair Estimates  |                                                                                     |                                                                                                                                                                                                           |
|------------------------------|-------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|                              | Quotation from ARC                                                                  | Adjusted by Surveyor, if applicable                                                                                                                                                                       |
| Total Labour Cost            | \$1,200.00                                                                          | \$400.00                                                                                                                                                                                                  |
| Total Spray Cost             | \$1,514.00                                                                          | \$200.00                                                                                                                                                                                                  |
| Total Spare Part Cost        | \$6,684.98                                                                          | \$2,361.07                                                                                                                                                                                                |
| Total Other Cost             | \$1,445.32                                                                          | \$795.32                                                                                                                                                                                                  |
| <b>TOTAL COST</b>            | <b>\$10,844.30</b>                                                                  | <b>\$3,756.39 (P/P)</b>                                                                                                                                                                                   |
| <b>Lump Sum Total</b>        | <b>\$0.00</b>                                                                       | <b>\$0.00</b>                                                                                                                                                                                             |
| Number of Repair Days        | 7.0                                                                                 | 3.0                                                                                                                                                                                                       |
| Prepared / Adjusted By       | Boon Chew Tay                                                                       | STEVE CHEN (LKK) / AIG                                                                                                                                                                                    |
| ARC / Surveyor Sign Off Date | 16/08/2024 6:35 PM                                                                  | 15/08/2024 3:39 PM                                                                                                                                                                                        |
| Signature                    |  |                                                                                                                        |
| Remarks                      | INITIAL = 7 DAYS<br>WITH SUPP = 0 DAY<br>TOTAL = 7 DAYS                             | INITIAL = 3 DAYS / EXTEND = 0 DAY<br>P/P REPAIR / BEFORE PAINT PHOTO , FOR CHECK<br>ITEM and REPLACE ITEM PLEASE CALL<br>SURVEYOR STEVE CHEN (LKK) / HP : 010-9429 541<br>/ Email : stevechen@lkkauto.com |

| Section C - Quotation and Accident Invoice Details |              |                |  |
|----------------------------------------------------|--------------|----------------|--|
| Quotation Number                                   | QN-2408-0234 | Invoice Number |  |
| Quotation Date                                     | 22.08.2024   | Invoice Date   |  |
| Invoice Amount                                     |              | Prepared Date  |  |

| Section D - Details of Repair Estimates |                   |                                     |
|-----------------------------------------|-------------------|-------------------------------------|
| Part 1 - Labour Works                   |                   |                                     |
| Job Scope                               | Quotation from AR | Adjusted by Surveyor, if applicable |
| TO REPAIR REAR PORTION LH               | \$1,200.00        | \$400.00                            |
| Total Labour                            | \$1,200.00        | \$400.00                            |

|                                                       |                    |                                     |
|-------------------------------------------------------|--------------------|-------------------------------------|
| Part 2 - Spray Painting & Panel Beating Related Works |                    |                                     |
| Job Scope                                             | Quotation from ARC | Adjusted by Surveyor, if applicable |
| TO RESPRAY REAR FENDER LH                             | \$428.00           | \$0.00                              |
| TO RESPRAY TAIL GATE                                  | \$428.00           | \$0.00                              |
| TO RESPRAY REAR BUMPER                                | \$428.00           | \$200.00                            |
| TO RESPRAY REAR PANEL                                 | \$230.00           | \$0.00                              |
| Total Spray Painting & Panel Beating                  | \$1,514.00         | \$200.00                            |

|                                                                     |                    |                                     |
|---------------------------------------------------------------------|--------------------|-------------------------------------|
| Part 3 - Other Costs - Accident and Accident Repair Related Expense |                    |                                     |
| Job Scope                                                           | Quotation from ARC | Adjusted by Surveyor, if applicable |
| TO WASH AND VACUUM                                                  | \$60.00            | \$0.00                              |
| TO CHECK WIRING AND SYSTEM FUNCTION                                 | \$120.00           | \$30.00                             |
| TO APPLY RUST-PROOFING ON AFFECTED AREA                             | \$100.00           | \$0.00                              |
| TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)         | \$445.32           | \$445.32                            |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM                             | \$120.00           | \$20.00                             |
| TO REPLACE SUNDRY PARTS                                             | \$100.00           | \$0.00                              |
| TO CHECK & RESET SYSTEM FUNCTION                                    | \$350.00           | \$150.00                            |
| ISOLATED OF (EV) (NET)                                              | \$150.00           | \$150.00                            |
| Total Other Costs                                                   | \$1,445.32         | \$795.32                            |

| Part 4 - Spare Parts / Material Usage |         |                  |                                  |          |                 |              |                  |                    |                   |
|---------------------------------------|---------|------------------|----------------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
| Part Number                           | Portion | Stock Number     | Part Name                        | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|                                       |         | 10328219-SEPP    | TAIL GATE ASM-LIFT               | 0.00     | \$1,928.26      | 0.00         | \$0.00           | Replace            | Not Given         |
|                                       |         | 10935050         | EMBLEM ASM-RR LIC PLT ( MG )     | 0.00     | \$62.92         | 0.00         | \$0.00           | Replace            | Not Given         |
|                                       |         | 10885560         | EMBLEM ASM-L/GATE ( MG5 SW)      | 0.00     | \$21.84         | 0.00         | \$0.00           | Replace            | Not Given         |
|                                       |         | 10896035         | EMBLEM ASM-L/GATE (SW EV )       | 0.00     | \$33.90         | 0.00         | \$0.00           | Replace            | Not Given         |
|                                       |         |                  | STICKER LOGO ( TAILGATE ))       | 0.00     | \$25.00         | 0.00         | \$0.00           | Replace            | Not Given         |
|                                       |         | 10345435 CC-SEPP | PANEL-BODY SI OTR RR FENDER - LH | 0.00     | \$1,201.52      | 0.00         | \$0.00           | Replace            | Not Given         |

**Strides Premier Accident Vehicle Repair Estimates**

|                                                   |  |
|---------------------------------------------------|--|
| Strides Premier Automotive Services Pte Ltd       |  |
| 60 Woodlands Industrial Park E4, Singapore 757705 |  |
| FAX Number : 63685592                             |  |
| Estimator Telephone Number : 68662623             |  |
| Accident Reporting Number : 68662672              |  |

Date Generated : 22/08/2024

User ID : PohSuan

|              |  |               |                                              |      |                   |       |                   |         |           |   |
|--------------|--|---------------|----------------------------------------------|------|-------------------|-------|-------------------|---------|-----------|---|
|              |  |               | STICKER ELECTRIC ( LOGO                      | 0.00 | \$21.60           | 0.00  | \$0.00            | Replace | Not Given | X |
|              |  | 10369261-SPRP | FASCIA-RR BPR                                | 1.00 | \$758.48          | 10.00 | \$682.63          | Replace | Replace   | √ |
|              |  | 10751490      | FASCIA-RR BPR LWR                            | 1.00 | \$230.68          | 10.00 | \$207.61          | Replace | Replace   | √ |
|              |  | 10359002      | FINISHER-RR BPR - LH                         | 0.00 | \$47.42           | 0.00  | \$0.00            | Replace | Check     | X |
|              |  | 10465727      | BRACKET ASM-RR BPR FASCIA SI - RH            | 0.00 | \$29.50           | 0.00  | \$0.00            | Replace | Check     | X |
|              |  | 10465723      | BRACKET ASM-RR BPR FASCIA SI - LH            | 0.00 | \$29.84           | 0.00  | \$0.00            | Replace | Check     | X |
|              |  | 10326371      | BRACKET-RR BPR FASCIA SI MTG - RH            | 0.00 | \$46.08           | 0.00  | \$0.00            | Replace | Check     | X |
|              |  | 10326369      | BRACKET-RR BPR FASCIA SI MTG - LH            | 0.00 | \$46.08           | 0.00  | \$0.00            | Replace | Check     | X |
|              |  | 10371766      | BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST | 1.00 | \$13.20           | 10.00 | \$11.88           | Replace | Replace   | √ |
|              |  | 10371768      | BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST | 1.00 | \$12.90           | 10.00 | \$11.61           | Replace | Replace   | √ |
|              |  | 10371790      | BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST | 1.00 | \$12.90           | 10.00 | \$11.61           | Replace | Replace   | √ |
|              |  | 10449056      | BRACKET-RR BPR FASCIA LWR MTG - RH           | 0.00 | \$12.80           | 0.00  | \$0.00            | Replace | Check     | X |
|              |  | 10449047      | BRACKET-RR BPR FASCIA LWR MTG - LH           | 0.00 | \$12.80           | 0.00  | \$0.00            | Replace | Check     | X |
|              |  | 90003417      | SCRIVET-RR BPR FASCIA                        | 0.00 | \$0.84            | 0.00  | \$0.00            | Replace | Not Given | X |
|              |  | 10327894      | BAR ASM-RR BPR IMP                           | 0.00 | \$339.77          | 0.00  | \$0.00            | Replace | Check     | X |
|              |  | 10395721-SEPP | PANEL ASM-RR END                             | 0.00 | \$708.66          | 0.00  | \$0.00            | Replace | Check     | X |
|              |  | 10376550-WSD  | SENSOR-RR PARK DIST CONT                     | 0.00 | \$65.00           | 0.00  | \$0.00            | Replace | Check     | X |
|              |  | 10587409      | LAMP ASM-TAIL(BODY SI) - LH                  | 1.00 | \$764.09          | 10.00 | \$687.68          | Replace | Replace   | √ |
|              |  | 10587411      | LAMP ASM-TAIL(LID SI) - LH                   | 1.00 | \$407.68          | 10.00 | \$366.91          | Replace | Replace   | √ |
|              |  | 10726676      | LAMP ASM-RR FOG - LH                         | 1.00 | \$36.30           | 10.00 | \$32.67           | Replace | Replace   | √ |
| <b>Total</b> |  |               |                                              |      | <b>\$6,870.06</b> |       | <b>\$2,012.60</b> |         |           |   |

| Added Spare Parts / Material Usage After Surveyor Signed off |         |              |                      |          |               |              |                  |           |                |
|--------------------------------------------------------------|---------|--------------|----------------------|----------|---------------|--------------|------------------|-----------|----------------|
| Part Number                                                  | Portion | Stock Number | Part Name            | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|                                                              |         | 10359002     | FINISHER-RR BPR - LH | 1.00     | \$47.42       | 10.00        | \$42.68          | Replace   | Replace        |
|                                                              |         | 10327894     | BAR ASM-RR BPR IMP   | 1.00     | \$339.77      | 10.00        | \$305.79         | Replace   | Replace        |
| Total                                                        |         |              |                      |          | 387.19        |              | 348.47           |           |                |

2,361.07  
+ 400.00  
+ 995.32  
-----  
3,756.39