

(02/11/13) Wef
ASS. REC. BY:

REF:

CS/ICS 24080214/Rnp3

957A

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNM 7361C

at Workshop m/s

of PANDAN CRESCENT

Insured:

ICS

Policy No.

Claims No.

Sum Insured:

Excess:

TBA


(Client's Record)

\$500

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

131K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

10

days

Res.:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNM 7361C

Yr Regn:

2020 / JULY

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA RMV 4 2.0 PREMIUM c.c 1987

Colour:

GR6Y

AC:

Insured / Std / NI / NA

Sp. Reading:

39479

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTMV 43EV 700042757

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/60R18

R:

11

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/08/24

D.O.I.

14/08/24

Survey held at

PANDAN C

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT-84K

We will be advising our principal a cost of repair P/P \$15375.72 /- with 10 days
(red, \$4200.83, 21%)

Date/Time, File Pass to?



: Prel. Report

Days Of Repair:

10

1)



: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

: \$ + RS. \$

: Photos

: Others

Report Format :

Lump Sum / I.B.I: (\$



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS	Mr Muhammad Azry Bin Kassim 606D Tampines Street 61 #03-372 Singapore 524606 Mobile: 98555543				
		Document No. 0					
		Document Date 12/08/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXAA52R	ANXGBW P2	24/07/2020	SNM7361C	0	32223	79/OD/SNM7361C
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTMV43FV70D042797		M20AV147012	60	Ong Wen Hong	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:MPC23A00369500 ACC DATE:11/08/2024 TOW/DRIVE IN:12/08/2024 EXCESS: DATE-IN:12/08/2024 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50	100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				100	280.00
3	B	BP-LAB2 TO REPLACE AND REPAIR ACCIDENT DAMAGED P @ 792x2				1584	3168.00
4	B	BP-RES2 TO RESPRAY ALL ACCIDENT AFFECTED AREAS @ 656				656	2099.20
5	B	BP-LAB2 TO CHECK WIRING SYSTEM					107.71
6	B	BP-LAB2 TO DRILL HOLE AND INSTALL REVERSE SENSOR					158.40
7	B	BP-LAB2 TO REMOVE AND TRANSFER BOOT COMPONENT TO NEW BOOT					475.20
8	B	BP-ECU2 TO RESET ECU AND REPROGRAMME					158.40
9	B	BP-WS2 TO REMOVE AND INSTALL REAR WINDSCREEN					475.20
10	S	BP-SUBLET TO SUPPLY SOLAR FILM FOR REAR WINDSCREEN					480.00
11	S	BP-SUBLET TO SUPPLY REAR NUMBER PLATE					80.00
12	1	T52159-42230 COVER, RR BUMPER	1.00	480.20	30.00		336.14
13	2	T52161-42944 PIECE, RR BUMPER, RH	1.00	472.20	30.00		330.54
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
		Sublet		Amount Due			
		Lubrication/Fluid					
		Others					

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICECICS	Mr Muhammad Azry Bin Kassim 606D Tampines Street 61 #03-372 Singapore 524606 Mobile: 98555543
	Document No. 0	
	Document Date 12/08/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXAA52R	ANXGBW P2	24/07/2020	SNM7361C	0	32223	79/OD/SNM7361C

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTMY43FV70D042797	M20AV147012	60	Ong Wen Hong	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
14	3	T52162-42944	PIECE, RR BUMPER, LH ?	1.00	472.20	30.00	330.54
15	4	T52453-42040 B0	GUARD, RR BUMPER, de	1.00	901.50	30.00	631.05
16	5	S52161-0K040	PIECE, RR BUMPER, ne	10.00	5.80	30.00	40.60
17	6	T52023-42060	REINFORCEMENT ?	1.00	551.50	30.00	386.05
18	7	T52562-42060	RETAINER, RR BUMPER, ?	1.00	150.50	30.00	105.35
19	8	T52563-42050	RETAINER, RR BUMPER, ?	1.00	150.50	30.00	105.35
20	9	T67005-42650	PANEL SUB-ASSY, BACK, st	1.00	3113.60	30.00	2179.52
21	0	T67881-42070	WEATHERSTRIP, BACK ?	1.00	465.30	30.00	325.71
22	1	T76802-42140	GARNISH SUB-ASSY, de	1.00	332.40	30.00	232.68
23	2	T68105-42300	GLASS SUB-ASSY, BACK, ne	1.00	1706.50	30.00	1194.55
24	3	T62785-60030	SPACER, QUARTER, ne	2.00	8.20	30.00	11.48
25	4	T67750-42060 C0	BOARD ASSY, BACK ?	1.00	647.90	30.00	453.53
26	5	T69350-42080	LOCK ASSY, BACK DOOR ?	1.00	1100.10	30.00	770.07
27	6	T90975-02070	EMBLEM, SYMBOL X	1.00	79.60	30.00	55.72
28	7	T75431-42180	EMBLEM, BACK DOOR, ne	1.00	75.70	30.00	52.99
29	8	T81551-42230	LENS & BODY, RR ?	1.00	748.10	30.00	523.67
30	9	T81561-42230	LENS & BODY, RR ?	1.00	748.10	30.00	523.67
31	0	T81581-42092	LENS & BODY, RR ?	1.00	672.10	30.00	470.47
32	1	T81591-42121	LENS & BODY, RR ?	1.00	352.50	30.00	246.75
33	2	S81910-0K030	REFLECTOR ASSY, REFL ?	1.00	91.80	30.00	64.26

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	Amount Due
		Lubrication/Fluid	
		Others	



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details	
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS	Mr Muhammad Azry Bin Kassim 606D Tampines Street 61 #03-372 Singapore 524606 Mobile: 98555543	
		Document No. 0		
		Document Date 12/08/2024		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXAA52R	ANXGBW P2	24/07/2020	SNM7361C	0	32223	79/OD/SNM7361C
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In	Collected On	
JTMV43FV70D042797		M20AV147012	60	Ong Wen Hong	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
34	3	S81920-0K010 REFLECTOR ASSY, REFL	1.00	91.80	30.00	64.26
35	4	T58307-42080 PANEL SUB-ASSY, BODY	1.00	1058.90	30.00	741.23
36	5	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	1.00	108.00	30.00	75.60
37	6	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	1.00	108.00	30.00	75.60
38	7	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00	30.00	140.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Handwritten notes:
Rasm
Hy 900mls
5 days
EXCESS: TBA
Revert
14/08/24
Res 5P paint

or & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature	Charge Summary	Total	17,969.49
Please acknowledge receipt of vehicle			Parts	GST 9.00%	1,617.25
			Labour		
			Sublet		
			Lubrication/Fluid	Less	0.00
			Others	Amount Due	19,586.74

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	957A
Vehicle Details	
Vehicle No.:	SNM7361C
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Aug 2024
Vehicle Make:	TOYOTA
Vehicle Model:	RAV4 2.0 PREMIUM SUV (AUTO) (2WD)
Primary Colour:	Grey
Manufacturing Year:	2020
Engine No.:	M20AV147012
Chassis No.:	JTMY43FV70D042797
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$29,957.00
Original Registration Date:	24 Jul 2020
First Registration Date:	24 Jul 2020
Transfer Count:	1
Actual ARF Paid:	\$33,940.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jul 2030
PARF Rebate Amount:	\$25,455.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jul 2030
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$35,001.00
COE Rebate Amount:	\$20,793.00
Total Rebate Amount:	\$46,248.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 14 Aug 2024

OK



Toyota Rav4 2.0A Premium

\$135,800 Instalment \$1,517/mth

PREMIUM AD

♡ Shortlist

✓ Get Warranty

📄 Loan Calculator



Overview Financial Leasing Photo Research

Depreciation	\$19,440 / year
Reg. Date	24-Sep-2020 (6yrs 1mth 9days COE left)
Manufactured	2020
Mileage	38,190 km (9.8k / year)
Transmission	Auto
Engine Cap	1,987 cc
Road Tax	\$1,198 / year
Power	127.0 kW (170 bhp) View specs of the Toyota RAV4 (2019-2022)
Curb Weight	1,530 kg
COE	\$40,790
OMV	\$29,957
ARF	\$33,940