



發 福 摩 哆 車 房
HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6988
BUSINESS REG NO. 375654/00C

Not Authorized
1/s #62001
15/8/24

4 - Lys
Zhe Jho. Hing

Carplate: SMD9806H
Chassis No: WDD2040452A691423
Accident Date: 13.8.2024
Make & Model: Mercedes C180 Kompressor

No.	Item	Price	✓/✗	Remarks
1	Front Bumper	\$ 1,698.30	1636.54	Cur ✓
2	Front Bumper Side Retainer RH	\$ 289.65		11 X
3	Front Bumper Bracket RH	\$ 198.20		11 X
4	Front Head Lamp RH	\$ 1,982.10		Scr/cng ✓
5	Front Fender RH	\$ 1,114.90	1085.00	10/12 ✓
6	Front Fender Splash Guard RH	\$ 424.10	225.00	10/12 ✓
7	Front Lower Arm RH	\$ 986.20	645.00	10/12 ✓
8	Front Anti Roll Bar Link RH	\$ 221.90		11 X
9	Front Shock Absorber RH	\$ 818.20		11 X
10	Front Shock Absorber Mounting RH	\$ 139.60		11 X
11	Front Knuckle Assembly RH	\$ 829.10		11 X
12	Front Wheel Bearing RH	\$ 382.90		11 X
13	Front Bumper Fog Lamp Garnish RH	\$ 186.20		11 X
14	Front Bumper Fog lamp Lower Garnish RH	\$ 181.90	166.50	11 X
15	Front Bumper Fog Lamp Assembly RH	\$ 389.20		11 X
16				
17				
18				
19				
20				
21				
22				
23				
24				
25				
26				
27				
28				
29				
30				
31				
32				
33				
34				
35				
36				

	<u>Special Nett Items</u>	Price	✓/✗	Remarks
1	Front Bumper Clips (1 Set)	\$ 40.00		net ✓
2	Front Fender Splash Guard Clips (1 Set)	\$ 40.00		net X
3	Front Alloy Rim RH	\$ 1,080.00		net 622 S/W
4	Front Tyre RH (Michelin 225/40 ZR18)	\$ 680.00		net X
5				
6				
7				
8				
9				
10				
11				
12				
13				
No.	All Necessary Work	Price	✓/✗	Remarks
1	To Carry Out Anti-rust Treatment	\$ 120.00		30
2	Rewiring to Facilitate repair works	\$ 120.00		20
3	To Conduct 4 Wheel Alignment	\$ 150.00		20
4	Front Undercarriage works; To Remove and Install Front Undercarriage including lower arms, shock absorber, spring, knuckle, brake calliper and all necessary	\$ 580.00		120
5	Labour to remove and replace, Knocking and Jacking of all necessary, including repositioning of replaced parts	\$ 1,000.00		300
6	Spray painting materials and respray of all affected and replaced parts necessary for paintwork	\$ 800.00		400
	Estimated No. of days for repairs and respray of all necessary	8 Days	3 dgs	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 6952-14

102

625693

640

950

7846.93

202

677