

Shiau Chan (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Thursday, 12 September 2024 3:59 PM
To: Allan Wu; SUR
Cc: 'claims'; carrine.leong@premiumauto.com.sg; jiayee.yap@premiumauto.com.sg; Shiau Chan (LKKAUTO)
Subject: Re: FINAL REVISION - SKS317G - OD AIG - SURVEYED ON 15 AUG 2024

Hi Allan,

We will be advising our principal a cost of repair P/P \$10,293.92 /- with 05 days of repair before GST, subject to their approval.

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth. Print only when necessary.

From: Allan Wu <allan.wu@premiumauto.com.sg>
Sent: Thursday, 12 September 2024 2:52 pm
To: SUR <sur@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: 'claims' <claims@premiumauto.com.sg>; carrine.leong@premiumauto.com.sg <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg <jiayee.yap@premiumauto.com.sg>
Subject: FINAL REVISION - SKS317G - OD AIG - SURVEYED ON 15 AUG 2024

Hi Rasul,

Attached are the before paint pictures and final revised estimate.

Kindly confirm repair cost of \$10,293.92 @ 5 Days.

Your early confirmation is appreciated.

Thank you and regards

Allan Wu

Bodyworks Department

Premium Automobiles Pte Ltd (Reg No 199902271W)

281 Alexandra Road Singapore 159938

p. +65 6836 2223 f. +65 6841 1183

e. allan.wu@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you