



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKS 317 G.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$ 480.00	Xnn
2	TO REMOVE AND TRANSFER LHS FRONT DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	/
3	TO REMOVE AND REINSTALL FRONT BUMPER. TO DISMANTLE AND RENEW LHS FRONT FENDER AND LHS FRONT DOOR. TO REPAIR LHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,600.00	500 /
4	TO RESPRAY LHS FRONT FENDER, LHS FRONT AND REAR DOORS, LHS FRONT AND REAR DOOR LOWER COVER AND LHS WING MIRROR COVER.	\$ 4,200.00	1900 /
5	TO INSTALL SOLAR FILM FOR LHS FRONT DOOR GLASS	S/N \$ 400.00	Xnn
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 292.00	/
TOTAL LABOUR CHARGES		: \$ 9,372.00	



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKS 317 G.

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT FENDER - LH <i>repair</i>	1	\$ 1,537.00	
2	FRONT FENDER ATTACHMENT - LH <i>XAN</i>	1	\$ 74.00	
3	FRONT WHEEL ARCH COVER - LH <i>OK</i>	1	\$ 639.00	<i>511.20</i>
4	FRONT DOOR - LH <i>bt</i>	1	\$ 3,215.00	<i>2572.00</i>
5	FRONT DOOR OUTER SEAL - LH <i>OK</i>	1	\$ 206.00	<i>164.80</i>
6	FRONT DOOR CATCH - LH <i>bt</i>	1	\$ 150.00	<i>120</i>
7	FRONT DOOR HINGE HALVES - LH UPPER <i>? XAN</i>	1	\$ 59.00	
8	FRONT DOOR HINGE HALVES - LH UPPER <i>? XAN</i>	1	\$ 59.00	
9	FRONT DOOR HINGE HALVES - LH LOWER <i>? XAN</i>	1	\$ 59.00	
10	FRONT DOOR HINGE HALVES - LH LOWER <i>? XAN</i>	1	\$ 59.00	
11	FRONT DOOR CORNER TRIM - LH <i>OK</i>	1	\$ 57.00	<i>45.20</i>
12	FRONT DOOR SEALING ELEMENT - LH <i>XAN</i>	1	\$ 31.00	
13	FRONT WINDOW SOLT SEAL - LH <i>XAN</i>	1	\$ 280.00	
14	FRONT DOOR LOWER COVER - LH <i>OK</i>	1	\$ 438.00	<i>350.40</i>
15	FRONT DOOR WINDOW <i>XAN</i>	1	\$ 296.00	
16	FRONT WING MIRROR MOUNTING - LH <i>OK</i>	1	\$ 2,560.00	<i>2048.00</i>
17	FRONT WING MIRROR CAP - LH <i>MIS</i>	1	\$ 269.00	<i>215.20</i>
18	FRONT WING MIRROR GLASS - LH <i>MIS</i>	1	\$ 1,038.00	<i>830.40</i>
19	FRONT WINDOW TRIM STRIP - LH <i>? XAN</i>	1	\$ 320.00	
20	REAR DOOR COVER - LH <i>OK</i>	1	\$ 413.00	<i>330.00</i>
21	SUNDRIES <i>? OK</i>	1	\$ 500.00	<i>1412</i>
TOTAL SPARE PARTS		:	\$ 12,259.00	
TOTAL LABOUR CHARGES		:	\$ 9,372.00	
GRAND TOTAL		:	\$ 21,631.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Repair - 4x 9001 m68
: 15/08/24
: 5 days
: excess TBA
: Repair
: Body by paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT