



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24080225/Uqh3
75 BRAS BASAH ROAD	Date:	23/08/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMW 4661R	Veh. Inspected	SLN 5315T
Policy No.	-	Coverage	0
Claim No.	MT/1290500-001	Excess	\$0.00
Assign From	NATALIE LEE	Assign Date	14/08/2024

### 2. Vehicle Details

Make & Model	HONDA ODYSSEY 2.4 EXV-S CVT SR NAVI RES	C.C	2356
Engine No.	K24W72013771	Year of Reg.	08/05/2017
Chassis No.	JHMRC1890GC209143	Colour	BLACK
Odometer	131765 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/55R17	DUNLOP	6
L/H Front Tyre	215/55R17	DUNLOP	6
R/H Rear Tyre	215/55R17	DUNLOP	6
L/H Rear Tyre	215/55R17	DUNLOP	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	10/08/2024	Inspection Date	15/08/2024 (10:37)
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days