

One Line Motorworks Trading

11, Tuas Bay Close #06-03 West Star, Singapore 636996

Tel: 62622106

Company Reg No: 53375959E

Email: tricia.onellnemotorworks@gmail.com

14th August 2024

BY HAND

THIRD-PARTY CLAIM XD4634F- REPAIR ESTIMATE FOR PC2410G

TRAFFIC ACCIDENT ON 02/06/2024, TRAFFIC ACCIDENT Near AYE, Jurong Hill Flyover, Singapore. JLN AHMAD IBRAHIM TWDS JLN BAHAR

To whomever it concerns,
We append below our repair estimate for PC2410G.

Repair Estimate

Parts required:

1. Side Mirror Assy (RHS) *bro ✓*

1000

\$ 1000.00

1000

900

Labour charges:

1. To replace side mirror assy
2. To spray paint side mirror assy

400


\$ 250.00 *200*
\$ 600.00 *200*

Total repair costs:

900
400
1300
=

\$ 1850.00

This estimate is based on visible damage only. Should any hidden parts and/or labour required during works in progress, insurer and/or their surveyor will be notified accordingly.



Neo Say Pheng
(HP: 9797 1868)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ramu
Hp 90010068
1 day
P/P
16/08/24
Pay after repair