

(08/11/13) Wef
ASS. REC. BY:

REF: CS/SMR24060107/Rnh3

072P

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD (TP/WS/TP RES/OD RES/EVA/INV/MV)
To inspect Vehicle No: SLC 5443P
at Workshop m/s MIDSUBISHI HC CAPITAL
of 8, POUARD LOKYANH RD
Insured: SMR
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 29k
IDAC Accident Report: Consistent?: Yes or No
GIA / PR Seen: Consistent?: Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLC 5443P Yr Regn: 2016 / MAY
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: MAZDA 3 SEDAN 1.5LSP c.c. 1496
Colour: RED AC: Insured / Std / Nil / NA
Sp. Reading: 102759 T/Radio: Insured / Std / Nil / NA
Eng/No: _____
C/No: JM6BM42A860339060
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/60R16
R: _____

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 12/06/24 D.O.I. 16/07/24
Survey held at LOKYANH

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Limit - 12K

We will be advising our principal a cost of repair P/P \$1,440.80/- with 03 days of repair
(red, \$2475.6, 63%)

Date/Time, File Pass to?

☐
☐

: Prel. Report

: Final Report

Days Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

1)

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

) S + RS \$ _____

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$ _____)

TOTAL

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE Dated 14/06/2024

MS FIRST CAPITAL

ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 12/06/2024 13:59hr
 VRN : **SLC5443P**
 MODEL : MAZDA 3
 YOUR REF : SHB5822G

PARTS REPLACEMENT

	Qty	S\$ Unit	S\$ Amt
1 rear bumper top <i>de 3 day X</i>	1	\$ 1,120.00	\$ 1,120.00
2 rear bumper lower garnish <i>3 day X</i>	1	\$ 1,232.00	\$ 1,232.00
3 rear tow cover <i>ms /</i>	1	\$ 56.00	\$ 56.00
			<u>\$ 2,408.00</u>
			<u>\$ 481.60</u>
			<u>\$ 1,926.40</u>

All List -20%

Special Nett

1 bumper clips (set) <i>ms /</i>	1	\$ 80.00	\$ 80.00 <i>40</i>
2 bumper under cover clips (set) <i>X</i>	1	\$ 80.00	\$ 80.00 <i>X</i>
3 rear parking sensor (set) <i>X</i>	1	\$ 580.00	\$ 580.00 <i>X</i>
			<u>\$ 740.00</u>

PARTS TOTAL \$ **2,666.40****B. Labour Charges**

1 Remove, repair and replace parts for the effected areas.	\$ 650.00 <i>200</i>
2 Spray painting on the effected areas with 2k paint.	\$ 400.00 <i>200</i>
3 Check wiring and ensure proper functioning.	\$ 80.00 <i>X</i>
4 Remove and reinstall bumper sensors.	\$ 120.00 <i>60</i>
	<u>\$ 1,250.00</u>

LABOURS TOTAL

Grand Total : \$ 3,916.40
 Add 9% GST : \$ 352.48
 Nett Total : \$ **4,268.88**

No. of repair days: 5

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
H/ 9001068
3 day
P/P
16/07/24
Reg by paint

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Foreign Identification Number

Vehicle Details

072P

Vehicle No.:

Vehicle to be Exported:

SLC5443P

Intended Deregistration Date:

No

Vehicle Make:

17 Jul 2024

Vehicle Model:

MAZDA

Primary Colour:

MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Manufacturing Year:

Red

Engine No.:

2016

Chassis No.:

P520360124

Maximum Power Output:

JM6BM42A8G0339060

Open Market Value:

88.0 kW (118 bhp)

Original Registration Date:

\$18,864.00

First Registration Date:

18 May 2016

Transfer Count:

18 May 2016

Actual ARF Paid:

0

Intended PARF Rebate Details

\$13,864.00

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

17 May 2026

PARF Rebate Amount:

\$7,625.00

Intended COE Rebate Details

COE Expiry Date:

17 May 2026

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$47,889.00

COE Rebate Amount:

\$8,779.00

Total Rebate Amount:

\$16,404.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.
The information contained herein is correct as at 17 Jul 2024

OK



Mazda 3 1.5A Sunroof

\$29,800 Instalment \$1,036/mth

PREMIUM AD

Apply for 2.48% loan

Shortlist

Get Warranty

TRENDING NOW

mycarforum

How to People Managed to Drive With Bald Tyres?

- Overview
- Financial
- Photo
- Research

Depreciation	<i>i</i> \$13,320 / year
Reg. Date	16-May-2016 (1yr 9mths 29days COE left)
Manufactured	<i>i</i> 2016
Mileage	<u>134,717 km</u> (16.5k / year)
Transmission	Auto
Engine Cap	1,496 cc
Road Tax	<i>i</i> \$682 / year
Power	88.0 kW (118 bhp) View specs of the Mazda 3 Sedan (2014-2019)
Curb Weight	<i>i</i> <u>1,321 kg</u>