



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS GREAT AMERICAN INSURANCE COMPANY	Ref:	CS/GAI24080241/Uqp3
3 TEMASEK AVENUE	Date:	15/08/2024
#16-01 CENTENNIAL TOWER	Code:	GAI
SINGAPORE 039190		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKS 9652D	Veh. Inspected	SMX 2267D
Policy No.	-	Coverage	0
Claim No.	CLMOMVP000001575	Excess	\$0.00
Assign From	JOCELYN TENG	Assign Date	15/08/2024

2. Vehicle Details

Make & Model	MAZDA 6 (A)	C.C	1998
Engine No.	PE21535954	Year of Reg.	31/12/2020
Chassis No.	JM6GL1073M0433712	Colour	RED
Odometer	35184 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/55R17	BRIDGESTONE	7
L/H Front Tyre	225/55R17	BRIDGESTONE	7
R/H Rear Tyre	225/55R17	BRIDGESTONE	7
L/H Rear Tyre	225/55R17	BRIDGESTONE	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/07/2024	Inspection Date	21/08/2024
Survey held at	AUTO EUROKARS PTE LTD 5 UBI CLOSE, SINGAPORE 408605		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days