

MS CAR AUTO PTE LTD

8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @KAKI BUKIT
SINGAPORE 415875

TO	: NTUC	DATE	: 14/8/2024
VEHICLE NO	: GBL2520R (2021)		
VEHICLE MODEL	: NISSAN NV200 VANETTE		Veron
CHASSIS NO	: VM20161700		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Delint</i>	1	\$ 698.90	\$ 698.90
2	REAR BUMPER SIDE HOLDER <i>Len</i>	2	\$ 38.90	\$ 77.80
3	REAR BUMPER SPONGE <i>cut</i>	1	\$ 198.70	\$ 198.70
4	REAR END PANEL OUTER <i>Reis</i>	1	\$ 624.70	\$ 624.70
5	REAR END PANEL TOP GRANISH <i>new</i>	1	\$ 140.20	\$ 140.20
6	TAILLAMP <i>LH cut</i>	2	\$ 308.90	\$ 617.80
7	TAILLAMP PANEL <i>Reis</i>	1	\$ 267.00	\$ 267.00
8	TAILGATE <i>Delint</i>	1	\$ 2,089.20	\$ 2,089.20
9	TAILGATE LOCK <i>Delint</i>	1	\$ 308.90	\$ 308.90
10	TAILGATE WEATHERSTRIPE <i>ht</i>	1	\$ 319.60	\$ 319.60
11	TAILGATE OUTER GARNISH <i>cut</i>	1	\$ 389.50	\$ 389.50
12	NISSAN LOGO	1	\$ 95.30	\$ 95.30
13	NV200 EMBLEM <i>3 per</i>	1	\$ 92.70	\$ 92.70
14	VANETTE EMBLEM	1	\$ 93.60	\$ 93.60
15	SPARE TYRE CARRIAGE <i>new</i>	1	\$ 439.70	\$ 439.70

TOTAL PRICE: \$ 6,453.60
LESS 10% \$ 645.36
SUB TOTAL PRICE: \$ 5,808.24

4555.30
4135.77

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>3 per</i>	1	\$ 30.00	\$ 30.00
2	REAR NUMBER PLATE HOLDER <i>3 per</i>	1	\$ 30.00	\$ 30.00
3	REAR BUMPER CLIPS <i>per</i>	1 SET	\$ 50.00	\$ 50.00
4	REVERSE SENSOR <i>2 per</i>	1 SET	\$ 280.00	\$ 280.00
5	REAR CAMERA <i>new</i>	1	\$ 480.00	\$ 480.00
6	REAR END PANEL TOP GARNISH CLIPS <i>per</i>	1 SET	\$ 20.00	\$ 20.00
7	REAR END PANEL SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00
8	TAILGATE OUTER GARNISH CLIPS <i>per</i>	1 SET	\$ 20.00	\$ 20.00
9	TAILGATE GLASS SEALANT <i>per</i>	1 SET	\$ 60.00	\$ 60.00
10	70KM/H STICKER <i>new</i>	1	\$ 15.00	\$ 15.00
11	6 PAX STICKER <i>new</i>	1	\$ 15.00	\$ 15.00

TOTAL : \$ 1,060.00

340

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	520	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	450	
3	WIRING CHECK	\$ 50.00	30	
4	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
5	TO REMOVE REAR CAMERA	\$ 100.00	50	
6	TO APPLY TUFF COAT	\$ 150.00	30	
7	TO REMOVE UPHOLSTERY TO FACILITATE REPAIRS	\$ 150.00	X	
8	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	60	
9	TO REMOVE AND REFIT TAILGATE GLASS	\$ 180.00	120	

TOTAL: \$ 3,080.00

ESTIMATE REPORT

TOTAL PARTS COST: \$ 6,868.24

TOTAL LABOUR COST: \$ 3,080.00

TOTAL REPAIR COST: \$ 9,948.24

total: 5765.77

4/5: 4.6k.

04 Days.
4.6k.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: