

Ready Auto Care Pte Ltd - We Care For All Your Car Needs

Unit 10 # 03-06 AMK Auto Point, Ang Mo Kio Ind Park 2A, Ang Mo Kio Ave 5. Singapore 568047
Tel : 64810304 Fax : 64815587 Reg No : 200600989K GST No : 200600989k

China Taiping Insurance (Singapore) Pte Ltd

Motorcar Claim Department

Attn Officer In Charge

Repair Estimate

Date :

13/8/2024

Accident Involving SJR1922U & YQ2287R On 10/08/2024 At AMK Ave 4 Carpark

Car No : SJR1922U

Mercedes C180

5 days

Item	Descriptions	Amount
1	Front Right Fender	\$ 728.00
2	RH Headlamp	\$ 2,295.80
3	RH Headlamp Lower Bracket	\$ 226.00
4	Front Right Fender Inne Shield	\$ 94.50
5	Front Bumper	\$ 1,250.00
6	Front Bumper Inner Center Bracket	\$ 223.00
7	Mercedes Logo	\$ 75.00
8	Front Bumper Center Bracket Aluminium	\$ 656.30
9	Front Right Bumper Retainer	\$ 32.00
10	Radar Sensor	\$ 1,120.00
11	Bonner Active RH & LH @\$232 X 2	\$ 464.00
12	Front Right Upper Arm	\$ 695.00
13	Front Right Knuckle Arm	\$ 843.20
14	Front Right Shock Absorber	\$ 598.00
15	Front Right Wheel Bearing	\$ 455.00
16	Front Right Wheel Cap	\$ 48.00
17	Front Right Pressure Sensor	\$ 265.50

108

LKK Auto Consultants hence the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total For Parts (Nett) \$ 10,069.30

S/N Item (s)

- Front Bumper Clips - 1 Set
- Front Right Sport Rim
- King Trollyery Towing Service

\$ 55.00
\$ 850.00
\$(Bill) 100.00

Total For S/N \$ 950.00

Labour & Misc

- To Remove All Damaged Parts, Knock Out Dents, Jack Out Damaged Panel Adjust, Replace, Reshape, Cut, Weld, Refix & Realign Body Structure
- Spray Painting For New And Repair Parts Including Supply Of Paints Materials
- Remove & Replace Undecariage Damaged Parts & Tyre Pressure Sensor
- Computerise 4 Wheels Alignment & Balancing
- Computerise Reprogramming Randa Sensor & All False Memory
- Cavity Preservation On All Affected Areas

\$ 1,500.00
\$ 800.00
\$ 450.00
\$ 100.00
\$ 350.00
\$ 100.00

\$ 3,300.00

Ready Auto Care Pte Ltd

Sulynn - 96606551

Total For Parts & Labour \$ 14,319.30

No Of Days For Repair

6 Days

5 days