

Name & Address:

Motor Claims Department

CHINA TAIPING INSURANCE P/L

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Email/Fax To:

Contact No:

Vehicle No:

SKU34L

Brand & Model:

Macan

Chassis/VIN No:

WP1ZZZ95ZJLB06094

WIP#:

10778

Date:

15-Aug-24

Franchise:

PORSCHE

Contact Person (Eurokars):

FAIZ

Contact No (Eurokars):

6331 0680

Type of Claim:

THIRD PARTY

YEAR MODEL:

23/02/2018

PARTS / MATERIAL CHARGES

MARK = Survey Marking (Kms "A" if item is approved)

NO	DESCRIPTION	PART NO	QTY	MARK	REVISED	PRICE
1	FRONT BUMPER <i>son /</i>	P95B-807-221-A -G2X	1		-	\$ 1,554.40
2	FRONT BUMPER LOWER SPOILER <i>cm /</i>	P95B-807-061-S -1E0	1		-	\$ 349.60
3	EXPANSION RIVET <i>mu /</i>	PPAF-038-501- -	16		-	\$ 44.80
4	GRILLE LH <i>? xsvl</i>	P95B-807-681- -1E0	1		-	\$ 108.60
5	DISC UPPER LH <i>X A7</i>	P95B-807-685- -1E0	1		-	\$ 67.00
6	DISC LOWER LH <i>? xsvl</i>	P95B-807-877- -1E0	1		-	\$ 58.30
7	GRILLE TRIM LH <i>sla /</i>	P95B-807-819- -1E0	1		-	\$ 72.10
8	SENSOR GASKET <i>ne /</i>	P5QD-919-133- -9B9	4		-	\$ 15.60
9	AIR DUCT CLOSED LH <i>? xsvl</i>	P95B-121-333- -1E0	1		-	\$ 84.40
10	FOGLAMP COVER LH <i>sla /</i>	P95B-807-795-B -1E0	1		-	\$ 46.70
11	CROSS MEMBER PEDESTRIAN <i>? xsvl</i>	P95B-805-241- -	1		-	\$ 290.30
12	FRONT BUMPER SPONGE <i>? xsvl</i>	P95B-807-550-G -	1		-	\$ 88.30
13	CHARGE AIR COOLER BRACKET LH <i>cm /</i>	P95B-805-295-E	1		-	\$ 301.70
14	GUIDE PIECE LH <i>? xsvl</i>	P95B-807-889-C -	1		-	\$ 103.80
15	STRUT BRACE LH <i>? xsvl</i>	P95B-805-527- -	1		-	\$ 132.20
16	BONNET <i>h /</i>	P95B-823-031-LY-GRV	1		-	\$ 5,534.70
17	GASKET FOR ENGINE COVER <i>ne /</i>	P95B-823-739- -	2		-	\$ 21.80
18	PORSCHE CREST <i>ne /</i>	P9P1-853-601- -	1		-	\$ 356.50
19	DESK PAD CREST <i>ne /</i>	P9P1-853-611- -	1		-	\$ 21.30
20	HOOD BADGE NUT <i>ne /</i>	PWHT-004-974- -	2		-	\$ 4.60
21	HEADLAMP (LEFT) <i>X m</i>	P95B-941-029-FA-	1		-	\$ 4,185.90
22	ADDITIONAL HEADLAMP LH <i>2 sla /</i>	P95B-941-181-E -	1		-	\$ 466.90
23						\$

Sub-Total (Parts Price) \$ - \$ 13,909.50

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE BONNET, FRONT BUMPER & ALL ACCIDENT DAMAGED BODY PARTS TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	3440	\$ 3,160.00
2	TO RESPRAY BONNET, FRONT BUMPER	2600	\$ 1,000.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION	150	\$ 250.00

4	TO SUPPLY 1 PC CHASSIS STICKER ON BONNET	nett	\$ 150.00
5	TO REMOVE & REPLACE CHARGE AIR COOLER BRACKET LH	nett	\$ 780.00
6	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM	nett	\$ 500.00
7	TO TRANSFER THE FRONT BUMPER SENSORS	nett	\$ 250 500.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING		\$ 150 250.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	nett	\$ 600.00
10	SUNDRIES	nett	\$ 20 50.00

Survey Date & Time: 21/08/24	Repair Days: 4 days + 1 = 5 days	Excess:
--	--	---------

Surveyor Remarks

*Resue
Hp 90010068
Res by paint*

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price) \$ - \$ 11,240.00

	REVISED	PRICE
Parts Price	\$ -	\$ 13,909.50
Labour Price	\$ -	\$ 11,240.00
Total (Initial Estimate)	\$ -	\$ 25,149.50
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ -	\$ 25,149.50
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ -	\$ 25,149.50
GST 9%	\$ -	\$ 2,263.46
GRAND TOTAL	\$ -	\$ 27,412.96

LKK Auto Consultants hence the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name & Address:

Motor Claims Department

CHINA TAIPING INSURANCE P/L

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Email/Fax No:

Contact No:

Type of Claim:

THIRD PARTY

YEAR MODEL:

23/02/2018

Vehicle No:

SKU34L

Brand & Model:

Macan

Chassis/VIN No:

WP1ZZZ95ZJLB06094

WIPR:

10778

Date:

4 Nov-24

Franchise:

PORSCHE

Contact Person (Eurokars):

FAIZ

Contact No (Eurokars):

6331 0680

FINALIZATION

PARTS / MATERIAL CHARGES

MARK = Survey Marking (Key "A" if item is approved)

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	FRONT BUMPER	P95B-807-221-A -GZX	1		\$ 1,554.40	\$ 1,554.40
2	FRONT BUMPER LOWER SPOILER	P95B-807-061-S -1E0	1		\$ 349.60	\$ 349.60
3	EXPANSION RIVET	PPAF-038-501- -	16		\$ 44.80	\$ 44.80
4	GRILLE LH	P95B-807-681- -1E0	1		\$ -	\$ 108.60
5	DISC UPPER LH	P95B-807-685- -1E0	1		\$ -	\$ 67.00
6	DISC LOWER LH	P95B-807-877- -1E0	1		\$ -	\$ 58.30
7	GRILLE TRIM LH	P95B-807-819- -1E0	1		\$ 72.10	\$ 72.10
8	SENSOR GASKET	P5Q0-919-133- -969	4		\$ 15.60	\$ 15.60
9	AIR DUCT CLOSED LH	P95B-121-333- -1E0	1		\$ -	\$ 84.40
10	FOGLAMP COVER LH	P95B-807-795-B -1E0	1		\$ 46.70	\$ 46.70
11	CROSS MEMBER PEDESTRIAN	P95B-805-241- -	1		\$ -	\$ 290.30
12	FRONT BUMPER SPONGE	P95B-807-550-G -	1		\$ -	\$ 88.30
13	CHARGE AIR COOLER BRACKET LH	P95B-805-295-E -	1		\$ 301.70	\$ 301.70
14	GUIDE PIECE LH	P95B-807-889-C -	1		\$ -	\$ 101.80
15	STRUT BRACE LH	P95B-805-527- -	1		\$ -	\$ 132.20
16	BONNET	P95B-823-031-LY-GRV	1		\$ 5,534.70	\$ 5,534.70
17	GASKET FOR ENGINE COVER	P95B-823-739- -	2		\$ 21.80	\$ 21.80
18	PORSCHE CREST	P9P1-853-601- -	1		\$ 356.50	\$ 356.50
19	DESK PAD CREST	P9P1-853-611- -	1		\$ 21.30	\$ 21.30
20	HOOD BADGE NUT	PWHT-004-974- -	2		\$ 4.60	\$ 4.60
21	HEADLAMP (LEFT)	P95B-941-029-FA-	1		\$ -	\$ 4185.90
22	ADDITIONAL HEADLAMP LH	P95B-941-181-E -	1		\$ 466.90	\$ 466.90
	SUPPLEMENTARY					
23	ANTIFREEZE PROTECTION <i>NA</i>	P000-043-305-15	6		\$ 268.20	\$ 268.20

Sub-Total (Parts Price) \$ 9,058.90 \$ 14,177.70

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE BONNET, FRONT BUMPER & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 3,440.00	\$ 5,160.00
2	TO RESPRAY BONNET, FRONT BUMPER	\$ 2,600.00	\$ 3,000.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 150.00	\$ 250.00