



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGS SINGAPORE 048581 ATTN: KAREN			Ref: CS/FCI24080258/Avp3m4(N) Date: 10/02/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1176J	Veh. Inspected	SMG 5479D	
Policy No.	D-24101861MFCT	Coverage (\$)	0.00	
Claim No.	D24006975MFCT	Excess (\$)	0.00	
Assign From	BETTY	Assign Date	15/08/2024	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JM6BN22A8K0264555	Colour	GREY	
Odometer	84782 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60R16	BRIDGESTONE	6 mm	
L/H Front Tyre	205/60R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/60R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/60R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/08/2024	Inspection Date	19/08/2024	
Survey held at	AUTO UNITED SG PTE LTD 1 KAKI BUKIT AVENUE 6, #01-92, AUTOBAY@KAKI BUKIT, SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	