

KAIZEN MOTORS

KAIZEN MOTORS PTE. LTD. UEN: 201502816H
68 Kaki Bukit Avenue 6, #02-12 Ark@KB, Singapore 417896
Tel: (+65) 6384 1956 Fax: (+65) 6384 1957
Webpage: <https://www.kaizenmotors.com.sg>



kaizenmotorsingapore



kaizen_motors



kaizenmotors

Not Authorized
mercus
28/8/24
2/6 + 3000
2 days

Date : 18/08/2024
Vehicle No : SNP8888C
Model : Audi Q7
Mileage :

Accident Damaged Parts

No	Job Description	Qty	Price / Unit	Amount
1	REAR TAILGATE	1	\$ 1,967.00	\$ 11 1,967.00 X
2	REAR LOCKING MECHANISM	1	\$ 1,537.00	\$ 11 1,537.00 X
3	REAR LOCKING PIN	1	\$ 106.00	\$ 11 106.00 X
4	REAR END PANEL	1	\$ 2,365.00	\$ R 2,365.00 X
5	REAR END PANEL TRIM	1	\$ 1,263.30	\$ 11 1,263.30 X
6	REAR BUMPER	1	\$ 1,795.44	\$ 20/10/11 1,795.44 /
7	REAR BUMPER DIFFUSER	1	\$ 1,334.10 1/20	\$ 7/11 1,334.10 /
8	REAR BUMPER REFLECTOR	2	\$ 537.50 40	\$ M/Sc 1,075.00 12 C
9	REAR BUMPER RETAINER	2	\$ 256.50	\$ 11 513.00 X
10	REAR BUMPER CLIPS	1 set 40	\$ 8.00	\$ 11 80.00 50 S/W
11	REAR END PANEL TRIMMING CLIPS	10	\$ 8.00	\$ 11 80.00 X
12	REAR LICENSE PLATE	1	\$ 50.00	\$ 11 50.00 X
13	REAR LICENSE PLATE BRACKET	1	\$ 50.00	\$ 11 50.00 X
14	REVERSE SENSOR	4	\$ 280.00	\$ 102 \$ 1,120.00 X
15	LABOUR FOR CHECKING WIRING		\$ 250.00	\$ 250.00 20
16	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS, INCLUDING WELDING, KNOCKING, REPAIRING, STRAIGHTENING, RESHAPE & ADJUSTMENT OF REAR TAILGATE, BUMPER, BEAM, END PANEL		\$ 2,100.00	\$ 2,100.00 300
17	SPRAYPAINTING & PUTTY OF TAIL GATE, END PANELS, REAR BUMPER, BUMPER GARNISH		\$ 1,900.00	\$ 1,900.00 400
18	APPLYING OF RUST-PROOFING		\$ 250.00	\$ 11 250.00 X
19	LABOUR FOR RETROFITTING WEATHER STRIP & MOULDING		\$ 250.00	\$ 11 250.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-3395-44
102
3055.90
50
720
3825.90
202
306.

Sub-Total \$ 18,085.84