

(08/11/13) wef

ASS. REC. BY:

REF:

CS/CT124080264/Ruh3

SOTC

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMV 6959A

at Workshop m/s KUMOKAP

of TANJONG PRAJURN

Insured: GBH 6822P CT1

Policy No.

Claims No. SNM24D204612

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

103K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMV 6959A

Yr Regn: 2020 / OCT

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MAZDA 6 SEDAN 2.0 AT ST c.c. 1998

Colour:

BLUE

A/C: Insured / Std / NI / NA

Sp. Reading:

31719

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6GL1073L0404817

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R17

R:

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

14/08/24

D.O.I.

21/08/24

Survey held at

TANJONG P

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIM 5 - 61K

2/10/24 Rasul confirmed final fig \$8885.92 (red 10,795.94, 54%)

Date/Time, File Pass to?



: Preli. Report



: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

) S + RS \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



QUOTATION

CODE: C0006
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

PAGE NO.: 1
DOCUMENT NO.: 2604
DOCUMENT DATE: 14/08/2024
POS ID: 12
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 15048
REF. NO.: DS/SMV6959A/2048
DATE IN:
EXT. WTY: 14/10/2025
MILEAGE: 0

CONTACT NO.: 6389 6111
MODEL: MAZDA6 IPM4 2L SDN STD BLACK L
CHASSIS NO.: JM6GL1073L0404817
ENGINE NO.: PE21346573
REG NO.: SMV6959A
REGN DATE: 15/10/2020

DESCRIPTION: Body repair

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
NOTES	SMV6959A -DOA:14/8/2024 -DS -China Taiping				0.00	O
SUB	TO REMOVE & REPLACE REAR BUMPER & BOOTLID.			1592	3,168.00	S
	TO REPAIR END PANEL.					
	AND ALL ACCIDENT AFFECTED AREA.					
SUB	TO RESPRAY REAR BUMPER, BOOTLID & REAR			1504	3,024.00	S
	REINFORCEMENT.					
SUB	TO SUPPLY REAR NUMBER PLATE.			X	70.00	S
SUB	TO TRANSFER REVERSE SENSORS.				330.00	S
SUB	TO CARRY OUT BODY CAVITY			150	250.00	S
	PRESERVATION.					
SUB	TO CHECK ELECTRICAL SYSTEM			180	250.00	S
	FOR PROPER FUNCTIONING.					
SUB	TO REPROGRAMME AFTER THE			250	300.00	S
	ACCIDENT REPAIR WORKS.					
SUB	SUNDRIES.			20	50.00	S
GSK1-50-221AB	REAR BUMPER W/PK SENSOR GL	1.00	1,260.75	STOCK		
BHN1-50-0Z1A	GROMMET, SCREW	4.00	2.36	STOCK	1,260.75	S
GSH7-50-2G1	RUBBER, SEAL GL	2.00	13.91	STOCK	9.44	S
C274-50-133	NUT, CLIP	4.00	2.36	STOCK	27.82	S
TK21-50-355	RIVET	2.00	7.42	STOCK	9.44	S
					14.84	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres :
5 Ubi Close Singapore 408605
Sales Tel: 6395 8888 Service Tel: 6395 8899

23 Leng Kee Road Singapore 159095
Sales Tel: 6603 6118 Service Tel: 6603 6128
Fax: 6476 7417

Eurokars Aftersales Centre:
27A Tanjong Penjuru Singapore 609042
Service Tel: 6331 0606
Service Fax: 6331 0620



QUOTATION

CODE: C0006
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

CONTACT NO.: 6389 6111
MODEL: MAZDA6 IPM4 2L SDN STD BLACK L
CHASSIS NO.: JM6GL1073L0404817
ENGINE NO.: PE21346573
REG NO.: SMV6959A
REGN DATE: 15/10/2020

PAGE NO.: 2
DOCUMENT NO.: 2604
DOCUMENT DATE: 14/08/2024
POS ID: 12
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 15048
REF. NO.: DS/SMV6959A/2048
DATE IN:
EXT. WTY: 14/10/2025
MILEAGE: 0

DESCRIPTION: Body repair

Item	Description	Qty.	Unit Price	Stk/Status	Gross GST amount Code
			SGD		SGD
EA01-50-037	RIVET <i>new</i>	6.00	7.34	STOCK	44.04 S
GSH7-50-EL1	BB COVER(L), TOWING HOOK GL3 <i>sun</i>	1.00	56.22	STOCK	56.22 S
GSH7-50-EK1	BB COVER(R), TOWING HOOK GL3 <i>mi</i>	1.00	56.22	STOCK	56.22 S
B45A-56-146A	FASTENER <i>new</i>	6.00	2.36	STOCK	14.16 S
GSH7-50-C51	COVER, UNDER-RR GL3 ?	1.00	147.34	STOCK	147.34 S
GRF5-51-5M0A	REFLECTOR LHR REFLEX-GL3 X	1.00	49.65	STOCK	49.65 S
GRF5-51-5L0A	REFLECTOR RHR REFLEX-GL3/KF X	1.00	49.65	STOCK	49.65 S
11-BCKA-50-0Z	GROMMET, SCREW <i>new</i>	4.00	2.36	STOCK	9.44 S
GJR9-50-2J1	RETAINER LHR BUMPE GJ ?	1.00	41.73	STOCK	41.73 S
GJR9-50-2H1	RETAINER RHR BUMPER GJ ?	1.00	41.73	STOCK	41.73 S
GSH7-50-350	SHIELD(L), SPLASH GL3 X	1.00	63.05	STOCK	63.05 S
H260-50-841	GROMMET, SCREW X	2.00	2.45	STOCK	4.90 S
GSH7-50-340	SHIELD(R), SPLASH GL3 X	1.00	63.05	STOCK	63.05 S
GRT6-56-375	NUT CLIP X	2.00	1.86	STOCK	3.72 S
DFR5-50-251	BRACKET, BUMPER SKYACTIV ?	1.00	4.64	STOCK	4.64 S
GHK1-50-260	REINF REAR BUMPER GJ/GL ?	1.00	523.08	STOCK	523.08 S
KD47-67-UC5A1	RETAINER S/ACTIV <i>new</i>	2.00	15.77	STOCK	31.54 S
KD45-67-UC5A1	RETAINER RR SENSOR GL <i>new</i>	2.00	15.77	STOCK	31.54 S
KD47-67-UC1	1.SENSOR, ULTRASONIC GJ/KG <i>short</i>	2.00	184.59	STOCK	369.18 S
GMK6-67-UC1	1.SENSOR, ULTRASONIC KE/BN/KG X	2.00	184.59	STOCK	369.18 S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 6346 1700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417

Eurokars Aftersales Centre:

27A Tanjong Penjuru Singapore 609042

Service Tel: 6331 0606

Service Fax: 6331 0620



QUOTATION

CODE: C0006
CUSTOMER: CHINA TAIPIING (SINGAPORE) PTE LT
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

PAGE NO.: 3
DOCUMENT NO.: 2604
DOCUMENT DATE: 14/08/2024
POS ID: 12
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 15048
REF. NO.: DS/SMV6959A/2048
DATE IN:
EXT. WTY: 14/10/2025
MILEAGE: 0

CONTACT NO.: 6389 6111
MODEL: MAZDA6 IPM4 2L SDN STD BLACK L
CHASSIS NO.: JM6GL1073L0404817
ENGINE NO.: PE21346573
REG NO.: SMV6959A
REGN DATE: 15/10/2020

DESCRIPTION: Body repair

Item	Description	Qty.	Unit Price	SGD	Stk/Status	Gross amount	GST Code
BCKA-50-EM1	TAPE,PROTECTOR <i>ne</i>	4.00	7.42	STOCK		29.68	S
GDDL-67-290	CORD SHORT RR. BUMPER GL <i>ne</i>	1.00	215.94	STOCK		215.94	S
GRF5-51-153	GASKET(R),RR.COMB. GL3 <i>ne</i>	1.00	52.77	STOCK		52.77	S
GRF5-51-163	GASKET(L),RR.COMB. GL3 <i>ne</i>	1.00	52.77	STOCK		52.77	S
GSJ4-51-150B	TAIL LAMP RH COMP GL IPM <i>X</i>	1.00	1,919.02	STOCK		1,919.02	S
GSJ4-51-160B	TAIL LAMP LH COMP GL IPM <i>X</i>	1.00	1,919.02	STOCK		1,919.02	S
GJ6A-51-14Y	FASTENER,LAMP <i>ne X</i>	2.00	14.84	STOCK		29.68	S
GHP9-51-146	FASTENER <i>ne</i>	2.00	2.36	STOCK		4.72	S
KD53-51-146B	FASTENER <i>ne</i>	2.00	3.71	STOCK		7.42	S
GRF5-51-3HX	BRACKET'A'(R),TRUNK LID GL3 <i>?</i>	1.00	33.72	STOCK		33.72	S
GRF5-51-3JX	BRACKET'A'(L),TRUNK LID GL3 <i>?</i>	1.00	33.72	STOCK		33.72	S
GRF5-51-3F0B	LAMP RH TRK LID GL/TC <i>X</i>	1.00	881.97	STOCK		881.97	S
GRF5-51-3G0B	LAMP LH TRK LID GL/TC <i>X</i>	1.00	881.97	STOCK		881.97	S
GRF5-51-3H8	GASKET(R), LAMP-TRUNK LID GL3 <i>ne</i>	1.00	82.18	STOCK		82.18	S
GRF5-51-3J8	GASKET(L), LAMP-TRUNK LID GL3 <i>ne</i>	1.00	82.18	STOCK		82.18	S
EG21-51-146	FASTENER <i>ne</i>	2.00	5.57	STOCK		11.14	S
GBY2-52-61X	TRUNK LID GL3 <i>U</i>	1.00	1,093.78	STOCK		1,093.78	S
D24H-62-866	COVER,HOLE RR LID S/ACTIV <i>ne</i>	3.00	2.36	STOCK		7.08	S
GBFN-56-951	WEATHERSTRIP,LID GL3 <i>?</i>	1.00	138.32	STOCK		138.32	S
GBEF-50-85ZA	MOULD,TRUNK LID GL3 <i>X?</i>	1.00	412.92			412.92	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417

Eurokars Aftersales Centre:

27A Tanjong Penjuru Singapore 609042

Service Tel: 6331 0606

Service Fax: 6331 0620



QUOTATION

CODE: C0006
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

PAGE NO.: 4
DOCUMENT NO.: 2604
DOCUMENT DATE: 14/08/2024
POS ID: 12
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 15048
REF. NO.: DS/SMV6959A/2048
DATE IN:
EXT. WTY: 14/10/2025
MILEAGE: 0

CONTACT NO.: 6389 6111
MODEL: MAZDA6 IP4 2L SDN STD BLACK L
CHASSIS NO.: JM6GL1073L0404817
ENGINE NO.: PE21346573
REG NO.: SMV6959A
REGN DATE: 15/10/2020

DESCRIPTION: Body repair

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
GDDC-51-721A	ORNAMENT RR "MAZDA 6" GL <i>re</i>	1.00	62.29	STOCK	62.29	S
GBEF-51-730A	MASCOT, REAR GL3 <i>re</i>	1.00	50.15	STOCK	50.15	S
GDDL-51-771	ORNAMENT "SKYACTIV G" GL <i>re</i>	1.00	52.60	*NO STOCK	52.60	S
GHY1-70-75Z	PANEL, REAR END GJ	1.00	716.94	STOCK	716.94	S
GRF5-51-26YA	LAMP, LICENSE GL <i>X</i>	1.00	171.53		171.53	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	GST Code	Rate	Service/Goods	GST	Before GST	GST	Total
Parts	12,239.86	O	-	-			
Surcharge	0.00	S	9.00%	19,681.86	1,771.37		
Labour	7,442.00						
Menus	0.00						
Gross					19,681.86	1,771.37	21,453.23
Less: Deposit**					0.00	0.00	0.00
Amount Due					19,681.86	1,771.37	21,453.23

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
No.

Date:

Customer signature

Authorised signature



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :
5 Ubi Close Singapore 408605
Sales Tel: 6395 8888 Service Tel: 6395 8899
Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095
Sales Tel: 6603 6118 Service Tel: 6603 6128
Sales Fax: 6476 7073 Service Fax: 6476 7417

Eurokars Aftersales Centre:
27A Tanjong Penjuru Singapore 609042
Service Tel: 6331 0606
Service Fax: 6331 0620

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	507C
Vehicle Details	
Vehicle No.:	SMV6959A
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Aug 2024
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 SEDAN 2.0 AT STANDARD I4
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	PE21346573
Chassis No.:	JM6GL1073L0404817
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$21,035.00
Original Registration Date:	15 Oct 2020
First Registration Date:	15 Oct 2020
Transfer Count:	0
Actual ARF Paid:	\$21,449.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Oct 2030
PARF Rebate Amount:	\$16,086.00
Intended COE Rebate Details	
COE Expiry Date:	14 Oct 2030
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$40,690.00
COE Rebate Amount:	\$24,996.00
Total Rebate Amount:	\$41,082.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 22 Aug 2024

OK



Mazda 6 2.0A

\$102,000


Instalment \$1,139/mth

DIRECT OWNER

💰 Apply for 2.48% loan

♡ Shortlist

✔ Get Warranty



Overview

Financial

Photo

Research

Depreciation

📘 \$14,910 / year

Reg. Date

30-Sep-2020

(6yrs 1mth 7days COE left)

Manufactured

📘 2019

Mileage

33,000 km (8.5k / year)

Transmission

Auto

Engine Cap

1,998 cc

Road Tax

📘 \$1,210 / year

Power

121.0 kW (162 bhp)

View specs of the [Mazda 6 Sedan \(2018\)](#)

Curb Weight

📘 1,514 kg

COE

📘 \$41,001

OMV

📘 \$21,309

ARF

📘 \$21,833

Dereg Value

📘 \$41,413 as of today