

PHOTOGRAPHS FOR VEHICLE NO. : SNG 269P



PHOTOGRAPHS FOR VEHICLE NO. : SNG 269P



PHOTOGRAPHS FOR VEHICLE NO. : SNG 269P



PHOTOGRAPHS FOR VEHICLE NO. : SNG 269P



PHOTOGRAPHS FOR VEHICLE NO. : SNG 269P





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 6 of 8)

PHOTOGRAPHS FOR VEHICLE NO. : SNG 269P



PHOTOGRAPHS FOR VEHICLE NO. : SNG 269P





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 8 of 8)

PHOTOGRAPHS FOR VEHICLE NO. : SNG 269P

