

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

## ESTIMATE OF REPAIR

Veh# XD9131K

Model:

MITSUBISHI

Accident Date :15/8/2024

Location : NEAR BEF SINGAPORE AVIATION

3P:

SNG6516L (INCOME)

| S/Nos. | Qty  | Description                            | List \$  | S/Nett \$ | Nett \$ |
|--------|------|----------------------------------------|----------|-----------|---------|
| 1      | 1 pc | Front bumper                           | 3186.60  | dd ✓      | 2250    |
| 2      | 1 pc | Front bumper LH garnish (Lower)        | 610.20   | Xnn       |         |
| 3      | 1 pc | Front RH head lamp                     | 2818.70  | cut ✓     | 1750    |
| 4      | 1 pc | Front LH signal lamp                   | 810.20   | cut ✓     | 550     |
| 5      | 1 pc | Front RH step garnish                  | 821.70   | Xnn       |         |
| 6      | 1 pc | Front RH step garnish reflector        | 120.00   | Xnn       |         |
| 7      | 1 pc | Front RH step aluminium (lower)        | 300.00   | *dd ✓     | 250     |
| 8      | 1 pc | Front RH step aluminium (upper)        | 300.00   | Xnn       |         |
|        |      | Front bumper LH garnish strip 3110 Xnn |          |           |         |
|        |      | Front LH step garnish upper RP         |          |           |         |
|        |      | Sub Total:                             | 8,967.40 | 0.00      | 0.00    |
|        |      |                                        | 25%      | 0%        | 0%      |
|        |      | After Less %:                          | 6,725.55 | 0.00      | 0.00    |
|        |      | <b>Labour</b>                          |          |           |         |
| 1      |      | To remove and replace damage parts     | 1200.00  | 600       |         |
| 2      |      | To spray painting.                     | 800.00   | 600       |         |
| 3      |      | To check wiring.                       | 200.00   | 50.       |         |
|        |      | Sub Total:                             | 2,200.00 |           |         |
|        |      | Total:                                 | 8,925.55 |           |         |
|        |      | After Less 20%:                        | 7,140.44 |           |         |

Chan

Chan San Choon  
Director  
DipEng, AAE MIMI,MSAE(Aust)

Tanfikh 97495749 / 62563561

WP 22/8/24 245pm.

2/3 Remedy after repair

5-4 days

tanfikh@khauto.com

3600

1250

4850

41593850

3 days \*



bizSAFE

8778 1999  
24 hr accident call



PAYNOW

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Complementary item(s) must be resurveyed and subject to final approval from Insurance Company

lodged by Repairer

S a:

Date:

XE9131K ESTIMATEPg1