

TwinCar AUTOMOTIVE PTE LTD

Company Registration and GST No. 200714616M

2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

Tel: 67440510

Fax: 67410510

Email: sales@n51.com.sg

LAI ENG KEAT

30 TANAH MERAH KECHIL RD

#07-09

SINGAPORE 465558

Repair Code: CLM16394

Date in: 16/08/2024

Vehicle No.: SNH8723L

Model: TOYOTA CAMRY HYBRID 4DR SEDAN (AT) ELEGANCE

Chassis/Eng#: JTNB23HK003116383/A25A5720602

SUPPLEMENTARY ITEMS

No	Description Of Parts		Qty	Unit Price	Amount
1	REAR EXHAUST SILENCER BOX	L	1	\$ 1,578.20	\$ 1,578.20
2	REAR EXHAUST GASKET	L	1	\$ 44.40	\$ 44.40
3	REAR EXHAUST RUBBER MOOUNTING	L	1	\$ 66.80	\$ 66.80
4	REAR LH FENDER INNER TRIM GARNISH	L	1	\$ 699.50	\$ 699.50
5	REAR LH BLIND SPOT MODULE	L	1	\$ 2,174.60	\$ 2,174.60
6	REAR LH BLIND SPOT MODULE WIRE HARNESS	L	1	\$ 379.60	\$ 379.60
	Sub total before discount:				\$ 4,943.10
	Percentage discount 25%:				\$ 1,235.78
	Sub-total 1 :				\$ 3,707.33
	Parts Total:				\$ 3,707.33

Adnan
w/s 20/08/24

379.60

284 70