



Your Ref : SNM24D204642/C01/LEEPG

Date: 23rd Aug 2024

Our Ref : CS/CTI24080282/Jnh3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLA 3862L
ACCIDENT ON 16/08/2024**

Instruction was received to inspect the vehicle Reg. No. SLA 3862L. The inspection was conducted on 19/08/2024 at the premises of M/s Ding Auto Pte Ltd, 60 Jalan Lam Huat #06-46/47 Carros Centre, Singapore 737869.

The following vehicle information was recorded:

Registration Number	: SLA 3862L
Make/Model	: Hyundai DM Santa FE 2.2 CRDI AT 4WD SR
Year of Registration	: 2016
Body Colour	: White
Chassis Number	: KMHSU81XSGU584178
Engine Capacity	: 2199 cc
Speedometer Reading	: Not Available

The vehicle sustained damages at the front, rear portion, n/s, o/s body, undercarriage and rooftop. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 41,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 28,662.00)
Nett Liability	<u>S\$ 12,338.00</u> =====

Vehicle Inspected By:



ELTON SEET BOON KIAT
Asst. Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.