

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH6271C

DATE 16.08.2024

MAKE REG. 02.07.2019

MODEL IONIQ G2

CHIANG/ECICS

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER / <i>ISR</i>			\$481.10
1	FRONT BUMPER GRILLE LH X <i>nn</i>			\$186.90
1	FRONT BUMPER BRACKET LH <i>x nn</i>			\$35.00
1	FRONT FENDER LH / <i>nn</i>			\$588.80
1	FRONT FENDER EMBLEM / <i>nn</i>			\$26.60
1	FRONT FENDER SHIELD LH X <i>nn</i>			\$164.70
1	HEADLAMP LH X <i>nn</i>			\$2,110.30
	SUB TOTAL		1096.50	\$3,593.40
	20.00%		-20%	\$718.68
	DISCOUNTED TOTAL		877.20	\$2,874.72
	Labour Charge			
	Panel Beating			\$760.00
	Spray Paint			\$700.00
	Check lighting			\$60.00
	TOTAL LABOUR			\$1,520.00
	ESTIMATE TOTAL		1160	\$4,394.72
			2037.20	
			L/S - 1629.76	
			= 1600	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Steve (LKK)

19/8/24, 3.09pm

L/S

L/S

L/S

3 d/s

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____