



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24060112/Anh3e2
75 BRAS BASAH ROAD	Date:	21/10/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGP 8803E	Veh. Inspected	SMF 6102P
Policy No.	-	Coverage	0
Claim No.	MT/1281843-002	Excess	\$0.00
Assign From	JULIE MANGUBAT	Assign Date	14/06/2024

2. Vehicle Details

Make & Model	HONDA CIVIC	C.C	1595
Engine No.	R16A14001505	Year of Reg.	10/07/2009
Chassis No.	JHMFD46209S200457	Colour	RED
Odometer	212144 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/45 R17	TOURADOR	6
L/H Front Tyre	225/45 R17	TOURADOR	6
R/H Rear Tyre	225/45 R17	TOURADOR	6
L/H Rear Tyre	225/45 R17	TOURADOR	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/06/2024	Inspection Date	19/06/2024 (14:23)
Survey held at	ONE GARAGE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-33 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days