

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT/2408028/14963**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SNK 851-7Jat Workshop m/s KY

of \_\_\_\_\_

Insured: SLG 5935R

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: 11756

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: 547M

Vehicle: IN / OUT

17A 8112950Veh No: SNK 851-7J Yr Regn: 19/25/23Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA / HybridMake: Suzuki / Landy C.C. 1797Colour: Black A/C: Insured / Std / NI / NASp. Reading: 100807 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 2WR909000561Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55-R17

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 16/08/24 D.O.I. 20/08/24

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear 2/5

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6/9/24 P/P 2708.88 Dep 186. Inform Raymond (Red 91237.52 31%)

Date/Time, File Pass to?

☐

: Preli. Report

1/06/24 MAR☐

: Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 4Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: EC claim SPLump Sum / I.B.I.: (\$ 2708.88 )

**KY AUTO PTE. LTD**  
**25 KAKI BUKIT ROAD 4**  
**#05-23 SYNERGY@KB**

**Insurer Reference: SNM24D204635/SLG5935R/  
C02/TANCHC**  
**Repairer Reference: 072262**  
**Date calculated: 23/08/2024 4:03 PM**

**Full Report**

**Registration: SNK8557J**  
**Printed: 23/08/2024 4:03 PM**

### Summary Information

#### Claim

Location: Singapore (SG)  
Printed by: KY AUTO  
Claim Reference: SNM24D204635/  
SLG5935R/C02/TANCHC  
Estimated Repair Time:  
Actual Repair Days:

Work Provider: China Taiping Insurance  
(Singapore) Pte Ltd  
Currency: SGD  
Date of Incident: 16/08/24  
Hire Car Start:  
Hire Car End:

### Vehicle Details

#### Vehicle

Manufacturer: TOYOTA  
Model: NOAH  
Sub Model: X  
Model Sheet Number: 70 NB 03  
Registration: SNK8557J  
VIN number:  
Odometer:

#### Model Specs

TWO COAT METALLIC PREPARE OFF VEHICLE

*not Authorised*  
*merant*  
*20/8/24*  
*P/P to 2708.88*  
*4 days*  
*Teleph. Before repair.*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## Vehicle Condition


### Vehicle Status

Pre-Accident Damage:

Date of Inspection:

### Damage Areas

All ☐  
Underbody ☐



## Tyres Condition

Tyre Brand	Tread (Left Middle), Tread (Left Outer), Tread (Left Inner), Tread (Right Inner), Tread (Right Outer), Tread (Right Middle), mm						Condition
	mm	mm	mm	mm	mm	mm	
Spare Tyre Brand	Tread (Spare), mm						

## Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
NO NUMBER	R + R R/R UPPER BUMPER COVER		3.0	13.50
NO NUMBER	R + R CTR TAILGATE COVER		2.0	9.00
NO NUMBER	R + R REAR NO-PLATE		1.0	4.50
NO NUMBER	R + R L/R NUMBER PLATE LAMP		2.0	9.00
NO NUMBER	R + R R/R NUMBER PLATE LAMP		2.0	9.00
NO NUMBER	R + R TAILGATE LOCK		3.0	13.50
NO NUMBER	R + R LEFT INNER TAILLAMP		5.0	22.50
NO NUMBER	R + R RIGHT INNER TAILLAMP		5.0	22.50
NO NUMBER	R + R TAILGATE LOCK STRIKER		4.0	18.00
NO NUMBER	RENEW REAR BUMPER		11.0	49.50
	INCLUDES: BUMPER AND ALL			
	REQUIRED ATTACHED PARTS R + R			
NO NUMBER	R + R L/R VENTILATION GRILLE		1.0	4.50
NO NUMBER	R + R RIGHT OUTER TAILLAMP		1.0	4.50
NO NUMBER	R + R TAILGATE SEAL		1.0	4.50
NO NUMBER	R + R L/R MUDFLAP		1.0	4.50
NN	RR BPR SENSOR R&R / NEW PARTS		10.0*	45.00
NN	RR TOW COVER R&R / NEW PARTS		5.0*	22.50

Code	Description		WU	Price SGD
1005	INSTALL WIRING	in	40.0*	180.00 X
1006	LABOUR	Repl	80.0*	360.00 X
2931	BOOTLID/TAILGATE REPAIR		60.0* 30	270.00 135
3482	R/R LOWER SIDE PANEL REPAIR		80.0* 40	360.00 180
3931	REAR CROSSMEMBER REPAIR		100.0* 60	450.00 270
4160	R/R WHEELHOUSE COVER REPAIR		5.0*	22.50 ✓
1007	LABOUR		20.0* 10	90.00 45
2624	R/R BUMPER BRACKET CHECK			

<b>Labour Cost</b>	<b>Hrs</b>	<b>WU</b>	
<b>Panel / Mechanical Labour</b>	44.20	442.0	1,989.00
<b>Total of Labour</b>			1,989.00

## Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	REAR BUMPER NEW PART PAINT K1R	9.0
	BOOTLID/TAILGATE REPAIR PAINTING <50%	22.0
	R/R LOWER SIDE PANEL REPAIR PAINTING <50%	16.0
	REAR CROSSMEMBER SURFACE PAINT	4.0
	R/R WHEELHOUSE COVER SURFACE PAINT	4.0

## Paint Material Per Part

Code	Description	Price SGD
2581	REAR BUMPER NEW PART PAINT K1R	38.38
2931	BOOTLID/TAILGATE REPAIR PAINTING <50%	43.93
3482	R/R LOWER SIDE PANEL REPAIR PAINTING <50%	26.49
3931	REAR CROSSMEMBER SURFACE PAINT	2.74
4160	R/R WHEELHOUSE COVER SURFACE PAINT	3.74

<b>Labour Cost - Paint</b>	<b>Hrs</b>	<b>WU</b>	<b>Price SGD</b>
Factor	45.00 SGD/h		
Time Paint		55.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.50	5.0	22.50
<b>Total</b>	10 WU/h	8.50	382.50

<b>Material Cost - Paint</b>	<b>Price SGD</b>
New Part Painting - Plastic K1R	38.38
Repair Painting	70.42
Surface-/Blend Paint	6.48
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
<b>Total</b>	152.88

## Spare Parts

prices as at 2015-06-01/01



Code	Description	Part Number	Part Source	Price SGD
3404	R/R BUMPER REFLECTOR	81910 47010	OEM	CRG / 70.00 ✓
2608	R/R UPP BUMPER COVER	52165 28010A0	OEM	Turn / 200.00 ✓
2581	REAR BUMPER	52159 28955	OEM	Turn / 540.00 ✓
1002	RR BPR SENSOR	RR BPR SENSOR	OEM	CRG / 300.00 ✓
1000	RR BUMPER CLIP	CLIP	Original	nm / 80.00 3i
1004	RR TOW COVER	RR TOW COVER	OEM	mis / 30.00 ✓
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 1,220.00
u: Used parts				Addition(+10.00%) 122.00
Total				1,342.00

### Extras

Code	Description	Price SGD
1003	SEALANT SEALANT	nm 80.00* X
Total Extras		80.00

### Final Calculation

	SGD	SGD
<b>Parts</b>		
Addition(+10.00%)	1,220.00	
<b>Total Parts</b>	122.00	1,342.00
<b>Labour Time Base 10 WU/h</b>		
Total 442.0 WU X 45.00 SGD/h	1,989.00	
<b>Total of Labour</b>		1,989.00
<b>Total Of Extras</b>		80.00
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 85.0 WU X 45.00 SGD/h	382.50	
Material Cost	152.88	
<b>Total Paint Including Material</b>		535.38
<b>Repair Cost Excludes GST</b>		3,946.38
GST (+9.00%)		355.17
<b>Repair Cost Included GST</b>		4,301.55

### Comments

\* - USER SUPPLIED DATA  
 NN - NO MANUFACTURERS CODE EXISTS  
 ) - WU PARTIAL INCL IN OTHER POSITIONS

P-1170  
 102  
 1287

### Assessment Note

No assessment notes entered.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	547M
<b>Vehicle Details</b>	
Vehicle No.:	SNK8557J
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Aug 2024
Vehicle Make:	SUZUKI
Vehicle Model:	LANDY HYBRID 1.8G CVT
Primary Colour:	Black
Manufacturing Year:	2023
Engine No.:	2ZR2T85737
Chassis No.:	ZWR909000561
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$29,883.00
Original Registration Date:	19 May 2023
First Registration Date:	19 May 2023
Transfer Count:	1
Actual ARF Paid:	\$18,837.00 9418
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 May 2033
PARF Rebate Amount:	\$14,127.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	18 May 2033
COE Category:	B - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$113,034.00
COE Rebate Amount:	\$98,823.00
<b>Total Rebate Amount:</b>	<b>\$112,950.00</b>
<b>Message</b>	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 20 Aug 2024

OK

Post an Advertisement

Sell it yourself! Advertise it at just

\$72 until it's SOLD!

2014 CLA250 at \$133K Only



2 Owners Only. Cheapest in the Market

S Werkz MotorStarAd

Free VICOM evaluation

Free grooming and 6 months maintenance

In-house workshop ensures quality service

Member of SVTA and hire purchase association

100% deposit refund for unapproved loan



YONG LEE SENG MOTOR PTE LTD

Post an AdAdvertiser LoginWays of Selling

Sort byDate Posted20results/page

4 vehicles

SUZUKI LANDY

Any Category

Advanced Search

Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	SUZUKI LANDY	Any	Any	2023	Any	Any	Any	Available



Suzuki Landy Hybrid 1.8A G\$219,800\$23,840 /yr09-Jun-20231,797 cc24,000 kmMPVAvailable

Fuel Type: Petrol-Electric

7-seater MPV and a fuel-efficient, spacious interior and generous size option that can accommodate to your family needs. Easy accessible hands-free dual power sliding doors. New safety feature "proactive driving assist"(PDA), which...

Privilege Motors Pte Ltd

Posted: 06-Aug-2024



Suzuki Landy Hybrid 1.8A G\$187,800\$19,120 /yr29-Dec-20231,797 cc57 kmMPVAvailable

Fuel Type: Petrol-Electric

Suzuki Landy 7-seater. PHV welcome. High loan applicable and in house loan applicable! Contact our sale steam now.

Think One Automobile & Trading

Posted: 29-Jul-2024

PREMIUM AD



Suzuki Landy Hybrid 1.8A G\$187,800\$19,430 /yr14-Nov-20231,797 cc-MPVAvailable

Fuel Type: Petrol-Electric

Newly registered black Suzuki Landy Hybrid. Immediate handover. Comes with warranty and free servicing. 100% loan welcomed.

Think One Automobile & Trading

Posted: 28-Jul-2024

PREMIUM AD



Suzuki Landy Hybrid 1.8A G\$218,800\$23,580 /yr11-Jul-20231,797 cc113,000 kmMPVAvailable

Fuel Type: Petrol-Electric

Super well maintained 7-seater MPV. Very fuel-efficient, this unit has a very spacious interior with plenty of boot space. comes with hands-free dual power sliding doors. New safety feature "proactive driving assist"(PDA), useful for any driv...

Posted: 02-Jul-2024

PREMIUM AD

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20results/page

Buy / Rent Cars

New Cars For Sale

Used Cars For Sale

Cars For Rent

Sell Your Car

Post an Ad

Compare