



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24080297/Unh3
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	10/09/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	CB 7247M	Veh. Inspected	SLS 1521P
Policy No.	-	Coverage	0
Claim No.	BVS24/0574	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	19/08/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ S350D (A)	C.C	2987
Engine No.	64286141746689	Year of Reg.	17/09/2015
Chassis No.	WDD2221322A217549	Colour	SILVER
Odometer	163141 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/50R18	PIRELLI	6
L/H Front Tyre	245/50R18	PIRELLI	6
R/H Rear Tyre	245/50R18	PIRELLI	6
L/H Rear Tyre	245/50R18	PIRELLI	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/08/2024	Inspection Date	20/08/2024
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days