

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LAM LEE KONG
62 FLORA RD #01-04
SINGAPORE 509746

Contact : 96224942 94301415

TP INC
Veron.

TAX INVOICE

Repair Code : CLM16397

Date in : 17/08/2024

Vehicle Num. : SNK6484Z

Model : SUBARU FORESTER 2.0I-S EYESIGHT HYBRID AWD CVT

Chassis/Eng# : JF1SKEKL5NG078137/FB20YS14740

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dishled</i>	1	917.40	✓ 917.40
REAR BUMPER LOWER DIFFUSER <i>crackd</i>	1	333.40	✓ 333.40
REAR BUMPER OUTER TOP GARNISH <i>crackd</i>	1	360.40	✓ 360.40
REAR BUMPER PARKING SENSOR <i>2 pieces damaged</i>	4	294.20	588.40 1,176.80
REAR BUMPER PARKING SENSOR 'O' RING <i>2 pieces New</i>	4	25.00	50.00 100.00
REAR BUMPER PARKING SENSOR HOLDER <i>new</i>	4	65.60	120 262.40
REAR BUMPER REFLECTOR L/R <i>2/1 crackd</i>	2	249.20	498.40 249.20
REAR BUMPER REINFORCEMENT <i>Dented</i>	1	330.70	✓ 330.70
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	25.50	+ 51.00
REAR BUMPER TOW HOOK COVER <i>Dented</i>	1	21.60	✓ 21.60
REAR END PANEL <i>Dented</i>	1	401.10	✓ 401.10
REAR END PANEL ANTENNA SENSOR <i>new</i>	1	129.40	+ 129.40
REAR END PANEL INNER TOP GARNISH <i>Dented</i>	1	91.60	✓ 91.60
REAR EXHAUST GASKET <i>2</i>	1	39.00	+ 39.00
REAR EXHAUST RUBBER MOUNTING <i>3 new</i>	2	19.90	+ 39.80
REAR EXHAUST SILENCER BOX	1	622.90	+ 622.90
REAR FENDER INNER TRIM BOARD L/R <i>2/1 crackd</i>	2	237.70	475.40 237.70
REAR FLOOR PANEL <i>Pier</i>	1	427.20	+ 427.20

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LAM LEE KONG
62 FLORA RD #01-04
SINGAPORE 509746

Contact : 96224942 94301415

TAX INVOICE

Repair Code : CLM16397

Date in : 17/08/2024

Vehicle Num. : SNK6484Z

Model : SUBARU FORESTER 2.0I-S EYESIGHT HYBRID AWD CVT

Chassis/Eng# : JF1SKEKL5NG078137/FB20YS14740

REAR FLOOR PANEL INNER TOP BOARD COVER	<i>Replaced</i>	1	399.40	<i>✓</i>	399.40
REAR FLOOR PANEL INNER TOP BOARD COVER SIDE L/R	<i>Replaced</i>	2	48.90	<i>✓</i>	97.80
REAR TAILGATE	<i>Replaced</i>	1	1238.00	<i>✓</i>	1,238.00
REAR TAILGATE 'AWD' EMBLEM	<i>New</i>	1	77.60	<i>✓</i>	77.60
REAR TAILGATE 'E-BOXES' EMBLEM		1	70.50	<i>✓</i>	70.50
REAR TAILGATE 'EYESIGHT' EMBLEM		1	53.20	<i>✓</i>	53.20
REAR TAILGATE 'FORESTER' EMBLEM		1	77.80	<i>✓</i>	77.80
REAR TAILGATE 'SUBARU' EMBLEM		1	79.50	<i>✓</i>	79.50
REAR TAILGATE AUTO DAMPER ASSY	<i>Replaced</i>	1	330.60	<i>✓</i>	330.60
REAR TAILGATE HINGES L/R	<i>Replaced</i>	2	89.40	<i>✓</i>	178.80
REAR TAILGATE INNER TRIM BOARD	<i>Replaced</i>	1	280.80	<i>✓</i>	280.80
REAR TAILGATE LOCK STICKER	<i>Replaced</i>	1	29.40	<i>✓</i>	29.40
REAR TAILGATE MECHANISM LOCK	<i>Jammed</i>	1	466.80	<i>350 ✓</i>	466.80
REAR TAILGATE OUTER GARNISH	<i>Replaced</i>	1	466.80	<i>✓</i>	466.80
REAR TAILGATE OUTER GARNISH 'LOGO' EMBLEM	<i>Replaced</i>	1	77.80	<i>✓</i>	77.80
REAR TAILGATE OUTER GARNISH CAMERA	<i>Replaced</i>	1	499.80	<i>✓</i>	499.80
REAR TAILGATE OUTER GARNISH NUMBER PLATE LAMP L/R	<i>Replaced</i>	2	42.80	<i>✓</i>	85.60
REAR TAILGATE OUTER GARNISH OPENER SWITCH	<i>Replaced</i>	1	68.90	<i>✓</i>	68.90

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LAM LEE KONG
62 FLORA RD #01-04
SINGAPORE 509746

Contact : 96224942 94301415

TAX INVOICE

Repair Code : CLM16397

Date in : 17/08/2024

Vehicle Num. : SNK6484Z

Model : SUBARU FORESTER 2.0I-S EYESIGHT HYBRID AWD CVT

Chassis/Eng# : JF1SKEKL5NG078137/FB20YS14740

REAR TAILGATE REFLECTOR L/R	LH and, RH and	2	464.10	✓	928.20
REAR TAILGATE TOP SPOILER	new	1	849.20	+	849.20
REAR TAILGATE TOP SPOILER OUTER GARNISH	new	1	214.50	+	214.50
REAR TAILGATE WEATHER STRIP	ext	1	124.30	✓	124.30
REAR TAILGATE WINDSCREEN MOULDING	new	1	149.20	✓	149.20
REAR TAILGATE WINDSCREEN OUTER SIDE GARNISH L/R	new	2	233.40	+	466.80
REAR TAILGATE WIPER ARM	3 new	1	46.60	+	46.60
REAR TAILGATE WIPER MOTOR		1	249.20	+	249.20
REAR TAILLAMP L/R	RH and	2	507.00	507	1,014.00

Subtotal before discount

14,899.60

Percentage discount 10%

1,489.96

Sub-total 1

13,409.64

REAR BUMPER CLIPS - SET	new	1	50.00	30	50.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	new	1	30.00	20	30.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	new	2	50.00	30	100.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	new	1	50.00	30	50.00
REAR TAILGATE NUMBER PLATE	best	1	25.00	✓	25.00
REAR TAILGATE NUMBER PLATE FRAME	deland	1	50.00	30	50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-177 #01-18 /Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LAM LEE KONG
62 FLORA RD #01-04
SINGAPORE 509746

Contact : 96224942 94301415

TAX INVOICE

Repair Code : CLM16397
Date in : 17/08/2024
Vehicle Num. : SNK6484Z
Model : SUBARU FORESTER 2.0I-S EYESIGHT HYBRID AWD CVT
Chassis/Eng# : JF1SKEKL5NG078137/FB20YS14740

REAR TAILGATE WINDSCREEN SEALANT	1	80.00	60	80.00
REAR TAILGATE WIPER BLADE	1	38.00	+	38.00
REAR TAILLAMP CLIPS L/R - SET	2	30.00	+	60.00
Subtotal before discount				483.00
Percentage discount 0%				0.00
Sub-total 2				483.00
Parts-total				13,892.64

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	80.00
To remove, reinstall tailgate windscreen	120 150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60 80.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	800 1,800.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	1980 + 100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	800 1,800.00
To apply anti-rust chemical on repaired and replaced panel.	60 120.00
To remove, reinstall tailgate mechanism and check for function	60 80.00
Labour Total	4,210.00
Parts & Labour Total	18,102.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

*** This is a computer-generated document which requires no signature.***

page 4

7.3K

Adm
F/S 20/08/24
obhys

Supplementary : 130.64
Total : 9113.56
C/S : 7.3K

TwinCar AUTOMOTIVE PTE LTD

Company Registration and GST No. 200714616M

2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

Tel: 67440510

Fax: 67410510

Email: sales@n51.com.sg

LAM LEE KONG

62 FLORA RD

#01-04

SINGAPORE 509746

Repair Code: CLM16397

Date in: 17/08/2024

Vehicle No.: SNK6484Z

Model: SUBARU FORESTER 2.0I-S EYESIGHT HYBRID AWD CVT

Chassis/Eng#: JF1SKEKL5NG078137/FB20YS14740

SUPPLEMENTARY ITEMS

No	Description Of Parts		Qty	Unit Price	Amount
1	REAR FLOOR SPONGE TRAY <i>culc</i>	L	1	\$ 116.70	\$ 116.70
2	REAR FLOOR RH TOOLS SPONGE TRAY <i>culc</i>	L	1	\$ 46.60	\$ 46.60
3	REAR HYBRID BLOWER MOTORS <i>Net 4</i>	L	1	\$ 643.30	\$ 643.30
	Sub total before discount:				\$ 806.60
	Percentage discount 10%:				\$ 80.66
	Sub-total 1:				\$ 725.94
	Parts Total:				\$ 725.94

Adnan G
H/S 20/08/24

163.30

130.64