

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		A 600 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
		Affiliated to Federation Internationa	ie Des Experts En		
MS	AUTO & GENERAL	, ,	Ref:	CS/AGI24080307/Uvp3	
	(BUDGET DIRECT I 190 CLEMENCEAU		Date:	06/09/2024	
	SINGAPORE SHOP	PING CENTRE SINGAPORE 239924	Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLJ 6004E	Veh. Inspected	SNH 7040E	
	Policy No.	P108385537R01	Coverage	0	
	Claim No.	C10031196/KC	Excess	\$0.00	
	Assign From	KIAN CHUAN	Assign Date	19/08/2024	
2. Vehicle Details					
	Make & Model	NISSAN KICKS PREMIUM 1.2L E- POWER (A)	c.c	1198	
	Engine No.	HR12445870C	Year of Reg.	21/11/2022	
	Chassis No.	MNTFEAP15Z0005493	Colour	ORANGE	
	Odometer	124340 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
				_	
	R/H Front Tyre	215/55R17	BRIDGESTONE	6	
	R/H Front Tyre L/H Front Tyre	215/55R17 215/55R17	BRIDGESTONE BRIDGESTONE	6	
	_		+		
	L/H Front Tyre	215/55R17	BRIDGESTONE	6	
4.	L/H Front Tyre R/H Rear Tyre	215/55R17 215/55R17	BRIDGESTONE BRIDGESTONE BRIDGESTONE	6 6	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	215/55R17 215/55R17 215/55R17	BRIDGESTONE BRIDGESTONE BRIDGESTONE of Damages	6 6 6	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	215/55R17 215/55R17 215/55R17 Description ©	BRIDGESTONE BRIDGESTONE BRIDGESTONE of Damages	6 6 6	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN LISION.	215/55R17 215/55R17 215/55R17 Description ©	BRIDGESTONE BRIDGESTONE BRIDGESTONE of Damages RTION. THE UNDER	6 6 6	
THE COL	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN LISION.	215/55R17 215/55R17 215/55R17 Description of ED DAMAGES AT THE REAR O/S POR	BRIDGESTONE BRIDGESTONE BRIDGESTONE of Damages RTION. THE UNDER	6 6 6	
THE COL	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN LISION. MAGES SEE DETAILS	215/55R17 215/55R17 215/55R17 Description of ED DAMAGES AT THE REAR O/S POR	BRIDGESTONE BRIDGESTONE BRIDGESTONE of Damages RTION. THE UNDEF	6 6 6 RCARRIAGE AFFECTED DUE TO	
THE COL	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN LISION. AGES SEE DETAILS Accident Date	215/55R17 215/55R17 215/55R17 Description of the properties of th	BRIDGESTONE BRIDGESTONE BRIDGESTONE Of Damages RTION. THE UNDEF	6 6 6 RCARRIAGE AFFECTED DUE TO	
THE COL DAN 5. 5a. A) T	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre EVEHICLE SUSTAIN LISION. MAGES SEE DETAILS Accident Date Survey held at HE INSPECTION WA	215/55R17 215/55R17 215/55R17 Description of the properties of th	BRIDGESTONE BRIDGESTONE BRIDGESTONE BRIDGESTONE Of Damages RTION. THE UNDEF formation Inspection Date UKIT AVENUE 6 #0* arks EJUDICE" BASIS.	6 6 6 RCARRIAGE AFFECTED DUE TO 19/08/2024 1-48 AUTOBAY @ KAKI BUKIT	

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days