



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987			S1000026 / ICECICS		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925		
			Document No. 0				
			Document Date 20/08/2024				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q2	21/11/2017	SLU0448P	0	32385	67/TP/SLU0448P
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU503575689		2ZRS110033	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP-SMX7709M ACC DATE:17/08/2024 TOW IN:19/08/2024 DATE-IN:19/08/2024 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				100.00	
2	B	BP-LAB2 REPLACE & REPAIR FRT ACC AFFECTED AREAS				1267.20	
3	B	BP-RES2 RESPRAY JOB ON FRT ACC AFFECTED AREAS				1049.60	
4	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR				158.40	
5	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST				158.40	
6	B	BP-LAB2 REPLACE & INSTALL REAR TAILGATE GLASS				475.20	
7	B	BP-LAB2 REPLACE & INSTALL REAR FIX GLASS				316.80	
8	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE				475.20	
9	Z	BP-SLANT SUPPLY SEALANT (NETT)				300.00	
10	B	BP-LAB2 REMOVE & INSTALL REAR SEAT,CAROET,GARNISH AND TRIMMING TO ASSIST REPAIR				633.60	
11	B	BP-MECH2 REMOVE & INSTALL FUEL TANK				633.60	
12	B	BP-MECH2 REMOVE & INSTALL REAR EXHAUST PIPE				316.80	
13	S	BP-SUBLET SUPPLY TYRE				380.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due

Company Copy



Borneo Motors

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details				
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987				S1000026 / ICECICS		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925				
				Document No. 0						
				Document Date 20/08/2024						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks			
2017	ZVW50R	AHXEBW Q2	21/11/2017	SLU0448P	0	32385	67/TP/SLU0448P			
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On			
JTDKB3FU503575689		2ZRS110033	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount	
14	B	BP-MECH2	REPLACE TYRE & RIM						158.40	
15	B	BP-MECH2	REPLACE & INSTALL REAR LH SUSPENSION SYS						633.60	
		TEM								
16	B	BP-MECH2	CONDUCT FULL WHEEL ALIGNMENT						158.40	
17	B	BP-ECU2	TO RESET ECU AND REPROGRAMME						158.40	
18	B	BP-LAB2	REPLACE REAR LH ACCIDENT DAMAGED PARTS						5702.40	
			STRAIGHTEN & ALIGN REAR LH ACCIDENT AFFECTED AREAS							
19	B	BP-RES2	RESPRAY JOB ON REAR LH ACCIDENT AFFECTED AREAS						5904.00	
20	1	U52119-47962	COVER, FR BUMPER				1.00	799.30	30.00	559.51
21	2	U53112-47240	GRILLE, RADIATOR,				1.00	237.60	30.00	166.32
22	3	U52159-47913	COVER, RR BUMPER				1.00	680.60	30.00	476.42
23	4	U52576-47040	RETAINER, RR BUMPER				1.00	177.50	30.00	124.25
24	5	U52575-47040	RETAINER, RR BUMPER				1.00	180.50	30.00	126.35
25	6	U52453-47010	GUARD, RR BUMPER,				1.00	884.60	30.00	619.22
26	7	U52566-47900	FILLER, RR BUMPER				1.00	170.50	30.00	119.35
27	8	U52565-47900	FILLER, RR BUMPER				1.00	170.50	30.00	119.35
28	9	U52023-47030	REINFORCEMENT				1.00	512.40	30.00	358.68
29	0	K52161-0K040	PIECE, RR BUMPER				10.00	5.80	30.00	40.60
30	1	U52169-47020	COVER, RR BUMPER,				1.00	21.40	30.00	14.98
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total			
			Please acknowledge receipt of vehicle		Parts		Less Amount Due			
					Labour					
					Sublet					
					Lubrication/Fluid					
					Others					

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987				S1000026 / ICECICS		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
				Document No. 0					
				Document Date 20/08/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2017	ZVW50R	AHXEBW Q2	21/11/2017	SLU0448P	0	32385	67/TP/SLU0448P		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTDKB3FU503575689		2ZRS110033	60	Sam San Joi	--/--/---- 0.00 --/--/----		0.00		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
31	2	U75392-35220 RETAINER, OUTSIDE				4.00	5.60	30.00	15.68
32	3	U52592-47040 SEAL, RR BUMPER				1.00	122.30	30.00	85.61
33	4	U58307-47090 PANEL SUB-ASSY, BODY				1.00	1000.10	30.00	700.07
34	5	U58311-47130 PAN, RR FLOOR				1.00	886.30	30.00	620.41
35	6	U58316-47012 EXTENSION, RR FLOOR				1.00	107.80	30.00	75.46
36	7	U66259-47010 COVER, RR BODY				1.00	318.60	30.00	223.02
37	8	U58399-47030 COVER, FLOOR UNDER,				1.00	334.70	30.00	234.29
38	9	U64716-47130 C0 COVER, DECK TRIM, RR				1.00	174.20	30.00	121.94
39	0	U64997-47060 BOX, DECK FLOOR, LH				1.00	433.30	30.00	303.31
40	1	U64993-47110 BOX, DECK FLOOR, RR				1.00	146.80	30.00	102.76
41	2	U64740-47190 C3 PANEL ASSY, DECK				1.00	492.80	30.00	344.96
42	3	U61602-47160 PANEL SUB-ASSY,				1.00	1339.40	30.00	937.58
43	4	U61622-47060 TROUGH, BACK DOOR				1.00	142.90	30.00	100.03
44	5	U62940-12200 DUCT ASSY, QUARTER				1.00	103.20	30.00	72.24
45	6	U77350-47050 LID ASSY, FUEL				1.00	234.60	30.00	164.22
46	7	U90269-06017 RIVET				2.00	5.40	30.00	7.56
47	8	U67005-47540 PANEL SUB-ASSY, BACK				1.00	1747.20	30.00	1223.04
48	9	U67881-47051 WEATHERSTRIP, BACK				1.00	515.40	30.00	360.78
49	0	U68105-47291 GLASS SUB-ASSY, BACK				1.00	2298.70	30.00	1609.09
50	1	U56117-50140 DAM, WINDOW GLASS				1.00	40.10	30.00	28.07
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total			
		Please acknowledge receipt of vehicle		Parts		Less Amount Due			
				Labour					
				Sublet					
				Lubrication/Fluid					
				Others					

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987			S1000026 / ICECICS		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
			Document No. 0					
			Document Date 20/08/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHXEBW Q2	21/11/2017	SLU0448P	0	32385	67/TP/SLU0448P	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKB3FU503575689		2ZRS110033	60	Sam San Joi	--/--/----		0.00 --/--/----	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
51	2	U64801-47031 GLASS SUB-ASSY, BACK			1.00	1052.00	30.00	736.40
52	3	U76801-47110 A1 GARNISH SUB-ASSY,			1.00	1283.40	30.00	898.38
53	4	U75403-48010 EMBLEM SUB-ASSY,			1.00	99.40	30.00	69.58
54	5	U75441-47130 PLATE, LUGGAGE COMPT			1.00	75.70	30.00	52.99
55	6	U75442-47130 PLATE, LUGGAGE COMPT			1.00	75.70	30.00	52.99
56	7	U67750-47080 C0 BOARD ASSY, BACK			1.00	358.40	30.00	250.88
57	8	U69350-47050 LOCK ASSY, BACK DOOR			1.00	647.10	30.00	452.97
58	9	U68810-47061 HINGE ASSY, BACK			1.00	84.90	30.00	59.43
59	0	U68810-47061 HINGE ASSY, BACK			1.00	84.90	30.00	59.43
60	1	U81561-47153 LENS & BODY, RR			1.00	677.90	30.00	474.53
61	2	U81498-47020 COVER, RR			1.00	89.40	30.00	62.58
62	3	U81496-52020 GUIDE, RR			2.00	3.60	30.00	5.04
63	4	U76817-26040 CLIP, BACK DOOR			2.00	5.10	30.00	7.14
64	5	U81591-47011 LENS & BODY, RR			1.00	777.30	30.00	544.11
65	6	T21000-20 SIKA 182010 SIKA TACK GO! (BLA			3.00	108.00	30.00	226.80
66	7	T21000-22 SIKA 207. G+P ADHESIVE PRIMER			2.00	200.00	30.00	280.00
67	8	SPC507-47001 16 BACK SENSOR WHITE PEARL SILVER			1.00	169.60	30.00	118.72
68	9	U42611-47450 WHEEL, DISC			1.00	2607.70	30.00	1825.39
69	0	U42602-47181 CAP SUB-ASSY, WHEEL			1.00	293.60	30.00	205.52
70	1	U48530-80791 ABSORBER SET, SHOCK,			1.00	176.20	30.00	123.34
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due		

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987			S1000026 / ICECICS		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
			Document No. 0					
			Document Date 20/08/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHXEBW Q2	21/11/2017	SLU0448P	0	32385	67/TP/SLU0448P	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKB3FU503575689		2ZRS110033	60	Sam San Joi	--/--/---- 0.00		--/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
71	2	U48730-47010 ARM ASSY, RR			1.00	628.60	30.00	440.02
72	3	U42305-47050 CARRIER SUB-ASSY, RR			1.00	1317.20	30.00	922.04
73	4	U48780-47010 ARM ASSY, TRAILING,			1.00	565.80	30.00	396.06
74	5	U48710-47010 ARM ASSY, RR			1.00	364.30	30.00	255.01
75	6	U48790-47010 ARM ASSY, UPR			1.00	641.00	30.00	448.70
76	7	U42450-76021 HUB & BRG ASSY, RR			1.00	824.00	30.00	576.80
77	8	T08826-08115 PANEL BONDING AD			1.00	267.20	30.00	187.04
For & on behalf of		Customer's Signature		Charge Summary		Total		38,767.04
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle				GST 9.00%		3,489.03
				Parts 19,787.04				
				Labour 18,600.00				
				Sublet 380.00				
				Lubrication/Fluid 0.00		Less 0.00		
				Others 0.00		Amount Due 42,256.07		